

Date: 04.01.2019
YTSS11F

TAXI SERVICE HISTORY

Time: 15:56:56
Page: 1

Taxi Nos: SHC8497L Model: I-40 Reg Date: 10.12.2015 Workshop: LY

Serviced on: 04.06.2018 / 15:14:00 Time Out: 04.06.2018 / 18:21:22
Remarks: (Next PM-18/07/2018 Time-10:30*)
Job Card Nos: 602798969 Type: JP Odometer Reading: 254,081

PM/PROBLEM REPORTED

HI6 HYUNDAI I-40 DOCKING 6
6.4 Engine Check Light ON [check intermittent 2x]
8.1 Engine Noisy [check]
14.1 Tyre Bald/Uneven Wear [check tyre noisy 70-80km/h check all tyre condition]
14.3 Wheel Alignment [check]
17.1 Wiper Blade/Washer [wiper blade change]
H000 Mechanic Team Repair - Wong Yau Bin
S010 AllBelts (except T/Belt)
S011 Engine/Transmission Service
S020 All Hoses & Clips (Check/Adjust/Replace)
S010 Brake System
S011 Tyres (Pressure Check)
S012 Tyre Rotation
S011 Undercarriage, Steering linkage & joints
S010 All Lightings
S021 All harness & connectors
S022 (i40) Check top hose bracket
S023 Check diesel / engine oil leakage
S030 llegal fittings, modifications & fusebox
S031 All seat belts & camera
S011 All coolant, fluid, water
S021 Service A/C filter and Radiator
S022 Clear A/C drain pipe
QC QC TEST BY LAT - Jeffrey Chong Kim Min

MATERIAL CHANGED

SN DESCRIPTION QTY
1 I40VC OIL FILTER 1.000 EAC
2 I40VC FILTER-AIR CLEANER 1.000 EAC
3 I40VC DIESEL FUEL FILTER 1.000 EAC
4 I40VC/IONIQ WIPER BLADE 16" (PASSENGER) 1.000 EAC
5 I40VC/IONIQ WIPER BLADE 26" (DRIVER) 1.000 EAC
6 I40VC ^PULLEY-IDLER DRIVE BELT 1.000 EAC
7 I40VC HANKOOK 205/60R16 H724 2.000 EAC
8 (ALL) (EURO IV)^ENGINE OIL F SYN SAE 5W30 4.900 L

REMARKS

SN DESCRIPTION
1 HI6 - 120,000 KM

Date: 04.01.2019
YTSS11F

TAXI SERVICE HISTORY

Time: 15:56:56
Page: 2

Serviced on: 18.06.2018 / 10:30:00 Time Out: 18.06.2018 / 14:29:00
 Remarks: (Check Light ON-1405 /2033 SENSOR*)
 Job Card Nos: 602824332 Type: JC Odometer Reading: 257,234

PM/PROBLEM REPORTED

 BRKD BREAKDOWN
 6.0 Mechanical Team Repair - Jeffrey Chong Kim Min
 6.4 Engine Check Light ON [P1405 P2033-sensor]
 QC QC TEST BY LAT - Jeffrey Chong Kim Min

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC ^SENSOR-EXH.TEMPERATURE	1.000 EAC

REMARKS

SN	DESCRIPTION
2	

Serviced on: 18.07.2018 / 10:48:00 Time Out: 18.07.2018 / 15:48:47
 Remarks: (Next PM-30/08/2018 Time-14:00)
 Job Card Nos: 602825443 Type: JP Odometer Reading: 264,337

PM/PROBLEM REPORTED

 H11 HYUNDAI I-40 DOCKING 1
 6.4 Engine Check Light ON [intermittance]
 15.5 Undercarriage Noisy - Front Suspension [check]
 15.6 Undercarriage Noisy - Rear Suspension [check]
 H000 Mechanic Team Repair - Wong Yau Bin
 S010 AllBelts (except T/Belt)
 S011 Engine/Transmission Service
 S020 All Hoses & Clips (Check/Adjust/Replace)
 S010 Brake System
 S011 Tyres (Pressure Check)
 S012 Tyre Rotation
 S011 Undercarriage, Steering linkage & joints
 S010 All Lightings
 S021 All harness & connectors
 S022 (i40) Check top hose bracket
 S023 Check diesel / engine oil leakage
 S030 llegal fittings, modifications & fusebox
 S031 All seat belts & camera
 S011 All coolant, fluid, water
 S021 Service A/C filter and Radiator
 S022 Clear A/C drain pipe
 QC QC TEST BY LAT - Chai Edwin

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC OIL FILTER	1.000 EAC
2	I40V2 SHOCK ABSORBER ASSY-RR	2.000 EAC
3	I40V2 LINK ASSY-FR STABILIZER	2.000 EAC
4	I40VC FILTER-AIR CLEANER	1.000 EAC
5	(ALL) (EURO IV) ^ENGINE OIL F SYN SAE 5W30	4.720 L

Date: 04.01.2019 TAXI SERVICE HISTORY Time: 15:56:56
 YTSS11F Page: 3

6	(ALL) (EURO IV) ^ENGINE OIL F SYN SAE 5W30	0.110 L
---	--	---------

REMARKS

 SN DESCRIPTION
 3 HI1 - 20,000 KM

Serviced on: 02.08.2018 / 08:00:00 Time Out: 03.08.2018 / 15:30:00
 Remarks: (OD 01.08.2018)
 Job Card Nos: 305195231 Type: OD Odometer Reading: 0

MATERIAL CHANGED

 SN DESCRIPTION QTY

1	I40VC MIRROR ASSY-RR VIEW O/S RH	1.000 EAC
2	I40VC PANEL-FENDER RH+	1.000 EAC
3	I40V3 BUMPER W LIP & FOG LAMP COVER+	1.000 EAC
4	I40V3 CAP ASSY-FR BPR	1.000 EAC
5	I40VC CAP ASSY-WHEEL HUB	1.000 EAC
6	I40V3 GUARD ASSY-FRONT WHEEL RH+	1.000 EAC
7	HYUNDAI BUMPER COVER CLIP REAR	10.000 EAC
8	(I40)FRT DOOR LOGO SONATA CTPL	1.000 EAC

Serviced on: 30.08.2018 / 13:50:00 Time Out: 30.08.2018 / 16:37:40
 Remarks: (+INSP+Next PM-11/10/2018 Time-08:30)
 Job Card Nos: 602852054 Type: JP Odometer Reading: 267,821

PM/PROBLEM REPORTED

 HI2 HYUNDAI I-40 DOCKING 2
 17.1 Wiper Blade/Washer [wiper blade change]
 H000 Mechanic Team Repair - Ismail Bin Ithnin
 S010 AllBelts (except T/Belt)
 S011 Engine/Transmission Service
 S020 All Hoses & Clips (Check/Adjust/Replace)
 S010 Brake System
 S011 Tyres (Pressure Check)
 S012 Tyre Rotation
 S011 Undercarriage, Steering linkage & joints
 S010 All Lightings
 S021 All harness & connectors
 S022 (i40) Check top hose bracket
 S023 Check diesel / engine oil leakage
 S030 llegal fittings, modifications & fusebox
 S031 All seat belts & camera
 S051 Check battery terminal secured
 S058 Check Fan Motor relay
 S059 Check CDI Wiring
 S060 Check Alt and Starter Harness
 S011 All coolant, fluid, water
 S021 Service A/C filter and Radiator
 S022 Clear A/C drain pipe
 QC QC TEST BY LAT - Ho Wee Beng

Date: 04.01.2019
 YTSS11F

TAXI SERVICE HISTORY

Time: 15:56:56
 Page: 4

MATERIAL CHANGED

 SN DESCRIPTION QTY

1	I40VC OIL FILTER	1.000	EAC
2	I40VC/IONIQ WIPER BLADE 26" (DRIVER)	1.000	EAC
3	I40VC/IONIQ WIPER BLADE 16" (PASSENGER)	1.000	EAC
4	I40VC HANKOOK 205/60R16 H724	2.000	EAC
5	(ALL) (EURO IV) ^ENGINE OIL F SYN SAE 5W30	5.310	L

REMARKS

SN	DESCRIPTION
----	-------------

1	HI2 - 40,000 KM
---	-----------------

Serviced on: 11.10.2018 / 09:06:00 Time Out: 11.10.2018 / 18:14:56
 Remarks: (Next PM-20/11/2018 Time-15:30[INSP])
 Job Card Nos: 602876187 Type: JP Odometer Reading: 285,858

PM/PROBLEM REPORTED

HI3	HYUNDAI I-40 DOCKING 3
INSP	PRE-VICOM INSPECTION
1.0	Aircon Team Repair - Chin Pau Keong
1.2	A/Con Poor Air Flow
11.1	Battery Weak/Terminal
12.1	Steering Noisy
14.2	Patch Tyre - FR / FL / RR / RL / S [FL]
17.1	Wiper Blade/Washer
H000	Mechanic Team Repair - Lew Shan Chi
S010	AllBelts (except T/Belt)
S011	Engine/Transmission Service
S020	All Hoses & Clips (Check/Adjust/Replace)
S010	Brake System
S011	Tyres (Pressure Check)
S012	Tyre Rotation
S011	Undercarriage, Steering linkage & joints
S010	All Lightings
S021	All harness & connectors
S022	(i40) Check top hose bracket
S023	Check diesel / engine oil leakage
S030	llegal fittings, modifications & fusebox
S031	All seat belts & camera
S051	Check battery terminal secured
S058	Check Fan Motor relay
S059	Check CDI Wiring
S060	Check Alt and Starter Harness
S011	All coolant, fluid, water
S021	Service A/C filter and Radiator
S022	Clear A/C drain pipe
QC	QC TEST BY LAT - Ho Wee Beng
S010	Fire Extinguisher

Date: 04.01.2019
YTSS11F

TAXI SERVICE HISTORY

Time: 15:56:56
Page: 5

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC OIL FILTER	1.000 EAC
2	I40VC V-RIBBED BELT	1.000 EAC
3	I40VC CABIN FILTER ASSY-AIR	1.000 EAC

4	I40V2 BRKT ASSY-ROLL ROD	1.000	EAC
5	I40VC ^^PULLEY-DAMPER	1.000	EAC
6	I40VC/IONIQ WIPER BLADE 26" (DRIVER)	1.000	EAC
7	I40VC/IONIQ WIPER BLADE 16" (PASSENGER)	1.000	EAC
8	I40VC HANKOOK 205/60R16 H724	2.000	EAC
9	(I40)ATF, FULLY SYN SPIV	4.000	L
10	(ALL) (EURO IV) ^ENGINE OIL F SYN SAE 5W30	4.630	L
11	I40VC MOTOR HEATER BLOWER	1.000	EAC

REMARKS

SN	DESCRIPTION
2	HI3 - 60,000 KM

Serviced on: 20.11.2018 / 14:48:00 Time Out: 20.11.2018 / 16:17:10
 Remarks: (Next PM-27/12/2018 time-10:30)
 Job Card Nos: 602900178 Type: JP Odometer Reading: 296,306

PM/PROBLEM REPORTED

HI4	HYUNDAI I-40 DOCKING 4
14.1	Tyre Bald/Uneven Wear [check all tyre / noisy]
14.3	Wheel Alignment [check]
17.1	Wiper Blade/Washer [wiper blade change]
H000	Mechanic Team Repair - Ng Jui Chun
S010	AllBelts (except T/Belt)
S011	Engine/Transmission Service
S020	All Hoses & Clips (Check/Adjust/Replace)
S010	Brake System
S011	Tyres (Pressure Check)
S012	Tyre Rotation
S011	Undercarriage, Steering linkage & joints
S010	All Lightings
S021	All harness & connectors
S022	(i40) Check top hose bracket
S023	Check diesel / engine oil leakage
S025	Check vehicle boot hinges
S030	llegal fittings, modifications & fusebox
S031	All seat belts & camera
S051	Check battery terminal secured
S058	Check Fan Motor relay
S059	Check CDI Wiring
S060	Check Alt and Starter Harness
S011	All coolant, fluid, water
S021	Service A/C filter and Radiator
S022	Clear A/C drain pipe
QC	QC TEST BY LAT - Chuah Shau Liang

Date: 04.01.2019
YTSS11F

TAXI SERVICE HISTORY

Time: 15:56:56
Page: 6

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC OIL FILTER	1.000 EAC
2	I40VC/IONIQ WIPER BLADE 26" (DRIVER)	1.000 EAC
3	I40VC/IONIQ WIPER BLADE 16" (PASSENGER)	1.000 EAC
4	(ALL) (EURO IV) ^ENGINE OIL F SYN SAE 5W30	4.530 L

REMARKS

SN	DESCRIPTION
3	HI4 - 80,000 KM

Serviced on: 20.12.2018 / 22:13:55 Time Out: 20.12.2018 / 23:00:00
Remarks: (VRS-BATTERY)
Job Card Nos: 305253112 Type: Z1 Odometer Reading: 0

Serviced on: 20.12.2018 / 22:45:00 Time Out: 20.12.2018 / 22:45:00
Remarks: (RNW BATTERY-CLY)
Job Card Nos: 305253209 Type: TC Odometer Reading: 0

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	(I40)BATTERY ASSY 110D26LBH 12V80AH	1.000 EAC

Serviced on: 23.12.2018 / 20:55:00 Time Out: 00.00.0000 / 00:00:00
Remarks: (OD 23.12.18 / FIRE CASE)
Job Card Nos: 305254416 Type: OD Odometer Reading: 0

Serviced on: 23.12.2018 / 21:28:59 Time Out: 23.12.2018 / 22:45:00
Remarks: (ARC-FIRE CASE)
Job Card Nos: 305253832 Type: Z1 Odometer Reading: 0

Serviced on: 27.12.2018 / 10:30:00 Time Out: 00.00.0000 / 00:00:00
Remarks: (Next PM-12/02/2019 Time-14:00)
Job Card Nos: 602921234 Type: JP Odometer Reading: 0

PM/PROBLEM REPORTED

HI5	HYUNDAI I-40 DOCKING 5	
H000	Mechanic Team Repair	
S010	AllBelts (except T/Belt)	
S011	Engine/Transmission Service	
S020	All Hoses & Clips (Check/Adjust/Replace)	
Date: 04.01.2019	TAXI SERVICE HISTORY	Time: 15:56:56
YTSS11F		Page: 7

S010	Brake System
S011	Tyres (Pressure Check)
S012	Tyre Rotation
S011	Undercarriage, Steering linkage & joints
S010	All Lightings
S021	All harness & connectors
S022	(i40) Check top hose bracket
S023	Check diesel / engine oil leakage
S025	Check vehicle boot hinges
S030	llegal fittings, modifications & fusebox
S031	All seat belts & camera
S051	Check battery terminal secured
S058	Check Fan Motor relay
S059	Check CDI Wiring
S060	Check Alt and Starter Harness

S011 All coolant, fluid, water
S021 Service A/C filter and Radiator
S022 Clear A/C drain pipe
QC QC TEST BY LAT

REMARKS

SN	DESCRIPTION
1	HI5 - 100,000 KM

Verify by: _____

*****End of report*****