

13/01/2019

ASS. REC. BY:

REF: CS3 / III 18020319 / N16-1

Special Instruction:

SUBJECT

N/AZ

ASSIGNMENT (Office)

From (Person):

Stanley Lui

of

III

Date/Time:

04/01/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 1521G

Insured:

SHA 4203E

at Workshop m/s

Kent Seng

Tel:

9004 8959

of

Bld 1016 Tishum Ind Park A #01-238

Policy No:

Claim No:

MCT18110227

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/12/18

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time:

01/12/18 10:15am

Person Contacted

An Seng

H.O.D. Endorsement:

Vehicle

OUT

Date/Time

Action/Instruction (X) Estimate

01/12/18 - X

SHA 4203E - NA / MSH1605773 / KY

01/12/18

18/1/2019

Dismantle: 13/11/2018 @ 10am

After repair: 16/11/2018 @ 11.25am

07/01/2019

Pending colour photograph from III

lump sum \$4550/- (Red: 1700; 27.2%)

7 days.

RECEIVED 22 JAN 2019

250-120-130

Catherine Chong (LKK Auto)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Sunday, 6 January, 2019 8:09 AM
To: Mekavathanan Sarangapani
Cc: Sundari Nagarajan - III; Natalia Lim; Stanley Lai; assignments; SUR
Subject: RE: MCT18110227 *LKK Ref: CS3/III18020319/Ncbe2

Dear Mr Meka,

Thank you for your email.

By copy to Assign/ SUR Team,

FYNA. CS3/III18020319/Ncbe2

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Sent: Friday, 4 January 2019 7:21 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Sundari Nagarajan - III <sundari@iii.com.sg>; Natalia Lim <NataliaLim@iii.com.sg>; Stanley Lai <stanley.lai@iii.com.sg>
Subject: MCT18110227

Paper survey please claim thru TP lawyers for S\$ 6K odd ??

Meka

REFERENCE

Handling Insurer: India International Insurance Pte Ltd
 Claimant Vehicle No : SMD1521G
 Date of Loss: 07/11/2018

Policy No:
 Insured Vehicle No :
 Nature of Claim:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1521G	
Make & Model:	HONDA CITY, 1.5 (A)	Engine /
Reg. Date	06/10/2016 (Man. Year: 2016)	Chassis
Colour:	Maroon	Odometer
Engine Capacity:	1497 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$)	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (S
Handbrake (Serviceable):	Yes	Engine Modification:	No
			Pre-accident

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:
Front Left Side:	Pirelli 6 mm	Rear Left Side:
Front Right Side:	Pirelli 6 mm	Rear Right Side:


The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's
Parts	0.00	0.00
Miscellaneous Items	0.00	0.00
Labour	0.00	0.00
Paintwork/Labour	0.00	0.00
Towing	0.00	0.00
Nett Amount (S\$)	0.00	0.00

INSPECTION

Date of Assignment:	09/11/2018		
Date Inspected:	09/11/2018	Inspected At:	Kent Seng Car Services (Yishun) (HQ)
			Blk 1016 Yishun Industrial Park A #01-23
			Singapore 768758



CUMSTANCES OF THE ACCIDENT

ON 7 NOV 2018 2215 hrs I VEH (A)

was driving along the above location

to make a left turn to CTE / PIE.

Suddenly VEH B instant E. brake I VEH A

cannot stop in time and hit VEH B rear.

at the point of accident VEH A going at

max. PAX not injured.

Accident Photo



8.26 x 11.69 in

Accident Photo



(03109.10)

Main	Offer Processing	Claim Details	Adjuster's Details	Docum
CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	-			
Vehicle Reg. No.:	SMD1521G	Date of Loss:	07/11/2018 00:00 - :59 [25 Months and 1 Days From	
Claim Type:	TP / MCT18110227	Policy/Cover Note No.:	MCOM0016	
Vehicle Reg. No. (Insured):	SHA4203E	Policy No. (Claimant):		
		Excess:		
Repairer:	Kent Seng Car Services (yishun) (HQ) PROFILE Blk 1016 Yishun Industrial Park A #01-238, 768758			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 634			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah 23/11/2018]			
CLAIM REGISTERED				

Best Regards,

Mekavathanan
HOD

Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6105 Fax: 6224 4174

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

MCT 1810227/01/SJO

	RESERVES			
	TPPD	PRESERVE		
	TPPI	PRESERVE		
	UNINSURED LOSS	PRESERVE		
	SUBRO	PRESERVE		
	LPPN			
	INVESTIGATION FEE			
	SURVEY FEES			
	LEGAL FEES			
	OTHERS			
	FRAUD CHECK			
	UPLOAD TO MERIMEN			
	GRANT RIGHTS			

MM
PL ✓
FL

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter



Branch Office: No. 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : lgene.lim@mneducos.com.sg

Our Ref : MN.JG.K2.1812752.st

Your Ref : SHA 4203E

3rd January 2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street,
#04/06-00, IOB Building
Singapore 049711

"WITHOUT PREJUDICE"
BY HAND

COMFORT TRANSPORTATION PTE LTD

383 Sin Ming Drive
Gas Building
Singapore 575717

CERTIFICATE OF POSTING
(for your information only)

Dear Sir,

CLAIMANT : MOHAMED YUNUS TAMIMUL ANSARI
ACCIDENT ON 01/10/2016 INVOLVING VEHICLES NO. SMD 1521G AND GBE 684B ALONG KENT ROAD AT ABOUT 1210 HOURS

We act for MOHAMED YUNUS TAMIMUL ANSARI, who was the owners of vehicle no. SMD 1521G.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 07/11/2018 ALONG SERANGOON ROAD involving our client's vehicle registration number SMD 1521G and vehicle registration number SHA 4203E driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01. Cost of Repair	S\$ 6,250.00
02. Rental fees for 9 days x \$120.00 per day	S\$ 1,080.00
03. Loss of Use for 2 days Pre-repair Survey	S\$ 160.00
04. Survey report fees	S\$ 643.00
05. GIA & LTA search fees	S\$ 36.49
06. Costs & Incidentals	S\$ 1,060.00
	<u>S\$ 9,229.49</u>

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

Page 2

Our Ref : MN.IG.K2.1812752.st

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SMD 1521G;
- (b) LTA Search;
- (c) Certificate of Insurance;
- (d) Rental agreement;
- (e) Final Repair Bill;
- (f) Surveyor's report & invoice and
- (g) **125 black and white photographs** depicting the damages to motor vehicle SMD 1521G.
[coloured-print photos will be forwarded to insurance company upon request]

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that a Notice of accident dated 8/11/2018 was sent to your insurers. A pre-repair survey on our client's damaged vehicle was carried out by your insurer's appointed surveyor.

Please also note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

M NEDUMARAN & CO

NEDUMARAN MUTHUKRISHNAN
(Branch Office)

Encls

cc. Client (By Fax 6753-0921 Only) – SMD 1521G

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 13:28
Date Of Accident	07/11/2018 22:50
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD1521G
Insured/Policyholder	
Name Of Registered Owner	MOHAMED YUNUS TAMIMUL ANSARI
NRIC No	S7561916B
Email Address	ANSARY2K@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91013674
Alternative Phone No	OTHERS-91013674
Vehicle Particulars	
Manufacturer	HONDA
Model	CITY 1.5 SV CVT
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103296550
Cover Note Number	29/08/18 - 28/08/19
Driver	
Name of Driver	MOHAMED YUNUS TAMIMUL ANSARI
NRIC No	S7561916B
Date Of Birth	28/09/1975
Occupation	INDOOR
Date Of Driving Pass	13/08/2018
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91013674
Fax Number	
Contact Number	OTHERS-91013674
Email Address	ANSARY2K@YAHOO.COM

Address	BLK 303 ANG MO KIO AVE 1 #06-1103
Postcode	560303
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED. (REPAIR BY KENT SENG VEHICLE REPAIRER)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA4203E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	WOO PENG HUI, ALVIN
NRIC/Passport Number	S8327526Z
Contact Number	92398501
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


VEHICLE NO.: SM21521G
INSURER: MSAC
DATE & TIME: 7/11/16 10:50pm


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am Mohammed Yunus Tahir Address: Je no: 57561916B
Making the Report about a Accident happened last night
10.50 PM Dated: 07- November 2018. (My car no 57561916B)
When I was driving to New Makio from Tekka
At the junction of End of Springest Road and to turn
LTF Exit I stopped my car to give way for the
Car crossing at the junction.
Unfortunatly the Taxi no: SHA 4203E Hit behind
my car - m/c heavy damage - as taken in the photo

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
Title: _____

() Claim Own Policy () Claim Third Party () Reporting Only
(x) Claim OOTPA at other workshop (None sent vol 48 Admin)

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SHA4203E As At 07 Nov 2018 / 22:50:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MN.IG.K2.1812752

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHA4203E
Make Description/Model: TOYOTA / PRIUS HYBRID 1.8 CVT
Insurance Company Name: INDIA INT'L INS PTE LTD



Lim Hwee Peng has successfully logged out.


Your last login date and time was 08 Nov 2018, 14:29:27.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (\$)	Log Date/Time
1	Vehicle	SHA4203E	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	08 Nov 2018 / 14:30:59



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

	EFFECTIVE DATE
Class 2B Motorcycles <= 200 cc	13 Aug 2018
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	13 Aug 2018

HP 428A



4584938

REG No: S7561916B

Date of Issue

07-08-2018

APT BLK 333 ANG MO KIO AVENUE 3 #05-1103
SINGAPORE 600003

S7561916B 04/09/2013

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5103296550

Cover : drive CLASSIC

- | | |
|---|--------------------------------|
| 1. Index mark and Registration Number of Vehicle | : SMD1S21G |
| Chassis Number | : MRHGM6660HP000259 |
| 2. Name of Policyholder | : MOHAMED YUNUS TAMIMUL ANSARI |
| 3. Effective Date of Insurance | : 29 Aug 2018 |
| 4. Expiry Date of Insurance | : 28 Aug 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover:

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: MOHAMED YUNUS TAMIMUL ANSARI
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DICKSON CAPITAL PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DICKSON INSURANCE AGENCY PTE. LTD. (00000573832)
Date of Issue : 29 Aug 2018 13:24 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

RENTAL AGREEMENT

Hirer's Name Mohamed Yunus Tamimi Ancari		Date of Birth	Passport/ Nric No. S7561916 B	Nationality
Address BK 303 Ang Mo Kio Ave 1		Occupation	Driving Licence No.	Date of Expiry
#06-1103	Postal Code 560303	Contact No.	Mobile Phone No.	
Joint Hirer's / Guarantor's Name		Date of Birth	Passport/ Nric No.	Nationality
Address		Occupation	Driving Licence No.	Date of Expiry
	Postal Code	Contact No.	Mobile Phone No.	

CHECK OUT

CHECK IN

Date 8.11.18	Time	Mileage KM	<table border="1"> <tr> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> </table>	E	1/4	1/2	3/4	F
E	1/4	1/2		3/4	F			
Date 17.11.18	Time	Mileage KM	Remarks					

IMPORTANT NOTES:-

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability - First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension:- One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT		RATE (\$)	TOTAL (\$)
RATE	9	@	\$120	\$1,080
DISCOUNT				
GST @ 7%				
TOTAL				
EXTENSION				
DEPOSIT (refundable) S\$	NIL			
CHANGED OVER FROM VEH.				DATE

I/We have read and agree to the terms and conditions of the rental agreement above and as set out hereat.
I/We declare that all information given on this form is true and accurate.


Hirer's Signature

Joint Hirer's/ Guarantor's Signature


for CHAN'S & SONS ENTERPRISE

VEHICLE NO. **SLA8516D**

MODEL **Toyota AHA 1.6 (A)**

FROM

RETURN

*Estimate Date. For actual return see CHECK IN

吉成修理汽車
KENT SENG CAR SERVICES

No. 1461

BLK 1017 YISHUN INDUSTRIAL PARK A #01-240 SINGAPORE 768759
TEL : 6257 9074 / 6758 8367 FAX : 6753 0921

Mr. Mohamed Yunus Tamimul Ansari 寶號先生

CASH / INVOICE

車號
Vehicle No. SMD 15219

TEL:

Date. 30-12-18

[illegible]



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

Messrs. Mohamed Yunus Tamimul Ansari
Block 303, Ang Mo Kio Avenue 1
#06-1103
Singapore 560303

Bill No. DN/TP/18/0207/KSCS
18/12/2018

Dr.

To

Survey Fee (S \$):
Photographs (S \$):
Transport (S \$):
Resurvey (S \$):
Site-Survey (S \$):

Services rendered including photographs and transport charges

(S \$) 643.00

Our reference : TP/0160/01/18
Insured :
Policy / Cert. No. :
Your Claim No. : Third Party Claim
Vehicle : : Honda City (A) - SMD 1521 G
Dollars : : Six Hundred Forty Three Only

Checked by

for PRIORITY SERVICES

E. & O. E.

Only our official receipt will be recognised for payment made on this account



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No.	TP/0160/01/18	Date of Report	: 18 December 18
To :	Mohamed Yunus Tamimul Ansari	Date of Request	: 8 November 18
		Report requested by	: Mohamed Yunus Tamimul Ansari
Block 303, Ang Mo Kio Avenue 1		Date of Accident	: 7 November 18
#06-1103		Date of Inspection	: 8 November 18
Singapore 560303		Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SMD 1521 G	Odometer Reading	: 58,958 km
Make	: Honda	Carrying Capacity	: 4
Model	: City (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2016	Air-Conditioner	: Yes
Colour	: Metallic Maroon	Wing Mirror	: Yes
Engine Capacity	: 1,497 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: MRHGM6660HP000259	Others	: Nil

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Pirelli	Make	: Pirelli
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Pirelli	Make	: Pirelli
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	6,417.60	4,270.40
Labour Charges :	2,490.00	1,890.00
Paint Work :	1,550.00	1,200.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	10,457.60	7,360.40

Reduction (S \$) : 4,207.60

Recommended Reserve (S \$) : 6,250.00 (Lump Sum)

Estimated Normal Period of Repairs : 9 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at Kent Seng Car Services, Block 1017, Yishun Industrial Park A, #01-240, Singapore 768759.

Follow-up inspection has been conducted.

Point of Impact

At the rear portion.

Damages

The boot lid, boot lid lamps, rear bumper, rear bumper reverse sensors, end panel, tail-lamps assembly, tail-lamp panels, spare tyre panel, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$7,360.40

Conclusion


The repairer has agreed to undertake repairs at a lump sum of \$6,250.00

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SMD 1521 G Honda City (A)
Workshop : Kent Seng Car Services

TP/0160/01/18

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %	
To Supply :						
1pc. Boot lid	Dented / Distorted	585.20		585.20	20	DEF
1pc. Boot lid 'City' emblem	Necessary	33.70		33.70	20	NE
1pc. Boot lid centre emblem	Necessary	37.10		37.10	20	NE
1pc. Boot lid 'i-Vtec' emblem	Necessary	28.90		28.90	20	NE
1pc. Boot lid LH lamp	Defaced	125.80		125.80	20	SC
1pc. Boot lid RH lamp	Defaced	125.80		125.80	20	SC
1pc. Boot lid RH number plate lamp	Refit	32.60		--	20	XSV
1pc. Boot lid LH number plate lamp	Cracked	32.60		32.60	20	XSV
1pc. Boot lid lock	Bent	110.30		110.30	20	BS
1pc. Boot lid lock catch	Bent	27.10		27.10	20	B
1pc. Boot lid RH hinge	Bent	79.50		79.50	20	KN
1pc. Boot lid LH hinge	Bent	79.50		79.50	20	KN
1pc. Boot lid chrome moulding	Refit	109.60		--	20	BSV
1pc. Boot lid inner trim	Refit	99.70		--	20	XSV
1set. Boot lid inner trim clips	Necessary	30.00		30.00	20	NE
1pc. Boot lid weatherstrip	Bent	101.60		101.60	20	DEF
1pc. Rear bumper	Dented	503.70		503.70	20	DEF
1pc. Rear bumper RH side reflector	Cracked	34.80		34.80	20	DEF
1pc. Rear bumper LH side reflector	Cracked	34.80		34.80	20	DEF
1pc. Rear bumper LH side retainer	Cracked	29.00		29.00	20	DEF
1pc. Rear bumper RH side retainer	Cracked	29.00		29.00	20	DEF
1pc. Rear bumper RH side reverse parking sensor	Dented / Malfunction	154.10		154.10	20	DEF
1pc. Rear bumper RH centre reverse parking sensor	Dented / Malfunction	154.10		154.10	20	DEF
1pc. Rear bumper LH centre reverse parking sensor	Dented / Malfunction	154.10		154.10	20	DEF
1pc. Rear bumper LH side reverse parking sensor	Dented / Malfunction	154.10		154.10	20	DEF
1pc. RH tail-lamp panel	Dented / Repair	88.80		--	20	XR
1pc. RH tail-lamp	Defaced	381.70		381.70	20	SCR
1set. RH tail-lamp lock clips	Necessary	20.00		20.00	20	NE
1pc. LH tail-lamp panel	Dented / Repair	88.80		--	20	XR
1pc. LH tail-lamp	Defaced	381.70		381.70	20	SCR
1set. LH tail-lamp lock clips	Necessary	20.00		20.00	20	NE
1pc. End panel	Dented	476.70		476.70	20	DEF
1pc. End panel inner garnish	Deformed	96.60		96.60	20	DEF
1pc. End panel buzzer sensor	Cracked	91.50		91.50	20	DEF
1pc. Rear fender RH inner trim	Torn / Deformed	140.90		140.90	20	KN
1set. Rear fender RH inner trim clips	Necessary	35.00		35.00	20	KN
1pc. Rear fender LH inner trim	Torn / Deformed	140.90		140.90	20	KN
1set. Rear fender LH inner trim clips	Necessary	35.00		35.00	20	KN
1pc. Spare tyre board	Cracked	119.30		119.30	20	DEF
1pc. Spare tyre panel	Dented / Distorted	548.90		548.90	20	DEF
1pc. Spare tyre panel insulator	Necessary	165.00		165.00	20	DEF
1pc. Exhaust silencer	Refit	580.10		--	20	XSV

1049 10

Vehicle No : SMD 1521 G Honda City (A)
Workshop : Kent Seng Car Services

TP/0160/01/18

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1set. Rear bumper clips	Necessary	40.00		40.00	20
Sub-Total :-		6,337.60		4794.60	
Total Discount :-		--		1,067.60	
		6,337.60		3,825.68	
Special Nett Items :-					
1pc. Rear number plate	Refit	80.00		--	
Total For Parts :-		6,417.60		4,270.40	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment.		1,600.00		1,300.00	800
Apply rust coating on the replaced & repaired panels.		100.00		70.00	50
Apply joint sealant on the replaced & repaired panels.		100.00		80.00	50
Remove, re-install & replace rear inner trims, garnishes & boards to assist repairs.		250.00		180.00	60
Remove, re-install & replace rear bumper reverse sensors & wire harness to assist repairs.		150.00		80.00	30
Remove & re-install exhaust silencer, rubber hangers & heat shield to assist repairs.		120.00		80.00	50
Check wiring & lighting system.		70.00		30.00	
Remove, re-install & re-adjust boot lid reverse camera.		100.00		70.00	30
Spray Painting :					
To putty & spray repaired & replaced body panels.		1,550.00		1,200.00	800
				1180	
Grand Total :-		10,457.60		7,360.40	

Surveyed By : Lawrence Ng

5015.68 / 7 DAY



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18020319/Ntbe2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 23-01-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4203E	Veh. Inspected	SMD 1521G
Policy No.		Coverage (\$)	0.00
Claim No.	MCT18110227	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	04/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CITY	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHGM6660HP000259	Colour	MAROON
Odometer	58959	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/11/2018	Inspection Date	09/11/2018
Survey held at	KENT SENG VEHICLE REPAIRER BLOCK 1016, YISHUN IND. PARK A #01-238 SINGAPORE 768758		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1521G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DEFORMED	585.20	585.20
1	BOOT LID 'CITY' EMBLEM	NECESSARY	33.70	33.70
1	BOOT LID CENTRE EMBLEM	NECESSARY	37.10	37.10
1	BOOT LID 'I-VTEC' EMBLEM	NECESSARY	28.90	28.90
1	BOOT LID LH LAMP	SCRATCHED	125.80	125.80
1	BOOT LID RH LAMP	SCRATCHED	125.80	125.80
1	BOOT LID RH NUMBER PLATE LAMP	SERVICEABLE	32.60	-
1	BOOT LID LH NUMBER PLATE LAMP	SERVICEABLE	32.60	-
1	BOOT LID LOCK	BENT	110.30	110.30
1	BOOT LID LOCK CATCH	BENT	27.10	27.10
1	BOOT LID RH HINGE	NOT NECESSARY	79.50	-
1	BOOT LID LH HINGE	NOT NECESSARY	79.50	-
1	BOOT LID CHROME MOULDING	SERVICEABLE	109.60	-
1	BOOT LID INNER TRIM	SERVICEABLE	99.70	-
1	SET BOOT LID INNER TRIM CLIPS	NECESSARY	30.00	30.00
1	BOOT LID WEATHERSTRIP	DEFORMED	101.60	101.60
1	REAR BUMPER	DEFORMED	503.70	503.70
1	REAR BUMPER RH SIDE REFLECTOR	CRACKED	34.80	34.80
1	REAR BUMPER LH SIDE REFLECTOR	CRACKED	34.80	34.80
1	REAR BUMPER LH SIDE RETAINER	CRACKED	29.00	29.00
1	REAR BUMPER RH SIDE RETAINER	CRACKED	29.00	29.00
1	REAR BUMPER RH SIDE REVERSE PARKING SENSOR	DEFORMED	154.10	154.10
1	REAR BUMPER RH CENTRE REVERSE PARKING SENSOR	DEFORMED	154.10	154.10
1	REAR BUMPER LH CENTRE REVERSE PARKING SENSOR	DEFORMED	154.10	154.10
1	REAR BUMPER LH SIDE REVERSE PARKING SENSOR	DEFORMED	154.10	154.10
1	RH TAIL-LAMP PANEL	TO REPAIR SEE LABOUR	88.80	-
1	RH TAIL-LAMP	SCRATCHED	381.70	381.70
1	SET RH TAIL-LAMP LOCK CLIPS	NECESSARY	20.00	20.00

Report Ref No. CS3/III18020319/Ntbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH TAIL-LAMP PANEL	TO REPAIR SEE LABOUR	88.80	-
1	LH TAIL-LAMP	SCRATCHED	381.70	381.70
1	SET LH TAIL-LAMP LOCK CLIPS	NECESSARY	20.00	20.00
1	END PANEL	DENTED	476.70	476.70
1	END PANEL INNER GARNISH	DEFORMED	96.60	96.60
1	END PANEL BUZZER SENSOR	CRACKED	91.50	91.50
1	REAR FENDER RH INNER TRIM	NOT NECESSARY	140.90	-
1	SET REAR FENDER RH INNER TRIM CLIPS	NOT NECESSARY	35.00	-
1	REAR FENDER LH INNER TRIM	NOT NECESSARY	140.90	-
1	SET REAR FENDER LH INNER TRIM CLIPS	NOT NECESSARY	35.00	-
1	SPARE TYRE BOARD	CRACKED	119.30	119.30
1	SPARE TYRE PANEL	DEFORMED	548.90	548.90
1	SPARE TYRE PANEL INSULATOR	NECESSARY	165.00	150.00
1	EXHAUST SILENCER	SERVICEABLE	580.10	-
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
	LESS 20% DISCOUNT		-	-955.92
			6,337.60	3,823.68
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	80.00	-
			80.00	-
	LABOUR			
	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT. INCLUSIVE OF THE REPAIR OF RH TAIL-LAMP PANEL AND LH TAIL-LAMP PANEL.		1,600.00	800.00
	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS.		100.00	50.00
	APPLY JOINT SEALANT ON THE REPLACED & REPAIRED PANELS.		100.00	50.00
	REMOVE, RE-INSTALL & REPLACE REAR INNER TRIMS, GARNISHES & BOARDS TO ASSIST REPAIRS.		250.00	60.00

Report Ref No. CS3/III18020319/Ntbe2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE, RE-INSTALL & REPLACE REAR BUMPER REVERSE SENSORS & WIRE HARNESS TO ASSIST REPAIRS.		150.00	30.00
	REMOVE & RE-INSTALL EXHAUST SILENCER, RUBBER HANGERS & HEAT SHIELD TO ASSIST REPAIRS.		120.00	50.00
	CHECK WIRING & LIGHTING SYSTEM.		70.00	30.00
	REMOVE RE-INSTALL & RE-ADJUST BOOT LID REVERSE CAMERA.		100.00	30.00
	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS.		1,550.00	800.00
			4,040.00	1,900.00
GRAND TOTAL			10,457.60	5,723.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,550.00

Report Ref No. CS3/III18020319/Ntbe2-1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.