

ASS. REC. BY:

REF

CS/FCI190000299/Uvd3

n2

Special Instructions

Surveyor

Manly

ASSIGNMENT (Office)

From (Person)

Karen Tan

of

PCI

Date/Time: 10:28am @ 7/1/19

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBA 9987P

Insured:

SHA 0716T

at Workshop m/s

Kivile Enterprise

Tel:

67488645

of

Blk 3007 Ubi Rd 1 # 01-408

Policy No:

Claim No:

D19000032MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/12/2018

CA / REV / REP. / REV 24 HRS

CDS

H.O.D. Endorsement:

Date/Time: 10:36am @ 7/1/19

Person Contacted:

Irene

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBA 9987P - CIG/AG17006081/ App 3y 2 DUA: 21/03/2017
	SHA 0716T - NR/AG17024093/r3 DUA: 19/12/2017
8/1/19	Email preli revised to PCI

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FA9887Pat Workshop m/s Kivile

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$6500

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

31/3/2020
Vehicle: IN / OUTVeh No: FA9887PYr Regn: 41 00

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB400c.c. 399Colour: Red

A/C: Insured / Std / M / NA

Sp. Reading: _____

T/Radio: Insured / Std / M / NA

Eng/No: NC391011136C/No: NC2362011137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60ZR17R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 25/12/18D.O.I. 7/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/1/19 LTA 117
2/5 \$3500 confirmed with owner. (Red 4640, 571)

MV: \$6500 (Est) LTA: \$117 NV: \$6383

RECEIVED 16 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

15/1 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$

3500/2)Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

160505085345



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000032MFSH

Our ref: CS/FCI19000299/Uvd3

DATE: 8/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. FBA 9987P


We thank for your instruction on 7/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 7/1/2019 at the premises of M/s KIVILE ENTERPRISE and have the following to report:-

Workshop Estimate Amount	: S\$8,140.00
Revised Estimate Amount	: S\$4,967.50
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion and o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	27-12-2018	Our Ref No. D19000032MFSH
Accident Date	25-12-2018	Claim Type. Third Party
Insured Vehicle	SHA0716T	Third Party Vehicle. FBA9987P
Survey Location	BLK 3007 UBI ROAD 1 #01-408	
Contact Person.	IRENE TOH	
Contact No.	67488645/ 0	Fax No. 67482553
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KIVILE ENTERPRISE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 January 2019 9:29 AM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000032MFSH/1, FBA 9987P
Attachments: FBA 9987P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBA 9987P
Date of survey: 7/1/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 7 January 2019 10:38 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000032MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 7 January 2019 10:28 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000032MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Honda CB400 Super 4 Spec 1

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Spec 1 (/listing/usedbike/model/honda-cb400-super-4-spec-1/)
Engine Capacity	399cc
Classification	2A
Registration Date	06/12/2000
COE Expiry Date	31/03/2020 (1 years 2 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

Price: ^{SGD}\$6000

DETAILS

Eligible for NEA Cash Incentive of \$3500. Honda CB400 Super 4 Spec 1 for Sale. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place! No Early Settlement Fee.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/LISTING/USEDBIKES/LISTING/)



Honda CB400 Super 4 Spec 1



Honda CB400 Super 4 Spec 1

Honda CB400 Super 4 Spec 1

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Spec 1 (/listing/usedbike/model/honda-cb400-super-4-spec-1/)
Engine Capacity	399cc
Classification	2A
Registration Date	25/09/2000
COE Expiry Date	31/08/2019 (7 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

Price: SGD\$6500

DETAILS

Eligible for NEA Cash Incentive of \$3500. Upgrade to Vtec2. New ECU & Meter. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place! No Early Settlement Fee.

Accessories

U

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1052J

Vehicle Details

Vehicle No.: FBA9987P
Vehicle to be Exported: No
Intended Deregistration Date: 07 Jan 2019
Vehicle Make: HONDA
Vehicle Model: CB400SFYJ
Primary Colour: Red
Manufacturing Year: 2000
Engine No.: NC23E2011137
Chassis No.: NC391011136
Maximum Power Output: -
Open Market Value: \$8,750.00
Original Registration Date: 24 Apr 2000
First Registration Date: 24 Apr 2000
Transfer Count: 7
Actual ARF Paid: \$1,313.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2020
COE Category: D - Motorcycle
COE Period(Years): 10
PQP Paid: \$884.00
COE Rebate Amount: \$117.00
Total Rebate Amount: \$117.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 07 Jan 2019



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBA9987P MODEL: HONDA CB 400

Handle Bar	Self	110	✓
Handle Balance	Self	45	✓
Handle Grip	Self	35	✓
Mirror	Self	80	✓
Handle Bracket	Self	75	✓
Meter Set	BR	780	✓
Head Lamp	Self	300	✓
Lamp Stay	Self	75	✓
Front Mudguard	Self	95	✓
Rim(REPAIR)	Self	250	X
Disc	Self	110	X
Tyre	Self	180	X
Wheel Shift	Self	95	✓
Brake Lever	Self	75	✓
Brake Pump	Self	185	✓
Throttle Cable	Self	55	✓
Tank	Self	500	✓
Radiator	Self	380	X
Engine Guard	Self	75	✓
Clutch Cover	Self	75	X
Exhaust Pipe Set (Yoshi)	Self	2500	1400s.w
Fork(REPAIR)	Self	280	LR60
Fork Lower Clamp	Self	120	X
Rear Box	Self	390	S.W
Rear Box Carrier	Self	100	S.W
Front Signal RH	Self	90	✓
Front Footrest RH	Self	55	✓
Transport	Self	50	35
SPRAY	Self	350	250
BODY ALIGHTMENT	Self	280	X
LABOUR	Self	350	280

TOTAL

8140

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To destroy damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Rep - modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Reparer

Signature:

Date:

P-2725
102
246250
18905.1
106625
3900

NOT Admitted
2/5 3500/2
4 day
Weight After up
7/1/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000299/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 716T	Veh. Inspected	FBA 9987P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000032MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	07/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2000	
Chassis No.	NC391011136	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60 ZR17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 ZR17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/12/2018	Inspection Date	07/01/2019	
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 9987P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	110.00	110.00
1	HANDLE BALANCE	SCRATCHED	45.00	45.00
1	HANDLE GRIP	NECESSARY	35.00	35.00
1	MIRROR	CUT	80.00	80.00
1	HANDLE BRACKET	BENT	75.00	75.00
1	METER SET	BROKEN	780.00	780.00
1	HEAD LAMP	DENTED	300.00	300.00
1	LAMP STAY	BENT	75.00	75.00
1	FRONT MUDGUARD	CUT	95.00	95.00
1	RIM	TO REPAIR SEE LABOUR	250.00	-
1	DISC	NOT NECESSARY	110.00	-
1	TYRE	NOT NECESSARY	180.00	-
1	WHEEL SHIFT	SCRATCHED	95.00	95.00
1	BRAKE LEVER	SCRATCHED	75.00	75.00
1	BRAKE PUMP	CUT	185.00	185.00
1	THROTTLE CABLE	CUT	55.00	55.00
1	TANK	DENTED	500.00	500.00
1	RADIATOR	NOT NECESSARY	380.00	-
1	ENGINE GUARD	BENT	75.00	75.00
1	CLUTCH COVER	TO REPAIR SEE LABOUR	75.00	-
1	FORK LOWER CLAMP	NOT NECESSARY	120.00	-
1	FRONT SIGNAL RH	BROKEN	90.00	90.00
1	FRONT FOOTREST RH	CUT	55.00	55.00
	LESS 10% DISCOUNT		-	-272.50
			3,840.00	2,452.50
SPECIAL NETT ITEMS				
1	EXHAUST PIPE SET (YOSHI)(SN)	DENTED / BENT	2,500.00	1,400.00
1	FORK (LOCAL REPAIR)(SN)	BENT	280.00	60.00
1	REAR BOX (SN)	CUT	390.00	390.00

Report Ref No. CS/FCI19000299/Uvd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BOX CARRIER (SN) <u>LABOUR</u> TRANSPORT. SPRAY. BODY ALIGHTMENT. LABOUR,INCLUSIVE OF THE REPAIR OF RIM AND CLUTCH COVER.	BENT	100.00	100.00
			3,270.00	1,950.00
		NOT NECESSARY	50.00	35.00
			350.00	250.00
			280.00	-
			350.00	280.00
			1,030.00	565.00
GRAND TOTAL		8,140.00	4,967.50	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00	

Report Ref No. CS/FCI19000299/Uvd3n2

MARKET VALUE: \$6,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$117.00=NETT VALUE: \$6,383.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.