

Form 100

ASS. RES. BY

Surveyor

Adrian

REP

CS/CT1 000306/And3

Report Instruction

ASSIGNMENT (Office)

From (Person)

Clair Cheung

of

CT1

Date/Time

4/1/19 @ 4:54pm

Estimated Cost

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

GBG 54884

Insured:

GBF 7828C

at Workshop n/s

JCN Auto Solution

Tel:

9677 5772

of

1 Kaki Bukit Ave 6 # 01-85 Autobay

Policy No.

Claim No.

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

31/12/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement

Date/Time

907am @ 7/1/19

Person Contacted

Chen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate Insp. 3 Defn June 12

GBG 54884 - X

GBF 7828C - CS/CT1 17 013419/Dth 302 Dg: 5/7/19

31/1/19

@ 10:20am Mr Chen will email us est

28/3/19

Adrian Confirmed \$ 1078.88 (Real 1173.80, 52%)

REF: CTE

ASSIGNMENT

From: Date: 07/01/2019

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBG 5488H
at Workshop n/s: JCN Autolution
of: 3 Defu June 12

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No: GBG 5488H Yt Regn: 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Every. cc 658

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 56628 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: DAIFV 241471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/80R12

R: 145/80R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A.

D.O.I. 0701-2019

Survey held at JCN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China

RECEIVED 01 APR 2019

Date/Time: File Pass to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation

S + RS 31

Notes

Others

TOTAL

Date/Time: File Return to?

1/4-8pist

Report Format: merimen

Lump Sum / LBt: (\$) 1078.88

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	(Not Notified)		01 Apr 2019 11:09 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	PATRICK DENTAL CERAMIC ARTS, Co. Reg. No.: 53019891J
Vehicle Reg. No.:	GBG5488H
Claim Type:	TP
Vehicle Reg. No. (Insured):	GBF7828C
Date of Loss:	31/12/2018 11:00 - :59
Policy/Cover Note No.:	
Policy No. (Claimant):	DMCPHQ18-005837
Excess:	S\$0.00
Repairer:	Jcn Autolution Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #07-23, Premier@ Kaki Bukit, 415875 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/04/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Friday, 4 January 2019 4:54 PM
To: serenefmm@yahoo.com.sg; 'assignments'
Subject: FW: PRI FOR VEHICLE GBG5488H / INSURED - GBF7828C (DOA - 31.12.2018)
Attachments: CHINA TAIPING INS. GBF7828C (GBG5488H) 1.odt

Importance: High

WITHOUT PREJUDICE

Dear Serene,

We refer to your email of 04.01.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle and propose direct settlement with quantum to be agreed.

Aside to LKK,

Please refer to the attachment and proceed to survey the third party vehicle.

Kindly acknowledge receipt. Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Serene Apple [mailto:serenefmm@yahoo.com.sg]
Sent: Friday, 4 January, 2019 2:37 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: Fw: PRI FOR VEHICLE GBG5488H

----- Forwarded message -----

From: Serene Apple <serenefmm@yahoo.com.sg>

To: Catherine Thia <catherine.thia@sg.cntaiping.com>

Sent: Friday, 4 January 2019, 10:49:17 AM GMT+8

Subject: PRI FOR VEHICLE GBG5488H

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>



JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813305W

📍 No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit, Singapore 417883.

☎ +65 6881 1772 ✉ sales@jcngroup.com

Date: 2nd January 2019

CHINA TAIPING INSURANCE(SINGAPORE) PTE LTD
3 ANSON ROAD, #16-00
SPRINGLEAF TOWER
Singapore 079909
Tel: +65 6389 6111

Fax: +65 6222 1033
Email: e-claims@sg.cntaiping.com

Attn: Motor Claims Department

Dear Sir/Madam

ACCIDENT INVOLVING VEHICLES GBG5488H AND GBF7828C ON 31-DEC-2018 AT 1125HRS AT CTE TOWARDS CITY (BEFORE PIE/BRADDELL EXIT).

1. We act for the Owner of Vehicle No. GBG5488H whose vehicle was damaged as a result of an accident with your Insured, the Driver of Vehicle No. GBF7828C on 31-DEC-2018.
2. As a result of the accident, our client's vehicle has been damaged. Please kindly revert back to us once you/Insurer have received this notice and a Pre-Repair Inspection will be arranged within the next 02 working days before we carry out any repairs to the mentioned vehicle.
3. If we do not receive any reply or instruction from you/Insurer within the stipulated timeline, our client/we shall proceed to repair the mentioned vehicle without further reference to you/Insurer.

Please kindly contact me @ 9677 5772 should you require more information.
Inspection & Repair Location: **3 Defu Lane 12 Singapore 539112**

Yours faithfully,

Chan
JCN Autolution Pte Ltd
M: 9677 5772
O: 6881 1772
E: erik@jcngroup.com

Vern Chen (LKKAUTO)

From: erik@jcgrp.com
Sent: Tuesday, 19 March 2019 11:34 AM
To: SUR
Subject: OUR REF: GBG 5488H YOUR REF: GBF 7828C Accident along CTE towards city on 31/12/2018 at about 1125hours
Attachments: [Untitled]_2019031911290091.pdf

Hi Adrian,

We refer the above vehicle.

Please find our estimate attached.

Kindly revert with a recommended costs of repair and also the number of days for repair.

Thank you.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9891J
Vehicle Details	
Vehicle No.:	GBG5488H
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	SUZUKI
Vehicle Model:	EVERY PA 660 AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	R06A2099016
Chassis No.:	DA17V241471
Maximum Power Output:	-
Open Market Value:	\$13,066.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$654.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$31,019.00
Total Rebate Amount:	\$31,019.00

The information contained herein is correct as at 01 Apr 2019

OK

MSLM19000346 / Soc Leon Motor Works - Kaki Bukit
 ENTRY DATE & TIME: 02/01/2019 13:43
 SUBMITTED BY: IRENE LEONG SUM PHENG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 13:43
Date Of Accident	31/12/2018 11:25
Exact Location Of Accident	CTE TOWARDS CITY (BEFORE PIE/BRADDELL EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG5488H
Insured/Policyholder	
Name Of Registered Owner	PATRICK DENTAL CERAMIC ARTS
Co Reg No	53019891J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93673371
Alternative Phone No	Office-68423371
Vehicle Particulars	
Manufacturer	SUZUKI
Model	EVERY-660CC GA (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-005837
Cover Note Number	
Driver	
Name of Driver	LIU TECK BOO
NRIC No	S1539638E
Date Of Birth	14/10/1962
Occupation	OUTDOOR
Date Of Driving Pass	20/08/1982
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96651167
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 113 HOUGANG AVE 1 #08-1232
Postcode	530113
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF7828C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIU DONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Patrick Dental Ceramic Arts

33 Ubi Ave 3 #08-30, Tower B
Veriax Singapore 408858
Tel: 6842 3321 Fax: 6842 7040

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31-12-2018 at 11:25 hrs, I was travelling along CTE towards PIE. My vehicle was stationary as the vehicle ahead stopped due to slow traffic. Suddenly, I felt a collision impact from the rear. Vehicle B travelling on right lane collided onto the rear of my vehicle. There is no injury at the point of accident.

VEHICLE A. ABG 5488H

VEHICLE B. GOF 7828C.

DECLARATION

I/We declare that the above is true in every respect.
Patrick Royal Ceramic Arts
 33 Ubi Ave 3 #08-30, Tower B
 Vertex Singapore 408868
 Tel: 6842 3371 Fax: 6842 7040



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Officer/Insurer's Signature
 Name:
 NRIC/FIN No.:



Sketch Plan #3



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





JCN Autolution Pte Ltd

COMPANY REG NO: 201813309W

8 Kold Bukit Ave 4, #07-23, Premier @ Kold Bukit,
Singapore 415875

+65 6881 1772 sales@jcngp.com

ESTIMATE

PATRICK DENTAL CERAMIC ARTS
33 UBI AVE 3 #08-30, TOWER B VERTEX
SINGAPORE Singapore 408868

Contact : 6842 3371 6842 7040

Code : C100038

Date in : 31/12/2018

Vehicle Num. : GBG5488H

Model : SUZUKI EVERY PA660 AUTO

Chassis/Eng# : DA17V241471/R06A2099016

TP Chinn.
VORON

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR TAILGATE <i>Repair</i>	1	675.05	675.05 ✓
REAR TAILGATE GLASS <i>Shattered</i>	1 <i>845.75</i>	845.75	845.75 ✓
Subtotal before discount <i>718.88</i>			1,520.80
Percentage discount 15%			228.12
Sub-total 1			1,292.68
REAR TAILGATE SEALANT <i>new</i>	1 <i>60</i>	60.00	60.00 ✓
Subtotal before discount			60.00
Percentage discount 0%			0.00
Sub-total 2			60.00
Parts-total			1,352.68

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE	50.00 ✓
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	100.00 ✓
TO REMOVE, CHANGE REAR TAILGATE WINDSCREEN.	100.00 ✓
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	400.00 <i>300</i> <i>200</i>
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	250.00 ✓
Labour Total	900.00
Parts & Labour Total	2,252.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 1

total: 1078.88
(P/P)
02 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2019 15:22		01 Apr 2019 11:09 Edit Adj Rpt	\$1,078.89 Edit Estimates	\$1,078.89 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ID: -								
Main Claimant:	PATRICK DENTAL CERAMIC ARTS , Co. Reg. No.: 53019891J								
Vehicle Reg. No.:	GBG5488H	Date of Loss:	31/12/2018 11:00 - :59 [16 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	GBF7828C	Policy No. (Claimant):	DMCPHQ18-005837						
		Excess:	\$0.00						
Repairer:	Jcn Autolution Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #07-23, Premier@ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG5488H
[GBF7828C]
TP
PATRICK DENTAL CERAMIC ARTS
Dec 31 2018 11:00AM
[-]
Jcn Autolution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/04/19 15:28	General View		Load PDF

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/01/19 14:06	Accident Statement		Load HTML

Photos/Images			3 per page	☒
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/01/19 13:59	Accident Photo		Load JPG
2	02/01/19 13:59	Accident Photo		Load JPG
3	02/01/19 13:59	Accident Photo		Load JPG
4	02/01/19 13:59	Accident Photo		Load JPG
5	02/01/19 13:59	Accident Photo		Load JPG
6	02/01/19 13:59	Accident Photo		Load JPG

Documentation			1 per page	☒
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/01/19 13:54	Sketch Plan		Load JPG
2	02/01/19 13:54	Sketch Plan #2		Load JPG
3	02/01/19 13:54	Sketch Plan #3		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119000306/AVD3Q2

Date: 04/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle
No : GBG5488H

Insured Vehicle No : GBF7828C

Date of Loss: 31/12/2018

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG5488H

Make & Model: SUZUKI EVERY, 660cc GA (M)

Engine No: R06A2099016

Reg. Date: 31/08/2017 (Man. Year: 2017)

Chassis No: DA17V241471

Colour: White

Odometer: 56628 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 145/80 R12

Rear Tyre Size: 145/80 R12

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,352.68	778.89	573.79	42.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	300.00	600.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,252.68	1,078.89	1,173.79	52.11

INSPECTION

Date of Assignment: 01/04/2019

Date Inspected: 07/01/2019 Inspected At:

Jcn Autolution Pte Ltd (HQ)
8 Kaki Bukit Ave 4 #07-23, Premier@ Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,078.88

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Apr 2019)	
Parts:	N/A	SUZUKI EVERY 660cc GA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5488H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	675.05 FL	*- FL
2	1		*REAR TAILGATE GLASS	Shattered	845.75 FL	*845.75 FL
3	1		*REAR TAILGATE SEALANT	Necessary	60.00 FS	*60.00 FS
					Sub Total (S\$)	905.75
					- List Item Discount on L Items 15.00/15.00% (S\$)	126.86
					Total Parts (S\$)	778.89

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING CHARGE	New	50.00	0.00
2	TO DIAGNOSE ,REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	100.00	0.00
3	TO REMOVE,CHARGE REAR TAILGATE WINDSCREEN	New	100.00	100.00
4	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	400.00	200.00
5	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	250.00	0.00
Gross Labour Cost (\$\$)			900.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >