

ASS. REC. BY:

REF:

CS/MSG19000313/Usd3 9

Special Instruction

SURVEYOR
Maximen
Firm (Person)

Manus
Fievel Foo

ASSIGNMENT (Office)

of

M8LG

Date/Time:

7/1/19 @ 11:16am

Estimated Cost

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 9034P

Insured:

SLT 29592

at Workshop n/a:

Infernum Automotive

Tel:

9821 8445

of

25 Kaki Bkt Rd 4 # 01-49 synergy

Policy No:

D9040559 ARW

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/1/19

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:03pm 7/1/18

Person Contacted

jasur

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLZ 9034P-X
	SLT 29592-X
08/01/19	@ 15:59 p.m. revert pending estimate from repairer to Fievel Foo via maximen.

(08/11/13) wcl

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL290342

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 786

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL290342 Regn: 5-18Type: M.Cer / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Hyundai Elantra c/c 1571Colour: Cmy A/C: Insured / Std / Nil / NASp. Reading 8643 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMMD841 CMJ468270Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXIA

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 31/1/19 D.O.I. 7/1/19

Survey held at _____

Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or

all n/sThe M/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 45318 have hadsurvey estimate29/3/19 contact n/s \$16,000 with Alen(\$ 37,261.50 red - 70%)1/4/2019

RECEIVED 02 APR 2019

Date/Time, File Pass to?

26/04/191) Typist

Date/Time, File Return to?

2) _____

☐ : Prelim. Report☒ : Final ReportDays Of Repair: 10Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 100

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

TOTAL _____

Report Format: _____

Lump Sum / I.B.I: (\$ 16,000/- 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 10:41		07 Jan 2019 11:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	FOO JI WEI KENNETH, ID: S9105757C	
Main Claimant:	GOH THIAM MENG, ID: S8219197F	
Vehicle Reg. No.:	SLZ9034P	Date of Loss: 03/01/2019 19:00 - :59 [7 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.: 29040559AVW (Comprehensive) Coverage: 25/10/2018 - 24/10/2019
Vehicle Reg. No. (Insured):	SLT2959Z	Policy No. (Claimant):
		Excess:
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/01/2019]	
Adj Asg. Remarks:	OI not reported, SJE agree - LKK, Contact : Jason at 9821 8445	

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9197F

Vehicle Details

Vehicle No.: SLZ9034P

Vehicle to be Exported: No

Intended Deregistration Date: 07 Jan 2019

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT (AMS)

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: G4FGJU185489

Chassis No.: KMHD841CMJU685270

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$11,757.00

Original Registration Date: 23 May 2018

First Registration Date: 23 May 2018

Transfer Count: 0

Actual ARF Paid: \$11,757.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 May 2028

PARF Rebate Amount: \$8,817.00

Intended COE Rebate Details

COE Expiry Date: 22 May 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$38,941.00

COE Rebate Amount: \$36,501.00

Total Rebate Amount: \$45,318.00

The information contained herein is correct as at 07 Jan 2019

OK

- VW free vehicle check and software update for old VWs
- What Did You Makan Today PT 5
- Car hit by fallen tree? NParks may cover claim

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Mark X G (New 10Yr COE) \$51,800



1 Owner, Genuine Mileage, Own
By Well Taken Care Owner.
Looking For 10 Year COE
Absolute Wheels StarAd



Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

elantra

Advanced Search Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
elantra		Any	Any	2018	Any	Any	Any	Available



Hyundai Elantra 1.6A GLS
(OPC)

\$54,999

\$5,130 /yr

03-Sep-2018

1,591 cc

688 km

Sedan

Available

Yes Done 688km Only. Cheapest Elantra In Market.Brand New Condition. Brand New Car Smell. Please Call Me For More Information. Higher Loan And Trade In Welcome. Can Sell With Normal Plate With \$16888 ...

Posted: 05-Jan-2019

Tags: 2018 Hyundai Elantra, 2018 Hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite

\$82,800

\$7,650 /yr

20-Nov-2018

1,591 cc

80 km

Sedan

Available

Priced To Sell! Keyless Entry And Push/Start! Top Of The Range Spec! All You Need In A Car Is Here! Very Low Mileage Done, Warranty By Komoco Till 2023, Black Interior! Hurry In To Secure This Once I...

GS Automobiles Pte Ltd

Posted: 16-Dec-2018

Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS
(OPC)

\$56,999

\$5,210 /yr

27-Nov-2018

1,591 cc

38 km

Sedan

Available

High Loan. As Low As \$600/Month Drive Away! No Admin/No Gimmicks. Contact Us To Seize This Good Deal!

GS Automobiles Pte Ltd

Posted: 02-Dec-2018

Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used elantra, elantra Singapore, used elantra Singapore, used elantra, used vehicles Singapore or even buy used elantra Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

View Sent Message

This mail is associated with :

***SLZ9034P (581157)
[SLT2959Z]**

TP
GOH THIAM MENG
Jan 3 2019 7:00PM
[FOO JI WEI KENNETH]
Imperium Automotive - Kaki Bukit

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 08/01/2019 15:59 PM.
To fievel_foo@sg.msg-asia.com
CC sur@lkkauto.com
Subject SLZ9034P (581157) [SLT2959Z] TP

Dear Fievel,

Please be informed that we have inspected the vehicle SLZ 9034P on 07/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2019 12:31
Date Of Accident	03/01/2019 19:50
Exact Location Of Accident	AYE > TUAS NEAR EXIT 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ9034P
Insured/Policyholder	
Name Of Registered Owner	GOH THIAM MENG
NRIC No	S8219197F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98751572
Alternative Phone No	OTHERS-98751572

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT (AMS)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101307470
Cover Note Number	DRIVO PREMIUM

Driver

Name of Driver	GOH THIAM MENG
NRIC No	S8219197F
Date Of Birth	17/06/1982
Occupation	INDOOR
Date Of Driving Pass	19/08/2004
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98751572
Fax Number	
Contact Number	OTHERS-98751572
Email Address	NOEMAIL

Address	17 TOH TUCK ROAD #02-35 THE CREEK @ BUKIT
Postcode	596155
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2959Z
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF 1.2 TSI AT 5G12BZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMD7766C
-----------------------------	----------

Vehicle Make/Model/Colour

PORSCHE MACAN PDK CYP E6

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

29. Nov. 2017 8:35

No. 8922 P. 2

SIGTCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and they copies of this report will be sent to the relevant insurance companies and interested parties.
7. By the judgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

04 JAN 2018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre
Address: 21 KAKI BUKIT LANE
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg


Sketch Plan #2 Pg. 1

29. Nov. 2017 8:35

A

No. 8927 P. 3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I travelling on the extreme right lane, the front car bearing (SLT 7766C) slowing down, I follow suit as I was 30 car length of the front car suddenly, a car bearing SLT 295172 which was from my left swerved to my lane, and hit onto the front portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

04 JAN 2018

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Personnel's Signature
Name: Email: vackb@singnet.com.sg
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190104/2080

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

1 of 3

Report No. T/20190104/2080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/01/2019 14:25		Vide Report No.:		Station Diary No.: 12
Informant's Particulars				
Name of Informant: GOH THIAM MENG		Address: 17 TOH TUCK ROAD #02-35 SINGAPORE 596155		
ID Type / ID No.: NRIC NO / S8219197F		Contact No.: Home/Office: Mobile: 98751572		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 36	Date of Birth: 17/06/1982	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: BANK		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/01/2019 19:50	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE Towards TUAS before Normanton Park				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLT2959Z	Car				Seriously Damaged	0
SLZ9034P	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT (AMS)	Silver	Seriously Damaged	0
SMD7766C	Car				Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20190104/2080

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

2 of 3

Report No. T/20190104/2080

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLZ9034P	NTUC Income Insurance Co-Operative Limited	5101307470	23/05/2018	22/05/2019

Brief Details.

On 03/01/2019 at about 1950hrs, I was driving a vehicle bearing registration no: SLZ9034P along AYE towards Tuas before Normanton Park.

I was driving at the extreme lane 1 and there was a vehicle bearing registration no: SMD7766C (V1) was in front of me came to a stop and there was a short distance between I and the front vehicle.

Shortly after that, a vehicle bearing registration no: SLT2959Z (V2) came into my lane without his signal lights on. When the said vehicle went into my lane. I then collided into his rear vehicle. After the collision, we then came down from the vehicle and take a look at the accident.

I then noticed that the vehicle came into my lane had collided into V1 in front of him. My vehicle also suffered damages at the left front bumper and lights. Airbag was also deployed. Shortly after, a LTA officer came and assessed the accident and left as there were no injuries.

On 04/01/2018, I went to the doctor to seek medical attention and treatment as I have a sharp pain at my lower back due to accident. However, the pain only comes in a day after the accident. I was then given 3 days of MC from the period of 04/01/2019 to 06/01/2019.

I wish to state that I have had an in car built camera.

The purpose of lodging this report for recording and insurance claims purposes.



**SINGAPORE
POLICE FORCE**



T/20190104/2080

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

3 of 3

Report No. T/20190104/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Sgt 1 WONG JUN LI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
04/01/2019 14:25

Officer In Charge Of Case:
TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Classification Of Case:

Authentication Stamp
NP168



IMPERIUM AUTOMOTIVE
25 KAKI BUKIT ROAD 4
#01-49
SINGAPORE 417800

VEHICLE NO: SLZ 9034P (KMHD841CMJU685270)

QTY	PARTICULAR
1 PCS	BONNET 1526
2 PCS	BONNET HINGES @\$165.00 49x2=98
1 PCS	BONNET INSULATOR
1 SET	BONNET INSULATOR CLIPS
1 PCS	BONNET INNER RUBBER
1 PCS	BONNET LOCK 129
1 PCS	FRONT BUMPER 543
1 PCS	FRONT BUMPER SPONGE 165
1 PCS	FRONT BUMPER REINFORCEMENT 855
2 PCS	FRONT BUMPER SIDE 12x10 3 @\$85.00 45x2=90
1 PCS	FRONT BUMPER LOWER RUBBER 185
1 PCS	FRONT BUMPER FOG LAMP N/S 295
1 PCS	FRONT BUMPER FOG LAMP GRILLE N/S 115
1 PCS	FRONT BUMPER CENTRE GRILLE 461
1 PCS	FRONT BUMPER LOWER COVER 181
1 PCS	FRONT BUMPER LOWER COVER CLIPS
1 PCS	FRONT BUMPER LAMP N/S • 225
1 PCS	FRONT SUPPORT PANEL 949
1 PCS	FRONT SUPPORT PANEL TOP GARNISH
2 PCS	HEADLAMPS \$1880.00 1198x2=2396
1 PCS	WIPER PANEL GARNISH 285
1 PCS	FRONT WINDSCREEN • 966
1 PCS	FRONT WINDSCREEN MOULDING 58
1 PCS	FRONT LICENCE PLATE GARNISH 40
1 PCS	AIR CON CONDENSER 1132
1 PCS	RADIATOR
1 PCS	RADIATOR FAN MOTOR
1 PCS	AIR CLEANER BOX ASSY 367
1 PCS	FUSE BOX TOP COVER
1 PCS	FUSE BOX LOWER COVER 105
1 PCS	AIR DUCT HOSE 182
1 PCS	AIR DUCT
2 PCS	FRONT FENDERS @\$871.00 766
2 PCS	FRONT FENDER INNER SHIELDS @\$199.20 145
1 SET	FRONT FENDER INNER SHIELD CLIPS
1 PCS	FRONT FENDER INNER PANEL N/S
1 PCS	FRONT SHOCK ABSORBER N/S
1 PCS	FRONT KNUCKLE ARM N/S
1 PCS	FRONT KNUCKLE ARM BEARING N/S 367
1 PCS	FRONT WHEEL HUB N/S 447
1 PCS	FRONT LOWER ARM N/S
1 PCS	FRONT DRIVESHAFT N/S
1 PCS	FRONT WHEEL HOUSING PANEL N/S
1 PCS	FRONT ENGINE CROSSMEMBER
1 PCS	FRONT LOWER SUPPORT BEAM 211.30

Not Authorized 1/4/10
Lala
7/1/19
4/5 \$16,000
10 day

Sub	\$1,551.30	✓
Sub/fin	\$330.00	✓
11	\$299.20	X
11	\$50.00	X
11	\$85.00	X
11	\$245.00	✓
7.5	\$981.20	✓
7.5	\$366.50	✓
7.5	\$499.20	✓
Sub	\$170.00	✓
7.5	\$211.20	✓
120	\$499.20	✓
7.5	\$215.00	✓
7.5	\$645.20	✓
7.5	\$366.10	✓
Sub	\$45.00	✓
320	\$355.50	✓
fin/cue	\$1,099.20	✓
NP	\$315.80	X
N/S AND DISC	\$3,760.00	10 C
cut	\$566.20	✓
Rey cut	\$1,488.30	✓
sub	\$155.60	✓
7.5	\$108.20	✓
7.5 / part	\$1,466.50	✓
11	\$1,865.30	X
11	\$965.20	X
cue	\$765.20	✓
11	\$285.30	X
cue	\$292.50	✓
cue	\$315.20	✓
11	\$185.40	X
N/S R O/S que	\$1,742.00	10 C
N/S TORN	\$398.40	10 C
sub	\$50.00	✓
11	\$711.20	X
11	\$525.30	X
11	\$665.20	X
Dye	\$350.00	✓
Dye	\$425.30	✓
11	\$617.30	X
11	\$1,650.00	X
11	\$1,152.30	X
11	\$1,625.30	X
Sub	\$322.50	✓

201/10



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 10:41		07 Jan 2019 11:16 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: FOO JI WEI KENNETH , ID: S9105757C									
Main Claimant: GOH THIAM MENG , ID: S8219197F									
Vehicle Reg. No.: SLZ9034P		Date of Loss: 03/01/2019 19:00 - :59 [7 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 581157		Policy/Cover Note No.: A29040559AVW (Comprehensive) Coverage: 25/10/2018 - 24/10/2019							
Vehicle Reg. No. (Insured): SLT2959Z		Policy No. (Claimant):							
		Excess:							
Repairer: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 08/01/2019]									
Adj Asg. Remarks: OI not reported, SJE agree - LKK, Contact : Jason at 9821 8445									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


































Claim Documents




*SLZ9034P (581157)
[SLT2959Z]
TP
GOH THIAM MENG
Jan 3 2019 7:00PM
[FOO JI WEI KENNETH]
Imperium Automotive - Kaki Bukit

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	07/01/19 16:59	Accident Statement From: SC - Reg. No: SLT2959Z, Claimant: FOO JI WEI, KENNETH (FU JI WEI)				 Load HTML			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	07/01/19 14:55	Chassis Number				 Load JPG		<input checked="" type="checkbox"/>	
2	07/01/19 14:56	Odometer Reading				 Load JPG		<input checked="" type="checkbox"/>	
3	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
20	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
21	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
22	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
23	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
24	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
25	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
26	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
27	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
28	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
29	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
30	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
31	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
32	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	
33	07/01/19 14:56	General View				 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
70	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
71	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
72	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
73	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
74	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
75	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
77	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
78	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
79	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
80	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
81	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
82	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
83	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
85	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
86	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
87	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
88	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
89	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
90	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
91	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
92	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
93	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
94	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
95	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
96	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
97	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
98	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
99	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
100	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
101	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
102	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
103	07/01/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
104	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	07/01/19 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
135	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
136	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
137	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
138	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
139	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
140	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
141	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
142	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
143	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
144	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
145	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
146	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
147	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
148	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
149	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
150	07/01/19 14:57	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
151	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
152	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
153	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
154	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
155	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
156	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
157	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
158	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
159	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
160	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
161	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
162	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
163	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
164	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
165	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
166	02/04/19 09:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/01/19 10:45	PRI from Catherine Lim LLC		Load PDF
2	07/01/19 10:45	SLZ9034P E-FILE REPORT		Load PDF
3	07/01/19 10:45	Survey Agree on SJE - LKK		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000313/USD3Q2

Date: 10/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29040559AVW

Claimant Vehicle No: SLZ9034P

Insured Vehicle No: SLT2959Z

Date of Loss: 03/01/2019

Nature of Claim: TP

Claim No: 581157

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ9034P

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A)

Engine No: G4FGJU185489

Reg. Date: 23/05/2018 (Man. Year: 2018)

Chassis No: KMHD841CMJU685270

Colour: Grey

Odometer: 8643 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 7 mm

Rear Left Side: Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,006.50	16,515.04	30,491.46	64.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,255.00	3,550.00	2,705.00	43.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,261.50	20,065.04	33,196.46	62.33
Approved Total (Overridden) (S\$)		16,000.00		
Nett Amount (S\$)	53,261.50	16,000.00	37,261.50	69.96

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 07/01/2019 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49

Synergy@KB

Singapore 417800

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts: 143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLZ9034P)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,551.30 F	*1,526.00 FL
2	2		*BONNET HINGES	Bent / Twisted	330.00 F	*98.00 FL
3	1		*BONNET INSULATOR	Not Necessary	299.20 F	*- FL
4	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
5	1		*BONNET INNER RUBBER	Not Necessary	85.00 F	*- FL
6	1		*BONNET LOCK	Twisted	245.00 F	*129.00 FL
7	1		*FRONT BUMPER	Distorted	981.20 F	*543.00 FL
8	1		*FRONT BUMPER SPONGE	Torn	366.50 F	*165.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Distorted	499.20 F	*499.20 FL
10	2		*FRONT BUMPER SIDE RETAINER	Bent	170.00 F	*90.00 FL
11	1		*FRONT BUMPER LOWER RUBBER	Distorted	211.20 F	*105.00 FL
12	1		*FRONT BUMPER FOG LAMP N/S	Broken	499.20 F	*295.00 FL
13	1		*FRONT BUMPER FOG LAMP GRILLE N/S	Distorted	215.00 F	*115.00 FL
14	1		*FRONT BUMPER CENTRE GRILLE	Torn	645.20 F	*461.00 FL
15	1		*FRONT BUMPER LOWER COVER	Torn	366.10 F	*181.00 FL
16	1		*FRONT BUMPER LOWER COVER CLIPS	Necessary	45.00 F	*45.00 FL
17	1		*FRONT BUMPER LAMP N/S	Broken	355.50 F	*225.00 FL
18	1		*FRONT SUPPORT PANEL	Twisted / Cracked	1,099.20 F	*949.00 FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not fitted	315.80 F	*- FL
20	2		*HEADLAMPS	N/S Broken / O/S Cracked	3,760.00 F	*2,396.00 FL
21	1		*WIPER PANEL GARNISH	Cut	566.20 F	*285.00 FL
22	1		*FRONT WINDSCREEN	Deep Cut	1,488.30 F	*966.00 FL
23	1		*FRONT WINDSCREEN MOULDING	Necessary	155.60 F	*58.00 FL
24	1		*FRONT LICENCE PLATE GARNISH	Torn	108.20 F	*40.00 FL
25	1		*AIR CON CONDENSER	Twisted / Punctured	1,466.50 F	*1,132.00 FL
26	1		*RADIATOR	Not Necessary	1,865.30 F	*- FL
27	1		*RADIATOR FAN MOTOR	Not Necessary	965.20 F	*- FL
28	1		*AIR CLEANER BOX ASSY	Cracked	765.20 F	*367.00 FL
29	1		*FUSE BOX TOP COVER	Not Necessary	285.30 F	*- FL
30	1		*FUSE BOX LOWER COVER	Cracked	292.50 F	*105.00 FL
31	1		*AIR DUCT HOSE	Cracked	315.20 F	*182.00 FL
32	1		*AIR DUCT	Not Necessary	185.40 F	*- FL
33	1		*FRONT FENDERS	N/S Repair / O/S Buckled	1,742.00 F	*766.00 FL
34	1		*FRONT FENDER INNER SHIELDS	N/S Torn	398.40 F	*145.00 FL
35	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
36	1		*FRONT FENDER INNER PANEL N/S	Repair	711.20 F	*- FL
37	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	525.30 F	*- FL
38	1		*FRON KNUCKLE ARM N/S	Not Necessary	665.20 F	*- FL
39	1		*FRON KNUCKLE ARM BEARING N/S	Damaged	350.00 F	*350.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT WHEEL HUB N/S	Damaged	425.30 F	*425.30 FL
41	1		*FRONT LOWER ARM N/S	Not Necessary	617.30 F	*- FL
42	1		*FRONT DRIVESHAFT N/S	Not Necessary	1,650.00 F	*- FL
43	1		*FRONT WHEEL HOUSING PANEL N/S	Repair	1,152.30 F	*- FL
44	1		*FRONT ENGINE CROSSMEMBER	Not Necessary	1,625.30 F	*- FL
45	1		*FRONT LOWER SUPPORT BEAM	Bent	322.50 F	*211.30 FL
46	1		*DRIVE AIR BAG	Activated	3,220.20 F	*1,490.00 FL
47	1		*AIR BAG SPIRAL SENSOR	Activated	425.30 F	*175.00 FL
48	1		*PASSENGER AIR BAG N/S	Activated	3,880.20 F	*1,951.00 FL
49	1		*DASHBOARD	Buckled	1,863.50 F	*1,474.00 FL
50	2		*FRONT SAFETY BELTS	Activated	1,700.00 F	*896.00 FL
51	1		*AIR BAG CONTRO UNIT	Activated	1,652.30 F	*1,543.00 FL
52	1		*ENGINE WIRE HARNESS	Not Necessary	1,800.00 F	*- FL
53	1		*FRONT STEERING WHEEL	Not Necessary	915.20 F	*- FL
54	1		*FRONT AIR CON SIDE GARNISH N/S	Torn	166.50 F	*85.00 FL
55	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
56	1		*BOLT AIR CON OIL	Necessary	50.00 FS	*30.00 FS
57	1		*FRONT SPORT RIM N/S	Serviceable	450.00 FS	*- FS
58	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	47,006.50	20,618.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	4,103.76
Total Parts (\$\$)	47,006.50	16,515.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	65.00	60.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO DISMANTLE & REPLACING FUSE BOX	New	100.00	50.00
4	TO DISMANTLE & REPLACING FRONT DASHBOARD	New	380.00	280.00
5	TO DISMANTLE & REPLACING FRONT AIR BAG }	New	350.00	350.00
6	TO REPROGRAMME AIR BAG SYSTEM }	New	450.00	0.00
7	TO DISMANTLE & REPLACING FRONT WINDSCREEN	New	150.00	120.00
8	TO DISMANTLE & REFIX FRONT ENGINE	New	450.00	0.00
9	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	400.00	120.00
10	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
11	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
12	TO REFILL AIR CON GAS	New	150.00	100.00
13	TO SPRAY RUST PROOFING	New	150.00	80.00
14	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	1,100.00
15	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			6,255.00	3,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >