

ASS. REC. BY:

REF:

CS3/AIG19000318/Bcd3²

Special Instruction:

SUBJECT:

FROM (PERSON):

Mr. Jim

chin lee ying

ASSIGNMENT (Office)

AIG

Date/Time: 7/1/2019 @ 9:34am

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGJ 8438H

Insured:

SMA 9015P

at Workshop m/s

MS car Auto

Tel:

9725 4442

of

& bek 3rd Ave 4 # 01-07 premier

Policy No:

Claim No:

114076802386

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:02am 7/1/19

Person Contacted:

Desmond

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SGJ 8438H-NA/INC19000088/24	DVA: 28/12/18
	SMA 9015P-NA/INC19000088/24	DVA: 28/12/18
	Dismantle: 7/1/2019	

PR3

REF: AIG

ASSIGNMENT

From Date: 7/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGJ 84384

at Workshop m/s MSCar Auto

of 8 kuki Bkt Ave 4 # 01-07 premier

Insured

Policy No

Claims No

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGJ 8438 H

Yr Regn: 22/7/2006

Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA WISH

C.C 1794

Colour: GREY

A/C: Insured / Std / NI / NA

Sp. Reading: 257602

T/Radio: Insured / Std / NI / NA

Eng/No: 122-FE

C/No: ZNE10-0320064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/12/18

D.O.I. 7/1/19

Survey held at MSCAR AUTO

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
MV	17,000/2
PV	12,025/2
NV	4,975/2

Torim Wai
7/1/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ Site Insp (\$

) S + RS \$

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Others

☐ Weekend (\$

TOTAL

Report Format :

DAR

Lump Sum / I.B.I. (\$

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 7/1/2019 9:34:13 AM
Attachments:  02012019124857.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: William Lee [mailto:william@roypartners.com.sg]
Sent: Wednesday, January 02, 2019 12:51 PM
To: Gan, Angiegeokling; Fong, Andy-SY; Ng, Hai-Chuan; Lim, Sheng Yang; Abu Kassim, Noor Mariesa
Cc: 'Ashley'; mscarautopl@gmail.com; msgroupoffice@gmail.com
Subject: Our Ref: MKR/307/8523/2019/as.wl; Your Ref: Your insured vehicle no. SMA 9015P;
Importance: High

Our Ref: MKR/307/8523/2019/as.wl;
Your Ref: Your insured vehicle no. SMA 9015P;

Dear Sirs,

Attn: Motor claims department

CLAIMANT: YAW LAM KEONG (OWNER OF SGJ 8438H)
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SGJ 8438H AND SMA 9015P ALONG ANG MO KIO AVENUE 5 ON 28.12.2018 AT ABOUT 2115 HOURS.

We refer to the above matter.

We act for Yaw Lam Keong, the owner of motor car No. **SGJ 8438H**.

We are instructed by our client to notify you of a road traffic accident on 28.12.2018 at about 9.15 pm along Ang Mo Kio Avenue 5 involving our client's motor car registration number **SGJ 8438H** and motor vehicle registration number **SMA 9015P** driven by your insured at the material time. A copy of the Singapore Accident Statement and traffic police report is attached.

As a result of the accident, our client's motor car **SGJ 8438H** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a after repair photo of our client's motor car **SGJ 8438H** at our client's repairer workshop, M/s MS Car Auto Pte Ltd at No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875, Your said surveyor may contact Mr. Desmond at 9725 4442. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

William Lee

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : william@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 15:34
Date Of Accident	28/12/2018 21:15
Exact Location Of Accident	AMK AVE 3 TWDS AMK AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGJ8438H
Insured/Policyholder	
Name Of Registered Owner	YAM LAM KEONG PETER
NRIC No	S1451261F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88762235
Alternative Phone No	OFFICE-88762235

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099315497
Cover Note Number	

Driver

Name of Driver	YAM LAM KEONG PETER
NRIC No	S1451261F
Date Of Birth	26/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	12/01/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88762235
Fax Number	
Contact Number	OFFICE-88762235
E-Mail Address	NOEMAIL


NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	YAM LAM KEONG PETER
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	SGJ8438H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As a police Report T/2018/229/2118

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

GADMAC SketchPlanForm_v3

2

Police Report



**SINGAPORE
POLICE FORCE**



T/20181229/2118

2 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20181229/2118

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGJ8438H	NTUC Income Insurance Co-Operative Limited	5099315497	29/03/2018	21/07/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YAW LAM KEONG PETER	ID No.	S1451261F
Related Vehicle	SGJ8438H (Car)	Contact No.	88762235
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/12/2018	Date Discharge	29/12/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	-	ID No.	S1717217D
Related Vehicle	NIL	Contact No.	84577727
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/12/2018 at about 2115hrs, I was driving my car bearing registration plate no. SGJ8438H along Ang Mo Kio Avenue 3 towards Ang Mo Kio Avenue 5 on lane 3. Subsequently, as the traffic light was in my favor, I had proceeded straight towards Central Expressway (CTE), however, another car bearing registration plate no. SMA9015P which was on my left had out of the sudden cut into my lane to make a right turn. As it was very sudden, I was unable to brake in time whereby I had collided into the right side of the said car. Thereafter, I alighted my car to make a check whereby I had discovered damages on my car front bumper, left side fender, left side mirror, front left rim and tire. No Ambulance or Traffic Police was called to scene.

On 29/12/2018, as I was feeling uncomfortable, I gone to Mount Alvernia Hospital to seek medical treatment and was given 5 days Medical Leave for the period from 29/12/2018 to 02/01/2019 whereby I had sustained from neck strain and back pain due to the collision. I wish to state that I have an in-car camera installed in my car. That is all.

Scanned by CamScanner

Police Report



**SINGAPORE
POLICE FORCE**



T/20181229/2118

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

4 of 4

Report No. T/20181229/2118

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 1 RICKSON ONG KIAN MENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 29/12/2018 23:04
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Authentication Stamp NP168	SN 085
Signature: 	
Singapore Police Force	

Scanned by CamScanner

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1261F

Vehicle Details

Vehicle No.: SGJ8438H
Vehicle to be Exported: No
Intended Deregistration Date: 07 Jan 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 A
Primary Colour: Grey
Manufacturing Year: 2006
Engine No.: 1ZZ2660818
Chassis No.: ZNE100320064
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,893.00
Original Registration Date: 22 Jul 2006
First Registration Date: 22 Jul 2006
Transfer Count: 6
Actual ARF Paid: \$20,783.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$24,240.00
COE Rebate Amount: \$12,025.00
Total Rebate Amount: \$12,025.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Jan 2019

OK

Dep 7460/41
622/1000

MV 16 K - 171K
PV 12,025/2
NV 4,975/2

hij

7/1/19

SmartCars Boutique Pte Ltd

Posted: 01-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A Aero Tourer (New 5-yr COE)

-

N.A

07-Jan-2009

1,794 cc

-

MPV

SOLD

\$3,000 Deposit! 100% Loan Approval, Well Kept Condition, Well Maintained! Very Smooth Transmission, Immaculate Condition, Kindly Call Us Today For Viewing.

PREMIUM AD

Universe Motoring

Posted: 31-Dec-2018 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A Aero Tourer (New 5-yr COE)

\$34,800

\$6,960 /yr

02-Sep-2008

1,794 cc

116,000 km

MPV

Available

Agent Car's, Comes With 6 Months Warranty From Reputable Workshop, Low Mileage. Fully Done Up With Receipts, See To Believe, Gtee Superb!

Posted: 29-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A Aero Tourer (New 5-yr COE)

\$31,888

\$6,370 /yr

31-Dec-2008

1,794 cc

108,000 km

MPV

Available

Bank And In House Loan Available! Up To 2 Years Warranty. Highest Trade In Value For Your Car! Priced Lowest In The Market Yet Comes With Full Accessories! Beautiful Interior! Lowest Price In The Mark...

JDM Cars

Posted: 29-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 12/2023)

\$34,800

\$7,020 /yr

23-Dec-2008

1,794 cc

-

MPV

Available

(Inclusive Insurance And 1st Month Installment), Low Monthly Installment! New 5 Years COE. High Trade In/High Flex Loan Available. Please Call Our Sales Consultant Now!

Viking Motor Pte Ltd

Posted: 29-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 06/2021)

\$20,300

\$8,190 /yr

12-Oct-2006

1,794 cc

-

MPV

Available

2 Owner Only. Quite Certain Is One Of The Best Well Kept Unit In Town, 100% Accident Free. Original Stock Conditions. Road Tax Till 10/2019. Clean Interior. Responsive Engine And Smooth Gear Box. See ...

Posted: 29-Dec-2018 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (New 5-yr COE)

\$36,800

\$7,360 /yr

20-Nov-2008

1,794 cc

109,000 km

MPV

Available

AA Trust Certified Pre Owned Vehicle! Beautiful White Exterior With Black Interior. Well Maintained By Previous Owner! The Most Affordable MPV At An Affordable Price Now! Spacious MPV With Ample Space...

AA Trust Automotive

Posted: 29-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X Aerosports (COE till 09/2023)

\$35,800

\$7,570 /yr

30-Sep-2008

1,794 cc

90,000 km

MPV

Available

AA Trust Certified Pre Owned Vehicle! Well Maintained By Previous Owner! Rare Toyota Wish With Rear Disc Brakes! The Most Affordable MPV At An Affordable Price Now! Spacious MPV With Ample Space For T...

AA Trust Automotive

Posted: 29-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 07/2021)

\$18,900

\$7,460 /yr

21-Jul-2006

1,794 cc

113,020 km

MPV

Available

Drive With Assurance! 1 Year Warranty! Easy Loan Approval! \$20.9k Best Deal! Monthly Installment At Only An Affordable \$73! Well Maintained Unit. Financing And Trade In Options Available! Call For A ...

CarQuotz Singapore

Posted: 29-Dec-2018 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 12/2023)

-

N.A

12-Dec-2008

1,794 cc

-

MPV

SOLD

Low Interest Rate At 3.18%! Very Well Maintained And Low Mileage, 2 Years Warranty/ Servicing By Platinum Motoring In House Workshop. New Paint Color Of Your Choice And New Pure Leather Seats. 1 To 1 ...

PREMIUM AD

Posted: 28-Dec-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Compare [1]

Toyota Wish 1.8A (COE till 02/2021)

-

N.A

15-Feb-2006

1,794 cc

-

MPV

SOLD

Select used cars to Compare or Add to Alert

Shortlist [1]



Toyota Wish 1.8A
(COE till 07/2021)
21-Jul-2006

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

Add to
Compare Now
Clear All

From Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	CUT	✓	
1006	991325	Frt Bumper Bracket	NEC	✓	
1007	991462	Frt Bumper Side Retainer	NEC	✓	1
1008	991433	Frt Bumper Reinforcement	NEC	✓	2
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DD	R	
1026	992025	Frt Support Panel Top Garnish Cover	DIS	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CUT	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

No. of items: 5

ACTRESS: Trum

Vehicle No. _____

SGJ 8438H

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	DD ✓		
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	CRA ✓		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
Labour Painting work			600.00		
			400.00		

Labour
Painting work

600 00
400.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	03 Jan 2019 Edit Reg		07 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BIS MOTORING PTE LTD, Co. Reg. No.: 201803437N		
Main Claimant:	-		
Vehicle Reg. No.:	SGJ8438H	Date of Loss:	28/12/2018 00:00 - :59 [149 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1140768023SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SMA9015P	Policy No. (Claimant):	
		Excess:	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 16/01/2019]		
Claimant's Solicitor:	ROY & PARTNERS - Tel: 65368466		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (08/01/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































Claim Documents

***SGJ8438H (1140768023SG)**
[SMA9015P]
TP

Dec 28 2018 12:00AM
[BIS MOTORING PTE LTD]
Ms Car Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/01/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	11/01/19 13:35	General View	Load JPG	✓
37	11/01/19 13:35	General View	Load JPG	✓
38	11/01/19 13:35	General View	Load JPG	✓
39	11/01/19 13:35	General View	Load JPG	✓
40	11/01/19 13:35	General View	Load JPG	✓
41	11/01/19 13:35	General View	Load JPG	✓
42	11/01/19 13:35	General View	Load JPG	✓
43	11/01/19 13:35	General View	Load JPG	✓
44	11/01/19 13:35	General View	Load JPG	✓
45	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
46	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
47	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
48	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
49	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
50	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
51	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
52	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
53	11/01/19 13:35	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/01/19 10:51	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19000318/BCD3S2**Date:** 14/01/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SGJ8438H**Insured Vehicle No :** SMA9015P

Date of Loss: 28/12/2018

Nature of Claim: TP

Claim No: 1140768023SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGJ8438H**

Make & Model: TOYOTA WISH, 1.8 (A)

Reg. Date: 22/07/2006 (Man. Year: 2006)

Colour: Grey

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1ZZ2660818

Chassis No: ZNE100320064

Odometer: 257602 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

205/55R16

Pirelli 6 mm

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 07/01/2019 Inspected At:

Estimated Period of Repair: 5.0 days

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI
BUKIT
Singapore 415875

Adjuster: Lim Teow Guan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
4	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
7	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*- F
8	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
9	1		*FRT LH FENDER	Dented	0.00 F	*- F
10	1		*FRT LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
F=Franchise part.				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >