



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: JEQ/161003/1016/LHS/jhl

Date: 26th Jun 2019

Our Ref: CS1/LAW19000322/Ksd3e2

M/s Jusequity Law Corporation

171 Chin Swee Road

#02-06 Ces Centre

Singapore 169877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XD 3374X
INSURED VEHICLE: XD 7320A
ACCIDENT DATE: 25/10/2016**

We thank you for your instruction on 31/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 3374X from M/s Chartered Auto Assessors.
- b) Final Repair Bill of XD 3374X from M/s Lian Hong Seng Motor Works.
- c) Singapore Accident Statement of Vehicles XD 3374X and XD 7320A.
- d) Colour damaged vehicle photographs of XD 3374Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XD 3374X
Make & Model	: Mitsubishi Fuso FV51JJ
Chassis Number	: FV51JJA00390
Year of Registration	: 2008
Engine Capacity	: 12882 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: LP/NTUC/2017-0379

Date: 26th Jun 2019

Our Ref: CS1/LAW19000322/Ksd3e2

M/s Ntuc Income Insurance Co-operative Ltd

C/O: Linda Phua Law Practice

20 Havelock Road

#02-45 Central Square

Singapore 059765

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XD 3374X

INSURED VEHICLE: XD 7320A

ACCIDENT DATE: 25/10/2016

We thank you for your instruction on 31/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 3374X from M/s Chartered Auto Assessors.
- b) Final Repair Bill of XD 3374X from M/s Lian Hong Seng Motor Works.
- c) Singapore Accident Statement of Vehicles XD 3374X and XD 7320A.
- d) Colour damaged vehicle photographs of XD 3374Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XD 3374X
Make & Model	: Mitsubishi Fuso FV51JJ
Chassis Number	: FV51JJA00390
Year of Registration	: 2008
Engine Capacity	: 12882 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.