



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                        |                              |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------|------------------------------|-------------------------------------------------------------------------------------|
| EQ INSURANCE COMPANY LTD                                                                                                               |                                                                                      |                        | Ref : CC3/EQI19000326/Jea3s2 |                                                                                     |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                                                    |                                                                                      |                        | Date : 12-05-2020            |  |
|                                                                                                                                        |                                                                                      |                        | Code : EQI                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                        |                              |                                                                                     |
| Insured Veh.                                                                                                                           | XD 2298P                                                                             | Veh. Inspected         | SMB 83X                      |                                                                                     |
| Policy No.                                                                                                                             | DMCPHQ18-002547                                                                      | Coverage (\$)          | 0.00                         |                                                                                     |
| Claim No.                                                                                                                              | DM18HO03531/JT                                                                       | Excess (\$)            | 0.00                         |                                                                                     |
| Assign From                                                                                                                            |                                                                                      | Assign Date            | 28/12/2018                   |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                        |                              |                                                                                     |
| Make & Model                                                                                                                           | MERCEDES BENZ OC500                                                                  | c.c                    | 11967                        |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.           | 2009                         |                                                                                     |
| Chassis No.                                                                                                                            | WEB63442021000202                                                                    | Colour                 | MULTI-COLOUR                 |                                                                                     |
| Odometer                                                                                                                               | -                                                                                    | Steering               | IN ORDER                     |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification           | STANDARD ALLOY RIM           |                                                                                     |
| General                                                                                                                                | FAIR                                                                                 |                        |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                        |                              |                                                                                     |
|                                                                                                                                        | Size                                                                                 | Make                   | Balance                      |                                                                                     |
| R/H Front Tyre                                                                                                                         | 275/70 R22                                                                           | FIRENZA                | 7 mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                         | 275/70 R22                                                                           | FIRENZA                | 7 mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 275/70 R22 (D)                                                                       | FIRENZA                | 7/7 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 275/70 R22 (D)                                                                       | FIRENZA                | 7/7 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                        |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                      |                        |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                        |                              |                                                                                     |
| Accident Date                                                                                                                          | 22/12/2018                                                                           | Inspection Date        | 28/12/2018                   |                                                                                     |
| Survey held at                                                                                                                         | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                        |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                        |                              |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                        |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                        |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      | <b>15 Working Days</b> |                              |                                                                                     |