

2503/2002

ASS. REC. BY:

REF:

CS / CTI 19000345 / Usd3 / n2

Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person):

Cheng Boon Sen

of

CTI

Date/Time:

7/1/19 @ 2:47pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SMA 6663M

Insured:

SGS 7967G

at Workshop m/s

ACE Automobile

Tel:

6844184

of

13 Kaki Bkt Rd 4 # 03-29

Policy No.:

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/1/2019

CA / REV / REP. / REV 24 HRS

cup?

H.O.D. Endorsement:

Date/Time:

3:19pm @ 7/1/19

Person Contacted:

Anna

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 6663M - X
	SGS 7967G - X

mercus

REF: C11

ASSIGNMENT

From: _____ Date: 09/01/19

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 6663M

at Workshop m/s: Ace Autolub

of 13 kaki Bkt Rd 4 # 03-29

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 66

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Vehicle: IN / OUT

Person Contacted: LIA 47592

Veh No: SMA 6663M Yr Regn: 614

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Mer Benz B180 C.C. 1595

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 126768 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2462412J229569

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	<u>6</u>	Rear	<u>6</u>
R/Bal.	mm	R/Bal.	mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	<u>2/1/19</u>	D.O.I.	<u>9/1/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

for n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

<u>7</u>	
N/S	O/S

Date / Time	Action / Instruction
	<u>Amely Estimate</u>
<u>4/3/19</u>	<u>L/S \$3400 confirmed with Anna</u> <u>(\$44,646.00 Rd - 59%)</u>

RECEIVED 05 MAR 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 05/03/19 ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 3,400/- HS

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		07 Jan 2019 14:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	ZALINA BINTE ZALI, ID: S7906572B
Vehicle Reg. No.:	SMA6663M
Claim Type:	TP
Vehicle Reg. No. (Insured):	SGS7967G
Date of Loss:	02/01/2019 22:00 - :59
Policy/Cover Note No.:	
Policy No. (Claimant):	5102813708
Excess:	S\$0.00
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2019 15:30
Date Of Accident	02/01/2019 22:45
Exact Location Of Accident	INSIDE WOODLAND AVENUE 1 ESSO STATION PETROL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA6663M
Insured/Policyholder	
Name Of Registered Owner	ZALINA BINTE ZALI
NRIC No	S7906572B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92965633
Alternative Phone No	OTHERS-92965633

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B180 (R16 BI)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102813708
Cover Note Number	

Driver

Name of Driver	MOHAMMED FAIZAL BIN ABDUL MUTALIB
NRIC No	S8004739H
Date Of Birth	29/02/1980
Occupation	INDOOR
Date Of Driving Pass	13/09/1999
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92965835
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 201D #02-561 COMPASSVALE DRIVE
Postcode	544201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS7967G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO CHER KWONG
NRIC/Passport Number	S1825173F
Contact Number	96937348
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg
Reporting Centre Personal Data
Name:
NRIC/FIN No:

SKETCH PLAN

Vehicle A: SMA6663M
Vehicle B: SG59676



On 2 Jan 2019 at around 10:45pm, I was, at Inside Woodland
stationary.
Avenue 1 ESSO petrol station. Suddenly, vehicle B (SGS7967G) reverse
I bang into my front portion.
I wish to add that, I have a video footage.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Name: **Tel: 67492305**
 Name: **Fax: 67492305**
 NRIC/FIN **Email: vackb@singnet.com.sg**

New Cars

Used Cars

Sell My Car


Directory

Products

Insurance

Articles

F



6303 6603


Wide selection of
Inchcape Certified
Pre-owned
LEXUS & TOYOTA

Christmas Sale

Free Tyre &
Service Credits
up to
\$3,000

Interest Rate
2.28%

Extended
Warranty
1yr



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2007 MITSUBISHI FE83 At \$26,300.

Cheapest In The Market, Good
Engine Condition.

A&L Automobile StarAd

PRIME MOT

(CHENG YONG CREDIT ENTERPRISES)

With over 200 units of vehi
to choose from, ranging fr
all European to Japanese






Browse by Category

Sort by Date Posted

16 vehicles

b180

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	b180		Any	Any	2014	Any	Any	
	Mercedes-Benz B-Class B180 Chrome		\$66,800	\$10,540 /yr	21-Jul-2014	1,595 cc	65,838 km	
Superb Condition! Fully Maintained And Serviced By C&C! Original Paintwork, Free 6 Months MBM Wheelpower Warranty And 1 Free Ser Attractive Loan Packages Available! Call Us Now For Viewing Or E...								
Posted: 09-Jan-2019			Tags: 2014 Mercedes-Benz B180, 2014 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180		\$69,800	\$10,750 /yr	22-Sep-2014	1,595 cc	86,000 km	
90% Loan Available! 1 Owner Full Agent Serviced! Tip Top Paintwork & Flawless Interior Condition! No Repairs Needed! Inclusive OF 6 I Warranty Coverage! Buy At Your Peace Of Mind! Call Us No...								
ST Carz Pte Ltd								
Posted: 09-Jan-2019			Tags: 2014 Mercedes-Benz B180, 2014 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180 Style		\$73,800	\$11,000 /yr	16-Dec-2014	1,595 cc	90,000 km	
STA Evaluated Accident-Free! Perfect Condition! Fully Serviced And Maintained By C&C, Own With A Peace Of Mind, Finance And Trade Hurry View The Car Now, For More Info. Call Or Sms.								
Posted: 07-Jan-2019			Tags: 2014 Mercedes-Benz B180, 2014 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180 Sunroof		\$70,800	\$10,950 /yr	14-Aug-2014	1,595 cc	44,000 km	
Latest Arrival! Rare Sunroof Model, Low Depreciation At \$29 Per Day Only, 1 Careful Owner, Low Mileage Done At 44000km Only, Full S With C&C Since Day 1, 100% Accident Free, No Repairs R...								
Horizon Motoring								
Posted: 06-Jan-2019			Tags: 2014 Mercedes-Benz B180, 2014 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	3A Car Mat							
Customized Car Mat for MERCEDES BENZ B180 Special promotion!								
More info about this product								

Compare

Mercedes-Benz B-Class B180	\$61,800	\$10,180 /yr	26-Mar-2014	1,595 cc	119,640 km
----------------------------	----------	--------------	-------------	----------	------------

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6572B

Vehicle Details

Vehicle No.:	SMA6663M
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 (R16 BI)
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	27091030321921
Chassis No.:	WDD2462422J229569
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,334.00
Original Registration Date:	25 Jun 2014
First Registration Date:	25 Jun 2014
Transfer Count:	1
Actual ARF Paid:	\$17,468.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2024
PARF Rebate Amount:	\$13,101.00

Intended COE Rebate Details

COE Expiry Date:	24 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$63,190.00
COE Rebate Amount:	\$34,491.00
Total Rebate Amount:	\$47,592.00

The information contained herein is correct as at 09 Jan 2019

OK



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SMA6663M MERCEDES B180

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER 1436.32	DO/MR	1980.00	
1	FRONT HEADLAMP LH 1866.15	SCR/CNR	2100.00	
1	FRONT HEADLAMP NOZZLE LH 245.00	CNR	320.00	
1	FRONT WIPER COVER LH	11	198.00	
1	FRONT WIPER COVER MOTOR LH	11	590.00	
1	FRONT BUMPER REFLECTOR LH	11	152.00	
			5340.00	
		less 10%	534.00	10%
			4806.00	
	SPECIAL ITEMS			
1 SET	PARKING SENSOR	SHUBH	280.00	235
1 SET	REAR BUMPER CLIPS	MR	80.00	50
	Total Parts		5166.00	

Not Authorized
HWH
9/1/19
2/5 3400/-
3 day.

P-3547.47
102
P-3192.72
S.W - 288.00
Labor - 78.00
4259.72
3406



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SMA6663M MERCEDES B180

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00 —	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00 —	400
3	To remove and refix wiring at damaged areas	180.00 —	30
4	To perform anti rust treatment on affected areas	150.00 —	11X
6	To remove & replace parking sensor	100.00 —	50
7	To clear fault code with diagnostic computer and reset to Mercedes specification .	250.00 —	11X
	Labour Total :	2880.00	
	TOTAL (PARTS & LABOUR):	8046.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19000345/USD3N2

Date: 06/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMA6663M	Insured Vehicle No :	SGS7967G
Date of Loss:	02/01/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6663M	Engine No:	27091030321921
Make & Model:	MERCEDES-BENZ B180, 1.6 (R16 BI) (A)	Chassis No:	WDD2462422J229569
Reg. Date:	25/06/2014 (Man. Year: 2013)	Odometer:	126768 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,166.00	3,477.72	1,688.28	32.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	780.00	2,100.00	72.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,046.00	4,257.72	3,788.28	47.08
Approved Total (Overridden) (\$\$)		3,400.00		
Nett Amount (\$\$)	8,046.00	3,400.00	4,646.00	57.74

INSPECTION

Date of Assignment:	07/01/2019	
Date Inspected:	09/01/2019 Inspected At:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2019)
Parts:	144	MERCEDES-BENZ B180 1.6 (R16 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6663M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Deformed	1,980.00 FL	*1,436.32 FL
2	1		*FRONT HEADLAMP LH	Scratched/Cracked	2,100.00 FL	*1,866.15 FL
3	1		*FRONT HEADLAMP NOZZLE LH	Cracked	320.00 FL	*245.00 FL
4	1		*FRONT WIPER COVER LH	Not Necessary	198.00 FL	*- FL
5	1		*FRONT WIPER COVER MOTOR LH	Not Necessary	590.00 FL	*- FL
6	1		*FRONT BUMPER REFLECTOR LH	Not Necessary	152.00 FL	*- FL
7	1		*SET PARKING SENSOR	Shorted	280.00 FS	*235.00 FS
8	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,700.00	3,832.47
- List Item Discount on L Items 10.00/10.00% (\$\$)	534.00	354.75
Total Parts (\$\$)	5,166.00	3,477.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,200.00	300.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	400.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
5	TO REMOVE & REPLACE PARKING SENSOR	New	100.00	50.00
6	TO CLEAR FAULT CODE WITH DIAGNOTIC COMPUTER AND RESET TO MERCEDES SPECIFICATION	New	250.00	0.00
Gross Labour Cost (S\$)			2,880.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >