

2006/2007

ASS. REC. BY:

REF: CS3 / TL18021042 / J96-1

Special Instructions:

Surveyor

Moham

ASSIGNMENT (Office)

From (Person):

Stanley Loi

of

II

Date/Time: 07012019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 8236K

Insured:

SID 4921A

at Workshop n/o

My Car Consultants

Tel:

of

53 DB Ave 1 #01-25

Policy No:

Claim No:

MCT18110579

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wop'

H.O.D. Endorsement:

Date/Time:

21-11-2018 9:15am

Person Contacted:

Curran

Vehicle

OUT

Date/Time

Action/Instruction (X) Estimate

SJT 8236K - 4/11/2018 15:00/16:00/17:00

7/11/2018


SID 4921A X

Dismantle: 22/11/2018 @ 9.40am

After repair: 4/12/2018 @ 2.35pm

Submit LS \$1700, 4 days.

(Red \$380, 18%)

  
10/11/2019

RECEIVED 11 JAN 2019

350-120

PRS  
Hwa Jie

REF: IV

# ASSIGNMENT

Form Date 21.11.2018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. 93T 8236K

at Workshop in/s My Car Consultants

of 55 Ubi Ave 1 #01-25

Insured

Policy No.

Claims No.

Sum Insured Excess

(Client's Record)

Make of Veh Look for Carmen.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle IN / OUT

N/S	O/S

Veh No: 55T 8236K Yr Regn: 31 Oct 2009

Type: ☒ M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan G.C. 1498

Colour: Brown A/C Insured / Std / NI / NA

Sp. Reading: 175 112 T/Radio: Insured / Std / NI / NA

Eng No.

C No: JM18AAG1120110372

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 18/11/18 D.O.I: 21/11/18 @ 10:40 AM

Survey held at: @ 1040

Des. of Damages: ☒ Front / Rear / O/S / ☒ UIC / Rooftop or

Front, N/S

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

CaseTime: File Pass to:

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee

Transportation

1. 1000 30

1. 1000

1. 1000

1000

Report Format: PRE

Lump Sum / LB 1:15

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Wks (\$

☐ 24hr Serv (\$

120
10
130

## Catherine Chong (LKK Auto)

---

**From:** Stanley Lai <stanley.lai@iii.com.sg>  
**Sent:** Monday, 7 January, 2019 2:57 PM  
**To:** Hsiao Tong (chewht@lkkauto.com); 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Zuhaidah Samsuri; Natalia Lim; Mekavathanan Sarangapani  
**Subject:** RE: MCT18110579

Dear Sirs,

Rights granted in Merimen for the above LOD.

Warmest regards,

Stanley Lai

**Motor Claims Department**

**India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

*S&P 'A-' rated Company*



---

**From:** Mekavathanan Sarangapani  
**Sent:** Friday, 28 December, 2018 8:55 AM  
**To:** Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>  
**Cc:** Zuhaidah Samsuri <aida@iii.com.sg>; Natalia Lim <NataliaLim@iii.com.sg>; Stanley Lai <stanley.lai@iii.com.sg>  
**Subject:** MCT18110579

Paper survey please on TP vehicle SJT 8263K.


Aida are we contesting this claim - We have CCTV footage

Meka

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT





Accident Photo



0 76 11 60 1

100

## SKETCH PLAN

Jalan Eunus Flyover &  
Kaki Bukit, Traffic light,  
Eunus Intersection



A-S  
B-S

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Report  
to the Police  
8/11/2014

Date:

#### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SJT6236K	Insured Vehicle No :	S
Date of Loss:	18/11/2018	Nature of Claim:	T

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT6236K	
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Engine No
Reg. Date:	31/10/2009 (Man. Year: 2009)	Chassis N
Colour:	Brown	Odometer
Engine Capacity:	1498 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Ser
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident C

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:
Front Left Side	Michelin 6 mm	Rear Left Side:
Front Right Side	Michelin 6 mm	Rear Right Side:

The above values represent the remaining tyre tread depth

#### COST OF CLAIMS

	Repairer's	Adjuster's
Parts	0.00	0.00
Miscellaneous Items	0.00	0.00
Labour	0.00	0.00
Paintwork Labour	0.00	0.00
Towing	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>

#### INSPECTION

Date of Assignment:	20/11/2018	
Date Inspected:	21/11/2018	Inspected At:
		My Car Consultant Pte Ltd (Ubi)
		53 Ubi Ave 1, #01-24, Pays Ubi Industrial P
		Singapore 408934
Estimated Period of Repair:	0.0 days	

Adjuster: ONG HWEE JIE

Manager: CELINE FONG



Main		20 Nov 2018 00:00	S\$0.00 (S\$139.10)	
------	--	-------------------	------------------------	--

Main	Offer Processing	Claim Details	Adjuster's Details	Documents
<b>CLAIM SUBFOLDER DETAILS</b>				[Created by adjuster]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	LIM SOON SIEW, ID: S1658153D			
Vehicle Reg. No.:	SJT8236K	Date of Loss:	18/11/2018 17:00 - :59 [108 Months and 18 Days Fro	
Claim Type:	TP	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	SHD4921A	Policy No. (Claimant):		
		Excess:		
Repairer:	My Car Consultant Pte Ltd (Ubi) <b>PROFILE</b> 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - €			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt d			
<b>CLAIM NOT REGISTERED</b>				
This claim is not registered. Click <b>Register</b> to register this claim.				
You need to register a claim if you want to link other related subfolders to it.				



Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

mt 1811 0579/01/28

RESERVES			
TPPD	PRESERVE		
TPPI	PRESERVE		PC - DC
UNINSURED LOSS	PRESERVE		
SUBRO	PRESERVE		
LPPN			
INVESTIGATION FEE			
SURVEY FEES			3000
LEGAL FEES			
OTHERS			
FRAUD CHECK			
UPLOAD TO MERIMEN			
GRANT RIGHTS			

MEM  
PL  
FL ✓

\*\*\*\*\*  
 \*\*\* FAX TX REPORT \*\*\*  
 \*\*\*\*\*

TRANSMISSION OK

JOB NO. 4498  
 DEPT. ID 1000  
 DESTINATION ADDRESS 964071427  
 SUBADDRESS  
 DESTINATION ID  
 ST. TIME 28/12 10:07  
 TX/RX TIME 00' 25  
 PGS. 1  
 RESULT OK



**AP LAW PRACTICE**

(UEN No. 53380739E)

9 Temasek Boulevard  
 #09-01 Suntec Tower 2  
 Singapore 038989

T: +65 6407 1429  
 F: +65 6407 1427  
 E: [enquiry@aplp.com.sg](mailto:enquiry@aplp.com.sg)

We do not accept service of Court documents by fax

Our ref: AP/2018/000356

WITHOUT PREJUDICE

Rajah Firros @Rajah Vijiyakumar@Ayadurai  
 Blk 275 Pasir Ris street 21  
 #06-528  
 Singapore 510275

By Certificate of Posting

India International Insurance Pte Ltd  
 Insurer of SHD4921A  
 64 Cecil Street  
 #05 IOB Building  
 Singapore 049711  
 Attn: Motor Claim Department  
 (Your ref: to be advised)

By Hand

Date: 17 December 2018

Dear Sirs,

CLAIMANT: LIM SOON SIEW  
 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 18 NOVEMBER 2018 AT 17:45 HRS  
 INVOLVING MOTOR VEHICLES NO(S). SJT8236K AND SHD4921A ALONG JLN EUNOS

We refer to the above matter.

We act for Mr Lim Soon Siew, owner of SJT8236K.

We are instructed by our clients to claim damages against you in connection to the above-mentioned road traffic accident involving our clients' vehicle and your vehicle bearing registration number SHD4921A.

We are instructed that the above-mentioned road traffic accident was caused by the negligence of your authorised driver in the driving, management and/or control of your vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

Costs of repair

\$ 2,080.00



PL

McT/18110579  
 A. de

28/12/2018

Our ref: AP/2018/000356

WITHOUT PREJUDICE

Rajah Firros @Rajah Vijiyakumar@Ayadurai  
Blk 275 Pasir Ris street 21  
#06-528  
Singapore 510275

By Certificate of Posting

India International Insurance Pte Ltd  
Insurer of SHD4921A  
64 Cecil Street  
#05 IOB Building  
Singapore 049711  
Attn: Motor Claim Department  
(Your ref: to be advised)

By Hand



PL

Date: 17 December 2018

Dear Sirs,

CLAIMANT: LIM SOON SIEW

CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 18 NOVEMBER 2018 AT 17:45 HRS  
INVOLVING MOTOR VEHICLES NO(S). SJT8236K AND SHD4921A ALONG JLN EUNOS

We refer to the above matter.

We act for Mr Lim Soon Siew, owner of SJT8236K.

We are instructed by our clients to claim damages against you in connection to the above-mentioned road traffic accident involving our clients' vehicle and your vehicle bearing registration number SHD4921A.

We are instructed that the above-mentioned road traffic accident was caused by the negligence of your authorised driver in the driving, management and/or control of your vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

<b>Costs of repair</b>		<b>\$ 2,080.00</b>
<b>Loss of use</b>		<b>\$ 1,080.00</b>
- Pre-repair	\$ 360.00	
(3 days including intervening weekend x \$120.00 per day)		
- During repair works	\$ 720.00	
(6 days including intervening weekend x \$120.00 per day)		
<b>Our Legal Costs</b>		<b>\$ 1,500.00</b>
<b>Disbursements (incurred to-date)</b>		<b>\$ 545.50</b>
- Survey report fees	\$ 374.00	
- GIA/LTA search/document fee	\$ 21.50	
- Other Incidentals	\$ 150.00	
<b>Total</b>		<b>\$ 5,205.50</b>

17 December 2018

AP/2018/000356

---

A copy each of the following supporting documents is enclosed:

- (a) Police report;
- (b) Motor surveyor's report by Prominent Appraiser Services Pte Ltd;
- (c) Survey report invoice;
- (d) Correspondences with India International Insurance Pte Ltd relating to pre-repair survey of our clients' vehicle.


In compliance with the pre-action protocol under the State Courts' Practice Direction 37, we had on 20 November 2018 notified your insurer, India International Insurance Pte Ltd, of the above-mentioned road traffic accident and to the best of our knowledge, your insurer had arranged for the pre-repair inspection of our client's vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt to us within fourteen (14) days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you a counterclaim against our client arising out of the above-mentioned accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully,



**Charles Hoon**  
enc.

*c.c. clients*

# My Car Consultant Pte Ltd

53, Ubi Avenue 1, Paya Ubi Industrial Park,

#01-33, Singapore 408934

HP: 9888 8885 (Jeremy) Email: Jeremy\_dav\_86@live.com

## INVOICE

Claimant: Mr Lim Soon Siew

Date of Invoice : 05/12/2018

C/o. M/s. My Car Consultant Pte Ltd

53, Ubi Avenue 1 #01-33

Paya Ubi Industrial Park

Singapore 408934

Claim Type : Third Party

Date of Accident : 18/11/2018

Vehicle Reg. No : SJT8236K

Vehicle Make/Model : Nissan Sylphy

Description	Amount (S\$)
Lump Sum Repairs As Per Recommendation.	\$ 2,080.00
<b>Total</b>	<b>\$ 2,080.00</b>

Singapore Dollar : Two Thousand Eighty Dollars Only.





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 8722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

## INVOICE

Mr Lim Soon Siew  
C/o. 53 Ubi Avenue 1 #01-33  
Paya Ubi Industrial Park  
Singapore 408934

Invoice No. : HA/1812-14

Date : 04/12/2018

Descriptions	Amount (SGD)
<b>Services rendered for appraiser / inspection report :-</b>	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
<b>Total :</b>	<b>SGD : \$ 374.00</b>
SGD Dollar : Three Hundred Seventy Four Dollars Only.	
Our Reference : PAS/TP/0571118	
Vehicle No. : SJT8236K	
Make & Model : Nissan Sylphy	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD"

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

## VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0571118

Date of Report: 04/12/2018

To: Mr Lim Soon Siew  
C/o. 53 Ubi Avenue 1 #01-33  
Paya Ubi Industrial Park  
Singapore 408934

Date of Assignment: 19/11/2018  
Report requested by: Mr Lim Soon Siew  
Date of Accident: 18/11/2018  
Date of Inspection: 19/11/2018  
Claim No.: Third Party Claim  
Policy No.: -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.: SJT8236K  
Make & Model: Nissan Sylphy  
Date of Registration: 31/10/2009  
Colour: Met. Grey

Engine Capacity (cc): 1498cc  
Mileage (km): 175112km  
Chassis / Frame No.: JN1BAAG11Z0110372  
Engine No.: HR15239489B

### TYRE CONDITION

Front LH	: 6 mm	Front RH	: 6 mm
Make	: Michelin	Make	: Michelin
Rear LH	: 6 mm	Rear RH	: 6 mm
Make	: Michelin	Make	: Michelin

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork: Good  
Paintwork: Good  
Handbrake: Serviceable  
Footbrake: Serviceable  
Steering: Serviceable  
Apparent Engine Modification: Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location: M/s. My Car Consultant Pte Ltd  
53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

### ASSESSMENT

Repairer's Estimate: \$ 3,182.57  
Revised Amount: \$ 2,606.94  
Less Excess: \$ -  
Recommended Reserve: \$ 2,080.00 (Lump Sum)

Estimated Normal Period of Repairs: 4 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 6508 Email: [pasvusi@hotmail.com](mailto:pasvusi@hotmail.com)

Business Reg. 201404434D

Vehicle No : SJT8236K

Report No. : PAS/TP/0571118

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. My Car Consultant Pte Ltd, 53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the LHF portion.

### DAMAGES

The front bumper, LHF fender, LHF fender inner panel, LH headlamp, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$2,606.94.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$2,080.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
**Prominent Appraiser Services Pte Ltd**

  
**Andrew How**  
**Automobile Appraiser**  
**MSAAA**  
**Licensed Appraiser**



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJT8236K

Report No. : PAS/TP/0571118

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
<b>PARTS NETT</b>					
1	1 pc	Frt bumper	Dented/Deformed	00 \$ 563.70	\$ 563.70 ✓
2	1 pc	Frt bumper absorber	Refit	\$ 180.60	\$ -
3	1 pc	Headlamp LH	Broken/Defaced	CRA \$ 428.10	\$ 428.10 ✓
4	1 pc	Frt fender LH	Dented/Distorted	00 \$ 650.80	\$ 650.80 ✓
5	1 pc	Frt fender cowling LH	Refit	\$ 70.10	\$ -
6	1 pcs	Frt bumper moulding R/L	Necessary (LH)	\$ 58.00	58 \$ <del>110.00</del> ✓
7	1 pc	Frt fender inner panel LH	Dented/Repair		(Refer labour no. 2 & 3)

	\$ 2,009.30	\$ 1,758.60
Less Discount : 10%	\$ 200.93	10% \$ 175.86
Nett Parts Sub-Total :	\$ 1,808.37	30% \$ 1,582.74

<b>PARTS S/NETT</b>					
1	6 pcs	Frt fender cowling clip LH	Necessary	\$ 2.20	NEC \$ 13.20
2	6 pcs	Frt bumper clip	Necessary	\$ 2.80	NEC \$ 16.80
3	1 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 22.10 (LH) CRA	\$ 44.20 ✓
Special Nett Sub-Total :				\$ 74.20	\$ 74.20
Parts Total :				\$ 1,882.57	\$ 1,656.94

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To check electrical system and focus headlamp.	\$ 50.00	\$ 30.00 ✓
2	To straighten, repair, realign on affected area and replace damaged parts.	\$ 600.00	\$ 440.00 ✓
3	To spray painting, blending on affected and adjacent area.	\$ 600.00	400 \$ <del>450.00</del> ✓
4	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ 30.00 ✓
Labour Total :		\$ 1,300.00	\$ 950.00
Total (Parts & Labour) :		\$ 3,182.57	\$ 2,606.94

### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 2,080.00

Total - \$1,700/- 4 days repair

Under normal circumstances, the repairs should be completed within a reasonable period of **4 Working Days.** (Exclude waiting days of PRL, Sunday, Public Holiday and awaiting of shipment for spare parts)

24 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.

## Schedule of Surveyor's Attendance for Conducting PRS

This document indicates that the 3rd party surveyor has inspected the vehicle as follows :

Workshop : My Car Consultant Pte Ltd  
Vehicle No. : SJT8336K  
Date of Accident : 12/11/18  
Name of TP Insurer Co. : India International P/L  
Surveyor's Firm & Name : LKK  
Contact No. : 91803151 / 62563561 91803151  
Date of Vehicle Send In : 19/11/18

### 1st PRS Conducted.

Date & Time of Inspection : 21/11/18 / 10am

Require of Resurvey Hidden/Check Items : YES / NO

[Signature] Hwee Jia  
Signature / Name

### 2nd PRS Conduct Hidden/Check Damages Items.

Date & Time Informed Surveyor : \_\_\_\_\_ / \_\_\_\_\_ (By Repairer)

Date & Time of Inspection : 21/11/18 / 945

Require of Resurvey After Repair : (YES) / NO

Remarks : \_\_\_\_\_

[Signature] Hwee Jia  
Signature / Name

### 3rd PRS Conduct After Repairs.

Date & Time Informed Surveyor : \_\_\_\_\_ / \_\_\_\_\_ (By Repairer)

Date & Time of Inspection : 28/11/18 / 2.40pm

[Signature] TC Lim  
Signature / Name

Enquire Vehicle & Owner Information | Vehicle No. SHD4921A As At 18 Nov 2018 / 17:45:00 |

- [Learn More About Us](#)

Search Reason	Insurance claim in relation to traffic accident
Law Firm Case No.	AR/2018/000356
Owner ID Type	Company
Owner ID	T99303821R
Owner Name	COMFORT TRANSPORTATION PTE LTD
Registered Address Type	Private Residential (Covers Apt or House) / Shipping / Office Complex
Registered Block/Room No.	383
Registered Street Name	SIRIMING DRIVE
Registered Unit No.	-
Registered Building Name	GAS BUILDING
Registered Postal Code	575717
Vehicle No.	SHD4921A
Make Description/Model	HYUNDAI / HD 1.7, CRDI AT ABS AIRBAG 4DR
Insurance Company Name	INDIA INTL INS PTE LTD



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-193955

Date of Request: 17/12/2018

Your Ref No: AP/2018/000356

A P LAW PRACTICE  
9 Temasek Boulevard  
#09-01 Suntec Tower Two  
Singapore 038989

Dear Sir/Madam,

Date of Accident: 18/11/2018

Vehicle No: SJT8236K

Place of Accident: JLN EUNOS F/OTWDS KAKI BUKIT, T/L JUNC JLNEUNOS/IP

Involving Vehicle No: SHD4921A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHD4921A	JLN EUNOS F/OTWDS KAKI BUKIT, T/L JUNC JLNEUNOS/IP	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2018 15:21
Date Of Accident	18/11/2018 17:45
Exact Location Of Accident	JLN EUNOS F/OTWDS KAKI BUKIT,T/L JUNG JLNEUNOS/IP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT8236K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM SOON SIEW
NRIC No	S1658153D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98206737
Alternative Phone No	OTHERS-98206737

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100278127-07
Cover Note Number	

### Driver

Name of Driver	GORDON LIM SOON LOKE
NRIC No	S1421837H
Date Of Birth	26/11/1960
Occupation	OUTDOOR
Date Of Driving Pass	19/05/1984
Driving Experience	34 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98206737
Fax Number	
Contact Number	OTHERS-98206737
Email Address	NOEMAIL



Address	BLK 650 JALAN TENAGA #04-36
Postcode	410650
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - BROTHER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20181118/2094

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4921A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	GORDON LIM SOON LOKE
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SJT8236K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Printed Name of Policyholder  
(Print & Sign)

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Printed Name of Insurer's Representative  
Name  
Printed Date

# Sketch Plan #2

SKETCH PLAN

Location: Bureau of Highway Patrol  
 Incident: Traffic Light Junction  
 Location: District 2 - South



A - SJT 3232  
 B - SHD 9212

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten notes in the description area include:

- 1st - 1st
- 2nd - 2nd
- 3rd - 3rd
- 4th - 4th
- 5th - 5th
- 6th - 6th
- 7th - 7th
- 8th - 8th
- 9th - 9th
- 10th - 10th
- 11th - 11th
- 12th - 12th
- 13th - 13th
- 14th - 14th
- 15th - 15th
- 16th - 16th
- 17th - 17th
- 18th - 18th
- 19th - 19th
- 20th - 20th
- 21st - 21st
- 22nd - 22nd
- 23rd - 23rd
- 24th - 24th
- 25th - 25th
- 26th - 26th
- 27th - 27th
- 28th - 28th
- 29th - 29th
- 30th - 30th
- 31st - 31st
- 32nd - 32nd
- 33rd - 33rd
- 34th - 34th
- 35th - 35th
- 36th - 36th
- 37th - 37th
- 38th - 38th
- 39th - 39th
- 40th - 40th
- 41st - 41st
- 42nd - 42nd
- 43rd - 43rd
- 44th - 44th
- 45th - 45th
- 46th - 46th
- 47th - 47th
- 48th - 48th
- 49th - 49th
- 50th - 50th
- 51st - 51st
- 52nd - 52nd
- 53rd - 53rd
- 54th - 54th
- 55th - 55th
- 56th - 56th
- 57th - 57th
- 58th - 58th
- 59th - 59th
- 60th - 60th
- 61st - 61st
- 62nd - 62nd
- 63rd - 63rd
- 64th - 64th
- 65th - 65th
- 66th - 66th
- 67th - 67th
- 68th - 68th
- 69th - 69th
- 70th - 70th
- 71st - 71st
- 72nd - 72nd
- 73rd - 73rd
- 74th - 74th
- 75th - 75th
- 76th - 76th
- 77th - 77th
- 78th - 78th
- 79th - 79th
- 80th - 80th
- 81st - 81st
- 82nd - 82nd
- 83rd - 83rd
- 84th - 84th
- 85th - 85th
- 86th - 86th
- 87th - 87th
- 88th - 88th
- 89th - 89th
- 90th - 90th
- 91st - 91st
- 92nd - 92nd
- 93rd - 93rd
- 94th - 94th
- 95th - 95th
- 96th - 96th
- 97th - 97th
- 98th - 98th
- 99th - 99th
- 100th - 100th

## DECLARATION

I/We declare the foregoing part(s) are true in every respect.

Reporting Officer's Signature  
 Date & Time

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

Reporting Centre Personnel's Signature  
 Name  
 NRIC/ID No.

### Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



7/2018/1182054

2 of 3

Police Station Of Origin:  
Marine Parade N.P.C.  
303 Marine Parade Road SINGAPORE  
449296  
Tel No: 1800-4428995

Report No: 7/2018/1182054

#### CONTINUATION OF REPORT

Driver Name	GORDON LIM SOON LOKE	ID No	S1421837H
Related Vehicle	SJT8236K (Car)	Contact No	98206737
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry NIL
Date Treatment	18/11/2018	Date Discharge	18/11/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

#### Brief Details:

On 18/11/2018, at around 1745hrs, I was driving along Jalan Eunos Flyover towards Kaki Bukit, and pulled up at the traffic light near Jalan Eunos Interim Park. I would like to inform there were some other vehicles in front and behind of me at the traffic light when I pulled up at the red light. When I was about to drive off when the front vehicle started moving, I felt an impact from the left side of my vehicle, and my vehicle was still stationary before the collision. After the collision, the other vehicle, SHD4921A, pulled up no vehicle directly in front of my vehicle with about 1 car length's distance away. I also got down from my vehicle to check on the damage and noticed that there were scratches on the left passenger door, and the other vehicle also had scratches on the right side of his vehicle. We both came to an agreement to report the matter to our insurance company, and I did not take down the particulars of the driver. However, when I returned back home, I felt some pain on my neck and my lower back, and some numbness on my left hand and left leg, and went to Mount Alvernia Hospital to seek medical attention and was given 3 days medical certificate.

I would like to inform that I do not have any in-car camera installed in my vehicle, and I do not know the estimated repair cost for my vehicle's damages. I would like to inform that I have yet to inform my insurance company about the accident.

#### Sketch Plan #4



Sketch Plan #5



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



# Police Report



SINGAPORE  
POLICE FORCE



T201811182034

1 of 3

Report No: T201811182034

Police Station of Origin  
Maine Parade N.P.C.  
100 Maine Parade Road SINGAPORE  
449290  
Tel No: 1800-4428999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
18/11/2018 22:55

File Report No

Station Diary No  
73

### Informant's Particulars

Name of Informant GORDON LIM SIKUN LOKE			Address APT BLK 650 JALAN TENAGA #04-38 SINGAPORE 410650		
ID Type / ID No NRIC NO / S1421837H			Contact No. Home/Office Mobile 98208737		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 57	Date of Birth 25/11/1960	Type of Informant Driver		
Race Chinese			Language English		
Occupation SERVICE ENGINEER			Institution / School Name		
			Driving Licence Information Class 3		
			Date of Expiry		

### General Information of the Accident

Type of Accident Injury	Drunk Drive No	Date/Time of Accident 18/11/2018 17:45	Type of Location Flyover
Location Along Road 1 JALAN EUNOS			
Description Main Express Flyover towards Kallang Road, Traffic light junction near Jalan Eunos Interchange			
Weather Clear	Road Surface Dry	Road Speed Limit	
Traffic Flow One Way	Traffic Control Traffic Light - Working	Traffic Volume Moderate	
Type of Collision Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance No

### Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHD4921A	Car				Slightly Damaged	1
SU10238K	Car				Slightly Damaged	0

### Details of Person Involved

No of Pedestrians Involved: No  
No of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

# Police Report



**SINGAPORE  
POLICE FORCE**



1/20181118/2004

2 of 3

Police Station Of Origin:  
Marine Parade N.P.C.  
6 Marine Parade Road SINGAPORE  
440200  
Tel No: 1800-44-25200

Report No: 1/20181118/2004

## CONTINUATION OF REPORT

Driver			
Name	GORDON LIM SOON LOKE	ID No	S1421837H
Registered Vehicle	S, T8236K (Car)	Contact No	98206737
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry NIL
Date Treatment	18/11/2018	Date Discharge	18/11/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

### Brief Details:

On 18/11/2018, at around 1745hrs, I was driving along Jalan Eunos Flyover towards Kaki Bukit, and pulled up at the traffic light near Jalan Eunos Interim Park. I would like to inform there were some other vehicles in front and behind of me at the traffic light when I pulled up at the red light. When I was about to drive off when the front vehicle started moving, I felt an impact from the left side of my vehicle, and my vehicle was still stationary before the collision. After the collision, the other vehicle, SHD4921A, pulled up his vehicle directly in front of my vehicle with about 1 car length's distance away. I also got down from my vehicle to check on the damage and noticed that there were scratches on the left passenger door, and the other vehicle also had scratches on the right side of his vehicle. We both came to an agreement to report the matter to our insurance company, and I did not take down the particulars of the driver. However, when I returned back home, I felt some pain on my neck and my lower back, and some numbness on my left hand and left leg, and went to Mount Alvernia Hospital to seek medical attention and was given 3 days medical certificate.

I would like to inform that I do not have any in-car camera installed in my vehicle, and I do not know the estimated repair cost for my vehicle's damages. I would like to inform that I have yet to inform my insurance company about the accident.



# Police Report



SINGAPORE  
POLICE FORCE

1. CONTACT INFO  
Name: [Name]  
Address: [Address]  
Phone: [Phone]  
Email: [Email]



1051811160094

Report No: 1051811160094

DATE/TIME OF REPORT

Sketch Plan

1. Sketch Plan (If you don't have a sketch plan)

2. ON A4: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have a copy, please fax a copy to 65474885 stating the report number as reference.

Signature Of Person Recording The Report

1051811160094

Signature Of Informant

Not applicable

Signature Of Informant

Date/Time

18/11/2018 22:55

Classification Of Case

1. A41

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094

1051811160094



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18021042/Jqbe2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 14-01-2019



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4921A	Veh. Inspected	SJT 8236K
Policy No.		Coverage (\$)	0.00
Claim No.	MCT18110579	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	07/01/2019

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BAAG11Z0110372	Colour	BROWN
Odometer	175112	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	18/11/2018	Inspection Date	21/11/2018
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 8236K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER	DENTED	563.70	563.70
1	FRT BUMPER ABSORBER	REFIT	180.60	-
1	HEADLAMP LH	CRACKED	428.10	428.10
1	FRT FENDER LH	DENTED	650.80	650.80
1	FRT FENDER COWLING LH	REFIT	70.10	-
2	FRT BUMPER MOULDING R/L @\$58.00	N/S SCRATCHED	116.00	58.00
1	FRT FENDER INNER PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-200.93	-
	LESS 30% DISCOUNT		-	-510.18
			1,808.37	1,190.42
<b><u>SPECIAL NETT ITEMS</u></b>				
6	FRT FENDER COWLING CLIP LH @\$2.20 (SN)	NECESSARY	13.20	13.20
6	FRT BUMPER CLIP @\$2.80 (SN)	NECESSARY	16.80	16.80
2	FRT BUMPER RETAINER R/L @\$22.10 (SN)	N/S CRACKED	44.20	22.10
			74.20	52.10
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL SYSTEM AND FOCUS HEADLAMP.		50.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT FENDER INNER PANEL LH.		600.00	440.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		600.00	400.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		50.00	30.00
			-	-
			-	-
			1,300.00	900.00
<b>GRAND TOTAL</b>			<b>3,182.57</b>	<b>2,142.52</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00
---	--	--	----------

Report Ref No. CS3/III18021042/Jqbe2-1

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.