

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI19000349/TICD302

Special Instruction:

Surveyor
Menimen

Tauhich

ASSIGNMENT (Office)

From (Person): cheng Ban Sen

of

CTI

Date/Time:

7/11/19 @ 1:56pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN6369C

Insured:

GBC774K

at Workshop m/s

AMA Autocare

Tel:

6333 2222 / 6223 9433

of

36 Jln Guen Rd East #01-36

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/12/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

5:59pm @ 7/11/19

Person Contacted:

Melvin

Vehicle:

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	YN6369C - X
	GBC774K - X:
	Dismantle: 8/1/2019
	After repair: 10/1/2019

Signature

Tanfer

REF: CTE

ASSIGNMENT

From: _____ Date: **8/01/2019**
Estimated Cost: _____
OD / ☒ WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: **YN 6369C**
at Workshop n/s: **AMA Autocare**
of: **36 foh Guen Rd East #01-36**
Insured: _____
Policy No.: _____
Claims No.: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: **Morning**

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: **3** days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)


Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **YN 6369C** Yr Regn: **2014 Sep**
Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **15434 NHR85** C.C. **2999cc**
Colour: **white** A/C: **Insured / Std / NI / NA**
Sp. Reading: **124313** T/Radio: **Insured / Std / NI / NA**
Eng/No: **NHR857015160**
C/No: _____
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: **Inorder** / Jammed / Leaked / Burnt or
Brake: **Inorder** / Jammed / Leaked / Burnt or
Modi: **Nil** / S/Rim / STD A/Rim or
Tyre Size: F: **195 / 75R15**
R: **165 / R13**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / **YOKO** or

Front Rear
R/Bal. **6** mm R/Bal. **6/6** mm
L/Bal. **6** mm L/Bal. **6/6** mm
D.O.A. _____ D.O.I. **8/1/19**
Survey held at **AMA Autocare**

Des. of Damages ☒ Fr / Rear / O/S / N/S / U/C / **Roof** or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
- Estimated repair range \$2,500 - \$3,000

14/1/2019

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: **PRQ.**
Lump Sum / I.B.I. (\$) _____

Days Of Repair: **3**
Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:	150
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified)		07 Jan 2019 13:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	KUNYI (SINGAPORE) PTE LTD, Co. Reg. No.: 199602299Z
Vehicle Reg. No.:	YN6369C
Claim Type:	TP
Vehicle Reg. No. (Insured):	GBC774K
Date of Loss:	26/12/2018 20:00 - :59
Policy/Cover Note No.:	
Policy No. (Claimant):	DMCSHQ18-000019
Excess:	S\$0.00
Repairer:	Ajax Mars Pte Ltd (Bukit Merah) 120 Lower Delta Road, #08-08 Cendex Centre, 169208 Bukit Merah - Tel: 6333 2222
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2019]

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2299Z
Vehicle Details	
Vehicle No.:	YN6369C
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2019
Vehicle Make:	ISUZU
Vehicle Model:	NHR85AUE4A
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	4JJ11M1856
Chassis No.:	NHR857015160
Maximum Power Output:	-
Open Market Value:	\$30,375.00
Original Registration Date:	17 Sep 2014
First Registration Date:	17 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$1,519.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,998.00
COE Rebate Amount:	\$17,040.00
Total Rebate Amount:	\$17,040.00

The information contained herein is correct as at 11 Jan 2019

OK

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF**COMMERCIAL VEHICLE - SCHEME****Comprehensive****Certificate No. : DMCSHQ18-000019****1. Index Mark and Registration Number of Vehicles**

YN6369C

2. Name of Policyholder

KUNYI (SINGAPORE) PTE LTD

3. Effective Date of the Commencement of Insurance for the purpose of the Act

17/09/2018

4. Date of Expiry of Insurance

16/09/2019 ✓

5. Person or Classes of persons entitled to drive*

Goods carrying - (MZ300) Authorised Driver.

Any of the following :-

1. The Policyholder

2. Any person on the order or with the permission of the Policyholder

Form: LCVP1

Excess:

Section 1:

Windscreen:

YEID-AC Additional:

S\$750.00

S\$100.00

S\$3,000.00

EQ Insurance MARS Motor
Accident Help Center**6311 3211**

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

1) Use in connection with the Insured's business.

2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.

3) Use for social domestic and pleasure purposes.

THE POLICY DOES NOT COVER

1) Use for hire or reward or for racing pace-making reliability trial or speed testing.

2) Use whilst drawing a greater number of trailers in all than is permitted by Law.

3) Use for the carriage of passengers for hire or reward.

4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

27.9.18

113935

#1386.40

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase : UNITED OVERSEAS BANK LIMITED

A000298/Tong Hin Insurance Agency Pte Ltd

Date of Issue : 16/08/2018 15:45

Authorised Signatory
EQ Insurance Company Limited

Exp No. : DMCSHQ17-000026

1/11/2019

E-FILE

MBHH18166735 / Ajax Mars Pte Ltd - Bukit Merah
ENTRY DATE & TIME: 28/12/2018 13:55
SUBMITTED BY: Joanne, Tham Pei Yan

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 28/12/2018 14:07

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2018 13:55
Date Of Accident	26/12/2018 20:15
Exact Location Of Accident	ALONG 553 UPPER JURONG RD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN6369C
Insured/Policyholder	
Name Of Registered Owner	KUNYI (SINGAPORE) PTE LTD
Co Reg No	199602299Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-97873454
Vehicle Particulars	
Manufacturer	ISUZU
Model	NHR85AUE4A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCSHQ18-000019
Cover Note Number	
Driver	
Name of Driver	LIM JUN XIAN BENJAMIN
NRIC No	S8441168Z
Date Of Birth	19/12/1984
Occupation	INDOOR
Date Of Driving Pass	22/07/2003
Driving Experience	15 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97873454

Fax Number

Contact Number

EMail Address

BENJAMIN@KUNYI.COM.SG

Address

NIL

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

My lorry was parked at 553 Upper Jurong Road from 7.30pm onwards just below our company dormitory. At 8.15pm, we heard a van GBC774K reversing and crashing onto my lorry. His rear hit the front of my lorry. Both side mirrors and support mounts are damaged. No injuries were involved.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Details of Witness 1

Name RASU PRABAHARAN

Phone Number

Email Address

Details of Witness 2

Name MARUTHA VELALAR

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

1/11/2019

E-FILE

Vehicle Registration Number

GBC774K

Vehicle Make/Model/Colour

NISSAN / NV200

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

DURASAMY MAHENDIRAN

NRIC/Passport Number

G2136506N

Contact Number

92751763

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

**VERIFIED BY AJAX MARS
REPORTING OFFICER
Johnny
Voo Cheon Yee
Witnessed by Reporting Centre
Personnel**

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan

Along 553 Upper Jurong Road.

A: VN6369C
B: GBC774K

Common Statement

ACCIDENT STATEMENT (2000 characters)

My lorry was parked at 553 Upper Jurong Road from 7.30pm onwards just below our company dormitory. At 8.15pm, we heard a van GBC774K reversing and crashing onto my lorry. His rear hit the front of my lorry. Both side mirrors and support mounts are damaged. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 December 2018 at 9:59 AM

Date/Time:

28 December 2018 at 9:59 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019 17:30		07 Jan 2019 13:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by insurer]	
Insured:	-, Co. Reg. No.: -				
Main Claimant:	KUNYI (SINGAPORE) PTE LTD, Co. Reg. No.: 199602299Z				
Vehicle Reg. No.:	YN6369C	Date of Loss:	26/12/2018 20:00 - :59 [51 Months and 9 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP	Policy/Cover Note No.:			
Vehicle Reg. No. (Insured):	GBC774K	Policy No. (Claimant):	DMCSHQ18-000019		
		Excess:	S\$0.00		
Repairer:	Ajax Mars Pte Ltd (Bukit Merah) 120 Lower Delta Road, #08-08 Cendex Centre, 169208 Bukit Merah - Tel: 6333 2222				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]				
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/01/2019]				

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*YN6369C
[GBC774K]
TP
KUNYI (SINGAPORE) PTE LTD
Dec 26 2018 8:00PM
[-]
Ajax Mars Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/01/19 14:29	General View					Load PDF		
2	11/01/19 14:29	Photographs of Damaged Parts					Load PDF		
3	11/01/19 14:30	Photo After Spray					Load PDF		

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	28/12/18 14:07	Accident Statement	1	Load HTM	

Photos/Images

3 per page ☒

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	28/12/18 14:00	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	28/12/18 14:00	Driving License	1	Load JPG	<input checked="" type="checkbox"/>
14	28/12/18 14:00	Driving License	1	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ☒

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	28/12/18 14:00	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	28/12/18 14:01	Common Statement	1	Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119000349/T1CD3E2

Date: 23/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : YN6369C

Insured Vehicle No : GBC774K

Date of Loss: 26/12/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN6369C

Make & Model: ISUZU NHR55E, 2.8 D (M)

Engine No: 4JJ11M1856

Reg. Date: 17/09/2014 (Man. Year: 2014)

Chassis No: NHR857015160

Colour: White

Odometer: 124313 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 165 R13 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 08/01/2019 Inspected At:

AMA AUTOMOTIVE PTE. LTD.
36 TOH GUAN ROAD EAST
#03-36 SINGAPORE 608580

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jan 2019)	
Parts:	N/A	ISUZU NHR55E 2.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN6369C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >