

Your Ref: AEMD/105/009/2018/186

Date: 10<sup>th</sup> January 2019

Our Ref: CS1/SPF19000362/Dtbs2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section

(Spore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SHC 1490B INSURED VEHICLE: YM 3785J ACCIDENT DATE: 16/11/2018**

We thank you for your instruction on 07/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 1490B from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 1490B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 1490B
Make & Model	: Hyundai AE IONIQ HEV 1.6 DCT
Year of Registration	: 2018
Chassis Number	: KMHC851CVKU114764
Engine Capacity	: 1580 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.