

2/20/2009

ASS. REC. BY:

REF: CS3/CTI18023097/Jvd3-1

Special Instruction:

Surveyor:  
Meunier

Fwef Jee

ASSIGNMENT (Office)

From (Person):

Irene Tay

638 96 192

of

CTI

Date/Time:

21/12/18 @ 5:20pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 6308M

Insured:

PC 4687L

at Workshop m/s

E-Motoring

Tel:

6910 0369 / 9183 5669

of

2 Yishun Ind. St. 1 # 01-23 Northpoint Bizhub

(Javier)

Policy No:

DMB1SN3026681800

Claim No:

JNM18D05884C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

18/12/2018

CA / REV / REP. / REV 24 HRS <sup>up</sup>

H.O.D. Endorsement:

Date/Time:

5:22pm @ 21/12/18

Person Contacted:

Robert

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
-	call was answered on 26/12/18 @ 2:06pm by Robert.
	FBG 6308M - X
	PC 4687L - X
14/2/19	@ 2:01pm vehicle still under repairing


RECEIVED 17 JUN 2019

PRS  
Hue Jia

REF: CT1

ASSIGNMENT

Form: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: **E-motoring 2 Yishun Ind St1**  
 at: **#01-23**  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: **FB66308M** Yr Regn: **20 Sep 2012**  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **Honda CBR1000RR** cc: **999**  
 Colour: **Black** A/C Insured / Std / NI / NA  
 Sp Reading: **44366** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 CTNo: **JH2SCS9A4CK401284**  
 Gen: Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modi: Nil / 2 Rim / STD A/Rim or  
 Tyre Size F: **120/70 R17**  
 R: **190/15 R17**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Diablo**  
 Front Rear  
 R/Bal 7 mm R/Bal 7 mm  
 L/Bal 7 mm L/Bal 7 mm  
 D.O.A. **18/12/18** D.O.I. **26/12/18**  
 Survey held at **E-motoring**  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
**Knock N/S, fall O/S**  
 The UIC / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction  
**Range: \$2,800 - \$3,500**  
**3 days**  
**28/12/2018**

**17/6/19 Confirmed L/S \$1800/- 2days of repair. (Real 12,743, 889)**

Update Time File Pass to /  
☐ : Preli. Report  
☐ : Final Report

Days Of Repair: **2**  
 Resurvey No. of Trip: **1**

Survey Fee  
 Transportation

150
190

Add Fee: ☐ Site Insp \$  
☐ Interview \$  
☐ Tech Insp \$  
☐ Planning \$

Report Format: **PRS -**  
 Lump Sum / L.B. /

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2894E
<b>Vehicle Details</b>	
Vehicle No.:	FBG6308M
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CBR1000RR
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	SC59E2405372
Chassis No.:	JH2SC59A4CK401284
Maximum Power Output:	-
Open Market Value:	\$16,572.00
Original Registration Date:	20 Sep 2012
First Registration Date:	20 Sep 2012
Transfer Count:	4
Actual ARF Paid:	\$2,486.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	19 Sep 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,852.00
COE Rebate Amount:	\$690.00
<b>Total Rebate Amount:</b>	<b>\$690.00</b>

The information contained herein is correct as at 27 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2018 12:45
Date Of Accident	18/12/2018 18:00
Exact Location Of Accident	2 YISHUN IND ST.1 #01-23 NORHTPOINT BIZHUB
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG6308M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG XING LE
NRIC No	S9622894E
Email Address	EMOTORINGSINGAPORE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98342153
Alternative Phone No	OTHERS-98342153
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	CBR1000RR
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5104032407
Cover Note Number	20/09/18 - 19/09/19
<b>Driver</b>	
Name of Driver	ONG XING LE
NRIC No	S9622894E
Date Of Birth	29/06/1996
Occupation	INDOOR
Date Of Driving Pass	16/01/2018
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98342153
Fax Number	
Contact Number	OTHERS-98342153
Email Address	EMOTORINGSINGAPORE@GMAIL.COM

Address	BLK 416 WOODLANDS ST.41 #09-153
Postcode	730416
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4687L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: FRG 6308 M

INSURER : NTUC


DATE & TIME: 18/12/18 @ 18:00


### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: (YS)  
NRIC/FIN No:

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No-T/20181219/2003

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No:

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
(✓) Claim ODP/TP at other workshop (by E-Metering)





**SINGAPORE  
POLICE FORCE**



T/20181219/2003

Police Station Of Origin  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1600-8529999

1 of 3

Report No: T/20181219/2003

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 19/12/2018 00:38		Vide Report No L/20181218/0104		Station Diary No 15	
<b>Informant's Particulars</b>					
Name of Informant: ONG XING LE			Address APT BLK 416 WOODLANDS STREET 41 #09-153 SINGAPORE 730416		
ID Type / ID No. NRIC NO / S9622894E			Contact No Home/Office Mobile: 98342153		
Nationality: SINGAPORE CITIZEN			Email:		
Sex Male	Age 22	Date of Birth: 29/06/1996	Type of Informant: Rider		
Race Chinese			Language: English		Institution / School Name
Occupation: NSF			Driving Licence Information Class: 2B, 2A		Date of Expiry

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive No	Date/Time of Accident: 18/12/2018 18:00	Type of Location: Car Park
Location:  YISHUN INDUSTRIAL STREET 1  2 YISHUN IND ST 1 #01-23 NORTH POINT BIZHUB S(768159)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Parked vehicles			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG6308M	Motorcycle	HONDA	CBR1000RR	White	Slightly Damaged	0
PC4687L	Van	TOYOTA		White	No Damage	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20181219/2003

Police Station Of Origin  
Yishun North N P C  
31 Yishun Central SINGAPORE 768827  
Tel No. 1800-8529999

2 of 3

Report No. T/20181219/2003

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBG6308M	NTUC Income Insurance Co-Operative Limited	5104032407	20/09/2018	19/09/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	ONG XING LE	ID No	S9622894E
Related Vehicle	PC4687L (Van)	Contact No	98342153
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 2B,2A Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 18/12/2018, at about 1800hrs, at the above mentioned location, I was inside a mechanic shop "E-motoring". I overheard one of the mechanics instructing his manager to move one of his vehicles away. Hence, I left the shop to observe the situation. As soon as I left the shop to observe, I noticed that my motorcycle (vehicle number: FBG6308M) was already lying down on the floor. I noticed that there was a van (vehicle number: PC4687L) in front of my motorcycle, and a lorry (unknown license plate) behind my motorcycle.

I did not notice any CCTVs around.

I believe that it was the van that reversed and knocked down my motorcycle due to his misjudgement.

PR



**SINGAPORE  
POLICE FORCE**



T/20181219/2003

Police Station Of Origin  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No 1800-8529999

3 of 3




Report No T/20181219/2003

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report: L / Sgt 2 LOW WEI DE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/12/2018 00:38
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No 65476151 	Classification Of Case:
Authentication Stamp NP168	

**QUOTATION FOR REPAIR : FBG6308M**

Qty	Description	Repairer's Estimate
1	FRONT WHEEL RIM NN	950.00 x
1	FRONT BRAKE DISC NN	850.00 x
1	FRONT FORK SET NN	1,800.00 x
1	FRONT FORK T-BRACKET NN	580.00 x
1	FRONT COVER (HEADLIGHT) NN	580.00 x
1	SIDE COVER (FRONT L SIDE) NN	380.00 x
1	SIDE COVER (FRONT R SIDE) NN	380.00 x
1	HEAD LIGHT (COMPLETE SET) NN	550.00 x
1	SIDE MIRROR (RH) SCR	180 550.00 /
1	FRONT SIGNAL SET (L/R) NN	250.00 x
1	FRONT BRAKE PUMP NN	680.00 x
1	BALANCER SCR	180.00 /
1	INNER COVER NN	300.00 x
1	METER SET NN	1,500.00 x
1	HEAD LIGHT WIRING NN	580.00 x
1	ARROW EXHUAUST PIPE SCR	1700 2,500.00 /
1	EXHUAUST GUARD SCR	120.00 /
1	CENTRAL COVER NN	380.00 x
1	INNER LEFT COVER NN	380.00 x
1	INNER RIGHT COVER NN	380.00 x
1	CENTER INNER COVER NN	380.00 x
1	SIDE STAND NN	150.00 x
2	REAR FOOT PEG (RH) SCR	88 220.00 /
1	ENGINE STARTER LEVER NN	280.00 x
1	RADIATOR COVER NN	250.00 x
1	EXHAUST COVER NN	280.00 x
1		
1		
1		
	Less 10%	15,430.00
		1,543.00
		13,887.00
	<u>Nett items</u>	
1	IU UNIT NN	156.00 x
	Total parts	14,043.00
	Towing fees	50.00 x
	Workmanship	450.00 200
	Total parts and labour charges	14,543.00
		2-12 days

D.O.I - 26/12/18  
Estimate Received - 8/1/18

L/S \$1800/- 2 days.

**Veron Chen (LKKAuto)**

---

**From:** Hwee Jie (LKK Auto)  
**Sent:** Thursday, 13 June 2019 5:30 PM  
**To:** samgui96@hotmail.com  
**Cc:** Veron Chen (LKKAuto)  
**Subject:** FBG 6308 FINALIZATION

Hi sam,

Finalized L/S \$1,800/- 2days of repair.

Please let me know if you're agree with the amount so I can proceed with finalization, thank you.

Best Regards,

**Hwee Jie | Assistant Automotive Assessor**

**LKK Auto Consultants**

Phone: 9180 3151 | Email: [Hweejie@lkkauto.com](mailto:Hweejie@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2018		21 Dec 2018 17:20 <a href="#">Edit Adj Rpt</a>	<b>S\$1,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

- , Co. Reg. No.: -

Main Claimant:

ONG XING LE

Vehicle Reg. No.:

FBG6308M

Claim Type:

TP / SNM18D05884C02

Vehicle Reg. No. (Insured):

PC4687L

Repairer:

E Motoring (HQ) 2 Yishun Industrial Street 1, Northpoint Bizhub #01-23, 768159 Yishun - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 19/06/2019]

Adj Asg. Remarks:

NO EST, ASSIGN MARCUS CHUA AS SJE.

Date of Loss:

18/12/2018 00:00 - :59  
[74 Months and 28 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

DMB1SN3026681800

Policy No. (Claimant):

Excess:

S\$0.00

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- CHINA\_TAIPING (17/06/2019): Report Send Back Alerts - FBG6308M (TP)

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBG6308M (SNM18D05884C02)  
[PC4687L]  
TP  
ONG XING LE  
Dec 18 2018 12:00AM  
[-]  
E Motoring

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
2	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
3	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
4	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
5	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
6	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
7	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
8	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
9	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
10	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
11	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
12	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
13	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
14	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
15	27/12/18 09:36	General View								Load JPG	<input checked="" type="checkbox"/>			
16	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
17	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
18	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
19	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
20	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
21	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
22	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
23	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
24	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
25	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
26	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
27	01/04/19 09:53	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
Documentation									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	21/12/18 17:19	PRS								Load PDF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	19/06/19 09:09	PRS Invoice								Load PDF				

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18023097/JVD3E2-1

Date: 19/06/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN3026681800  
 Claimant Vehicle No: FBG6308M Insured Vehicle No: PC4687L  
 Date of Loss: 18/12/2018 Nature of Claim: TP Claim No: SNM18D05884C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG6308M**  
 Make & Model: HONDA CBR1000RR, 998cc Engine No: SC59E2405372  
 Reg. Date: 20/09/2012 (Man. Year: 2012) Chassis No: JH2SC59A4CK401284  
 Colour: Black Odometer: 44366 km  
 Engine Capacity: 999 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 190/15 R17  
 Front Left Side: DIABLO 7 mm Rear Left Side: DIABLO 7 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,043.00	2,041.20	12,001.80	85.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	200.00	300.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,543.00</b>	<b>2,241.20</b>	<b>12,301.80</b>	<b>84.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,543.00</b>	<b>1,800.00</b>	<b>12,743.00</b>	<b>87.62</b>

### INSPECTION

Date of Assignment: 21/12/2018  
 Date Inspected: 26/12/2018 Inspected At: E Motoring (HQ)  
 2 Yishun Industrial Street 1, Northpoint  
 Bizhub #01-23  
 Singapore 768159  
 Estimated Period of Repair: 2.0 days

**Adjuster:** ONG HWEE JIE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jun 2019)	
Parts:	N/A	HONDA CBR1000RR 998cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG6308M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL RIM	Not Necessary	950.00 FL	*- FL
2	1		*FRONT BRAKE DISC	Not Necessary	850.00 FL	*- FL
3	1		*FRONT FORK T-BRACKET	Not Necessary	580.00 FL	*- FL
4	1		*FRONT COVER (HEADLIGHT)	Not Necessary	580.00 FL	*- FL
5	1		*SIDE COVER (FRONT L SIDE)	Not Necessary	380.00 FL	*- FL
6	1		*SIDE COVER (FRONT R SIDE)	Not Necessary	380.00 FL	*- FL
7	1		*HEAD LIGHT (COMPLETE SET)	Not Necessary	550.00 FL	*- FL
8	1		*SIDE MIRROR	O/S Scratched	550.00 FL	*180.00 FL
9	1		*SET FRONT SIGNAL (L/R)	Not Necessary	250.00 FL	*- FL
10	1		*FRONT BRAKE PUMP	Not Necessary	680.00 FL	*- FL
11	1		*BALANCER	Scratched	180.00 FL	*180.00 FL
12	1		*INNER COVER	Not Necessary	300.00 FL	*- FL
13	1		*SET METER	Not Necessary	1,500.00 FL	*- FL
14	1		*HEAD LIGHT WIRING	Not Necessary	580.00 FL	*- FL
15	1		*ARROW EXHAUST PIPE	Scratched	2,500.00 FL	*1,700.00 FL
16	1		*EXHAUST GUARD	Scratched	120.00 FL	*120.00 FL
17	1		*CENTRAL COVER	Not Necessary	380.00 FL	*- FL
18	1		*INNER LEFT COVER	Not Necessary	380.00 FL	*- FL
19	1		*INNER RIGHT COVER	Not Necessary	380.00 FL	*- FL
20	1		*CENTER INNER COVER	Not Necessary	380.00 FL	*- FL
21	1		*SIDE STAND	Not Necessary	150.00 FL	*- FL
22	1		*REAR FOOT PEG	O/S Scratched	220.00 FL	*88.00 FL
23	1		*ENGINE STARTER LEVER	Not Necessary	280.00 FL	*- FL
24	1		*RADIATOR COVER	Not Necessary	250.00 FL	*- FL
25	1		*EXHAUST COVER	Not Necessary	280.00 FL	*- FL
26	1		*IU UNIT	Not Necessary	156.00 FS	*- FS
27	1		*SET FRONT FORK	Not Necessary	1,800.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,586.00</b>	<b>2,268.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,543.00</b>	<b>226.80</b>
<b>Total Parts (\$\$)</b>	<b>14,043.00</b>	<b>2,041.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEES	New	50.00	0.00
2	WORKMANSHIP	New	450.00	200.00
Gross Labour Cost (S\$)			500.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >