

23/03/2012

ASS. REC. BY:

REF:

cs/16R19000402/Kvd3<sup>52</sup>

Special Instruction:

Surveyor:

From (Person):

Kenneth

Azlen Syazairindira

ASSIGNMENT (Office)

LCR

Date/Time: 9:12am 8/1/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

FBB 298Z

Insured:

SLJ 4027C

To Inspect Vehicle No:

Tel:

64639903

at Workshop m/s

GA Motor

of

Blk 32 Sin Ming Drive # 01-331

Policy No:

0999994805

Claim No:

0838692150 SG

Sum Insured:

Excess:

D.O.A. 4/01/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time: 9:13am 8/1/19

Person Contacted:

Mr. Tan

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBB 298Z-x

SLJ 4027C-CC4/ASM18013156/Rleb3q2

D.O.A: 12/7/18

21/2 11Lm 8320d enal &amp; confirm (Red 1863, 37/9)

REF: AIG

## ASSIGNMENT

From: Date: 8/1/2019

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: FBB 298Z  
at Workshop m/s: GA Motor  
of: Blk 32, Sin Ming Drive # 01-331

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 810k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>cap</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBB 298Z Yr Regn: 01 / 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1 File pass to

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 21/2 - typist

Report Format:

Lump Sum / I.B.I. (\$) 3200/-

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

|     |
|-----|
| 250 |
|     |
|     |
|     |
|     |
| 10  |
|     |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt | Adj Submitted | Ins Auth'd | Status  |
|------|---|---------------|--|---------|---------------|------------|---|
| Main | 09 Jan 2019<br><a href="#">Edit Reg</a> |               | 08 Jan 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> |         |               |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |  |                        |                        |
|-----------------------------|--|------------------------|------------------------|
| Insured:                    | LCRF Pte Ltd, Co. Reg. No.: 201624597K   |                        |                        |
| Main Claimant:              | DEIVANAI D/O SOJE MANY, ID: S7935274H  |                        |                        |
| Vehicle Reg. No.:           | FBB298Z  | Date of Loss:          | 04/01/2019 00:00 - :59 |
| Claim Type:                 | TP / 0838692150SG  | Policy/Cover Note No.: | 0999994805             |
| Vehicle Reg. No. (Insured): | SLJ4027C   | Policy No. (Claimant): |                        |
|                             |  | Excess:                |                        |
| Repairer:                   | Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903  |                        |                        |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/01/2019]        |                        |                        |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)


- AIG\_SG (09/01/2019): No OI GIA report
- AIG\_SG (09/01/2019): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

- Pre repair inspection request - FBB298Z VS SLJ4027C (OI) DOA: 04/01/2019

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi, Kaur, Baljit  
Sent: 8/1/2019 9:11:15 AM  
Attachments:  NEW PRI - SLJ4027C.pdf

---

Hi,

Please refer to the enclosed request from **Catherine Lim LLC**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours.

If you have any queries/concerns, please let us know.  
Kindly assist to assign **Kenneth Kong** as **Single Joint Expert** as requested.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** info@catherinelimllc.com [mailto:info@catherinelimllc.com]  
**Sent:** Monday, January 07, 2019 5:42 PM  
**To:** Azlan, Syazairdina  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ4027C AND FBB298Z ON 04/01/2019

Dear Sir (Without Prejudice)

We confirm Kenneth Kong as single joint expert.

Regards

Catherine Lim LLC

---

**From:** Azlan, Syazairdina  
**Sent:** Mon, 7 Jan 2019 09:15:52 +0000  
**To:** info@catherinelimllc.com  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ4027C AND FBB298Z ON 04/01/2019

Hi,

Please confirm that you are nominating Kenneth Kong from LKK named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** info@catherinelimllc.com [mailto:info@catherinelimllc.com]  
**Sent:** Monday, January 07, 2019 4:39 PM  
**To:** Azlan, Syazairdina  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ4027C AND FBB298Z ON 04/01/2019

Dear Sir (Without Prejudice)

We refer to your email.

Our client wish to appoint LKK, Kenneth Kong.

Regards

Catherine Lim LLC

---

**From:** Azlan, Syazairdina  
**Sent:** Mon, 7 Jan 2019 07:48:40 +0000  
**To:** info@catherinelimllc.com  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan,

Yoke Shi, Kaur, Baljit

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ4027C AND FBB298Z ON 04/01/2019

Without Prejudice

Your Reference : CL/190116/T/GA.sg  
Our Reference : SLJ4027C

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor         | Company Name                           |
|--------------------------|--|
| AIG In House Surveyor    | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee     | Priority Services                      |
| Jeffrey Ong Leng Kiat    | Priority Services                      |
| Jimmy Lee                | Priority Services                      |
| EC Looi                  | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd             |
| Ng You Han               | Formteam Adjusters Pte Ltd             |
| Soon HanXin (Gary)       | Formteam Adjusters Pte Ltd             |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd             |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd             |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd           |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd           |
| Marcus Chua              | LKK Auto Consultants Pte Ltd           |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd           |
| Adrian Ling              | LKK Auto Consultants Pte Ltd           |
| Mohammed Rasul           | LKK Auto Consultants Pte Ltd           |
| Kenneth Kong             | LKK Auto Consultants Pte Ltd           |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazardina.Azlan@aig.com](mailto:Syazardina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazardina Azlan@aig.com  
To: info@catherinelimlc.com  
Cc: Andy SY Fong@aig.com, Lee-Ying Chin@aig.com, NoorMariess.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinnul Hor@aig.com, yokeshi.chan@aig.com, Bal  
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ4027C AND FBB298Z ON 04/01/2019  
Date: Mon, 7 Jan 2019 07:48:40 +0000  
Without Prejudice

Your Reference : CL/190116/T/GA.sg  
Our Reference : SLJ4027C

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor         | Company Name                           |
|--------------------------|--|
| AIG In House Surveyor    | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee     | Priority Services                      |
| Jeffrey Ong Leng Kiat    | Priority Services                      |
| Jimmy Lee                | Priority Services                      |
| EC Looi                  | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd             |
| Ng You Han               | Formteam Adjusters Pte Ltd             |
| Soon HanXin (Gary)       | Formteam Adjusters Pte Ltd             |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd             |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd             |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd           |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd           |
| Marcus Chua              | LKK Auto Consultants Pte Ltd           |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd           |
| Adrian Ling              | LKK Auto Consultants Pte Ltd           |
| Mohammed Rasul           | LKK Auto Consultants Pte Ltd           |
| Kenneth Kong             | LKK Auto Consultants Pte Ltd           |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazaidina.Azlan@aig.com](mailto:Syazaidina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

**CATHERINE LIM LLC**

林 ADVOCATES & SOLICITORS  
梁 NOTARY PUBLIC - 公证官  
玲 COMMISSIONER FOR OATHS - 宣誓官  
律  
陈 CATHERINE C.L.LIM  
馆 DIRECTOR  
LL.B (HONS) SINGAPORE - 法律系 - 律师  
M.B.A. (BUSINESS LAW) - 商业系 - 硕士

20 Havelock Road #03-01  
Central Square Singapore 059765  
UEN No. 201310922K

Tel: (65) 6438 5500  
Fax: (65) 6438 0111  
www.catherinelimllc.com  
Email: info@catherinelimllc.com  
CATHERINE LIM LLC is a law corporation  
with limited liability

Your Ref: SLJ 4027C  
Our Ref: CL/190116/I/GA.sg

07 January 2019

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120  
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

LCRF Pte Ltd  
60 Anson Road  
#11-01 Mapletree Anson  
Singapore 079914

**CERTIFICATE OF POSTING**  
(Please be informed that all supporting documents  
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBB 298Z / SLJ 4027C ON 4.1.2019 ALONG ORCHARD TURN**

We are instructed by DEIVANAI D/O SOJE MANY to notify you of a road traffic accident involving our client's vehicle No. FBB 298Z and vehicle No. SLJ 4027C driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: GA Motor  
Blk 32 Sin Min Drive  
#01-331  
Singapore 575706

Tel: 6453 9903 Contact Person: Mrs Tan

Yours faithfully



cc: clients



MVA219001973 / VAG - Sin Ming  
 ENTRY DATE & TIME: 05/01/2019 11:01  
 SUBMITTED BY: CHRISTINA ONG Mui Lan

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforosaid.

## ACCIDENT STATEMENT

Date Of Report 05/01/2019 11:01  
 Date Of Accident 04/01/2019 20:00  
 Exact Location Of Accident ORCHARD TURN  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number FBB298Z  
 Insured/Policyholder  
 Name Of Registered Owner  
 NRIC No DEIVANAI D/O SOJE MANY  
 Email Address S7935274H  
 Mobile Phone No NOEMAIL  
 Alternative Phone No (LOCAL) +65-97690977  
 OTHERS-97690977

## Vehicle Particulars

Manufacturer YAMAHA  
 Model JUPITER MX (HC)  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category MOTORCYCLE

## Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy NO  
 Policy Number 5077288833-02 (TPFT)

## Cover Note Number

## Driver

Name of Driver DEIVANAI D/O SOJE MANY  
 NRIC No S7935274H  
 Date Of Birth 22/10/1979  
 Occupation INDOOR  
 Date Of Driving Pass 11/12/2003  
 Driving Experience 15 YEARS AND 0 MONTHS  
 Gender FEMALE  
 Mobile Number (LOCAL) +65-97690977  
 Fax Number  
 Contact Number OTHERS-97690977  
 Email Address NOEMAIL



Address BLK 406 #07-239 SIN MING AVENUE  
 Postcode 570406  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY :**

Vehicle Registration Number SLK4027C  
 Vehicle Make/Model/Colour HONDA SUV  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number 91205731  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON :**

Name DEIVANAI DIO SOJE MANY

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


Address

Postcode

BRUISES ON RIGHT LEG AND LEFT THIGH  
FB8298Z

NO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the day 04/01/2019 my de bike FBB 298Z was involve in a accer  
 accident when I was riding towards to Orchard turn a car SLJ 4027C  
 hit me from behind. At I fell onto the road.  
 The driver immediately came to my assistent. My bike  
 was damaged at the back and side right side of  
 the bike was also damaged.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

*PR* 05/01/19 05 JAN 2019

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:





# 盛 摩 哆 GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575703

TEL: 4539903, 4539904 FAX: 4539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.  
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date :07-01-2019

Estimated repair list for the accident motorcycle Yamaha Sniper MX150 vehicle No. FBB298Z

|       |                                  |         |          |      |
|-------|----------------------------------|---------|----------|------|
| 1 pc  | Handle bar                       | Di      | \$105.00 | ✓    |
| 1 set | Handle balancer                  | Di      | \$28.00  | ✓    |
| 1 set | Mirror                           | Red/wh  | \$80.00  | ✓    |
| 1 pc  | Brake lever                      | R       | \$35.00  | ✓    |
| 1 pc  | Phone holder                     | CN      | \$20.00  | ✓    |
| 1 pc  | Front mudguard                   | R       | \$120.00 | X    |
| 2 pcs | Front fork inner tubes           | 77/101  | \$380.00 | ✓    |
| 2 pcs | Fork oil seal & fork oil         | me      | \$55.00  | ✓    |
| 1 pc  | Steering stem                    | R       | \$150.00 | ✓    |
| 1 pc  | Steering cone & bearing          | me      | \$60.00  | ✓    |
| 1 pc  | Front disc plate                 | Wap     | \$220.00 | ✓    |
| 1 pc  | Front fairing                    | del/wh  | \$250.00 | ✓    |
| 1 pc  | Side fairing (right)             | Br/whap | \$375.00 | ✓    |
| 1 pc  | Front signal light (right)       | Gr      | \$115.00 | ✓    |
| 1 pc  | Brake pedal                      | R       | \$95.00  | ✓    |
| 1 pc  | Front footrest & footrest rubber | Red/wh  | \$75.00  | ✓    |
| 1 pc  | Footrest bar                     | R, S    | \$80.00  | X    |
| 1 pc  | Rear footrest                    | R       | \$70.00  | X    |
| 1 pc  | Clutch cover                     | Di      | \$265.00 | ✓    |
| 1 pc  | Rear side board (right)          | my car  | \$250.00 | ✓    |
| 1 pc  | Exhaust pipe                     | Di      | \$750.00 | ✓    |
| 1 pc  | Rear box                         | Gr      | \$180.00 | ✓    |
| 1 pc  | Rear carrier                     | Di      | \$150.00 | ✓    |
| 1 pc  | No. plate                        | R       | \$25.00  | 155m |
| 1 pc  | Rear tyre                        | R       | \$90.00  | X    |
| 1 pc  | Rear fender                      | Br      | \$120.00 | ✓    |
| 1 pc  | Rear fender holder               | CN      | \$75.00  | ✓    |
| 1 pc  | Tail light                       | Br      | \$85.00  | ✓    |
|       | Press rear frame                 |         | \$350.00 | 1801 |
|       | Towing                           |         | \$30.00  | ✓    |
|       | Labour                           |         | \$380.00 | 2001 |

108

Not Withstand  
1/1000 832001  
Recovery After Paint  
4 days

Total: \$5063.00

Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
|------|---|---------------|---|--|--|-------------|---|
| Main | 09 Jan 2019<br><a href="#">Edit Reg</a> |               | 08 Jan 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,200.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,200.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |  |                        |  |
|-----------------------------|--|------------------------|--|
| Insured:                    | LCRF Pte Ltd, Co. Reg. No.: 201624597K   |                        |  |
| Main Claimant:              | DEIVANAI D/O SOJE MANY, ID: S7935274H  |                        |  |
| Vehicle Reg. No.:           | FBB298Z  | Date of Loss:          | 04/01/2019 20:00 - :59<br>[35 Months and 14 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 0838692150SG  | Policy/Cover Note No.: | 0999994805 (Comprehensive)   |
| Vehicle Reg. No. (Insured): | SLJ4027C   | Policy No. (Claimant): |  |
|                             |  | Excess:                |  |
| Repairer:                   | Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903  |                        |  |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Ng, Hai-Chuan</b> ] Hai-Chuan.Ng@aig.com |                        |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 17/01/2019]        |                        |  |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (09/01/2019): No OI GIA report
- AIG\_SG (09/01/2019): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |































## Claim Documents

**\*FBB298Z (0838692150SG)**  
**[SLJ4027C]**  
**TP**  
**DEIVANAI D/O SOJE MANY**  
**Jan 4 2019 8:00PM**  
**[LCRF Pte Ltd]**  
**Ga Motor**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser ▼](#)

| Photos/Images |                 |                                   | 3 per page ▼   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 2             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 4             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 5             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 6             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 7             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 8             | 21/02/19 13:36  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 9             | 21/02/19 13:36  | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 10            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 11            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 12            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 13            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 14            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 15            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 16            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 17            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 18            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 19            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 20            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 21            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 22            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 23            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 24            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 25            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 26            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 27            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 28            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 29            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 30            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31            | 21/02/19 13:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32            | 21/02/19 13:42  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 33            | 21/02/19 13:42  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 34            | 21/02/19 13:42  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 35            | 21/02/19 13:42  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |



| Photos/Images |                 |   | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)             | Thumbnail    | Print                               |
| 36            | 21/02/19 13:42  | Reinspection Photo                            | Load JPG     | <input checked="" type="checkbox"/> |
| 37            | 21/02/19 13:42  | Reinspection Photo                            | Load JPG     | <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)             | Thumbnail    | Print                               |
| 1             | 09/01/19 13:49  | TP GIA REPORT                                 | Load PDF     |                                     |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)     | Thumbnail    | Print                               |
| 1             | 23/01/19 09:46  | Singapore Accident Statement<br>OI GIA REPORT | Load PDF     |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR19000402/KVD3S2  
Date: 21/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994805  
Claimant Vehicle No: FBB298Z Insured Vehicle No: SLJ4027C  
Date of Loss: 04/01/2019 Nature of Claim: TP Claim No: 0838692150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBB298Z**  
Make & Model: YAMAHA JUPITER MX, 134cc HC Engine No: G3E6E0133921  
Reg. Date: 21/01/2016 (Man. Year: 2015) Chassis No: MH3UG0740F0006579  
Colour: Multi-colour Odometer: 22306 km  
Engine Capacity: 150 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90R17 Rear Tyre Size: 120/70R17  
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 4,303.00        | 3,613.20        | 689.80          | 16.03        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 760.00          | 410.00          | 350.00          | 46.05        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,063.00</b> | <b>4,023.20</b> | <b>1,039.80</b> | <b>20.54</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>3,200.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>5,063.00</b> | <b>3,200.00</b> | <b>1,863.00</b> | <b>36.80</b> |

INSPECTION

Date of Assignment: 08/01/2019  
Date Inspected: 08/01/2019 Inspected At: Ga Motor (HQ)  
Estimated Period of Repair: 4.0 days Blk 32 Sin Ming Drive, #01-331  
Singapore 575706

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition        | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------|------------------|------------|------------|
| 1   | 1   |          | *HANDLE BAR                       | Distorted        | 105.00 F   | *105.00 FL |
| 2   | 1   |          | *SET HANDLE BALANCER              | Dented           | 28.00 F    | *28.00 FL  |
| 3   | 1   |          | *SET MIRROR                       | Dented / Cut     | 80.00 F    | *80.00 FL  |
| 4   | 1   |          | *BRAKE LEVER                      | Bent             | 35.00 F    | *35.00 FL  |
| 5   | 1   |          | *PHONE HOLDER                     | Cracked          | 20.00 F    | *20.00 FL  |
| 6   | 1   |          | *FRONT MUDGUARD                   | Repair           | 120.00 F   | *- FL      |
| 7   | 2   |          | *FRONT FORK INNER TUBES           | Twisted / Dented | 380.00 F   | *380.00 FL |
| 8   | 2   |          | *FORK OIL SEAL & FORK OIL         | Necessary        | 55.00 F    | *55.00 FL  |
| 9   | 1   |          | *STEERING STEM                    | Bent             | 150.00 F   | *150.00 FL |
| 10  | 1   |          | *STEERING CONE & BEARING          | Necessary        | 60.00 F    | *60.00 FL  |
| 11  | 1   |          | *FRONT DISC PLATE                 | Warped           | 220.00 F   | *220.00 FL |
| 12  | 1   |          | *FRONT FAIRING                    | Dented / Cut     | 250.00 F   | *250.00 FL |
| 13  | 1   |          | *SIDE FAIRING (RIGHT)             | Buckled / Warped | 375.00 F   | *375.00 FL |
| 14  | 1   |          | *FRONT SIGNAL LIGHT (RIGHT)       | Cut              | 115.00 F   | *115.00 FL |
| 15  | 1   |          | *BRAKE PEDAL                      | Bent             | 95.00 F    | *95.00 FL  |
| 16  | 1   |          | *FRONT FOOTREST & FOOTREST RUBBER | Dented / Cut     | 75.00 F    | *75.00 FL  |
| 17  | 1   |          | *FOOTREST BAR                     | Bent             | 80.00 F    | *80.00 FL  |
| 18  | 1   |          | *REAR FOOTREST                    | Repair           | 70.00 F    | *- FL      |
| 19  | 1   |          | *CLUTCH COVER                     | Dented           | 265.00 F   | *265.00 FL |
| 20  | 1   |          | *REAR SIDE BOARD (RIGHT)          | Mtg Cracked      | 250.00 F   | *250.00 FL |
| 21  | 1   |          | *EXHAUST PIPE                     | Dented           | 750.00 F   | *750.00 FL |
| 22  | 1   |          | *REAR BOX                         | Cut              | 180.00 F   | *180.00 FL |
| 23  | 1   |          | *REAR CARRIER                     | Distorted        | 150.00 F   | *150.00 FL |
| 24  | 1   |          | *NO. PLATE                        | Bent             | 25.00 FS   | *15.00 FS  |
| 25  | 1   |          | *REAR TYRE                        | Serviceable      | 90.00 F    | *- FL      |
| 26  | 1   |          | *REAR FENDER                      | Buckled          | 120.00 F   | *120.00 FL |
| 27  | 1   |          | *REAR FENDER HOLDER               | Cracked          | 75.00 F    | *75.00 FL  |
| 28  | 1   |          | *TAIL LIGHT                       | Broken           | 85.00 F    | *85.00 FL  |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>4,303.00</b> | <b>4,013.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | <b>0.00</b>     | <b>399.80</b>   |
| <b>Total Parts (\$\$)</b>                                 | <b>4,303.00</b> | <b>3,613.20</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars       | Lab.Type | Repairer's | Amount |
|-------------------------|-------------------|----------|------------|--------|
| <u>Labour Items</u>     |                   |          |            |        |
| 1                       | PRESS REAR FRAME. | New      | 350.00     | 180.00 |
| 2                       | TOWING.           | New      | 30.00      | 30.00  |
| 3                       | LABOUR.           | New      | 380.00     | 200.00 |
| Gross Labour Cost (S\$) |                   |          | 760.00     | 410.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >