

ASS. REC. BY:

REF

CS/TMJ/9000405/Tlgd321

Special Instruction:

Surveyor

Mentmer

From (Person)

Telma Gomez

of

TMJ

Date/Time

8/1/19 @ 10:11 am

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No:

SHC 2182

Insured:

GBE 2268G

at Workshop m/s

Comfort Delgro

Tel:

G2148300

of

SQ Loyang Drive

Policy No:

MT106972

Claim No:

M1900104

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

04/01/19

CA / REV / REP. / REV 24 HRS

cup

Date/Time:

10:17 am 8/1/19

Person Contacted:

H.O.D. Endorsement:

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHC 2182 - CC3/AXA12014864/Hled21

D.O.A: 30/07/12

GBE 2268G - X

Signature

Taufik

REF:

JM1

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 2182J Yr Regn: 2016 out

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 C.C. 1655

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 293295 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 1CM HLB4/UM H4095384

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 7/1/19

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/2/19 \$1202.40, 2 days initial to Chng.  
(Red \$377.60, 24%)

RECEIVED 31 JAN 2019

30/1/2019

Date/Time, File Pass to?

31/1/2019 Taufik

Date/Time, File Return to?

2)

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1202.40

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

250

10

260

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019		08 Jan 2019 10:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	CHUA AH TEE, Co. Reg. No.: 53317091E		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC2182J	Date of Loss:	04/01/2019 21:00 - :59
Claim Type:	TP / M1900104	Policy/Cover Note No.:	MT106972 (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBE2268G	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 17/01/2019]</b>		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Taufikh (LKKAuto)  
**Sent:** Friday, 25 January 2019 6:12 PM  
**To:** 'Chiang Liat Choon'  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** RE: SHC2182J FINALIZE

Hi Chiang,

COR \$1202.40 , 2 days.

Regards  
Taufikh  
Lkk Auto

---

**From:** Chiang Liat Choon [mailto:chianglc@cdge.com.sg]  
**Sent:** Thursday, 17 January 2019 9:02 AM  
**To:** Taufikh (LKKAuto)  
**Subject:** Fw: SHC2182J FINALIZE

Dear Taufikh,

Before paint with kalvin camera.

Best Regards  
Chiang Liat Choon  
Taxi Crash Repair ComfortDelGro Engineering Pte Ltd  
Off: 62148314 Fax: 65468156

---

**From:** ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>  
**Sent:** Thursday, 17 January 2019 8:57 AM  
**To:** Chiang Liat Choon  
**Subject:** Scan Data from CDG\_LO\_AW\_A5570

Number of Images: 3  
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570  
Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/01/2019 09:34
Date Of Accident	04/01/2019 21:40
Exact Location Of Accident	PIE JALAN TOA PAYOH TOWARDS NEWTON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2182J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	YEO YONG KOON
NRIC No	S7251011I
Date Of Birth	29/02/1972
Occupation	OUTDOOR
Date Of Driving Pass	11/12/2003
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96732429
Fax Number	
Contact Number	
EMail Address	JEFFREYYEO90@YAHOO.COM

Address	BLK 488B TAMPINES STREET 45 #09-147
Postcode	521488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CHANGI N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20190105/2050

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2268G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CAIFU JIE
NRIC/Passport Number	S8935178B
Contact Number	87495689
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

YEO YONG KOON

Approximate Age

46

Injuries Sustain

BACK AND NECK PAIN. ON 3 DAYS MC.

Injured person in which vehicle?

SHC2182J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Fauzy  
NRIC/FIN No.:



SKETCH PLAN

Refer Attached Sketch plan.

DOA: 4/01/19 @ 2140hrs.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Attached Police report No. T/20190105/2050.

There is (1) Male Pax on board at my taxi and No injury.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199203321R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Fauzy  
NRIC/FIN No.:



A - SHC - ~~3394~~ H2182J

B - GBE - 2268 - G.



**SINGAPORE  
POLICE FORCE**



T/20190105/2050

1 of 3

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

Report No. T/20190105/2050

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/01/2019 11:24	Vide Report No.:	Station Diary No.: 31
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: YEO YONG KOON			Address: APT BLK 488B TAMPINES STREET 45 #09-147 SINGAPORE 521488	
ID Type / ID No.: NRIC NO / S72510111			Contact No.: Home/Office: Mobile: 96732429	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 46	Date of Birth: 29/02/1972	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 04/01/2019 21:40	Type of Location: Straight Road
Location:  PAN-ISLAND EXPRESSWAY (JALAN TOA PAYOH)				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE2268G	Lorry					0
SHC8394H 4C2182	Car				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190105/2050

2 of 3

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

Report No. T/20190105/2050

## CONTINUATION OF REPORT

Driver			
Name	Cai Fu Jie	ID No.	S8935178B
Related Vehicle	GBE2268G (Lorry)	Contact No.	87495689
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YEO YONG KOON	ID No.	S7251011I
Related Vehicle	SHC2394H (Car) SHC2182J	Contact No.	96732429
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	05/01/2019	Date Discharge	05/01/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 04/01/2019 at about 2140hrs, I was driving from airport towards Jalan Toa Payoh. I was along Jalan Toa Payoh and was on lane 2 of the road. There was a car in front of who suddenly applied brake. As such, I also step on brake but the vehicle behind me could not react on time and hit my vehicle. After which, we exchange particular and left the scene. I suffer slight discomfort on my body. My vehicle suffered damages on the bumper. There is no government property damage.

On 05/01/2019, I went to see a doctor and was given 3 days of medical leave. There is an in-car camera installed in my vehicle however I am not too sure whether it is recording.



SINGAPORE  
POLICE FORCE



T/20190105/2050

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

3 of 3



Report No. T/20190105/2050





CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Staff Sgt KOH SIEN KHAI, KELVIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/01/2019 11:24
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp NP168	 SIGNATURE







**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

<b>Claim Type:</b>	THIRD PARTY	<b>Ref. No:</b>	
<b>Policy No:</b>		<b>Date of Loss:</b>	04/01/2019
<b>Vehicle Reg. No.:</b>	SHC2182J	<b>Driveable?</b>	YES
<b>Party At Fault:</b>	UNKNOWN		

<b>Make/Model:</b>	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	<b>Vehicle Reg. Date:</b>	13/10/2016
<b>Vehicle Colour:</b>	BLUE	<b>Gen Condition:</b>	GOOD
<b>Engine No:</b>	D4FDGU683902	<b>Chassis No:</b>	KMHLB41UMHU095384
<b>Odometer:</b>	293295 KM		

<b>Paint Type:</b>	
<b>List Item Discount:</b>	20.00 %
<b>Total Loss?</b>	NO
<b>Est. Duration of Repair (day)</b>	3

**Present Location:** COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

**COST OF CLAIMS**

Parts		
Miscellaneous Items		
Labour		
Paintwork Labour		
Towing		
		<b>Amount</b>
		760.00
		10.00
		810.00
		0.00
		0.00
		<b>Gross Total (\$\$)</b>
		<b>1,580.00</b>
		<b>+ GST 7.00% (\$\$)</b>
		<b>110.60</b>
		<b>Nett Amount (\$\$)</b>
		<b>1,690.60</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Tanflm 47495744*  
*- WP*  
*7/1/19 @ 1645*  
*Resurvey before paint*  
*02 days*  
*Tanflm @ Thantanto.com*

This claim is handled by: JUMANI BIN MASUDIN

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*



**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 07 Jan 2019)

**Parts:** 143      HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2182J/07/01/2019 16:01

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	✓ *553.00 FL de
2	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL de x nn
3	1		*REAR BUMPER RUBBER MAT	0	0.00	✓ *50.00 FS de
4	1		*REAR BUMPER ADVERTISEMENT	0	0.00	✓ *50.00 FS de
5	1		*REAR FENDER ADVERTISEMENT	0	0.00	✓ *200.00 FS de
Sub Total (\$\$)						875.00
- List Item Discount on L Items (\$\$)						115.00
Total Parts (\$\$)						760.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC2182J/07/01/2019 16:01. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

442.40  
50  
50  
200  
742.40

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 200	400.00
2	SPRAY PAINTING	New 200	300.00
3	WIRING	New 20	30.00
4	REMOVE /REFIX REVERSE SENSOR	New 30	80.00
Gross Labour Cost (S\$)			810.00 430

ComfortDelGro Engineering Pte Ltd/SHC2182J/07/01/2019 16:01. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

742.40

10

450

1202.40

#

Date/Time: 07.01.2019 10:47

Page : 1

Team: ARC Repair TP(CLSO)1

## JOB CARD

Sales Order:

JC NO.: 305257292

CUSTOMER

REGN NO.:

SHC2182J

MILEAGE

MS

COMFORT TRANSPORTATION PTE LTD

7010045

CUSTOMER NO.

ADDRESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

05.01.2019 12:15

YR OF MANU

13.10.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU095384

COMPLETION DATE/TIME:

COUNT CARD NO.

## JOB DESCRIPTION

Accident Date: 04.01.2019


NATURE: 3P 04.01.19

S/NO

LABOR CODE

DESCRIPTION

FRONT



REAR

LEFT SIDE

RIGHT SIDE

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHC2182J

CHIANG

Vehicle No.:

SHC2182J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.01.2019

REPAIR ESTIMATE

Time: 11:04:59

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305257292  
REGN NO : SHC2182J  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.10.2016  
DATE/TIME IN : 05.01.2019 12:15  
ACCIDENT DATE : 04.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,202.40

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2019		08 Jan 2019 10:11 <a href="#">Edit Adj Rpt</a>	<b>S\$1,202.40</b> <a href="#">Edit Estimates</a>	<b>S\$1,202.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------


  

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CHUA AH TEE, Co. Reg. No.: 53317091E	
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	SHC2182J	Date of Loss: 04/01/2019 21:00 - :59 [26 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1900104	Policy/Cover Note No.: MT106972 (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBE2268G	Policy No. (Claimant):
		Excess: S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300	
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/01/2019]	































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS 										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*SHC2182J (M1900104)**  
**[GBE2268G]**  
**TP**  
**COMFORT TRANSPORTATION PTE LTD**  
**Jan 4 2019 9:00PM**  
**[CHUA AH TEE]**  
**ComfortDelGro Engineering Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	07/01/19 12:22	<b>Accident Statement</b> From: SC - Reg. No: GBE2268G, Claimant: CHUA AH TEE	 Load HTM	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	07/01/19 09:49	<b>Accident Statement</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	07/01/19 09:44	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	25/01/19 18:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	25/01/19 18:10	<b>General View</b>	 Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
20	25/01/19 18:12	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
21	25/01/19 18:12	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
22	25/01/19 18:12	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	08/02/19 18:00	Letter of Demand from Third Party		Load TIF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/01/19 09:49	Sketch Plan [Linked Accident Report Documents]		Load TIF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/01/19 09:49	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	07/01/19 09:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/01/19 09:49	Sketch Plan		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19000405/T1QD3E2

Date: 13/02/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT106972

Claimant Vehicle No : SHC2182J

Insured Vehicle No : GBE2268G

Date of Loss: 04/01/2019

Nature of Claim: TP Claim No: M1900104

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC2182J

Make &amp; Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU683902

Reg. Date: 13/10/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU095384

Colour: Blue

Odometer: 293295 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	760.00	742.40	17.60	2.32
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	810.00	450.00	360.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,580.00</b>	<b>1,202.40</b>	<b>377.60</b>	<b>23.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>110.60</b>	<b>84.17</b>	<b>26.43</b>	<b>23.90</b>
<b>Nett Amount (S\$)</b>	<b>1,690.60</b>	<b>1,286.57</b>	<b>404.03</b>	<b>23.90</b>

## INSPECTION

Date of Assignment: 08/01/2019

Date Inspected: 07/01/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC2182J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
4	1		*REAR BUMPER ADVERTISEMENT	Necessary	50.00 FS	*50.00 FS
5	1		*REAR FENDER ADVERTISEMENT	Necessary	200.00 FS	*200.00 FS
					<b>Sub Total (S\$)</b>	<b>875.00 853.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>115.00 110.60</b>
					<b>Total Parts (S\$)</b>	<b>760.00 742.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	WIRING	New	30.00	20.00
4	REMOVE / REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			810.00	450.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;