

2/03/2002

ASS. REC. BY:

REF

CS/MSG19000411/R1td30

Special Instruction:

Survivor  
Meimen

Rasu

ASSIGNMENT (Office)

From (Person):

Fievel P00

of

MSG

Date/Time:

8/1/19 @ 10 45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1604K

Insured:

SKL 20094

at Workshop m/s

Premier Taxis

Tel:

6544 6676

of

28 Changi South Ave 2 # 03-02

Policy No:

A80376754QMX

Claim No:

58 1114

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/01/19

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:47am @ 8/1/19

Person Contacted:

Vincet

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SHD 1604K - CS / TM113005740 / M1y/d1

DOA: 25/03/2013

SKL 20094 - X

9/11-

Revised via menmen preli advise.

Part by Part \$721.45 (Red: 783-11 : 520%)

Survivor *Form*

REF: MSIG

4975H.

# ASSIGNMENT

From: Date: 8/1/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 1604K  
at Workshop m/s premier taxis  
of 23 changi south Ave 2 #03-02

Insured

Policy No.

Claims No.

Sum Insured.


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 1604K Yr Regn: 2017 / ANG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer of

Make: Hyundai I30 1.6 C.C. 1582

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 143537 T/Radio: Insured / Std / NI / NA

Eng/No:

CtNo: TMAD281U VH J134114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 06/01/19

D.O.I. 08/01/19

Survey held at

PREMIER

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 JAN 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.L: (\$

TP 721.45

150
10
160

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 15:29		08 Jan 2019 10:45 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIEW SIAO PING, ID: S8406432G			
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H			
Vehicle Reg. No.:	SHD1604K	Date of Loss:	06/01/2019 14:00 - :59 [16 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 581114	Policy/Cover Note No.:	A80376754QMX (Comprehensive) Coverage: 28/06/2018 - 27/06/2019	
Vehicle Reg. No. (Insured):	SKL2009U	Policy No. (Claimant):		
		Excess:		
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2019]			
Driver/Custodian (Insured):	KOH TUCH WENG ( / Male), NRIC: S8622625A			
Adj Asg. Remarks:	Liability 100%, Contact : 6544 6676 or 6544 6689, To survey at 23 Changi South Avenue 2, #01-02.			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 29 January 2019 9:12 AM  
**To:** 'Goh Wee Dek'  
**Cc:** SUR; Rasul (LKKAuto)  
**Subject:** RE: SHD1604K- FINALIZE

Dear Wee Dek,

Confirm part by part \$721.45, 2days.

Please submit all relevant documents to MSIG.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Goh Wee Dek <[weedek.goh@premiertaxi.com](mailto:weedek.goh@premiertaxi.com)>  
**Sent:** Saturday, 26 January 2019 10:44 AM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SHD1604K- FINALIZE

Dear Rasul

Please confirm PxP \$721.45, 2days.

Rear bumper adjust to repair under 10WU

Regards

Goh Wee Dek  
Assistant Claims Manager  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511**  
**Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)**

---

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/01/2019 10:53
Date Of Accident	06/01/2019 14:15
Exact Location Of Accident	SLIP OF PIE - JURONG INTO CORPORATION ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD1604K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

### Driver

Name of Driver	TAN CHUNG HENG ANDREW
NRIC No	S7627425H
Date Of Birth	18/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	12/11/1997
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97278881
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 537 #03-4060 ANG MO KIO AVE 5
Postcode	560537
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PAX IN THE REAR SEAT - MALAY GENDER: : FEMALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - MALAY GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEH. A - 2 PAX VEH. B - 1 PAX

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	MDM BALKIS BINTI OSMAN - PAX IN VEH. A
Phone Number	
Email Address	

#### Details of Witness 2

Name	MDM HALIMAHTON ABDUL RAHMAN - PAX IN VEH. A
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL2009U
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	KOH TUCK WENG
NRIC/Passport Number	S8622625A
Contact Number	98368230
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT PORTION
No. Of Passenger (Including Driver)	2

#### DETAILS OF INJURED PERSON 1

Name	TAN CHUNG HENG ANDREW - DRIVER OF VEH. A
Approximate Age	
Injuries Sustain	WILL SEEK FOR MEDICAL TREATMENT IF NECESARY
Injured person in which vehicle?	SHD1604K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Signature]* 76274254  
SHD1604K

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


07 JAN 2019 *[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan Pg. 2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PIE/JURONG

A: SHD1604K

B: SKL 2009U.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

07 JAN 2019

762742SH  
SHD1604K

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 06/01/2019 @ 1415HRS, I WAS DRIVING MY TAXI (SHD 1604 K), TRAVELLING ALONG THE SLIP ROAD OF PIE/JURONG INTO CORPORATION ROAD WITH 2 PASSENGERS ONBOARD.

I SLOWED DOWN MY TAXI TO A COMPLETE STOP – CHECKING FOR CLEARANCE FROM THE RIGHT.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( SKL 2009 U – TOYOTA ) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT PORTION.


BOTH MY PASSENGERS – MDM BALKIS BINTI OSMAN & MDM HALIMAHTON ABDUL RAHMAN, WILLING TO BE MY WITNESS.


AS A RESULT, I FELT SOME DISCOMFORT & WILL SEEK FOR MEDICAL TREATMENT IF NECESSARY. NO AMBULANCE AT SCENE.

VEHICLE B HAD A PASSENGER ONBOARD.

\*VIDEO FOOTAGE CAPTURED

DAMAGES FOUND ON VEHICLE A & VEHICLE B



  
S 7627425H  
Driver's Signature & NRIC Number

Text size + -

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHD1604K  
Previous Vehicle No.: -  
Effective Date of Ownership: 30 Aug 2017  
Original Regn Date: 30 Aug 2017  
Registration Date: 30 Aug 2017  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ134114  
Engine No.: D4FBGZ144446  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: \$20,185.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Aug 2025  
Minimum PARF Benefit: \$7,655.00  
No. of Transfers: 0  
IU Label No.: 1050707050  
COE No.: 2017083001004057W  
COE Expiry Date: 29 Aug 2025  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)

**Premier Automotive Services Pte  
Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

**Claim Reference:**  
**Assessment number: SHD1604K**  
**Version: 1712**  
**Date calculated: 01/08/2019 09:37 AM**

**Full Report**  
**Registration: SHD1604K**  
**Printed: 01/08/2019 9:37 AM**

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-06
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

<b>Vehicle</b>	
Manufacturer:	HYUNDAI
Model:	I30 (GD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 80 01
Registration:	SHD1604K
VIN number:	
Odometer:	
<b>Model Specs</b>	
5-DOOR (HATCHBACK)	

**Premier Automotive Services Pte  
Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

Claim Reference:  
 Assessment number: SHD1604K  
 Version: 1712  
 Date calculated: 01/08/2019 09:37 AM

Full Report  
 Registration: SHD1604K  
 Printed: 01/08/2019 9:37 AM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS		6.0	30.00
NO NUMBER	R + R TAILGATE BADGE		2.0	10.00
2640	REAR BUMPER SUPPORT REMOVE		10.0*	50.00
2711	REAR PANEL REPAIR		10.0*	50.00
2931	BOOTLID/TAILGATE REPAIR		10.0*	50.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>3.80</b>	<b>38.0</b>
<b>Total of Labour</b>				<b>190.00</b>

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHD1604K

Version: 1712

Date calculated: 01/08/2019 09:37 AM

Full Report

Registration: SHD1604K

Printed: 01/08/2019 9:37 AM

## Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		11.0	
	REAR PANEL REPAIR PAINTING <50%		11.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%		15.0	

## Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	46.42
2711	REAR PANEL REPAIR PAINTING <50%	10.50
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	20.25

### Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			37.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
<b>Total</b>		<b>10 WU/h</b>	<b>5.70</b>	<b>57.0</b>	<b>285.00</b>

### Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	46.42
Repair Painting	30.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>104.27</b>

## Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	86611A6000	Repair	811.11
3020	BADGE "130"	86310A5000	se X	27.80
f: OEM Parts	<b>Savings</b>			<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>			<b>838.91</b>
u: Used parts	<b>Subtotal Discount(+35.00%)</b>			<b>-293.62</b>

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHD1604K

Version: 1712

Date calculated: 01/08/2019 09:37 AM

Full Report

Registration: SHD1604K

Printed: 01/08/2019 9:37 AM

**Total** **545.29**

## Extras

Code	Description	Price SGD
1000	REVERSE SENSOR X <i>mm</i>	280.00*
1001	BOOTLID STICKERS <i>mm</i>	100.00*
<b>Total Extras</b>		<b>380.00</b>

## Final Calculation

	SGD	SGD
<b>Parts</b>		
Total Discount(+35.00%)		
<b>Total Parts</b>		<b>545.29</b>
<b>Labour Time Base 10 WU/h</b>		
Total 38.0 WU X 50.00 SGD/h		
<b>Total of Labour</b>		
<b>Total Of Extras</b>		
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 57.0 WU X 50.00 SGD/h		
Material Cost		
<b>Total Paint Including Material</b>		
<b>Repair Cost Excludes GST</b>		<b>1,504.56</b>
GST (+7.0%)		<b>105.32</b>
<b>Repair Cost Included GST</b>		<b>1,609.88</b>

## Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Premier Automotive Services Pte  
Ltd  
#01-02, 23 Changi Sth Ave 2  
486443**

**Claim Reference:**  
**Assessment number: SHD1604K**  
**Version: 1810**  
**Date calculated: 01/26/2019 10:42 AM**

**Full Report**  
**Registration: SHD1604K**  
**Printed: 26/01/2019 10:43 AM**

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-06
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

<b>Vehicle</b>	
Manufacturer:	HYUNDAI
Model:	I30 (GD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 80 01
Registration:	SHD1604K
VIN number:	
Odometer:	
<b>Model Specs</b>	
5-DOOR (HATCHBACK)	



**Premier Automotive Services Pte  
Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

Claim Reference:  
 Assessment number: SHD1604K  
 Version: 1810  
 Date calculated: 01/26/2019 10:42 AM

Full Report  
 Registration: SHD1604K  
 Printed: 26/01/2019 10:43 AM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection: 2019-01-26

### Damage Areas

All ☐  
 Underbody ☐



## Labour

		Time Base 10 WU/h	Price = 50.00 SGD/h	
Code	Description		WU	Price SGD
2640	REAR BUMPER SUPPORT REMOVE		10.0*	50.00
2583	REAR BUMPER REPAIR		10.0*	50.00
2711	REAR PANEL REPAIR		10.0*	50.00
2931	BOOTLID/TAILGATE REPAIR		10.0*	50.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>4.00</b>	<b>40.0</b>	<b>200.00</b>
<b>Total of Labour</b>				<b>200.00</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	

**Premier Automotive Services Pte  
Ltd  
#01-02, 23 Changi Sth Ave 2  
486443**

Claim Reference:  
Assessment number: SHD1604K  
Version: 1810  
Date calculated: 01/26/2019 10:42 AM

Full Report  
Registration: SHD1604K  
Printed: 26/01/2019 10:43 AM

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR PANEL REPAIR PAINTING <50%		11.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%		15.0	

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER REPAIR PAINT PLASTIC	39.90
2711	REAR PANEL REPAIR PAINTING <50%	10.50
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	20.25

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h		41.0	
Time Paint				
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
<b>Total</b>	<b>10 WU/h</b>	<b>6.40</b>	<b>64.0</b>	<b>320.00</b>

Material Cost - Paint		Price SGD
Repair Painting		30.75
Repair Painting Plastic		39.90
Material-constant Metal		18.10
Material-constant Plastic		12.70
<b>Total</b>		<b>101.45</b>

**Extras**

Code	Description	Price SGD
1001	BOOTLID STICKERS	100.00*
	<b>Total Extras</b>	<b>100.00</b>

**Premier Automotive Services Pte  
Ltd  
#01-02, 23 Changi Sth Ave 2  
486443**

**Claim Reference:**  
**Assessment number: SHD1604K**  
**Version: 1810**  
**Date calculated: 01/26/2019 10:42 AM**

**Full Report**  
**Registration: SHD1604K**  
**Printed: 26/01/2019 10:43 AM**

**Final Calculation**

	SGD	SGD
<b>Labour Time Base 10 WU/h</b>		
Total 40.0 WU X 50.00 SGD/h	200.00	
<b>Total of Labour</b>		<b>200.00</b>
<b>Total Of Extras</b>		<b>100.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 64.0 WU X 50.00 SGD/h	320.00	
Material Cost	101.45	
<b>Total Paint Including Material</b>		<b>421.45</b>
<b>Repair Cost Excludes GST</b>		<b>721.45</b>
GST (+7.0%)		50.50
<b>Repair Cost Included GST</b>		<b>771.95</b>
<b>Lump Sum</b>		<b>771.95</b>

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2019 15:29		08 Jan 2019 10:45 <a href="#">Edit Adj Rpt</a>	<b>S\$721.45</b> <a href="#">Edit Estimates</a>	<b>S\$721.45</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LIEW SIAO PING, ID: S8406432G								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHD1604K	Date of Loss:	06/01/2019 14:00 - :59 [16 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 581114	Policy/Cover Note No.:	A80376754QMX (Comprehensive) Coverage: 28/06/2018 - 27/06/2019						
Vehicle Reg. No. (Insured):	SKL2009U	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 07/02/2019]								
Driver/Custodian (Insured):	KOH TUCH WENG ( / Male), NRIC: S8622625A								
Adj Asg. Remarks:	Liability 100%, Contact : 6544 6676 or 6544 6689, To survey at 23 Changi South Avenue 2, #01-02.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHD1604K (581114)**  
**[SKL2009U]**  
**TP**  
**PREMIER TAXIS PTE LTD**  
**Jan 6 2019 2:00PM**  
**[LIEW SIAO PING]**  
**Premier Taxis Pte Ltd - Changi**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail		Print
<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b>					
1	07/01/19 15:59	<b>Accident Statement</b> <small>From: SC - Reg. No: SKL2009U, Claimant: LIEW SIAO PING</small>	Load HTM		
<b>LKK Auto Consultants Pte Ltd (HQ)</b>					
1	09/01/19 11:07	<b>Adjuster Immediate Advice</b>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail		Print
<b>LKK Auto Consultants Pte Ltd (HQ)</b>					
1	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
2	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
3	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
4	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
5	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
6	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
7	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
8	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
9	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
10	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
11	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
12	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
13	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
14	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
15	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
16	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
17	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
18	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
19	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
20	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
21	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
22	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
23	29/01/19 09:18	<b>General View</b>	Load JPG		<input checked="" type="checkbox"/>
24	29/01/19 09:18	<b>Reinspection Photo</b>	Load JPG		<input checked="" type="checkbox"/>
25	29/01/19 09:18	<b>Reinspection Photo</b>	Load JPG		<input checked="" type="checkbox"/>
26	29/01/19 09:18	<b>Reinspection Photo</b>	Load JPG		<input checked="" type="checkbox"/>
27	29/01/19 09:18	<b>Reinspection Photo</b>	Load JPG		<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail		Print
<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b>					
1	07/01/19 15:31	<b>PRI from Premier Taxis Pte Ltd</b>	Load PDF		
2	07/01/19 15:32	<b>SHD1604K E-file report</b>	Load PDF		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000411/R1TD3E2

Date: 29/01/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A80376754QMX

Claimant Vehicle No : SHD1604K

Insured Vehicle No : SKL2009U

Date of Loss: 06/01/2019

Nature of Claim: TP

Claim No: 581114

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD1604K

Make &amp; Model: HYUNDAI I30 (FD), 1.6 DOHC (A)

Engine No: D4FBGZ144446

Reg. Date: 30/08/2017 (Man. Year: 2016)

Chassis No: TMAD281UVHJ134114

Colour: Grey

Odometer: 143537 km

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	925.29	100.00	825.29	89.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	624.27	621.45	2.82	0.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,549.56</b>	<b>721.45</b>	<b>828.11</b>	<b>53.44</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>108.47</b>	<b>50.50</b>	<b>57.97</b>	<b>53.44</b>
<b>Nett Amount (\$\$)</b>	<b>1,658.03</b>	<b>771.95</b>	<b>886.08</b>	<b>53.44</b>

### INSPECTION

Date of Assignment: 08/01/2019

Date Inspected: 08/01/2019 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)

23 Changi South Ave 2 #03-02

Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2019)
<b>Parts:</b>	144	HYUNDAI I30 (FD) 1.6 DOHC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD1604K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	811.11 FL	*- FL
2	1		*BADGE 130	Not Necessary	27.80 FL	*- FL
3	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
4	1		*BOOTLID STICKERS	Necessary	100.00 FS	*100.00 FS
					<b>Sub Total (\$\$)</b>	<b>1,218.91 100.00</b>
					<b>- List Item Discount on L Items 35.00/35.00% (\$\$)</b>	<b>293.62 0.00</b>
					<b>Total Parts (\$\$)</b>	<b>925.29 100.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL 38.0 WU X 50.00 SGD / H	New	200.00	200.00
2	LABOUR COST 57.0 WU X 50.00 SGD / H	New	320.00	320.00
3	MATERIAL COST	New	104.27	101.45
Gross Labour Cost (S\$)			624.27	621.45

Report was unsubmitted during this print-out.

< END OF ESTIMATES >