

ASS. REC. BY:

REF

CS3/AIG19000-414/Gcd302

Special Instruction:

Surveyor:
Mammen

Guo Jiong
Chin Lee Yng

ASSIGNMENT (Office)

From (Person):

of

AIG

Date/Time

8/11/19 @ 10:59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGE 82D

Insured:

SLB 9297Z

at Workshop m/s

Yeow Koon Motor

Tel:

6785 3286

of

Blk 9002, Tampines street 93 #01-34

Policy No:

2100463352

Claim No:

872686805586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

21/12/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:05pm 8/11/19

Person Contacted:

Mr. Goh

Vehicle IN OUT

| Date/Time | Action/Instruction (x) Estimate |
|-----------|---------------------------------------|
| | SGE 82D - CS / TP / 00 / 29 / 4 / Acr |
| | SLB 9297Z - X |
| | Dismantle: 9/1/2019 |
| | |
| | |
| | |
| | |
| | |

D.O.A: 25/04/2010

PRS
Xtal

REF: A167

8633C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Yelow Koon Motor
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: \$88K

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE 82D Yr Regn: 01 Aug 2011

Type: M. Car / PM. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Merce S300L c.c. 2997

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 11/855 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W01D 2211542A396597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 255/45 2R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 08-01-18 19

Survey held at w/s 4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FA O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 180

Transportation: _____

S + RS, SI _____

Photos _____

Others 70

TOTAL 200

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format: DAR

Lump Sum / I.B.I: (\$ _____)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 8/1/2019 10:59:46 AM

Attachments:  [FMC12065-AIG_20190104145743.pdf](#)
 [FMC12065-AIG_20190104163225.pdf](#)  [tmp365B.TIF](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Legiste Law Corporation

24 Peck Seah Street
#04 - 06, Nehsons Building
Singapore 079314
Telephone +65-62279909 Facsimile +65-62272767
E-mail advocates@legiste.com.sg

Yr Ref 8726865055SG003
Email syazairdina.azlan@aig.com
Our Ref FMC.12065.18.45.GP

ADVOCATES & SOLICITORS
NOTARIES PUBLIC
COMMISSIONERS FOR OATHS
INCORPORATED WITH LIMITED LIABILITY
Cn. & GST Regn No 200305183Z

FOK MUN CHEONG
TAN KIM KEE
NG LAI LENG

4th January 2019

URGENT

The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
Attn: Ms Syaza Irdina Azlan

BY EMAIL ONLY

Dear Sirs


PRE-REPAIR SURVEY ("PRS")
ACCIDENT ON 21.12.18 INVOLVING SGE 82D & SLB 9297Z
AT THE CAR PARK LOCATED AT BLK 929 TAMPINES ST 91
CLAIMANT(S): LEE SIAN FAAT
ADDRESS : BLK 61 TAMPINES AVE 1 #01-02 SINGAPORE 529776

We refer to your email of even date @ 3.31 pm, the contents of which are noted.

Pursuant to paragraph 2.9 of the Pre-Action Protocol for Non-Injury Motor Accident Cases, kindly instruct your surveyor to complete the PRS by 8th January 2019 at our client's workshop particularized as follows:

| | | |
|----------------|---|--|
| Name | : | Yeow Koon Motor Spray Painting |
| Address | : | 9002 Tampines Street 93 #01-34 Tampines Industrial Park A Singapore 528836 |
| Contact Person | : | Mr Goh Beng Tee |
| Tel | : | 6785 3286 |

Yours faithfully


Joseph Fok Mun Cheong
Legiste Law Corporation

cc client

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 8633C |

Vehicle Details

| | |
|-------------------------------|--------------------|
| Vehicle No.: | SGE82D |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 08 Jan 2019 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | S300L |
| Primary Colour: | Black |
| Manufacturing Year: | 2011 |
| Engine No.: | 27294631824701 |
| Chassis No.: | WDD2211542A396597 |
| Maximum Power Output: | 170.0 kW (227 bhp) |
| Open Market Value: | \$85,396.00 |
| Original Registration Date: | 01 Aug 2011 |
| First Registration Date: | 01 Aug 2011 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$85,396.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 31 Jul 2021 |
| PARF Rebate Amount: | \$51,237.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------|
| COE Expiry Date: | 31 Jul 2021 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$56,490.00 |
| COE Rebate Amount: | \$14,349.00 |
| Total Rebate Amount: | \$65,586.00 |

The information contained herein is correct as at 08 Jan 2019

OK

▶ Mercedes-Benz s300l Used Vehicle List (2 vehicles)

| Car Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Company | Availabi |
|--------------------------------|----------|--------------|-------------|----------|---------|---------------------|----------|
| Mercedes-Benz S-Class S300L | \$91,800 | \$17,020 /yr | 28-Nov-2011 | 2,997 cc | - | Faster Auto Trading | Availal |

100% Loan And Balloon Scheme Available, Full Serviced Histories With C&C, Ex-Bankruptcy And Bad Credit Welcome, Guarantee Buy Back At \$47,000 By Nov 2021.

Office No. - 64761970

Yi De - 97480900 | Jimmy - 91010213 | Thomas - 96645002

| | | | | | | | |
|--------------------------------|----------|--------------|-------------|----------|-----------|--|---------|
| Mercedes-Benz S-Class S300L | \$85,000 | \$17,180 /yr | 27-May-2011 | 2,997 cc | 82,000 km | | Availal |
|--------------------------------|----------|--------------|-------------|----------|-----------|--|---------|

Facelifted Model! C&C Unit. Well Maintained With Low Mileage, STA Evaluation Welcome. Vehicle Conditioned By Professional Groomer. Class Brown On Brown Leather Interior. 100% Accident Free, Immediat...

Office No. - -

Sherley Teo - 98780008

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

MVA318165839 / VAC - Kaki Bukit
 ENTRY DATE & TIME: 26/12/2018 16:27
 SUBMITTED BY: Norhaini Bte Abdul Majid

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 26/12/2018 16:37

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------------|
| Date Of Report | 26/12/2018 16:27 |
| Date Of Accident | 21/12/2018 19:25 |
| Exact Location Of Accident | B/92B TAMPINES ST 91 (OPEN CARPARK) |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|---------------------------------------|
| Vehicle Registration Number | SGE82D |
| Insured/Policyholder | |
| Name Of Registered Owner | LEE SIAN FAAT |
| NRIC No | S2508633C |
| Email Address | RONALD@ATSE.COM.SG |
| Mobile Phone No | (LOCAL) +65-96355739 |
| Alternative Phone No | OFFICE-96355739 |
| Vehicle Particulars | |
| Manufacturer | MERCEDES-BENZ |
| Model | S300L |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | INDIA INTERNATIONAL INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 18MPC00000761 (COMP) |
| Cover Note Number | |
| Driver | |
| Name of Driver | LEE SIAN FAAT |
| NRIC No | S2508633C |
| Date Of Birth | 04/07/1957 |
| Occupation | INDOOR |
| Date Of Driving Pass | 15/02/1979 |
| Driving Experience | 39 YEARS AND 10 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96355739 |
| Fax Number | |
| Contact Number | OFFICE-96355739 |
| E-Mail Address | RONALD@ATSE.COM.SG |

Address BLK 61 TAMPINES AVENUE 1 #01-02
 Postcode 529776
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BEDOK POLICE DIVISIONAL HQ (G DIVISION)
 Police Station Address ROAD: 30 BEDOK NORTH ROAD, POSTCODE: 469676, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2440000 - FAX NO: 64443009
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons; WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB9297Z
 Vehicle Make/Model/Colour NISSAN TEANA 2.0 XL CVT
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 02 Jan 2019 Edit Reg | | 08 Jan 2019 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [\[Created by adjuster\]](#)

Insured: **Barco Singapore Private Limited**, Co. Reg. No.: NA

Main Claimant: **LEE SIAN FAAT**, ID: S2608833C

| | | | |
|-----------------------------|--------------------------|------------------------|--|
| Vehicle Reg. No.: | SGE82D | Date of Loss: | 21/12/2018 19:00 - :59 [88 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 8726865055SG | Policy/Cover Note No.: | 2100463352 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLB9297Z | Policy No. (Claimant): | |
| | | Excess: | |

Repairer: **Yeow Koon Motor Spray Painting (HQ)** BLK 9002 TAMPINES ST 93 #01-34 TAMPINES IND PARK A, 528836 Tampines - Tel:

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Foo, Chit Yan**] Chityan.Foo@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... **[Final Rpt due 17/01/2019]**

Claimant's Solicitor: **LEGISTE LAW CORPORATION** - Tel: 62279909

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (09/01/2019): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SGE82D (8726865055SG)**
[SLB9297Z]
TP
LEE SIAN FAAT
Dec 21 2018 7:00PM
[Barco Singapore Private Limited]
Yeow Koon Motor Spray Painting

| Upload Documents | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View | View in Browser <input type="checkbox"/> |
|---------------------------|-----------------|--|--|--------------------|--|--------------|--|--------------|----------|-------------------------------------|--|
| Assessment Reports | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | | Thumbnail | | Print | |
| 1 | 09/01/19 14:30 | Accident Statement From: SC - Reg. No: SLB9297Z, Claimant: BARCO SINGAPORE PRIVATE LIMITED | | | | | | 1 | Load HTM | | |
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | Thumbnail | | Print | |
| 1 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 11/01/19 11:15 | General View | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 11/01/19 11:15 | Photographs of Damaged Parts | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | |

Documents Checklist

| | | | |
|--|-----------------------|----------------------|-----------------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

| |
|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) |
| <div style="border: 1px solid black; height: 40px; width: 100%;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19000414/GCD3E2

Date: 16/01/2019

REFERENCE

| | | |
|--|-----------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100463352 |
| Claimant Vehicle No : SGE82D | Insured Vehicle No : | SLB9297Z |
| Date of Loss: 21/12/2018 | Nature of Claim: | TP |
| | | Claim No: 8726865055SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGE82D | | |
| Make & Model: | MERCEDES-BENZ S300L, 3.0 (A) | Engine No: | 27294631824701 |
| Reg. Date: | 01/08/2011 (Man. Year: 2011) | Chassis No: | WDD2211542A396597 |
| Colour: | Black | Odometer: | 111855 km |
| Engine Capacity: | 2997 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 255/45Z R18 | Rear Tyre Size: | 255/45Z R18 |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 08/01/2019 | |
| Date Inspected: | 08/01/2019 Inspected At: | Yeow Koon Motor Spray Painting (HQ) BLK 9002 TAMPINES ST 93 #01-34 TAMPINES IND PARK A Singapore 528836 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-----------|------------|--------|
| 1 | 1 | | *FRT BUMPER | Torn | 0.00 F | *- F |
| 2 | 1 | | *FRT BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 1 | | *FRT BUMPER SIDE RETAINER RH | Crumpled | 0.00 F | *- F |
| 4 | 1 | | *FRT BUMPER SPONGE RH | Torn | 0.00 F | *- F |
| 5 | 1 | | *FRT BUMPER MOULDING CHROME RH | Broken | 0.00 F | *- F |
| 6 | 1 | | *FRT RH BUMPER FOG LAMP COVER | Cut | 0.00 F | *- F |
| 7 | 1 | | *FRT RH BUMPER FOG LAMP CHROME MOULDING | Cut | 0.00 F | *- F |
| 8 | 1 | | *FRT RH HEADLAMP ASSY | Cracked | 0.00 F | *- F |

F=Franchise part.

| | | |
|---------------------------|-------------|-------------|
| Total Parts (\$\$) | 0.00 | 0.00 |
|---------------------------|-------------|-------------|

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >