

1/4/2019

INS. CASE OWNER:

CC 4/AIG1900

LKK

IDAC:

Survivor:

RBC

DOE

ASSIGNMENT

8/1/19

Date / Time :

7/1/19

Registered in Merimen:

8/1/19

Pre-assign / CCU / FTE

GW 6456A



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner?

(YES)

Nature of Accident :

If NO, Driver Name / Age : YED FALSAH bin SYED MOHAMMAD

Driver Tel No. :

(VA, YES / NO) TAME

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

017652445546

99944609/100805473-10071

M540W

105 MURRIC RD UPAN CP

U/GIA REPORT: (YES) NO : TP GIA REPORT: YES / NO

Insured Liability : Final ? Yes / No

SUB 4287E

REAR PEE



INSRS:

WSP:

Tel :

Liability :

RMKS:

complete vms



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

15/1/19

w/c

1015/10/1/19

-Chowhan

1/2/19

29/2/19

SUB 4287E - X

GW 6456A - X

Spoke to client re: MS ready. Informed of TP claim, agreed to settle 9 months ago with no further action.

FILE PAS TO TYPE MANIMATE

FILE PAS TO LSP TO CLOIE

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI: 2-10/1/19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

SS

(Agreed / Assessed) BOLA S/N No. : 25

If NO or B 28, Ass. Lia:

Repair Cost:

(w/65)

SS

2911.75

COID REVERTED (INCLUDE PARKED TP)

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

800.00 (\$ 100 x 8 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☒

SS

LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search:

SS

36.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3320

Total:

SS

8748.20

Global Sum SS: 8700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

8700.00

Name 1:

Complete vms Atc Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ALH

ASSIGNMENT

From

Date:

08/11/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLB 4387E

at Workshop n/s

Complete vms

of

Blk 176 Sin Ming Dr #03-14

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res: Yes or No

Lum Sum:

1-B.1 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 4387E

Yr Regn:

04 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Wagon

1999

Colour:

M. L. Brown

A/C

Insured / Std / NI / NA

Sp. Reading

2562P

T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

KMHJ3813M14U205503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

5/1/19

D.O.I.

8/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11

File parts to

Est not ready

P/P - \$7394.16 (Real \$4071.01 / 36%)

Date/Time: File Pass to?



Prel. Report

11



Final Report

Date/Time: File Return to?

25

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. E+P. 24

1. Phone

1. Others

1. 1

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) :

Add Fee:



Site Insp (\$



Interview (\$



Tech tips (\$



Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|----------------------------|------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CC4/AIG19000433/Khb3 | | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 08-01-2019 | |  |
| Code : AIG | | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GW 6456A | Veh. Inspected | SLB 4387E | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 08/01/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 05/01/2019 | Inspection Date | 08/01/2019 | |
| Survey held at | COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

PRITHIPAL SINGH S/O BHASANT SINGH
BLK 109 MCNAIR ROAD #12-277
SINGAPORE 320109

Attention : Motor Claim Department
Contact : 90014221

Estimate : ES006566

Date : 05/01/2019
Vehicle Num. : SLB4387E
Make/Model : HYUNDAI TL TUCSON 2.0-2016
Chassis/Eng# : KMHJ3813MHU205503/G4NAGU1752
Accident Date : 05/01/2019
Claim No. :
Reference :
Policy No. :

Not Notarized
Reamy B4 paint
8,7394.16

S/N Quantity Particular Unit Price Amount S\$

| | | | | | |
|-----|---|--|-------|----------|---|
| | | LIST ITEMS : | | | |
| 1. | 1 | FRONT BUMPER TOP | | 589.50 | X |
| 2. | 8 | FRONT BUMPER CLIP | 5.00 | 40.00 | X |
| 3. | 1 | FRONT BUMPER SIDE RETAINER | | 32.00 | X |
| 4. | 1 | FRONT BUMPER LOWER GARNISH | | 381.00 | X |
| 5. | 1 | FRONT HEADLAMP R/H | | 2,677.90 | X |
| 6. | 1 | FRONT HEADLAMP BRACKET R/H | | 54.00 | X |
| 7. | 1 | FRONT FENDER R/H | | 584.80 | X |
| 8. | 1 | FRONT FENDER OUTER GARNISH R/H | | 155.90 | X |
| 9. | 1 | FRONT FENDER INNER SHIELD | | 130.60 | X |
| 10. | 1 | FRONT SIDE MIRROR ASSY | | 1,132.20 | X |
| 11. | 1 | FRONT DOOR R/H | | 1,361.10 | X |
| 12. | 2 | FRONT DOOR STICKER R/H | | 73.20 | X |
| 13. | 1 | FRONT DOOR OUTER CHROME HANDLE R/H | 36.60 | 324.30 | X |
| 14. | 1 | FRONT DOOR OUTER CHROME HANDLE INNER R/H | | 67.90 | X |
| 15. | 1 | FRONT DOOR INNER LOCK R/H | | 261.80 | X |
| 16. | 1 | FRONT DOOR KEY LOCK R/H | | 452.00 | X |
| 17. | 1 | FRONT DOOR HANDLE SENSOR | | 382.00 | X |
| 18. | 1 | FRONT DOOR OUTER HANDLE GASKET R/H | | 25.00 | X |
| 19. | 1 | REAR DOOR R/H | | 1,208.00 | X |
| 20. | 2 | REAR DOOR STICKER R/H | 32.00 | 64.00 | X |

List Total S\$:

16.00% Discount S\$:

208

9,997.20
1,499.58
8,497.62

LABOUR :

TRANSFER R/H FRONT DOOR COMPONENTS TO NEW DOOR
RUST PROOFING TREATMENT

150.00
100.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

PRITHIPAL SINGH S/O BHASANT SINGH
BLK 109 MCNAIR ROAD #12-277
SINGAPORE 320109

Attention : Motor Claim Department
Contact : 90014221

Estimate : ES006566

Date : 05/01/2019
Vehicle Num. : SLB4387E
Make/Model : HYUNDAI TL TUCSON 2.0-2016
Chassis/Eng# : KMHJ3813MHU205503/G4NAGU1752
Accident Date : 05/01/2019
Claim No. :
Reference :
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|--|------------|---------------|
| | | CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION | | |
| | | TRANSFER R/H REAR DOOR COMPONENTS TO NEW DOOR | | |
| | | SPRAY PAINT DAMAGED AREA AFFECTED | | |
| | | TO CHANGE HEADLAMP, FRONT BUMPER, R/H FRONT DOOR, DOOR | | |
| | | MIRROE AND REAR DOOR | | |
| | | Labour Total S\$: | | |
| | | | | 90.00 206 |
| | | | | 150.00 x |
| | | | | 1,100.00 8001 |
| | | | | 950.00 5506 |
| | | | | 2,540.00 |

SingDollars : Eleven Thousand Thirty-Seven & Cents Sixty-Two Only

Total S\$: 11,037.62
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

PRITHIPAL SINGH S/O BHASANT SINGH
BLK 109 MCNAIR ROAD #12-277
SINGAPORE 320109

Supplementary Estimate : ES006569

Attention : THE OWNER
Contact : 90014221

Date : 11/01/2019
Vehicle Num. : SLB4387E
Make/Model : HYUNDAI TL TUCSON 2.0-2016
Chassis/Eng# : KMHJ3813MHU205503/G4NAGU1752
Accident Date : 11/01/2019
Claim No. :
Reference :
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|-----------------------------|------------|------------|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | FRONT DOOR PROTECTOR R/H | | |
| | | FRONT DOOR INNER HANDLE R/H | | |
| | | List Total S\$: | | |
| | | 15.00% Discount S\$: | | |
| | | 201 | | |
| | | | 178.00 | |
| | | | 325.00 | |
| | | | 503.00 | |
| | | | 75.45 | |
| | | | 427.55 | |

SingDollars : Four Hundred Twenty-Seven & Cents Fifty-Five Only

Total S\$: 427.55
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

- Pre repair inspection request - SLB4387E VS GW6456A (OI) DOA: 05/01/2019

From: Azlan, Syazairdina

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinnul, Chan, Yoke Shi, Kaur, Baljit

Sent: Monday, 7 January, 2019 4:13:25 PM

Attachments: [image003.tif](#)

Hi,

Please refer to the enclosed request from **Complete VMS PTE LTD**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as **Single Joint Expert** as requested.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOI, Claims Operations - Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com www.aig.sg

From: lihui@completevms.com.sg [mailto:lihui@completevms.com.sg]

Sent: Monday, January 07, 2019 3:59 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinnul, Chan, Yoke Shi, Kaur, Baljit; lihui@completevms.com.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GW6456A AND SLB4387E ON 05/01/2019

Without Prejudice

Dear OIC,

Please arrange Mr Kenneth Kong (LKK Auto Consultants Pte Ltd) to conduct survey.

Thank you & Best Regards,

Gan Li Hui (Ms)

Complete VMS PTE LTD

Tel: 6455 0012 Fax: 6554 0012

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

From: Azlan, Syazairdina

Sent: Mon, 7 Jan 2019 06:14:50 +0000

To: lihui@completevms.com.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinnul, Chan, Yoke Shi, Kaur, Baljit

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GW6456A AND SLB4387E ON 05/01/2019

Without Prejudice

Your Reference : SLB4387E

Our Reference : GW6456A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

| Name of Surveyor | Company Name |
|------------------|--------------|
|------------------|--------------|

| | |
|--------------------------|--|
| AIG In House Surveyor | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufik | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com www.aig.sg

From: Zhou, Aiping

Sent: Monday, January 07, 2019 2:01 PM

To: PROSG.FNOL

Cc: Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; Chin, Ann; Md Ishak, Mohd Imran; Ho, Choon-Poh; Tan, Lily (AIG); Quek, Joyceline-CH

Subject: 05# GW6456A#002,002#DEFAULT

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLB4387E (0136529488SG)**
[GW6456A]
TP
PRITHIPAL SINGH S/O BHASANT SINGH
Jan 5 2019 10:00AM
[KST Auto Rental Pte Ltd]
COMPLETE VMS PTE LTD

Reply Reply All Mark as Unread Print Message Delete Message Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **26/07/2019 10:45 AM**.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$8748.20) - SLB4387E - Claim Handler: Lee, Ming-Yao**

Approved:8748.20.

DOCUMENTS SUMMARY
There are no documents.



Your Ref: GW6456A
Our Ref : TPDS19014 - SLB4387E

22nd January 2019

By Postage

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way #07-16
Chartis Building
Singapore 079120

Attention: Motor Claims Department

Dear OIC,

ACCIDENT INVOLVING VEHICLE: SLB4387E AND GW6456A ALONG BLK 109 MCNAIR ROAD CARPARK LOT 302 ON 05.01.2019.

We are the authorized repair workshop for the owner of motor vehicle no. **SLB4387E** which is involved in the captioned accident with your insured vehicle **GW6456A**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

| | | | |
|---|--|--------------|-------------------|
| 1 | Cost of Repair as agreed with surveyor | S\$ 7,911.75 | (Inclusive GST) |
| 2 | 14days of Loss of Use@ \$100.00 | S\$ 1,400.00 | 2 x \$100 = \$200 |
| 3 | LTA/GIA Search fee | S\$ 36.45 | |
| | Total | S\$ 9,348.20 | \$8748.20 |

We enclosed herewith the following documents to support the claims:-

- a. Proforma Invoice
- ~~b. Rental-agreement~~
- c. Lta/GIA search fee

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours Faithfully

Chiu Siong Lim
For Complete VMS Pte Ltd

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 10 May 2019 12:04 PM
To: 'kstteam@singnet.com.sg'
Subject: ACCIDENT INVOLVING GW6456A & SLB4387E ALONG/AT BLK 108 MCNAIR RD OPEN SPACE CARPARK ON 05/01/2019

KST AUTO RENTAL PTE LTD
3021A UBI ROAD 1
#01-42
KAMPONG UBI INDUSTRIAL ESTATE
SINGAPORE 408715

Attn: Ms. Wendy

Dear Sir/Madam,

ACCIDENT INVOLVING GW6456A & SLB4387E ALONG/AT BLK 108 MCNAIR RD OPEN SPACE CARPARK ON 05/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLB4387E against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

To: Complete VMS Pte Ltd
176, Sin Ming Drive,
#03-14, Sin Ming Autocare Complex
Singapore 575721

LETTER OF AUTHORIZATION

RE: ACCIDENT BETWEEN SLB4387E / GW6456A. (Vehicle Numbers)
ON 5/1/2019 10am (Date of Accident) AT Blk 109 Menair Road Carpark Lot 309

1. I/We, the owner of vehicle no. SLB4387E hereby appoint you to act for me to repair and recover damages sustained to my vehicle in the above accident from the third party driver and / or his / her insurers.
2. In this respect, I/We have authorized you to repair, correspond, negotiate and settle on my behalf, all claims against the parties involved in the subject accident. All final financial awards in my favor pertaining to the subject accident claim are to be paid to Complete VMS Pte Ltd.
3. By way of this Letter of Authorization, I/We also further authorized you to sign all Discharge Vouchers and any other related documents in settlement of the subject accident claims. I/We hereby undertake to ratify and reaffirm such signing of Discharge Vouchers and/or documents from any third party insurers by us.
4. During the settlement process with the third party insurers / drivers, you may act fully on my behalf and all negotiations and correspondences given by you to the third party insurers / driver are as if given directly from me. With regards to the settlement of the above subject accident claim, I/We agree and undertake to ratify all correspondences and negotiations given by you to the third party insurers / driver and further agree and undertake to be bound by all acts performed or carded out by you.
5. I/We understand that should the subject accident claims fail or not able to reach an amicably settlement with the third party insurers or driver, I/We will have to appointed a solicitors by way of signing a warrant to act in present of the appointed solicitor to further pursue the matter and to commence legal proceedings in Court in my/our name against the third party driver and/or his employers (if applicable). I/We further agrees that should I/We fails or disagrees to appoint a solicitors at that stage, I/We shall be fully liable for all costs incurred to you until that point of time.
6. I/We further confirm my/our understanding that I/We shall render my/our full co-operation pertaining to the settlement of the subject accident and method of repair adopted shall be in accordance to the standard practices of the industry and will be at the full discretion of you.
7. I/We hereby agree that upon settlement of the above subject accident claim, I/We are required to sign Discharge Voucher/s issued by the third party insurers. After which all settlement monies shall be used to settle all costs and fee incurred to carry out the above subject accident repairs and claims. This settlement monies shall constitute a full discharge of your payment obligation to us.
8. Any indemnity / discharge voucher signed by the workshop is without prejudice to my rights to claim for compensation for my personal injury (if any). Complete VMS Pte Ltd is only authorized to negotiate and finalized with Third Party for my property damages

Signature

Witness's Name & Signature

Name

Prithpal Singh s/o bhasant
Singh - Hp: 90014221

Date _____

Company Stamp (if applicable) : _____

Email:

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **COMPLETE VMS PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,700.00** (Global Sum) for vehicle no. **SLB 4387E** that was damaged pursuant to the accident which occurred on **05/01/2019** (date) along **BLK 109 MCNAIR ROAD CARPARK LOT 302** involving vehicle no/s **GW 6456A**.

This is pursuant to the inspection conducted on **08/01/2019** (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner **PRITHIPAL SINGH S/O BHASANT SINGH** ("the third party claimant") of vehicle no. **SLB 4387E** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLB 4387E** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 (day) of July (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

This indemnity is signed without prejudice
to my rights to claim for compensation
for my personal injury.

COMPLETE VMS PTE LTD

176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare Complex, 5575721
Tel: 6455 0012 Fax: 6554 0012 Email: main@completevms.com.sg
Business Reg. No. 200416180E GST Reg. No.: 200416180E



AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16 CHARTIS BUILDING
SINGAPORE 079120

Tax Invoice : VM014574

Invoice Date : 29/07/2019
Vehicle Num. : SLB4387E
Make/Model : HYUNDAI TL TUCSON 2.0
Mileage(Km) :
PO/NO/RO# :
Ref./Remark : CC4/AIG19000433/Kdb3

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|-----------------------------|------------|------------|
| | | COST OF REPAIR AS AGREED AT | | 7,394.16 |

SingDollars : Seven Thousand Nine Hundred Eleven & Cents Seventy-Five Only

A handwritten signature in black ink, appearing to be 'L' followed by a flourish.

COMPLETE VMS PTE LTD

| | |
|------------------|----------|
| Total S\$: | 7,394.16 |
| GST S\$: | 517.59 |
| Amount Due S\$: | 7,911.75 |
| | ===== |
| Terms : | Cash |

www.completevms.com.sg

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 07 Jan 2019 / 11:50:19

Receipt Date/Time : 07 Jan 2019 / 11:50:19

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190107-001311

Previous Receipt No. :

| S/N | Item Description/ Business Transaction Reference No. | Amount Before GST (\$\$) | GST Amount (\$\$) | Amount After GST (\$\$) |
|--|--|---------------------------------|-------------------------|-------------------------------|
| Result of Insurance Enquiry - GW6456A | | | | |
| As at 05 Jan 2019/00:00:01 | | | | |
| Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD. | | | | |
| 1 | Insurance Enquiry - GW6456A Enquiry Fee 20190107114907220139 | 7.00 | 0.49 | 7.49 |
| Sub-Total | | 7.00 | 0.49 | 7.49 |
| Total Before Rounding | | 7.00 | 0.49 | 7.49 |
| Rounding Difference | | | | 0.04 |
| Total Amount Payable | | | | 7.45 |
| Paid By | | | | |
| | xxxxxxxxxxxx5909 | Credit Card: Visa/MasterCard | | 7.45 |
| Total | | | | 7.45 |
| Cash Change | | | | 0.00 |
| Tendered Amount | | | | 7.45 |
| Excess Refundable Amount | | | | 0.00 |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-007322

Date of Request: 14/01/2019

Your Ref No: WALK IN CHIU KM

COMPLETE VMS PTE LTD
176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX
SINGAPORE 575721

Dear Sir/Madam,

Date of Accident: 05/01/2019

Vehicle No: SLB4387E

Place of Accident: BLK 109 MCNAIR ROAD CARPARK LOT 302

Involving Vehicle No: GW8456A

With reference to your application for the accident report, we have attached the following accident reports as requested:

| DOCUMENTS | ACCIDENT LOCATION | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|-------------------------------------|---------------|-----|--------------|
| GW8456A | BLK 109 MCNAIR ROAD CARPARK LOT 302 | 14.00 | 1 | 13.08 |
| GST Amount | | | | 0.92 |
| Total Amount Due (GST Inclusive) | | | | 14.00 |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-19-004109
Date of Request: 08/01/2019

Your Ref No: WALK IN CHIU KM

COMPLETE VMS PTE LTD
176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX
SINGAPORE 575721

Dear Sir/Madam,

Your Vehicle No: SLB4387E
Date of Accident: 05/01/2019
Place of Accident: MCNAIR RD C/P BLK 109
Involving Vehicle No: GW6456A (NO REPORT) VALID TILL 9-17/1

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| E-File Search Fee (Public) | 14.02 |
| GST Amount | 0.98 |
| Total Amount Due (GST Inclusive) | 15.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

8/4

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING











| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|--|--|------------|---|
| Main | 08 Jan 2019 Edit Reg | | 07 Jan 2019 00:00 Edit Adj Rpt | \$57,394.16 Edit Estimates | \$57,394.16 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | KST Auto Rental Pte Ltd , Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | PRITHIPAL SINGH S/O BHASANT SINGH , ID: S1433729F | | | | | | | | |
| Vehicle Reg. No.: | SLB4387E | Date of Loss: | 05/01/2019 10:00 - :59 [32 Months and 28 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 0136529488SG | Policy/Cover Note No.: | 0999994609 (Third Party Only) | | | | | | |
| Vehicle Reg. No. (Insured): | GW6456A | Policy No. (Claimant): | M496594 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com | | | | | | | | |
| Claimant's Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/01/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG_EXPRESS (26/07/2019): Alert - Adj Mandate Approved (\$58748.20) - SLB4387E - Claim Handler: Lee, Ming-Y... AIG_SG (09/01/2019): NO OI GIA REPORT | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLB4387E (0136529488SG)
[GW6456A]
TP
PRITHIPAL SINGH S/O BHASANT SINGH
Jan 5 2019 10:00AM
[KST Auto Rental Pte Ltd]
COMPLETE VMS PTE LTD

| | | | | |
|---|-----------------|--|---|-----------|
| Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio | | | View View in Browser | |
| Letters/Correspondences | | | 1 per page <input type="checkbox"/> | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | (Draft) | Third Party Express Settlement - Payment Breakdown | | Edit |
| Assessment Reports | | | 1 per page <input type="checkbox"/> | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 01/02/19 13:59 | Accident Statement <small>From: SC - Reg. No: GW6456A, Claimant: KST AUTO RENTAL PTE LTD</small> | | Load HTML |
| Photos/Images | | | 3 per page <input type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 23/07/19 10:32 | General View | | Load JPG |
| 2 | 23/07/19 10:32 | General View | | Load JPG |
| 3 | 23/07/19 10:32 | General View | | Load JPG |
| 4 | 23/07/19 10:32 | General View | | Load JPG |
| 5 | 23/07/19 10:32 | General View | | Load JPG |
| 6 | 23/07/19 10:32 | General View | | Load JPG |
| 7 | 23/07/19 10:32 | General View | | Load JPG |
| 8 | 23/07/19 10:32 | General View | | Load JPG |
| 9 | 23/07/19 10:32 | General View | | Load JPG |
| 10 | 23/07/19 10:32 | General View | | Load JPG |
| 11 | 23/07/19 10:32 | General View | | Load JPG |
| 12 | 23/07/19 10:32 | General View | | Load JPG |
| 13 | 23/07/19 10:32 | Odometer Reading | | Load JPG |
| 14 | 23/07/19 10:32 | Chassis Number | | Load JPG |
| 15 | 23/07/19 10:32 | General View | | Load JPG |
| 16 | 23/07/19 10:32 | General View | | Load JPG |
| 17 | 23/07/19 10:32 | General View | | Load JPG |
| 18 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 19 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 20 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 21 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 22 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 23 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 24 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 25 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 26 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| 27 | 23/07/19 10:37 | Reinspection Photo | | Load JPG |
| Documentation | | | 1 per page <input type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 08/01/19 15:05 | EMAIL FROM AIG DD 07012019 |  Load PDF | |
| 2 | 08/01/19 15:05 | WKSP NOTICE |  Load PDF | |
| 3 | 09/01/19 18:36 | TP GIA REPORT |  Load PDF | |
| 4 | 10/05/19 12:04 | EMAIL TO OI |  Load PDF | |
| 5 | 22/07/19 11:56 | GIA SEARCH |  Load PDF | |
| 6 | 22/07/19 11:56 | LTA SEARCH |  Load PDF | |
| 7 | 23/07/19 10:29 | TP ESTIMATE - MARKED |  Load PDF | |
| 8 | 08/08/19 10:50 | WORKSHOP INVOICE |  Load PDF | |
| 9 | 08/08/19 10:50 | AUTHORISATION TO ACT FORM |  Load PDF | |
| 10 | 08/08/19 10:50 | Release Voucher |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|--------------------|--------|------------------------|
| Vehicle No: | GW5456A (Insd veh) | Model: | HYUNDAI TUCSON 2.0 (A) |
| | SLB4387E (TP veh) | | |
| Date of Accident: | 05/01/2019 | | |

| | | | | | |
|-----------------------------------|---|---|-----|------------------------------|-------------------------------|
| Global Sum Settlement | : | <input checked="" type="checkbox"/> [X] | Yes | <input type="checkbox"/> [] | No |
| Repair Estimate | : | \$ | | | 12,267.73 |
| Final Repair Cost | : | \$ | | | 8,700.00 |
| Loss of Use | : | \$ | | | 8.00 days at \$100.00 per day |
| Rental (if any) | : | \$ | | | days |
| LTA / GIA Search Fee | : | \$ | | | |
| Others: | : | \$ | | | |
| | : | \$ | | | |
| Final Settlement Sum (Global Sum) | : | \$ | | | 8,700.00 |

Is Third Party Workshop GIA Registered? ☐ [] **YES** ☒ [X] **NO** (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|----------------------|------|----------|
| 1) | COMPLETE VMS PTE LTD | : \$ | 8,700.00 |
| 2) | | : \$ | |
| 3) | | : \$ | |
| 4) | | : \$ | |

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 Aug
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19000433/KHB3Q2

Date: 08/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994609

Claimant Vehicle No : SLB4387E

Insured Vehicle No : GW6456A

Date of Loss: 05/01/2019

Nature of Claim:

TP

Claim No: 0136529488SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB4387E

Make & Model: HYUNDAI TUCSON, 2.0 (A)

Engine No: G4NAGU175244

Reg. Date: 08/04/2016 (Man. Year: 2016)

Chassis No: KMHJ3813MHU205503

Colour: Metallic Light Brown

Odometer: 25629 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Kumho 7 mm

Rear Left Side: Kumho 7 mm

Front Right Side: Kumho 7 mm

Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre tread's depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 8,925.17 | 5,904.16 | 3,021.01 | 33.85 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,540.00 | 1,490.00 | 1,050.00 | 41.34 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 11,465.17 | 7,394.16 | 4,071.01 | 35.51 |
| + GST 7.00/7.00% (S\$) | 802.56 | 517.59 | 284.97 | 35.51 |
| Nett Amount (S\$) | 12,267.73 | 7,911.75 | 4,355.98 | 35.51 |
| + Loss of Use (8.0 x S\$100.00/day) (S\$) | | 800.00 | | |
| + Doc/Search Fee (S\$) | | 36.45 | | |
| Nett Liability (S\$) | | 8,748.20 | | |
| Global Sum Settlement (S\$) | | 8,700.00 | | |

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 08/01/2019 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER TOP | Repair | 589.50 FL | *- FL |
| 2 | 8 | | *FRONT BUMPER CLIP | Not Necessary | 40.00 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER SIDE RETAINER | Serviceable | 32.00 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER LOWER GARNISH | Serviceable | 381.00 FL | *- FL |
| 5 | 1 | | *FRONT HEADLAMP R/H | Cut | 2,677.90 FL | *2,677.00 FL |
| 6 | 1 | | *FRONT HEADLAMP BRACKET R/H | Repair | 54.00 FL | *- FL |
| 7 | 1 | | *FRONT FENDER R/H | Bent | 584.80 FL | *584.80 FL |
| 8 | 1 | | *FRONT FENDER OUTER GARNISH R/H | Scratched | 155.90 FL | *155.90 FL |
| 9 | 1 | | *FRONT FENDER INNER SHIELD | Serviceable | 130.60 FL | *- FL |
| 10 | 1 | | *FRONT SIDE MIRROR ASSY | Cracked | 1,132.20 FL | *1,031.20 FL |
| 11 | 1 | | *FRONT DOOR R/H | Bent | 1,361.10 FL | *1,361.10 FL |
| 12 | 2 | | *FRONT DOOR STICKER R/H | Necessary | 73.20 FL | *73.20 FL |
| 13 | 1 | | *FRONT DOOR OUTER CHROME HANDLE R/H | Cracked | 324.30 FL | *324.30 FL |
| 14 | 1 | | *FRONT DOOR OUTER CHROME HANDLE INNER R/H | Missing | 67.90 FL | *67.90 FL |
| 15 | 1 | | *FRONT DOOR INNER LOCK R/H | Dented | 261.80 FL | *261.80 FL |
| 16 | 1 | | *FRONT DOOR KEY LOCK R/H | Bent | 452.00 FL | *315.00 FL |
| 17 | 1 | | *FRONT DOOR HANDLE SENSOR | Serviceable | 382.00 FL | *- FL |
| 18 | 1 | | *FRONT DOOR OUTER HANDLE GASKET R/H | Necessary | 25.00 FL | *25.00 FL |
| 19 | 1 | | *REAR DOOR R/H | Repair | 1,208.00 FL | *- FL |
| 20 | 2 | | *REAR DOOR STICKER R/H | Not Necessary | 64.00 FL | *- FL |
| 21 | 1 | | *FRONT DOOR PROTECTOR R/H | Mtg Cracked | 178.00 FL | *178.00 FL |
| 22 | 1 | | *FRONT DOOR INNER HANDLE R/H | Distorted | 325.00 FL | *325.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 10,500.20 | 7,380.20 |
| - List Item Discount on L Items 15.00/20.00% (\$\$) | 1,575.03 | 1,476.04 |
| Total Parts (\$\$) | 8,925.17 | 5,904.16 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | TRANSFER R/H FRONT DOOR COMPONENTS TO NEW DOOR | New | 150.00 | 60.00 |
| 2 | RUST PROOFING TREATMENT | New | 100.00 | 60.00 |
| 3 | CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION | New | 90.00 | 20.00 |
| 4 | TRANSFER R/H REAR DOOR COMPONENTS TO NEW DOOR | New | 150.00 | 0.00 |
| 5 | SPRAY PAINT DAMAGED AREA AFFECTED | New | 1,100.00 | 800.00 |
| 6 | TO CHANGE HEADLAMP ,FRONT BUMPER ,R/H FRONT DOOR ,DOOR MIRROR AND REAR DOOR | New | 950.00 | 550.00 |
| Gross Labour Cost (\$\$) | | | 2,540.00 | 1,490.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >