



Our Ref :T 0119 / SH 9647H /JW(st)	_		
Your ref: Date : 30-Jan-19	CDGE Taxi Claims Dept	ComfortDelGro E	ingineering Pte Ltd d Singapore 579701
Bate : Os dan 10	59 Loyang Drive 4th Flr		nline +65 6383 6280
EQ Insurance Company Limited	Singapore 508969		milie +65 6280 9755
5 Maxwell Road, MND Complex			www.cdge.com.sg
#17-00 Tower Block		Company R	egistration No: 199506048W
			Workshops
Singapore 069110	THOUT DDF HIDICE		Braddell 205 Braddell Road
Attn: Motor Claims Department WI Dear Sir	THOUT PREJUDICE		Singapore 579701
ACCIDENT INVOLVING OUR TAXI SH 9647H	YOUR INSURED GU	3439E	59 Loyang Drive Singapore 508969
AND OTHER	ON <u>04.01.19</u>		Sin Ming 383 Sin Ming Drive Singapore 575717
We are the authorised repair workshop for Comfort	Transportation Pte Ltd, the	e owner of motor	Pandan
Vehicle No: SH 9647H which was involved in the	captioned accident with yo	our insured	45 Pandan Koad
vehicle. The vehicle owner and the taxi driver conce	erned have requested and	authorized us to	Ubi
assist them in presenting their claims against the pa arising from the damage to the vehicle.	arty responsible for all appl	icable matters	320 Ubi Road 3 Singapore 408649
As the accident was caused by the negligent act o	f your insured driving GL	3439E	Senoko 24 Senoko Loop Singapore 758156
we are submitting these claims for your consideration	on on behalf of the claimar	nts.	Sungei Kadul
TAXI OWNER'S CLAIM			7 Sungei Kadut Way Singapore 728791
1 Cost of Repair	\$	835.67	Yishun
2 4 days Loss of Rental @ \$ 125.19	per day\$_	500.76 _{501 Yis}	hun Industrial Park A
3 Survey Report Fees (Surveyed by M/s LKK)	\$ \$ \$		Singapore 768732
4 LTA Search Fees	\$	7.49	
5 GIA / Police Report Fees	\$		
6 Towing / Medical / Transporation Fees		-	
	Sub Total : \$	1,343.92	
HIRER'S CLAIM 7 4 days Loss of Income @ \$ 80.00	0 perday\$_	320.00	
74days Loss of Income @\$60.00	Total Claims: \$	1,663.92	
	Total Glamo.	1,000.00	
We enclose herewith the following documents to su	ipport the claims: -		
a) Original repair bill and photocopies of photogra	aphs:	7 pcs.	
b) LTA search slip/s of : GU 3439E			
c) GIA / Police report/s of : SH 9647H	1		
d) Letter of authority from owner / hirer / operator			
() Witness statement/s () Towing/Medical bill/	receipts () Certificate of In	surance	
(X) Photograph/s of Accident Scene (x) Downtin	me/Mileage record (x) Rental Rate lette	er
Kindly look into the matter and let us hear from you		aid claims as	
soon as possible.		(p) (1)	
Please note that it is a condition of any settlement r	reached that it shall be with	nout prejudice	

Yours faithfully Jim Wong

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

to any personal injury claim (if any) of the taxi driver.

This is a computer generated letter. No signature is required.









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SH9647H , GU3439E

ON 04-Jan-19 09:45

ALONG

T JUNCTION OF QUEEN ST AND MANILA ST

I / We

CHIO ENG JONG

(Hirer) NRIC No.: S0686440F

and/or

(Relief) NRIC No .:

Taxi Number

SH9647H

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

04-Jan-2019

Name of Hirer

CHIO ENG JONG

Hirer NRIC

S0686440F

Signature:

Ch

Address

64 MARINE DRIVE #11-136

440064

Contact No.

98786588



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page:

200.00

20.00

420.00

8010325 INV. NO/DATE 91422945 28.01.2019 VEHCLE NO SH 9647H EQ INSURANCE COMPANY LIMITED JOB NO. 305256729 MAKE 5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110 HYUNDAI ODOMETER READING MODEL IONIQ(G2) CONTACT NO: 62239433 DATE/TIME IN 04.01.2019 11:15 DATE OF REG 08.11.2018 CHASSIS CODE KMHC851CVKU115143 Description: 3P 04.01.2019 Oty Unit Price %Disc Net S/No Part No. PART REQUISITION 1 451.25 20.00 361.00 0001 04-01-0104-2533 IONIQV2 MOULDING ASSY-RR 361.00 SUB-TOTAL JOB NATURE 200.00 200.00 PANEL BEATING 0001 L

SPRAYPAINT ON AFFECTED AREA

REMOVE/REFIX REVERSE SENSOR

ComfortDelGro Engineering Pte Ltd A member of COMFORIDELGRO

23-502

0002

0003 L

Head Office:

205 Braddell Road Singapore 579701

BANK/CHQ No. **AMOUNT** ACCOUNT No. INVOICE No. 91422945 835.67 8010325

200.00

20.00

SUB-TOTAL

Kindly note that no receipt shall be issued unless requested.



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

8010325

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

VEHCLE NO SH 9647H

INV. NO/DATE 91422945 28.01.2019

MAKE HYUNDAI JOB NO. 305256729

MODEL IONIQ(G2) ODOMETER READING

DATE OF REG 08.11.2018

DATE/TIME IN 04.01.2019 11:15

CHASSIS CODE KMHC851CVKU115143

Items total

781.00

Add GST @

7.000 %

54.67

Invoice amount

835.67

Issued by : CHEWBEELENG 28.01.2019 16:01:34 Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 91422945 835.67 8010325

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19010081

Date: 28 January 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

04/01/2019 @ 09:45 hrs

ALONG

T JUNCTION OF QUEEN ST AND MANILA ST

INVOLVING

GU3439E

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SH9647H (the "Taxi"). The Taxi was hired to CHIO ENG JONG IC NO S0686440F a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.

Incident Date/Time

Search Status

Insurance Company Code

Insurance Company Name

GU3439E

04 Jan 2019 / 09:45:00

Successful

E04

EQ INSURANCE COMPANY LTD

Previous

OK

SH9647H

















