

22/03/2003

ASS. REC. BY:

REF:

CS/CT19000486/Jqd307

Special Instruction:

Surveyor:

Hwee Jee

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

9/1/19 @ 10:32am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 8927H

Insured:

GBE 277T

at Workshop m/s

World Auto

Tel:

63621776

of

No. 1 Kunji Group

Policy No:

DMCVSN 30546818000

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:39am 9/1/19

Person Contacted:

Ainee

Vehicle:

~~IN~~ / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLN 8927H - CC3 / 10R17012740 / M / 29392 DOA: 2/6/17

GBE 277T - X

Surveyor Hwee Jie

REF: CTI

ASSIGNMENT

From: _____ Date: 09/01/19

Estimated Cost: _____

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SIN 8927H

at Workshop n/s

of

Insured

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. SIN 8927H Yr Regn: 22 May 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C/C 1797

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 132310 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/N: JTDKB3FU903SS8880

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/1/19 D.O.I. 9/1/19

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S ☒ N/S ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/1/19	Confirmed L/S \$4,400/- with 5 days repair. (Used \$6432.75, 89%)

RECEIVED 18 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report

11/8/19 ^{Final}

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 220

Transportation: _____

Add Fee: ☐ Site Insp (\$)

) \$ + RS. \$

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

Report Format: WER-TP

Lump Sum / I.B.T. (\$) 4400

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019		09 Jan 2019 11:02 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	SEAH KOK HWEI		
Vehicle Reg. No.:	SLN8927H	Date of Loss:	02/01/2019 07:00 - :59
Claim Type:	TP / GBE277T	Policy/Cover Note No.:	DMCVSN30546818000
Vehicle Reg. No. (Insured):	GBE277T	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	World Auto (HQ) NO. 1 KRANJI LOOP, 739535 Kranji - Tel: 97422188		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/01/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 9 January 2019 10:32 AM
To: assignments
Cc: ainee31@worldauto.com.sg
Subject: FW: Request for Third Party Motor Claim Survey (SLN8927H) DOA: 02-01-2019
Attachments: SLN8927H 02012019 TP.PDF; SLN8927H 02012019 TP.pdf

Dear Sir/Mdm (LKK),

Please get your surveyor to liaise with Ainee from World Auto by today to conduct a PRS.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: Tuesday, 8 January, 2019 4:31 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: worldautopl@yahoo.com.sg; 'Kana' <kana@worldauto.com.sg>; worldautopl@yahoo.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLN8927H) DOA: 02-01-2019

Dear Irene

Here is GIA report & repairs estimate

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Tuesday, January 8, 2019 2:59 PM
To: 'Irene Tay' <irene.tay@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>; 'Kana' <kana@worldauto.com.sg>;
'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>
Subject: FW: Request for Third Party Motor Claim Survey (SLN8927H) DOA: 02-01-2019

Dear Irene

As spoken at phone please arranging LKK surveyor our vehicle

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Tuesday, January 8, 2019 12:00 PM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'lucas.lee@sg.cntaiping.com' <lucas.lee@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>
Subject: RE: Request for Third Party Motor Claim Survey (SLN8927H) DOA: 02-01-2019

Dear All,

Any updates for this??

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Wednesday, January 2, 2019 11:44 AM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>

Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>

Subject: Request for Third Party Motor Claim Survey (SLN8927H) DOA: 02-01-2019

Good afternoon,

We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLN8927H

Your Insured: GBE277T

DOA: 02-01-2019

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 63631250

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Chinai Taiiping

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 10:30
Date Of Accident	02/01/2019 07:50
Exact Location Of Accident	AYER RAJAH COMMUNITY CLUB
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN8927H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995087
Cover Note Number	

Driver

Name of Driver	SEAH KOK HWEI
NRIC No	S8520216B
Date Of Birth	26/06/1985
Occupation	OUTDOOR
Date Of Driving Pass	01/02/2007
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90065717
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH (REMARKS : TP REVERSING COLLIDED WITH OUR CAR)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE277T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/orsaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


Sketch Plan



A. SUN8907H
B. GBE 277T

On 2/1/19, 7:55am I was travelling straight towards Ager Rajah community club
Out of sudden, a white GBE333T release without signalling and hit on my left side car

INA declare the foregoing particulars are true in every respect.





Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan #3



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING

Estimate : ES000139

Date : 02/01/2019

Vehicle Num. : SLN 8927H (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 02/01/2019

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT DOOR - LH DD	1200	1,450.00 /
2.	1	FRONT DOOR GLASS REGULATOR MOTOR RH NN		450.00 X
3.	1	FRONT DOOR HINGE LH LOWER NN		120.00 x
4.	1	FRONT DOOR HINGE LH LOWER (repair item)		120.00 x
5.	1	FRONT DOOR CHECKER LH NN		180.00 x
6.	1	FRONT DOOR LOCK ASSY - LH NN		750.00 x
7.	1	SIDE MIRROR COVER - LH SCA	140	488.00 /
8.	1	FRONT FENDER LH BUC		850.00 /
9.	1	FRONT FENDER HYBRID EMBLEM LH NEL	50	89.00 /
10.	1	FRONT FENDER UNDER DUST COVER LH BUC		250.00 /
11.	1	FRONT DOOR LOCK ASSY - LH NN		180.00 X
12.	1	FRONT DOOR OUTER HANDLE LH SCA	70	440.00 /
13.	1	FRONT DOOR LOCK ASSY - LH (repair item)		580.00 x
14.	1	REAR DOOR - LH DD	1200	1,450.00 /
15.	1	REAR DOOR HINGE LH LOWER NN		120.00 X
16.	1	REAR DOOR HINGE LH UPPER NN		120.00 x
17.	1	REAR DOOR CHECKER LH NN		180.00 x
18.	1	REAR FENDER LH Repair		150.00 X
19.	1	SIDE SKIRT LH NN		550.00 X
20.	1	REAR DOOR OUTER HANDLE LH NN		110.00 x
21.	1	REAR DOOR GLASS REGULATOR MOTOR LH NN		450.00 X
22.	1	SIDE MIRROR ASSY LH CPA		750.00 /
23.	1	REAR DOOR SUB RUBBER SEAL LH CUT		180.00 /

List TotalS\$:

9,377.00

25.00% Discount S\$:

2,344.25

7,032.75

SPECIAL NETT ITEMS :				
1.	1	SIDE SKIRT CLIPS LH NN		40.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING

Estimate : ES000139

Date : 02/01/2019

Vehicle Num. : SLN 8927H (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 02/01/2019

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	FRONT FENDER UNDER DUST COVER CLIPS <i>NEC</i>		30 40.00 ✓
		Special Nett Total S\$:		80.00
		LABOUR :		
		TRANSFER DOOR MECHANISM (X2 DOORS)		100 360.00 ✓
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE BODY PARTS		700 1,400.00 ✓
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)		850 1,600.00 ✓
		TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACE PARTS		60 180.00 ✓
		TO REMOVE, REARRANGE ALL ELECTRICAL WIRING, CHECK LIGHTENINGS & RESET HEADLAMP FOCUSING		30 180.00 ✓
		Labour Total S\$:		3,720.00

E. & O.E.

Total S\$: 10,832.75

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
10/1/19
Huee Lee - LKK

9/1/19

L/S 5 days

Total - \$4,400

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2019		09 Jan 2019 11:02 Edit Adj Rpt	S\$4,400.00 Edit Estimates	S\$4,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: SEAH KOK HWEI									
Vehicle Reg. No.: SLN8927H		Date of Loss: 02/01/2019 07:00 - :59 [19 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / GBE277T		Policy/Cover Note No.: DMCVSN30546818000							
Vehicle Reg. No. (Insured): GBE277T		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: World Auto (HQ) NO. 1 KRANJI LOOP, 739535 Kranji - Tel: 97422188									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 18/01/2019]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN8927H (GBE277T)
[GBE277T]
TP
SEAH KOK HWEI
Jan 2 2019 7:00AM
[-]
World Auto

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
3	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
16	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
17	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
18	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
19	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
20	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
21	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
22	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
23	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
24	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
25	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
26	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
27	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
28	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
29	10/01/19 11:38	General View		Load JPG	<input checked="" type="checkbox"/>
30	15/01/19 17:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
31	15/01/19 17:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
32	15/01/19 17:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
33	15/01/19 17:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
34	15/01/19 17:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19000486/JQD3E2

Date: 21/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30546818000
Claimant Vehicle No :	SLN8927H	Insured Vehicle No :	GBE277T
Date of Loss:	02/01/2019	Nature of Claim:	TP
		Claim No:	GBE277T

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8927H	Engine No:	2ZRS048670
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903558880
Reg. Date:	22/05/2017 (Man. Year: 2017)	Odometer:	132310 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,112.75	3,547.50	3,565.25	50.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	1,940.00	1,780.00	47.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,832.75	5,487.50	5,345.25	49.34
Approved Total (Overridden) (\$\$)		4,400.00		
	10,832.75	4,400.00	6,432.75	59.38
+ GST 7.00/7.00% (\$\$)	758.29	308.00	450.29	59.38
Nett Amount (\$\$)	11,591.04	4,708.00	6,883.04	59.38

INSPECTION

Date of Assignment:	09/01/2019	Inspected At:	World Auto (HQ)
Date Inspected:	09/01/2019		NO. 1 KRANJI LOOP
			Singapore 739535
Estimated Period of Repair:	5.0 days		

Adjuster: ONG HWEE JIE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8927H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	1,450.00 FL	*1,200.00 FL
2	1		*FRONT DOOR GLASS REGULATOR MOTOR RH	Not Necessary	450.00 FL	*- FL
3	1		*FRONT DOOR HINGE LH LOWER	Not Necessary	120.00 FL	*- FL
4	1		*FRONT DOOR HINGE LH LOWER	Repeated	120.00 FL	*- FL
5	1		*FRONT DOOR CHECKER LH	Not Necessary	180.00 FL	*- FL
6	1		*FRONT DOOR LOCK ASSY - LH	Not Necessary	750.00 FL	*- FL
7	1		*SIDE MIRROR COVER - LH	Scratched	188.00 FL	*140.00 FL
8	1		*FRONT FENDER LH	Buckled	850.00 FL	*850.00 FL
9	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	89.00 FL	*50.00 FL
10	1		*FRONT FENDER UNDER DUST COVER LH	Buckled	250.00 FL	*250.00 FL
11	1		*FRONT DOOR LOCK ASSY - LH	Not Necessary	180.00 FL	*- FL
12	1		*FRONT DOOR OUTER HANDLE LH	Scratched	110.00 FL	*70.00 FL
13	1		*FRONT DOOR LOCK ASSY - LH	Repeated	580.00 FL	*- FL
14	1		*REAR DOOR - LH	Dented	1,450.00 FL	*1,200.00 FL
15	1		*REAR DOOR HINGE LH LOWER	Not Necessary	120.00 FL	*- FL
16	1		*REAR DOOR HINGE LH UPPER	Not Necessary	120.00 FL	*- FL
17	1		*REAR DOOR CHECKER LH	Not Necessary	180.00 FL	*- FL
18	1		*REAR FENDER LH	Repair	150.00 FL	*- FL
19	1		*SIDE SKIRT LH	Not Necessary	550.00 FL	*- FL
20	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	110.00 FL	*- FL
21	1		*REAR DOOR GLASS REGULATOR MOTOR LH	Not Necessary	450.00 FL	*- FL
22	1		*SIDE MIRROR ASSY LH	Cracked	750.00 FL	*750.00 FL
23	1		*REAR DOOR SUB RUBBER SEAL LH	Cut	180.00 FL	*180.00 FL
24	1		*SIDE SKIRT CLIPS LH	Not Necessary	40.00 FS	*- FS
25	1		*FRONT FENDER UNDER DUST COVER CLIPS	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,457.00	4,720.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,344.25	1,172.50
Total Parts (\$\$)	7,112.75	3,547.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR MECHANISM (X2 DOORS)	New	360.00	100.00
2	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER)	New	1,600.00	850.00
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACE PARTS	New	180.00	60.00
4	TO REMOVE & REARRANGE ALL ELECTRICAL WIRING, CHECK LIGHTENINGS & RESET HEADLAMP FOCUSING	New	180.00	30.00
5	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE BODY PARTS	New	1,400.00	900.00
Gross Labour Cost (S\$)			3,720.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >