

ASS. REC. BY:

REF

CS3/LeR19000523/Kcd302

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Chin lee Ying

 O_1^f

LCR

Date/Time

09/01/17 9:51 am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 642S

Insured:

SLH 4782R

at Workshop m/3

Convince Auto

Tel:

9342 7766

of

176 Sin Ming Drive # 04-04

Policy No:

0999994821

Claim No:

0962258917SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/01/2019

CA / REV / REP. / REV 24 HRS

1 up?

H.O.D. Endorsement:

Date/Time: _____

9/11/9 @ 10-06am

Person Contacted:

Melvin

Vehicle(IN)OUT

Date/Time

Action/Instruction	(X)	Estimate
1. Review the project schedule and identify critical path activities.		
2. Conduct a risk assessment for each activity.		
3. Develop contingency plans for high-risk activities.		
4. Communicate the results of the assessment to the project team.		
5. Implement the contingency plans as needed.		
6. Monitor the project progress and adjust the schedule as necessary.		
7. Report the final project status to the stakeholders.		

XD6428-X

SH4782R-X

ASS. REC. BY:

REF:

AG /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

XD 6425

Yr Regn:

09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Isuzu CXZ 50K

c.c 12068

Colour:

White / Blue

A/C: Insured / Std / NI / NA

Sp. Reading

518590

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

7A2CXZ50K67000043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

B.S

1000 X 20 X 16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

9.9

1010

mm

L/Bal.

7

mm

L/Bal.

9.9

1010

mm

D.O.A.

6/1/19

D.O.I.

9/1/19

Survey held at

Lor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/1

File pass to Car, no key to open door no estimate

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

-

Survey Fee:

180

Transportation:

S + RS. SI

Photos

Others

20

TOTAL

200

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

DAR

Lump Sum / I.B.I: (\$

- Pre-inspection - XD642S & SLH4782R (DOA: 06/01/2019)

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 9/1/2019 9:51:01 AM
Attachments:  642.pdf

Hi LKK,

Kindly assist to survey.

10:06am @ 9/1/19
vehicle not in
person @ Melvin

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: melvinchua@convinceauto.com.sg [mailto:melvinchua@convinceauto.com.sg]

Sent: Wednesday, January 09, 2019 9:37 AM

To: AIG SGP, Claims-Survey

Cc: daphne@convinceauto.com.sg

Subject: RE: Pre-inspection - XD642S & SLH4782R (DOA: 06/01/2019)

hi, good morning . the vehicle can be inspect anytime , but is at the customer site office. need to arrange to go there to do survey. The address is at LOR CHENCHARU. Near Sembawang Road. kindly contact me to do arrangement at hp 93427766.Melvin . I need to contact owner to open the gate.

From: Daphne Lee [mailto:daphne@convinceauto.com.sg]

Sent: Tuesday, January 08, 2019 4:12 PM

To: AIG SGP, Claims-Survey

Cc: melvinchua@convinceauto.com.sg

Subject: Pre-inspection - XD642S & SLH4782R (DOA: 06/01/2019)

Dear Sir,

Please arrange pre-inspection for the vehicle a.s.a.p.

Kindly contact Mr. Melvin Chua at 9342 7766 for any arrangement.

Thank you

Regards

Daphne Lee

Convince Auto Pte Ltd

176 Sin Ming Drive

#04-04 Sin Ming Autocare

Singapore 575721

Tel: 6556 1131 | Fax: 6553 0802

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4981K
Vehicle Details	
Vehicle No.:	XD642S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	ISUZU
Vehicle Model:	CXZ50K
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	6WA1400381
Chassis No.:	JALCXZ50K67000093
Maximum Power Output:	-
Open Market Value:	\$70,913.00
Original Registration Date:	14 Sep 2006
First Registration Date:	14 Sep 2006
Transfer Count:	2
Actual ARF Paid:	\$3,546.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$48,087.00
COE Rebate Amount:	\$36,906.00
Total Rebate Amount:	\$36,906.00

The information contained herein is correct as at 10 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/01/2019 16:12
Date Of Accident	06/01/2019 08:00
Exact Location Of Accident	UPPER THOMSON FLYOVER TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XD642S
Insured/Policyholder	
Name Of Registered Owner	TECK HENG LANDSCAPE AND CONSTRUCTION PTE LTD
Co Reg No	NA 201014981K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94263240
Alternative Phone No	OFFICE-94263240
Vehicle Particulars	
Manufacturer	ISUZU
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	SD18V08723/VCH/R00
Cover Note Number	
Driver	
Name of Driver	SAHABUDEEN MOHAMED ALI
Passport No/FIN	F8152224M
Date Of Birth	03/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2016
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94263240
Fax Number	
Contact Number	OFFICE-94263240
EEmail Address	NOEMAIL

Address	421 TAGORE INDUSTRIAL AVENUE #03-25 TAGORE 8 SINGAPORE
Postcode	787805
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH4782R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: XD642S B: SLH 4782R

On the 6 Dec 2018 Around 8 Am Morning,
I was task to deploy my Company vehicle
XD 642S at this location for tree pruning.
I just stop my vehicle and wanted to start
my job Sudden Suddenly a vehicle SLH 4782R
Hit into my vehicle at the rear as the
TMA was damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature




(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



For more information, please contact us here

+65 6276 7997

Wheel Stopper & Choke

(<http://www.trafficnetwork.com.sg/products/wheel-stopper-chock/>)

TRUCK MOUNTED ATTENUATOR (TMA)

Truck Mounted Attenuator (TMA), is an impact attenuator attached to vehicles that are prone to being struck by oncoming vehicles. TMAs are designed to absorb the energy of the colliding vehicle and even redirect the vehicle away from a hazard, roadway machinery and workers with the intention to reduce damage to the lowest possible. Work Zone regulations specify a minimum safety, or buffer, distance between the vehicle, with an attached TMA, and the work zone.

For more information, please contact us at 6276 7997 or sales@trafficnetwork.com.sg (<mailto:sales@trafficnetwork.com.sg>).

-

(01) Bent (02) Dented (03) Deformed (04) Cracked (05) Cor (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

(d) lot Concordant: 80%

5440 • J. Neurosci., September 24, 2008 • 28(39):5435–5444

VAN / LORRY (Rear)

Vehicle No:

$\times 10^6 425$

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

[illegible]

TMA

TM A lamp RH

BT ✓
BR ✓

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019 Edit Reg		09 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	TECK HENG LANDSCAPE AND CONSTRUCTION PTE LTD, Co. Reg. No.: 201014981K		
Vehicle Reg. No.:	XD642S	Date of Loss:	06/01/2019 08:00 - :59 [147 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0962258917SG	Policy/Cover Note No.:	0999994821 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH4782R	Policy No. (Claimant):	SD18V08723/VCH/R00
		Excess:	
Repairer:	Convince Auto Pte Ltd (HQ) 176 SIN MING DRIVE #04-04, SIN MING AUTOCARE, 575721 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/01/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD642S (0962258917SG)**

[SLH4782R]

TP

TECK HENG LANDSCAPE AND CONSTRUCTION PTE LTD

Jan 6 2019 8:00AM

[LCRF Pte Ltd]

Convince Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		View
Photos/Images															3 per page		▼	☑	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print			
1	11/01/19 15:33	General View												1	Load JPG	☑			
2	11/01/19 15:33	General View												1	Load JPG	☑			
3	11/01/19 15:33	General View												1	Load JPG	☑			
4	11/01/19 15:33	General View												1	Load JPG	☑			
5	11/01/19 15:33	General View												1	Load JPG	☑			
6	11/01/19 15:33	General View												1	Load JPG	☑			
7	11/01/19 15:33	General View												1	Load JPG	☑			
8	11/01/19 15:33	General View												1	Load JPG	☑			
9	11/01/19 15:33	General View												1	Load JPG	☑			
10	11/01/19 15:33	General View												1	Load JPG	☑			
11	11/01/19 15:33	General View												1	Load JPG	☑			
12	11/01/19 15:33	General View												1	Load JPG	☑			
13	11/01/19 15:33	General View												1	Load JPG	☑			
14	11/01/19 15:33	General View												1	Load JPG	☑			
15	11/01/19 15:33	General View												1	Load JPG	☑			
16	11/01/19 15:33	General View												1	Load JPG	☑			
17	11/01/19 15:33	General View												1	Load JPG	☑			
18	11/01/19 15:33	General View												1	Load JPG	☑			
19	11/01/19 15:33	General View												1	Load JPG	☑			
20	11/01/19 15:33	General View												1	Load JPG	☑			
21	11/01/19 15:33	General View												1	Load JPG	☑			
22	11/01/19 15:33	General View												1	Load JPG	☑			
23	11/01/19 15:33	General View												1	Load JPG	☑			
24	11/01/19 15:33	General View												1	Load JPG	☑			
25	11/01/19 15:33	General View												1	Load JPG	☑			
26	11/01/19 15:33	General View												1	Load JPG	☑			
27	11/01/19 15:33	General View												1	Load JPG	☑			
Documentation															1 per page		▼	☑	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print			
1	09/01/19 16:04	EMAIL FROM AIG DD 09.01.2019												1	Load PDF				
2	09/01/19 16:04	TP GIA REPORT												1	Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print			
1	10/01/19 14:38	OI GIA REPORT												1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR19000523/KCD3E2

Date: 17/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994821

Claimant Vehicle
No : XD642S

Insured Vehicle No : SLH4782R

Date of Loss: 06/01/2019

Nature of Claim:

TP

Claim No: 0962258917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD642S

Make & Model: ISUZU CXZ50K, 12.1 D (M)

Engine No: 6WA1400381

Reg. Date: 14/09/2006 (Man. Year: 2006)

Chassis No: JALCXZ50K67000093

Colour: White/Blue

Odometer: 516590 km

Engine Capacity: 12068 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 1000X20X16

Rear Tyre Size: 1000X20X16 (D/D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: West Lake 9/9/10/10 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: West Lake 9/9/10/10 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/01/2019

Date Inspected: 09/01/2019 Inspected At:

Convince Auto Pte Ltd (HQ)
176 SIN MING DRIVE #04-04, SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TMA	Bent	0.00 F	*- F
2	1		*TMA LAMP RH	Broken	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >