



Your Ref: 18.25542 PD-O

Date: 16th January 2019

Our Ref: CS3/ASM18003915/Eqbs2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKM 4252P
INSURED VEHICLE: SLK 7710M
ACCIDENT DATE: 26/02/2018**

We thank you for your instruction on 07/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKM 4252P from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of SKM 4252P from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicle SKM 4252P.
- d) Colour damaged vehicle photographs of SKM 4252P.

Pre-Repair Inspection Date : 28/02/2018 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|---------------------|
| Registration Number | : SKM 4252P |
| Make & Model | : Nissan Almera 1.5 |
| Year of Registration | : 2014 |
| Chassis Number | : MNTBBAN17Z0000542 |
| Engine Capacity | : 1498 cc |

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.