

ASS. REC. BY:

REF:

08/ASM19000528/Tlgd302

Initial Instruction.

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person)

Yvonne Ang

of

ASIA CAXA

Date/Time:

19/01/19

Estimated Cost:

Bill to:

OD/TP+WS/TP RES/OD RES/EVA/INV/MV/CS,

To Inspect Vehicle No:

SKR 5916A

Insured:

at Workshop m/s

Comfort Penden

Tel:

68676916

of

45 Penden Road

Policy No:

Claim No:

S9M0180S

Sum Insured:

Excess:

\$400.00

Make of Veh:

(Client's Record)

D.O.A.

31/12/2018

CA / REV

REP. / REV 24 HRS

10/01/19

H.O.D. Endorsement:

Date/Time:

30/1pm @ 9/1/19

Person Contacted:

C.K.

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Pending addendum to amend OD.
	SKR 5916A - CC3/CAI15067972/Rh 3XX Don 7/5/15
11/1/19 @ 3.51pm	revert to Yvonne Ang via Smart Claim (pending addendum 91A)
21/1/19 @ 2.03pm	Yvonne Ang informed C/A via Smart Claim (addendum 91A uploaded).
21/1/19 @ 2.49pm	informed Chae Wei C/A & C/S & C/A by email.
15/3/19 @ 1.53pm	2nd revert to Yvonne Ang via Smart Claim (supplementary).
27/3/19 @ 3.08pm	Yvonne Ang informed C/A @ 5.03p. 27 with supplementary before EXB

DATE

Tafm

REF: ASM(AXA)

ASSIGNMENT

From Date: 10/01/2019

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SKR 5916A
Comfort Delgro
45 punden Road

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured:


Excess: \$400.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$48K

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

8

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKR 5916A - Yr Regn: 2015 Feb.

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Fluence - C.C. 1461

Colour: Cream A/C: Insured / Std / NI / NA

Sp. Reading: 64814 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

UFIL ZLE DES 24577

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ SRim / STD A/Rim or

Tyre Size: F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I.

10/1/19

Survey held at

404 E Punden

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear, 4/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/2/19 @ 7:03pm confirmed with Mr Wong final Ag @ 5038.27, 8 days.
(Red @ 1361.82, 21%)
no lump sum

RECEIVED 20 MAR 2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation

G + RS, SI

Photos

Other

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format:

Smart Claim

Lump Sum / I.B.I. (\$

5038.27

TOTAL

200

28/3/2019

◀ Service Request Details

Claim

S9M0180S

Reference

None 

Loss Date

December 31, 2018

Request Date

January 9, 2019

Due Date

January 16, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKR5916A

Make

RENAULT

RATAN BHOSALE Pragati

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Wednesday, January 09, 2019 10:15 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: SKR5916A DOA @ 31/12/2018 OD CLAIMS
Attachments: AUDATEX ESTIMATION.pdf; GIA.PDF

Categories: Pragati

Dear Sir / Madam ,

With refer to attachment ,We would like to proceed own damaged claims for your insured vehicle no. SKR5916A

Please arrange survey as soon as possible .

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

Shiau Chan (LKKAUTO)

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Wednesday, 27 March 2019 7:03 PM
To: Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)
Subject: Re: GIA for SKR5916A
Attachments: DV.pdf; INVOICE REPAIR.pdf

Hi Shiau Chan ,

Ok ,Confirmed cost of repair @ \$5038.27(before less excess)8 day repair.

With refer to attach our invoice repair and DV for your action.

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 27 March 2019 5:48:21 PM
To: CDGE Pandan Private Cars Crash Repair Counter; Taufikh (LKKAUTO)
Subject: RE: GIA for SKR5916A

Dear Mr Wong,

WITHOUT PREJUDICE

Offer final fig \$5,038.27 before excess \$400.00 & GST and 8 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Saturday, 23 March 2019 8:32 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Re: GIA for SKR5916A

Dear All ,

With refer to attach for above mentioned vehicle for you advice and confirm cost of repair .



Re:RE: SUPPLEMENTARY LIST UPLOADED

Type

🔗 Question

Message

Please proceed with supplementary revise cost \$5038.27 before excess \$400

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

25/3/2019

Survey Details:

Date of loss	31-Dec-18
Date of appointment	9-Jan-19
Date of survey	10-Jan-19
Location of survey	COMFORTDELGRO - PANDAN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKR 5916A
Make and Model	RENAULT FLUENCE 1.5L DCI 110AT GEARBOX
Date of registration	23/2/2015
Excess	\$ 400.00
Market Value	\$ 48,000.00
Parf Rebate	\$ 41,670.00
Nett Loss	\$ 6,330.00

Repair details:

Initial Estimate	\$ 6,400.09	(ESTIMATE \$6,193.09 + SUPP \$207.00))
------------------	-------------	---

Proposed/Revised repair cost:

Parts	\$ 3,414.70
Check items (estimate)	\$ -
Labour	\$ 1,623.57
Total	\$ 5,038.27
Lump Sum(if applicable)	-

Number of days for repair	<u>8</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

31 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
KINDLY APPROVE ON SUPPLEMENTARY.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408953 TEL : (065) 62563561 FAX : (065) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

15/3/2019

Survey Details:

Date of loss	31-Dec-18
Date of appointment	9-Jan-19
Date of survey	10-Jan-19
Location of survey	COMFORTDELGRO - PANDAN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKR 5916A
Make and Model	RENAULT FLUENCE 1.5L DCI 110AT GEARBOX
Date of registration	23/2/2015
Excess	\$ 400.00
Market Value	\$ 48,000.00
Parf Rebate	\$ 41,670.00
Nett Loss	\$ 6,330.00

Repair details:

Initial Estimate	\$ 6,400.09	(ESTIMATE \$6,193.09 + SUPP \$207.00))
------------------	-------------	--

Proposed/Revised repair cost:

Parts	\$ 2,897.00
Check items (estimate)	\$ -
Labour	\$ 1,428.09
Total	\$ 4,325.09
Lump Sum(if applicable)	-

Number of days for repair	<u>8</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
KINDLY APPROVE ON SUPPLEMENTARY.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 21 January 2019 2:10 PM
To: 'CDGE Pandan Private Cars Crash Repair Counter'; SUR
Subject: RE: GIA for SKR5916A

Dear Chee Wei,

As instructed by our client, please proceed to repair the insured vehicle **SKR 5916A (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Monday, 21 January 2019 11:19 AM
To: SUR <sur@lkkauto.com>
Subject: GIA for SKR5916A

Hi Sir/Mdm ,

Kindly refer to attachment .

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919



AUTHORIZE

Type

❗ Question

Message

Please proceed to authorize repair

Reply



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

11/1/2019

Survey Details:

Date of loss	31-Dec-18
Date of appointment	9-Jan-19
Date of survey	10-Jan-19
Location of survey	COMFORTDELGRO - PANDAN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKR 5916A
Make and Model	RENAULT FLUENCE 1.5L DCI 110AT GEARBOX
Date of registration	23/2/2015
Excess	\$ 400.00
Market Value	\$ 48,000.00
Parf Rebate	\$ 41,670.00
Nett Loss	\$ 6,330.00

Repair details:

Initial Estimate	\$ 6,193.09
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,690.00
Check items (estimate)	\$ -
Labour	\$ 1,428.09
Total	\$ 4,118.09
Lump Sum(if applicable)	-

Number of days for repair	<u>8</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
PENDING FOR ADDENDUM GIA REPORT. WE HAVE NOT
AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7719J
Vehicle Details	
Vehicle No.:	SKR5916A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	FLUENCE 1.5L DCI 110 AT GEARBOX EURO 5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	K9KN837D173649
Chassis No.:	VF1LZLF0E52015791
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$18,190.00
Original Registration Date:	23 Feb 2015
First Registration Date:	23 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,002.00
COE Rebate Amount:	\$37,920.00
Total Rebate Amount:	\$41,670.00

The information contained herein is correct as at 11 Jan 2019

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Any Vehicle, 100% Deposit Refund For Unapproved Loan, Classic Credit - Suzuki

HIN LUNG AUTO
 Ho Bee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

30 years
 of car sale

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

4 vehicles

Fluence 1.5A dCi

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Fluence 1.5A dCi		Any	Any	2015	Any	Any	Any	Available
	Renault	Fluence Diesel 1.5A dCi	\$56,800	\$8,520 /yr	25-May-2015	1,461 cc	41,878 km	Sedan	Available
Fuel Type: Diesel (Euro 5 Engine and Above) New Arrival! Cheapest In Town! Genuine Price! 1st Owner! Management Car! Fully Maintained By Wearnes Since Day One! Genuine Low Mileage Of 13000km Clocked Annually! Car Is In Brand New Condition!... Posted: 05-Jan-2019 Tags: 2015 Renault Fluence, 2015 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault	Fluence Diesel 1.5A dCi	\$56,999	\$8,540 /yr	29-May-2015	1,461 cc	51,900 km	Sedan	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Cheapest In Town! 1 Owner! Fully Maintained By Wearnes Since Day One! Low Mileage 51k Km! Car Is In New Condition! Nice Dark Grey Color! Powerful And Responsive DCI Engine! Super Fuel Efficient! Avera... Posted: 01-Jan-2019 Tags: 2015 Renault Fluence, 2015 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault	Fluence Diesel 1.5A dCi	\$50,888	\$7,680 /yr	30-Apr-2015	1,461 cc	38,000 km	Sedan	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Agent Warranty Till April 2020. Pristine Condition. Whatsapp For More Details. Posted: 30-Nov-2018 Tags: 2015 Renault Fluence, 2015 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault	Fluence Diesel 1.5A dCi	\$53,800	\$7,970 /yr	17-Jun-2015	1,461 cc	85,000 km	Sedan	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Well Kept! Low Mileage. Fully Serviced By Wearnes Automotive. Bank Loans And In-house Financing Available. View Now! Posted: 17-Nov-2018 Tags: 2015 Renault Fluence, 2015 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & GPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Fluence 1.5A dCi, Fluence 1.5A dCi Singapore, used Fluence 1.5A dCi Singapore, used Fluence 1.5A dCi, used vehicles Singapore or even buy used Fluence 1.5A dCi Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S481900206 / GST Reg. No.: S480017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCO 719 000085 Vehicle Registration No: SKR 5916A
 Name (as shown in NRIC): Sammunda Virukanand NRIC/FIN/Passport No: S264 734 J
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: APT B1A 62B Tunj west street 64 #05-334 Singapore (64) 5611
 Contact (Tel): _____ Mobile No.: 92380941
 Email Address: Virukan @ gmail . com
 Date of Accident: 31/07/18 Time of Accident: 1150 am
 Place of Accident: 46 Tuen Road R J Singapore
 Insurance Company: AVA Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

from "No" change to "Yes" to claiming under own insurance
policy for repair to my vehicle with Recovery against Third party

S. Virukanand
 Policyholder / Driver's Signature
 Date: 10/01/2019

CONFIDENTIAL DOCUMENTS PTE LTD
 INTERNAL USE ONLY ON REPORT NUMBER
 NAME & SIGNATURE: [Signature]
 DESIGNATION: _____ DATE: 31/1/19

Reporting Centre Personnel's Signature
 Name: Chen Che King
 NRIC/FIN No.: G26011734
 Date: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 09:34
Date Of Accident	31/12/2018 11:50
Exact Location Of Accident	NEAR 46, TUAS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR5916A
Insured/Policyholder	
Name Of Registered Owner	SAMMANDA VIVEKANANDAN
NRIC No	S2647719J
Email Address	VIVEKNAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92380941
Alternative Phone No	OFFICE-92380941

Vehicle Particulars

Manufacturer	RENAULT
Model	FLUENCE-1.5 D DCI 110 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMUTING TO OFFICE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA310552/1
Cover Note Number	

Driver

Name of Driver	SAMMANDA VIVEKANANDAN
NRIC No	S2647719J
Date Of Birth	25/08/1953
Occupation	INDOOR
Date Of Driving Pass	02/06/1992
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92380941
Fax Number	
Contact Number	OFFICE-92380941
Email Address	VIVEKNAN@GMAIL.COM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 09:34
Date Of Accident	31/12/2018 11:50
Exact Location Of Accident	NEAR 46, TUAS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR5916A
Insured/Policyholder	
Name Of Registered Owner	SAMMANDA VIVEKANANDAN
NRIC No	S2647719J
Email Address	VIVEKNAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92380941
Alternative Phone No	OFFICE-92380941

Vehicle Particulars

Manufacturer	RENAULT
Model	FLUENCE-1.5 D DCI 110 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMUTING TO OFFICE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA310552/1
Cover Note Number	

Driver

Name of Driver	SAMMANDA VIVEKANANDAN
NRIC No	S2647719J
Date Of Birth	25/08/1953
Occupation	INDOOR
Date Of Driving Pass	02/06/1992
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92380941
Fax Number	
Contact Number	OFFICE-92380941
Email Address	VIVEKNAN@GMAIL.COM

Address BLK 662B JURONG WEST STREET 64 #05-324
 Postcode 642662
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: MS ELLEN TONG
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] NANYANG N.P.C
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: TO LARGE UNABLE TO UPLOAD OR SEND BY EMAIL
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GW7517B
 Vehicle Make/Model/Colour MITSUBISHI/FB511/WHITE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

1. The first part of the plan is to determine the scope of the project. This involves identifying the goals and objectives of the project, and determining the resources available to complete the project.

2. The second part of the plan is to develop a timeline for the project. This involves identifying the key milestones of the project, and determining the time required to complete each milestone.

3. The third part of the plan is to develop a budget for the project. This involves identifying the costs of the project, and determining the sources of funding for the project.

4. The fourth part of the plan is to develop a risk management plan. This involves identifying the risks associated with the project, and determining the strategies to mitigate these risks.

5. The fifth part of the plan is to develop a communication plan. This involves identifying the key stakeholders of the project, and determining the methods of communication with these stakeholders.

6. The sixth part of the plan is to develop a monitoring and evaluation plan. This involves identifying the key performance indicators of the project, and determining the methods of monitoring and evaluation.

7. The seventh part of the plan is to develop a closure plan. This involves identifying the tasks required to complete the project, and determining the resources required to complete these tasks.

8. The eighth part of the plan is to develop a post-project plan. This involves identifying the tasks required to evaluate the project, and determining the resources required to complete these tasks.


Handwritten signature: J. K. [illegible]

Signature: [illegible]
 Title: [illegible]
 Date: [illegible]
 in the [illegible]
 [illegible]

2. Stopped my car and tried not to check the damage to my car. I discovered a hole in the floor inside near the rear wheel and a scuffing of paint on the left door as well.

2. there would be the heavy losses & decrease about the accident and to share particularities. For the more numerous interviewed he did not see exchange particularities involved in them. Instead he told me about the accident and that he was not in the

Schematic Sketch



On 31 Dec 2018 at about 11.50 hrs, I was driving my car (SKR 5916A) along Tuas Road towards South and I was also accompanied by my colleague. I was driving behind a lorry (Plate Number GW 7517B), maintaining a safe distance. Near Applied Engineering Pte Ltd (46, Tuas Road, Singapore 638 499), I noticed that the lorry was slowing down suddenly, but the brake lights were not glowing though. To avoid collision, I turned the car slightly to the right side of the road. In the meanwhile, the lorry was also turning to the right without any indication, leading to the collision of the lorry to the left side of my car. I heard a big bang and the car was also moved, but neither I nor my colleague was injured.

I stopped my car and came out to check the damage. I discovered a large dent on the left side near the rear wheel and scrapping of paint on the left door as well.

I then went to the lorry driver to discuss about the accident. But he was neither interested to discuss nor to exchange personal particulars, contact number, insurance details etc. Instead, he told me to report the accident and that he will do so too.

I took pictures of the lorry and the damages to my car. There was an in-vehicle camera installed in my car at the time of the accident but I was not sure if it was working. Later I discovered that the accident was captured in the in-vehicle camera.

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20181231/2116

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No: T/20181231/2116

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/12/2018 17:17	Vide Report No.:	Station Diary No.: 107
--	------------------	---------------------------

Informant's Particulars

Name of Informant: SAMMANDA VIVEKANANDAN			Address: APT BLK 662B JURONG WEST STREET 64 #05-324 SINGAPORE 642662		
ID Type / ID No.: NRIC NO / S2647719J			Contact No.: Home/Office: Mobile: 92380941		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 25/08/1953	Type of Informant: Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: COMMERCIAL MANAGER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 31/12/2018 11:50	Type of Location: Straight Road
Location: Along Road 1 TUAS ROAD				
Outside Applied Engineering Pte Ltd				
Weather:	Road Surface:		Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control:		Traffic Volume: No Traffic	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GW7517B	Lorry	MITSUBISHI	FB511BOJS RDE	White	No Damage	1
SKR5916A	Car	RENAULT	FLUENCE 1.5L DCI 110 AT GEARBOX EURO 5	White	Slightly Damaged	2



**SINGAPORE
POLICE FORCE**



T/20181231/2116

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 3

Report No. T/20181231/2116

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKR5916A	AXA INSURANCE SINGAPORE PTE LTD	GA310552	23/02/2018	22/02/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SAMMANDA VIVEKANANDAN	ID No.	S2647719J
Related Vehicle	NIL	Contact No.	92380941
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 31/12/2018 at about 1150hrs, I was driving my car (plate no: SKR5916A) along Tuas Road outside Applied Engineering Pte Ltd with my colleague. I was driving behind a lorry (plate no: GW7517B). I noticed that the lorry was speeding, hence I maintained a safe distance between my car and the lorry. Subsequently, the lorry did a sudden break and to avoid the collision, I turned my car slightly to the right side of the road. However, at the same time the lorry did a sudden illegal right turn without indicating a signal and hit the left side of my car. I heard a bang sound and subsequently came out of the car to see the damage. I made a check on my vehicle and discovered that there is a dent on the left side near the back door and the paint near the dent was scraped off. I then went to talk to the lorry driver regarding the accident, however, he did not wish to talk about it and asked me to make a police report. He also refused to give his particulars when I asked for it. I would like to further state that this is the first time such an incident happened. There is an in-vehicle camera installed in my car but I am not sure if it is in working condition. I have also pictures of the lorry that hit my car and the damage on my car.



SINGAPORE
POLICE FORCE



T/20181231/2115

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 3

Report No. T/20181231/2116

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /
Sgt 2 NG JIA YI

Signature Of Informant:

S. Vorgerücktem

Signature Of Interpreter:
Not applicable

Date/Time:
31/12/2018 17:17

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP168

CN 127



Signature :

Singapore Police Force



1508 543 4533 (Within Singapore)
(65) 6860 4838 (International)
165) 8850 4740
customer.care@sona.com.sg
www.sona.com.sg

15233

© 1997 by John Wiley & Sons, Inc. All rights reserved. This publication is a registered trademark of John Wiley & Sons, Inc. All other trademarks are the property of their respective owners.

Policy details

Policyholder name	SAMARDA VIVEKANANDAS	Certificate number	GA110582 / 1
Company name	Comprehensive	Chassis number	VF112L F082015791
Vehicle make	Essential	Engine number	UGANG370173048
Vehicle registration number	50%		
Period of insurance	SKN5516A		
From to to date	from 22/02/2018 to 22/02/2019 (both dates inclusive)		
	Nil		

Persons or classes of persons entitled to drive*

- (d) The Policyholder.
- (e) Any Person Driver as stated in the Policy.
3. REMAINS IN SITUATION
- (a) Any person who is driving on the Policyholder's order or with their own consent.

I/We hereby certify that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf then during the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policeholder's business.

The Pontiac does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples of merchandise with any trade or business or use for any purpose in connection with motor trade; or what the Motor Car, whether stationary, is used or otherwise, is or is on, a racing track, circuit, route, course or any other roads be whatever name called that are typically used for racing, pace-making or such similar purposes.

[†] For further material, consult the Section 5 of the Motor Vehicle Theft (Theft) Act, Title 18, United States Code, and Section 101 of the Food Inspection Act, 21 USC 101, and 1 of the National Motor Vehicle Theft Act, 18 USC 101.

EXCESS	Basic Own Damage Excess	154,400.00
	Windscreen Excess	950.00

has Additional Excess is applicable as follows:

1. \$500 for undeclared Authorized Driver
2. \$500 for declared Young and Inexperienced Drivers
3. \$45,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$52,500 if you have chosen ACA Premium Reduction.

Additional clauses & endorsements to your policy

1010

I do hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risk and Compensation) Act, (Chapter 159) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

4

Received 11 November 2003; accepted 12 February 2004

Important note

Undergraduate students who are not full-time students at a college or university must complete the Declaration of Independence and the Pledge of Allegiance separately. If the student is a business, the form must be submitted as a Business Declaration to the school that he or she is attending. Please do not sign this declaration as an official under the State Seal of Office. Parts Two & and Commencement Act 1890.

The *Journal of American Studies* is a quarterly journal of American literature, culture, and history. It is published by Cambridge University Press. The journal is a leading international forum for the study of American literature, culture, and history. It is a required reading for students and scholars of American literature, culture, and history. The journal is a leading international forum for the study of American literature, culture, and history. It is a required reading for students and scholars of American literature, culture, and history.



redefining insurance

SAMMANDA VIVY SHANMUGAM
852B JURONG WEST STREET 64
#05-324
SINGAPORE 642662

AYA Insurance Pte Ltd
1800 800 4888 (Within Singapore)
(65) 6889 4888 (International)
(65) 6230 4748
sastaman@ayainsurance.com.sg
www.aya.com.sg

New business

Date
02/01/2018

Your servicing distributor
AMEX-ELLAHE RAMOS / 15232

Your servicing distributor contact
1800-800-4888

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	SAMMANDA VIVY SHANMUGAM	Policy number	VA1 / 0A310552
Cover	Comprehensive	PN / NINO	\$26477191
Period of Insurance	from 23/02/2018 to 22/02/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	\$60 1,128.58
Total Discounts	- SGD 60.17
7% GST	SGD 74.80
Final Premium	SGD 1,143.31

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for Twelve (12) Months
- Loss or Damage
- Legal Liability

Vehicle details

Make & Model of Vehicle	RENAULT FLUENCE 1.5 DCI	Year of manufacture	2015
Vehicle registration number	SK15916A	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1461
Seating capacity (incl driver)	4	Engine number	K9KN837D173049
Off-Peak car	No	Chassis number	VF1LZLF0E52015701

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	Nil

Excess applicable (refer to Policy Wording for other applicable & exempt)

Basic Own Damage Excess	SGD 400.00
Windscreen Excess	SGD 100.00

Drivers details

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Summary Information

Claim

Location: Singapore (SG)

Printed by: CDGE Pandan

Claim Reference:

Estimated Repair Time:

Actual Repair Days:

Work Provider:

Currency:

Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

2018-12-31

[Signature]
11/1/19

Vehicle Details

Vehicle

Manufacturer:

RENAULT

Model:

FLUENCE (L3)

Sub Model:

BASE MODEL

Model Sheet Number:

12 87 01

Registration:

SKR5916A

VIN number:

VF1LZLF0E52015791

Odometer:

Tan Kah 97495719
Not Authorised, Revant
Ex \$400
Part by part
Resurvey before paint.
sur@lkkauto.com.
10/1/19 @ 3pm.
Soleys.

Vehicle Condition

Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All

Underbody

☐☐

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
A0YH KA	R + R LEFT REAR DOOR INCLUDES: ADJUSTING DOOR LOCK		3.0	13.50
4493 KA)	RENEW LEFT REAR DOOR (REMOVED)		10.0	45.00
5059 KA	R + R L/R DOOR LOCK STRIKER		2.0	9.00
5377 VA	RENEW REAR BUMPER		1.0	4.50
NO NUMBER	R + R L/R BUMPER BRACKET		1.0	4.50
NO NUMBER	R + R R/R BUMPER BRACKET		1.0	4.50
A02Q KA	R + R REAR SCREEN		13.0	58.50
NO NUMBER	R + R ATTACHED PARTS OF THE L/R WING INCLUDES: R + R BUMPER, TAILLAMPS, REAR SEAT, SIDE AIRBAG, WHEEL AND ALL TRIMS IN THE REPAIR SECTION		27.0	121.50
4751 KA)	RENEW L/RR WING CPL		100.0	450.00
4907 KA	R + R BOOTLID		6.0	27.00
A0NH KA	R + R LEFT INNER TAILLAMP		2.0	9.00
6307 KA)	R + R LEFT FLOOR CARPET		3.0	13.50
7061 KA	R + R OR RENEW HEADLINING INCLUDES: R + R UPPER A-PILLAR TRIMS, UPPER CENTRE PILLAR TRIMS, ROOF CONSOLE AND ALL NECESSARY ATTACHED PARTS		10.0	45.00
3116 KA)	R + R RIGHT REAR WHEEL		1.0	4.50
3121 KA)	R + R LEFT REAR TYRE		1.0	4.50
3121 KA)	R + R RIGHT REAR TYRE		1.0	4.50
3113 VA)	L/R ROAD WHEEL BALANCE		1.0	4.50
3113 VA)	BALANCE R/R WHEEL		1.0	4.50
3577	L/R LAMP PANEL REPAIR		10.0*	45.00
4101	L/R INNER WING REPAIR		20.0*	90.00
4165	L/R INNER WHEELHOUSE REPAIR		10.0*	45.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		22.40	224.0	1,008.00
Total of Labour				1,008.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	L/R DOOR NEW PART PAINTING		14.0	
	L/R SIDE PANEL NEW PART PAINTING		27.0	
	L/R LAMP PANEL SURFACE PAINT		4.0	
	L/R INNER WING SURFACE PAINT		5.0	
	L/R INNER WHEELHOUSE SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
1781	L/R DOOR NEW PART PAINTING	31.03
3481	L/R SIDE PANEL NEW PART PAINTING	32.34
3577	L/R LAMP PANEL SURFACE PAINT	1.94
4101	L/R INNER WING SURFACE PAINT	6.34
4165	L/R INNER WHEELHOUSE SURFACE PAINT	6.34

Labour Cost - Paint

	Factor	45.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			55.0	
	Preparation Main Work Metal		1.70	17.0	76.50
Total		10 WU/h	7.20	72.0	324.00

Material Cost - Paint

	Price SGD
New Part Painting	63.37
Surface-/Blend Paint	14.62
Material-constant Metal	18.10
Total	96.09

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGD
1781	L/R DOOR	82 10 111 73R		Rx 1,550.00
2581	REAR BUMPER	85 02 295 39R		de 650.00
2603	L/R BUMPER BRACKET	85 04 200 27R		res 60.00
2604	R/R BUMPER BRACKET	79 18 200 09R		x 60.00
2650	RR BUMPER CLAMP KIT	60 03 836 33R		res 30.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Code	Description	Part Number	Supplier	Price SGD
3160	REAR SCREEN BOND KIT	77 11 785 626		0.00
3163	REAR SCREEN FIX SET	82 01 057 684		0.00
3164	REAR SCREEN SPACER	90 35 627 59R		0.00
3281	L/R OUTER LAMP	26 55 528 02R		150.00
3283	L/R INNER LAMP	26 55 500 41R		155.00
3481	L/R SIDE PANEL	78 10 174 09R		1,280.00
9551	L/R WHEEL	40 30 097 40R		550.00
9552	R/R WHEEL	40 30 097 40R		0.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 4,485.00
u: Used parts				Total 4,485.00

Extras

Code	Description	Price SGD
1000	BODY SEALANT BODY SEALANT	80.00*
1001	SEALANT SEALANT	40.00*
1002	BODY SEALANT BODY SEALANT	80.00*
1003	ANTI-RUST ANTI-RUST	80.00*
Total Extras		280.00

Rear LH tyre ant ✓ 80% 700

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Final Calculation

	SGD	SGD
Parts	4,485.00	
Total Parts		4,485.00
Labour Time Base 10 WU/h		
Total 224.0 WU X 45.00 SGD/h	1179 1,008.00	
Total of Labour		1,008.00
Total Of Extras		280.00
Paint Work Time Base 10 WU/h		
Labour Cost 72.0 WU X 45.00 SGD/h	791 324.00	
Material Cost	43.59 96.09	
Total Paint Including Material		420.09
Repair Cost Excludes GST		6,193.09
GST (+7.0%)		433.52
Repair Cost Included GST		6,626.61

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

6266.61

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel:68676919 Fax: 62626950

Spare PartsVehicle No. : **SKR5916A**Submit By : **WONG**Make & Model : **RENUALT FLUENCE 1.5L DCI 110**Year Manufacture : Chassis No. : **VF1LZLF0E52015791**Engine No. : **K9KNE****Supplementary****Cost / List**Steve
11/3/19

S/No.	Part Description	Qty	Unit Price	Cost Price
1	L/RAER FENDER UNDER LINER	1	del ✓	\$195.00
2	REVERT L/SIDE BRACKET REAR BUMPER	4	HL ✓	\$12.00
3		1		
4		1		
5		1		
6		1		
7		1		
8		1		
9		1		
10		1		
11		1		
12		1		
13		1		
14		1		
15		1		
16		1		
17		1		
18		1		
19		1		
20		1		
21		1		
22		1		
23		1		
24		1		
25		1		
26		1		
27		1		
28		1		
29		1		
30		1		

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916

Printed: 01/09/2019 9:58 AM

Summary Information

Claim

Location: Singapore (SG)

Printed by: CDGE Pandan

Claim Reference:

Estimated Repair Time:

Actual Repair Days:

Work Provider:

Currency:

Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

2018-12-31

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration:

VIN number:

Odometer:

RENAULT

FLUENCE (L3)

BASE MODEL

12 87 01

SKR5916A

VF1LZLF0E52015791

Tan Kah 97495749
Not insurance, revert
Ex \$400
Part by part
Resurvey before paint
sur@thekanto.com
10/1/19 @ 3pm

Vehicle Condition

Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Steve
11/3/19


Def. spray & spp

2 days

Damage Areas

All

Underbody

☐☐

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916A

Printed: 01/09/2019 9:58 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGI
	L/R DOOR NEW PART PAINTING		14.0	
	L/R SIDE PANEL NEW PART PAINTING		27.0	
	L/R LAMP PANEL SURFACE PAINT		4.0	
	L/R INNER WING SURFACE PAINT		5.0	
	L/R INNER WHEELHOUSE SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGI
1781	L/R DOOR NEW PART PAINTING	31.0
3481	L/R SIDE PANEL NEW PART PAINTING	32.3
3577	L/R LAMP PANEL SURFACE PAINT	1.9
4101	L/R INNER WING SURFACE PAINT	6.3
4165	L/R INNER WHEELHOUSE SURFACE PAINT	6.3

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGI
Time Paint			55.0	
Preparation Main Work Metal		1.70	17.0	76.50
Total	10 WU/h	7.20	72.0	324.00

Material Cost - Paint

	Price SGI
New Part Painting	63.3
Surface-/Blend Paint	14.6
Material-constant Metal	18.1
Total	96.0

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGI
1781	L/R DOOR	82 10 111 73R		Rx 1,550.00
2581	REAR BUMPER	85 02 295 39R		de 650.00
2603	L/R BUMPER BRACKET	85 04 200 27R		re 60.00
2604	R/R BUMPER BRACKET	79 18 200 09R		x 60.00
2650	RR BUMPER CLAMP KIT	60 03 836 33R		re 30.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1712

Date calculated: 01/09/2019 09:58 AM

Full Report

Registration: SKR5916

Printed: 01/09/2019 9:58 AM

Code	Description	Part Number	Supplier	Price SGI
3160	REAR SCREEN BOND KIT	77 11 785 626		0.00
3163	REAR SCREEN FIX SET	82 01 057 684		0.00
3164	REAR SCREEN SPACER	90 35 627 59R		0.00
3281	L/R OUTER LAMP	26 55 528 02R		150.00
3283	L/R INNER LAMP	26 55 500 41R		155.00
3481	L/R SIDE PANEL	78 10 174 09R		1,280.00
9551	L/R WHEEL	40 30 097 40R		550.00
9552	R/R WHEEL	40 30 097 40R		0.00

● OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings	0.00
Subtotal	4,485.00
Total	4,485.00

Extras

Code	Description	Price SGI
1000	BODY SEALANT BODY SEALANT	80.00
1001	SEALANT SEALANT	40.00
1002	BODY SEALANT BODY SEALANT	80.00
1003	ANTI-RUST ANTI-RUST	80.00
Total Extras		280.00

Rear LH tyre ant ✓ 80%

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1810

Date calculated: 03/23/2019 08:15 AM

Full Report

Registration: SKR5916A

Printed: 23/03/2019 8:17 AM

Summary Information

Claim

Location: Singapore (SG)

Printed by: CDGE Pandan

Claim Reference:

Estimated Repair Time:

Actual Repair Days:

Work Provider:

Currency:

Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

2018-12-31

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration:

VIN number:

Odometer:

RENAULT

FLUENCE (L3)

BASE MODEL

12 87 01

SKR5916A

VF1LZLF0E52015791

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD286B -**AAD1706-075**

To Check Electrical Lighting Concerned.

\$

170.00 *2cl***TOTAL \$ 21,980.00****Over All Total \$ 102,852.38**

< parts by parts > Repair Days

~~30~~ DAYS*8 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged parts during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Current Production" basis
- No illegal modification is allowed
- Supplementary items must be re-surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1810

Date calculated: 03/23/2019 08:15 AM

Full Report

Registration: SKR5916A

Printed: 23/03/2019 8:17 AM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
7133 KA	R + R LEFT REAR DOOR TRIM		2.0	9.00
5735 KA)	R + R LEFT REAR DOOR LOCK		5.0	22.50
3948 KA)	R + R LEFT REAR DOOR WINDOW GLASS		3.0	13.50
5736 KA)	R + R L/R WINDOW REGULATOR		2.0	9.00
NO NUMBER	R + R L/R FIXED DOOR WINDOW		1.0	4.50
A0CS KA	R + R L/R DOOR PROTECTIVE MLDG		2.0	9.00
5059 KA	R + R L/R DOOR LOCK STRIKER		2.0	9.00
A0H4 KA)	R + R L/R WINDOW FRAME MOULDING FRONT		1.0	4.50
5167 KA)	R + R LEFT REAR WINDOW GUIDE		1.0	4.50
5377 VA	RENEW REAR BUMPER		1.0	4.50
NO NUMBER	R + R L/R BUMPER BRACKET		1.0	4.50
A02Q KA	R + R REAR SCREEN		13.0	58.50
NO NUMBER	R + R ATTACHED PARTS OF THE L/R WING INCLUDES: R + R BUMPER, TAILLAMPS, REAR SEAT, SIDE AIRBAG, WHEEL AND ALL TRIMS IN THE REPAIR SECTION		27.0	121.50
4751 KA)	RENEW L/RR WING CPL		100.0	450.00
4907 KA	R + R BOOTLID		6.0	27.00
6307 KA)	R + R LEFT FLOOR CARPET		3.0	13.50
7061 KA	R + R OR RENEW HEADLINING INCLUDES: R + R UPPER A-PILLAR TRIMS, UPPER CENTRE PILLAR TRIMS, ROOF CONSOLE AND ALL NECESSARY ATTACHED PARTS		10.0	45.00
3121 KA)	R + R LEFT REAR TYRE		1.0	4.50
3113 VA)	L/R ROAD WHEEL BALANCE		1.0	4.50
1781	L/R DOOR REPAIR		30.0*	135.00
3577	L/R LAMP PANEL REPAIR		10.0*	45.00
4101	L/R INNER WING REPAIR		20.0*	90.00
4165	L/R INNER WHEELHOUSE REPAIR		20.0*	90.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		26.20	262.0	1,179.00
Total of Labour				1,179.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD286B -**AAD1706-075**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD286B - CANDY

VF1ABL15AUC282335

RENAULT

LATITUDE

07.06.2017

SUPPLEMENTARY PARTS**LIST**

1	1	BUMPER COVER REAR	\$	1,108.46	
2	1	BUMPER LOWER REAR	\$	768.84	
3	1	BUMPER BRACKET CTR REAR	\$	113.47	
4	1	BUMEPB BRACKET SIDE RH REAR	\$	135.97	
5	1	BUMEPB RETAINER RH REAR	\$	44.99	
6	1	BUMPER REFLECTOR RH	\$	43.61	
7	1	BUMEPB BRACKET SIDE LH REAR	\$	135.97	
8	1	BUMEPB RETAINER LH REAR	\$	44.99	
9	1	BUMPER BEAM REAR	\$	777.52	
10	1	BUMPER BEAM BRACKET RH REAR	\$	225.95	
11	1	FENDER PANEL REAR RH	\$	3,299.13	
12	1	WHEELARCH REAR RH	\$	543.47	
13	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	3,039.04	
14	1	FENDER PANEL INNER TRIM REAR RH	\$	671.45	
15	1	AIR VENT	\$	97.29	
16	1	TAILLAMP RH	\$	552.55	
17	1	TAILLAMP PANEL RH	\$	986.70	
18	1	ROCKER PANEL OUTER RH	\$	987.49	
19	1	DOOR PANEL REAR RH	\$	2,844.66	
20	1	DOOR GUIDE REAR RH	\$	176.82	
21	1	DOOR SEAL REAR RH	\$	162.02	
22	1	DOOR CASING REAR RH	\$	1,509.06	
23	1	DOOR FINISHER REAR RH	\$	423.10	
24	1	DOOR HINGE UPPER RH	\$	274.50	
25	1	DOOR HINGE LOWER RH	\$	300.55	
26	1	DOOR CHECK REAR RH	\$	203.06	
27	1	DOOR HANDLE OUTER REAR RH	\$	126.49	
28	1	DOOR HANDLE CAP REAR RH	\$	35.52	
29	1	DOOR HANDLE SEAL REAR RH	\$	7.89	
30	1	DOOR HANDLE COVER REAR RH	\$	13.22	
31	1	DOOR HANDLE MODULE REAR RH	\$	133.60	

Kr

Not Authorised

13.1

Primary Bypart

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1810

Date calculated: 03/23/2019 08:15 AM

Full Report

Registration: SKR5916A

Printed: 23/03/2019 8:17 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	L/R SIDE PANEL NEW PART PAINTING		27.0	
	L/R DOOR REPAIR PAINTING <50%		14.0	
	RR TOWING LUG COVER SURFACE PAINT PLAST.		3.0	
	L/R LAMP PANEL SURFACE PAINT		4.0	
	L/R INNER WING SURFACE PAINT		5.0	
	L/R INNER WHEELHOUSE SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
3481	L/R SIDE PANEL NEW PART PAINTING	32.34
1781	L/R DOOR REPAIR PAINTING <50%	19.25
2593	RR TOWING LUG COVER SURFACE PAINT PLAST.	0.26
3577	L/R LAMP PANEL SURFACE PAINT	1.94
4101	L/R INNER WING SURFACE PAINT	6.34
4165	L/R INNER WHEELHOUSE SURFACE PAINT	6.34

Labour Cost - Paint

	Factor	45.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			58.0	
	Preparation Main Work Metal		1.70	17.0	76.50
	Preparation Comp. Work Plastic		0.30	3.0	13.50
Total		10 WU/h	7.80	78.0	351.00

Material Cost - Paint

	Price SGD
New Part Painting	32.34
Repair Painting	19.25
Surface-/Blend Paint	14.62
Surface Painting Plastic	0.26
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	93.57

Spare Parts

prices as at 2001-01-01

TRANS-CAB AUTO SERVICES PTE LTD

AAD1706-075

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD286B -

32	1	DOOR GRAB HANDLE REAR RH	\$	Sm	210.96	X
33	1	DOOR MOULDING REAR RH	\$	Sm	176.82	X
34	1	DOOR LOCK REAR RH	\$	R	908.75	X
35	1	DOOR PANEL FRT RH	\$	R	2,844.66	X

TOTAL	\$	13,576.90
10%	\$	1,357.69
	\$	12,219.21

Specical Nett

1	1SET	PARKING AID	\$	Sm	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	X
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	X
4	1SET	BUMEPB BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMEPB RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
7	1SET	BUMPER BEAM BOLT	\$	Sm	33.00	X
8	1SET	WHEELARCH CLIP REAR RH	\$	nn	45.00	X
9	2	Rear Windscreen Sealant	\$	nn	80.00	40sm
10	1	Rear Windscreen Inner Sponge Seal	\$	nn	150.00	30sm
11	1	RIM (ROUE 7J 16H 2547)RH RR	\$	Sm	385.00	X
12	1	TYRE RH RR	\$	Sm	330.00	X
13	1	CAP HUB RH REAR	\$	Sm	35.60	X
14	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
15	1	DOOR STICKER "Classic"	\$	nn	15.00	X
16	1	DOOR STICKER "6555-3333"	\$	nn	80.00	60sm

TOTAL	\$	2,128.60
TOTAL PARTS	\$	14,347.81

Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	8001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1810

Date calculated: 03/23/2019 08:15 AM

Full Report

Registration: SKR5916A

Printed: 23/03/2019 8:17 AM

Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	85 02 295 39R		650.00
2603	L/R BUMPER BRACKET	85 04 200 27R		60.00
2650	RR BUMPER CLAMP KIT	60 03 836 33R		30.00
3160	REAR SCREEN BOND KIT	77 11 785 626		0.00
3163	REAR SCREEN FIX SET	82 01 057 684		0.00
3164	REAR SCREEN SPACER	90 35 627 59R		0.00
3481	L/R SIDE PANEL	78 10 174 09R		1,280.00
4201	L/R WHEELHOUSE COVER	76 74 900 20R		195.00
9551	L/R WHEEL	40 30 097 40R		550.00
1004	REVERT	L/R BMPR BRKT		12.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,777.00
u: Used parts	Addition(+10.00%)			277.70
	Total			3,054.70

Extras

Code	Description	Price SGD
1000	BODY SEALANT BODY SEALANT	80.00*
1001	SEALANT SEALANT	40.00*
1003	ANTI-RUST ANTI-RUST	40.00*
1005	L/ REAR TYRE TYRE	200.00*
	Total Extras	360.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SKS5916A @ PANDAN

Version: 1810

Date calculated: 03/23/2019 08:15 AM

Full Report

Registration: SKR5916A

Printed: 23/03/2019 8:17 AM

Final Calculation

	SGD	SGD
Parts	2,777.00	
Addition(+10.00%)	277.70	
Total Parts		3,054.70
Labour Time Base 10 WU/h		
Total 262.0 WU X 45.00 SGD/h	1,179.00	
Total of Labour		1,179.00
Total Of Extras		360.00
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 45.00 SGD/h	351.00	
Material Cost	93.57	
Total Paint Including Material		444.57
Repair Cost Excludes GST		5,038.27
GST (+7.0%)		352.68
Repair Cost Included GST		5,390.95

Comments

* USER SUPPLIED DATA

N - NO MANUFACTURERS CODE EXISTS

) WU PARTIAL INCL IN OTHER POSITIONS



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKR5916A PO:4500804523

ORDER BY NETTY

Tax Invoice No: SIN1556087

Date: 15/01/2019

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	BUMPER R/FLU 1.5 REAR +SENS -2581	1	650.00	650.00
2	BUMPER BKT R/FLU 1.5 R/LH side -2603	1	60.00	60.00
3	RIVET/CLIP R/MEG3/FLU REAR - 2650	10	3.00	30.00
Products received and checked to be in good condition			Sub-Total:	SGD 740.00
			G.S.T(7%):	51.80
			Total:	SGD 791.80

500100332

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external business without warranty and defects. Exchanges are not allowed.	
Issued by: <u>16/1/19</u>	Received by: <u>12/1/19</u>
Name: <u>12/1/19</u>	Name: <u>12/1/19</u>
Sign/Date: <u>12/1/19</u>	Sign/Date: <u>12/1/19</u>
SCM, CPD	Cash Repair

Customer's Signature / Company Stamp

Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:	
TIME:	

WEE - 15/01/2019 12:49:14 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G



Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKR5916A P:O 4500804528
ORDER BY: WONG CHEE WEI

Tax Invoice No: SIN1557505
Date: 07/03/2019
Area Code: 3A DELIVER
Credit Terms: 30Days
Kian Hua Sales: JON.G

No.	Description	Qty	Unit Price	Amount
1	FENDER R/FLU L33F 17>R/LH - 3481	1	1,280.00	1,280.00
2	SPORT RIM R/FLU 1.5 L33F 15>-9551	1	550.00	550.00

D0031029

Products received and checked to be in good condition Sub-Total: SGD 1,830.00
G.S.T(7%): 128.10
Total: SGD 1,958.10

COMFORTDEL	
Items Issued	8/3/19
Issued by:	
Name: 10.H9	
Sign/Date	
SCM, CPD	Crash Repair

Customer's Signature / Company Stamp
Products sold are not returnable.

5001012 849

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:	
TIME:	

JON.G - 07/03/2019 5:27:06 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G



Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKR5916A P:O 4500806438

ORDER BY WONG CHEE WEI

P/O No: 5001012159 WONG CHEE WEI

D003103

No.	Description	Qty	Unit Price	Amount
1	FENDER SHIELD R/FLU 15>R/LH 4201	1	195.00	195.00
2	RIVET R/MEG3/FLU REAR 1004	4	3.00	12.00

Products received and checked to be in good condition Sub-Total: SGD 207.00
G.S.T(7%): 14.49
Total: SGD 221.49

COMFORTDELGRO ENGINEERING PTE LTD	
Item No.	8/3/19
Issued by:	10.49
Name	
Sign/Date	
SCM, CPD	
Crash Repair	

Customer's Signature / Company Stamp
Products sold are not returnable.

500101289

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:	
TIME:	

JON.G - 07/03/2019 5:33:57 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



redefining insurance

SATISFACTION VOUCHER / WORKSHOP'S WARRANTY

To: AXA Insurance Pte Ltd

I/We Sammunda Vivekanandan hereby confirm that I/we have taken delivery of my/our vehicle of registration number SKR 5916A from the Workshop, Messrs Comfort Dabro Engineering Pte and that all necessary and reasonable repairs arising from the accident involving my/our vehicle that occurred on 24/12/2018 have been effected to my/our entire satisfaction. Save for my/our rights under the Warranty set out below, I/we confirm that I/we have no further claims against the Workshop in respect of such repairs.

I/We hereby authorise my/our insurer, AXA Insurance Pte Ltd, to pay the costs of such repairs (less the excess) which amounts to S\$ 4,962.95 directly to the said Workshop and I/we confirm that such payment shall wholly discharge any and all liability on the part of AXA Insurance Pte Ltd to indemnify me/ us for all damage to my/our said vehicle arising from the said accident.

Dated: 15/03/2019


Signature of the Policyholder or duly authorized representative and company stamp where applicable.

WORKSHOP'S WARRANTY

Subject to provisions (a) to (d) below, the repairs effected to the abovementioned vehicle are warranted good by the Workshop for twelve (12) months from the date of this Satisfaction Voucher and during this period, rectification of repairs effected by the Workshop which prove to be faulty shall be undertaken by the Workshop free of charge.

This Warranty shall be inapplicable to:

- (a) faults arising out of abnormal usage of the vehicle;
- (b) faults due to attempts to correct any defect in the repairs effected by the Workshop or the mishandling of rectification work to the vehicle by persons other than the Workshop;
- (c) manufacturing defects in any parts replaced that could not reasonably have been detected by the Workshop at the time the repairs were effected;
- (d) faults or defects arising out of normal wear and tear, misuse, neglect, accident, flood, acts of God, or use in violation of the specifications relevant to the vehicle.

FOR THE WORKSHOP:

EXTENDED BUSINESS HOURS SERVICE

NAME & SIGNATURE

DESIGNATION

DATE: 15.03/2019

Signature and stamp of the Workshop

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
Headline + 65 6365 1288
Faxline + 65 6280 5755
www.cdge.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
15 Upper Cross Street Singapore 050086
45 Pandan Road Singapore 600486
361 Serangoon Drive Singapore 557117
7 Sungei Road Singapore 600009
220 Ubi Road 2 Singapore 408609
501 Yishun Industrial Park 2 Singapore 760752
www.SPARKcarcare.com

Sin 6265 2110
Tel 6274 2300
Tel 6268 2778
Tel 6263 6400
Tel 6869 2389
Tel 6848 1721
Tel 6257 8886



ComfortDelGro Engineering

GST REG. NO. M2-8921817-3

COMPANY REG. NO: 199506048W

TAX INVOICE

8042547

VEHICLE NO
SKR5916AINVOICE NO./DATE
91434578 27.03.2019

COMPANY AXA INSURANCE PTE LTD

MAKE
RENAULTJOB NO.
3052602978 SHENTON WAY AXA TOWER #24-01
SG 068811MODEL
FLUENCE 1.5L DCI 110

ODOMETER READING

CONTACT NO: 63387288

DATE/TIME IN
07.02.2019 11:30DATE/TIME OUT
15.03.2019 18:00

S/NO	DESCRIPTION	QTY	UNIT PRICE (S\$)	DISCOUNT	NET PRICE (S\$)
01	REAR BUMPER 2581	1 PC	650.00	NA	650.00
02	LHR BUMPER BRACKET 2603	1 PC	60.00	NA	60.00
03	REAR BUMPER CLIP 2650	10 PC	3.00	NA	30.00
04	REAR LEFT FENDER 3481	1 PC	1,280.00	NA	1,280.00
05	SPORT RIM REAR LEFT 9551	1 PC	550.00	NA	550.00
06	L/REAR FENDER UNDER LINER 4201	1 PC	195.00	NA	195.00
07	REVERT L/SIDE BRACKET RR BUMPER 1004	4 PC	3.00	NA	12.00
08	TOTAL OF LABOUR	1 EAC	1,179.00	NA	1,179.00

PAGE: 1 OF 3

Cheque should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8042547	91434578		

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
Tel: 6362 0100
Fax: 6362 0101
www.cdeng.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
53 Upper S' Drive Singapore 534989
43 Fernvale Road Singapore 461559
383 Seletree Drive Singapore 757117
7 Sengkang Parkway Singapore 757117
120 Ubi Road 1 Singapore 408606
501 Yishun Industrial Park A Singapore 768732
www.SPD.sg

Tel: 6362 0100
Tel: 6362 0101
Tel: 6362 0102
Tel: 6362 0103
Tel: 6362 0104
Tel: 6362 0105
Tel: 6362 0106
Tel: 6362 0107



ComfortDelGro Engineering

COMPANY REG. NO: 199506048W

TAX INVOICE

GST REG. NO. M2-8921817-3

8042547

VEHICLE NO
SKR5916AINVOICE NO./DATE
91434578 27.03.2019

COMPANY AXA INSURANCE PTE LTD

MAKE
RENAULTJOB NO.
3052602978 SHENTON WAY AXA TOWER #24-01
SG 068811MODEL
FLUENCE 1.5L DCI 110

ODOMETER READING

CONTACT NO: 63387288

DATE/TIME IN
07.02.2019 11:30DATE/TIME OUT
15.03.2019 18:00

S/NO	DESCRIPTION	QTY	UNIT PRICE (\$)	DISCOUNT	NET PRICE (\$)
09	WHEEL ALIGNMENT	1 EAC		NA	
10	MARK FROM PARTS COST 10%	1 PC	277.70	NA	277.70
11	BODY SEALANT	1 PC	80.00	NA	80.00
12	SEALANT WINDSCREEN	1 PC	40.00	NA	40.00
13	ANTI - RUST	1 PC	40.00	NA	40.00
14	L / REAR TYRE 80%	1 PC	200.00	NA	200.00
15	PAINT OF LABOUR	1 EAC	351.00	NA	351.00
16	PAINT MATERIAL	1 PC	93.57	NA	93.57

Total Amount	5,038.27
Excess-30146	400.00-
Total Amount before GST	4,638.27
Add GST 7.00 %	324.68
Net Amount Payable	4,962.95

PAGE: 2 OF 3

Cheque should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

ComfortDelGro Engineering Pte Ltd**Corporate Office**

205 Braddell Road
Singapore 379701
Tel: 6388 5280
Fax: 6388 5733
www.cdge.com.sg

Car Care Centres

205 Braddell Road Singapore 379701
58 Layong Drive Singapore 600126
45 Pandan Road Singapore 600126
383 Serangoon Drive Singapore 556112
7 Selegie Road Way Singapore 128791
120 Ubi Road 3 Singapore 400149
851 Yishun Industrial Park A Singapore 768712
www.SPARKcars.com

Tel: 6261 0110
Tel: 6214 8300
Tel: 6388 8778
Tel: 6351 0400
Tel: 6388 1300
Tel: 6345 072
Tel: 6717 7886



ComfortDelGro Engineering

GST REG. NO. M2-8921817-3

COMPANY REG. NO: 199506048W

8042547

COMPANY AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SG 068811

CONTACT NO: 63387288

TAX INVOICE

VEHICLE NO.
SKR5916A

MAKE
RENAULT

MODEL
FLUENCE 1.5L DCI 110

DATE/TIME IN
07.02.2019 11:30

INVOICE NO./DATE
91434578 27.03.2019

JOB NO.
305260297

ODOMETER READING

DATE/TIME OUT
15.03.2019 18:00

Issued by
Repair Type
Payment term

: DEASEX08 27.03.2019 18:48:35
: CPSO/52/50
: Cash Term

PAGE: 3 OF 3

Cheque should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"

ComfortDelGro Engineering Pte Ltd

A member of COMFORTGROUP

Head Office:

205 Braddell Road
Blk C Ext 1 Level 2
Singapore 379701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.