

22/03/2002

ASS. REC. BY:

REF:

CSS / ALI19000560 / Gcd344

Special Instruction:

Surveyor:

Gino Ciarro

ASSIGNMENT (Office)

From (Person):

Mulvin
Chin Lee Ying

of

AIG

Date/Time:

9/1/19 @ 12:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 1671K

Insured:

SLS 2165C

at Workshop m/s

A-Tec Automotive

Tel:

6384 5206

of

8 Lukki Bkt Ave 4 # 04-20 premier

Policy No:

0999994800.

Claim No:

3515104578SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS

10/1/19

H.O.D. Endorsement:

Date/Time:

1:55pm @ 9/1/19

Person Contacted:

Mulvin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJJ 1671K - NA / ALI19000250/24

Out: 6/40/2019

SLS 2165C - X

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 9/1/2019 12:57:38 PM

Attachments:  Surveyor List.pdf  20190108152515401.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJJ 1671K (Jr)

Your Ref : To be advised

8 January 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

BY EMAIL ONLY

Dear Sirs,

RE: **PROPERTY DAMAGE CLAIM**
CLAIMANT : HAIROMEE BIN JUMAIN
ACCIDENT INVOLVING SJJ 1671K & SLS 2165C ALONG AIRPORT
BOULEVARD ON 4 JANUARY 2019
PRE-REPAIR SURVEY NOTICE

1. We act for Hairomee Bin Jumain, the owner of motor vehicle no. SJJ 1671K which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SLS 2165C for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

| | |
|----------------|---|
| Workshop | A-TEC Automotive Pte Ltd |
| Address | 8 Kaki Bukit Avenue 4 #04 - 20 Premier Singapore 415875 |
| Contact Person | Ms. Peggie (6384 5206) |

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next **two (2) working days** (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

M/s Chia S Arul LLC
Page 2

Our Ref : SJJ 1671K (Jr)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

Enquire Vehicle & Owner Information (Vehicle No. SLS2165C As At 04 Jan 2019 / 08:15:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SJJ 1671K

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 60

Registered Street Name: ANSON ROAD

Registered Unit No.: # 11 - 01

Registered Building Name: MAPLETREE ANSON

Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLS2165C

Make Description/Model: KIA / FORTE K3 1.6A

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|--------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 1015B |
| Vehicle Details | |
| Vehicle No.: | SJJ1671K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 11 Jan 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | ALLION 1.5 A |
| Primary Colour: | White |
| Manufacturing Year: | 2008 |
| Engine No.: | 1NZD133437 |
| Chassis No.: | NZT2603030043 |
| Maximum Power Output: | 81.0 kW (108 bhp) |
| Open Market Value: | \$14,582.00 |
| Original Registration Date: | 02 Sep 2008 |
| First Registration Date: | 02 Sep 2008 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$9,860.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 01 Sep 2023 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 5 |
| PQP Paid: | \$16,170.00 |
| COE Rebate Amount: | \$15,005.00 |
| Total Rebate Amount: | \$15,005.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 11 Jan 2019

OK

► Allion Used Vehicle List (12 vehicles)

| Car Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Company | Availabl |
|---|-----------------|--------------|-------------|----------|------------|------------------------------------|-----------------|
| Toyota Allion 1.5A G (New 5-yr COE) | \$27,888 | \$5,570 /yr | 05-Jan-2009 | 1,496 cc | 98,386 km | SG Auto Pte Ltd | Availabl |
| Yet Another Lowest Mileage Allion In Town! Immaculate Condition! High Loan Or Trade In Avail! Good Enough For 10 Yrs Coe Renewal! Hur Down For A No Obligation Test Drive Today Before Its Gone Again! | | | | | | | |
| Office No. - 68484844 Koh - 92475893 B.k - 97705282 | | | | | | | |
| Toyota Allion 1.5A (New 5-yr COE) | \$29,800 | \$5,960 /yr | 09-Jan-2009 | 1,496 cc | 108,366 km | Creative Auto | Availabl |
| Monthly Only \$647, High Loan Available, Good Condition, No Repair Needed, Free Road Tax Till July 2019, Call To Make Appointment Now. | | | | | | | |
| Office No. - - Cedric Yeak - 97294443 Alex Tan - 97556887 Terence Leow - 90290899 | | | | | | | |
| Toyota Allion 1.5A (New 5-yr COE) | \$29,800 | \$5,960 /yr | 11-Dec-2008 | 1,496 cc | 116,784 km | Creative Auto | Availabl |
| Low Mileage Done, Beautifully Maintained, Excellent Engine And Responsive Gear Condition, Very Solid Condition For COE Renewal. Call Or S Our Friendly Staff Before Coming To Confirm Availability And... | | | | | | | |
| Office No. - - Francis Yao - 93275727 Alex Tan - 97556887 Terence Leow - 90290899 | | | | | | | |
| Toyota Allion 1.5A (COE till 11/2023) | \$29,888 | \$6,160 /yr | 17-Nov-2008 | 1,496 cc | 113,000 km | JDM Cars | Availabl |
| Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade In Welcome! Priced Lowest In The Market Yet Comes Wi... | | | | | | | |
| Office No. - 62994111 Patrick - 93865066 John - 90105163 William Chew - 96463854 Yang - 92981269 | | | | | | | |
| Toyota Allion 1.5A (COE till 11/2023) | \$30,800 | \$6,300 /yr | 02-Dec-2008 | 1,496 cc | - | Viking Motor Pte Ltd | Availabl |
| Very Well Maintained By Previous Owner! No Repairs Needed! Low Monthly Installment! Non-Smoker Car! Trade In Welcome! Bank Loan Or House Loan Available! Call Me Now To View The Car Before It's Sold... | | | | | | | |
| Office No. - 63146133 Ayden - 97153214 Daryl - 88111812 Richard - 90081978 Jeffrey - 86601482 | | | | | | | |
| Toyota Allion 1.5A (New 5-yr COE) | \$30,800 | \$6,160 /yr | 29-Dec-2008 | 1,496 cc | 97,000 km | ED Automobile | Availabl |
| 100% Immediate Loan Approval Package! Additional 6 Months Warranty And Road Tax For You! 1 Doctor Owner Unit With No Accident Recc With Zero Repairs Needed! Priced Lowest In The Market! Superbly We... | | | | | | | |
| Office No. - - Joe Chua - 90066521 Enzo Sim - 96885210 | | | | | | | |
| Toyota Allion 1.5A (COE till 09/2023) | \$31,000 | \$6,570 /yr | 29-Sep-2008 | 1,496 cc | - | William Lee Car Aircon Engineering | Availabl |
| Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today. | | | | | | | |
| Office No. - 63821006 Keith - 98290368 Erik - 96812139 Ben - 98274488 Shen Qiang - 94557994 | | | | | | | |
| Toyota Allion 1.5A (COE till 12/2023) | \$31,800 | \$6,430 /yr | 23-Dec-2008 | 1,496 cc | 112,138 km | Car House Pte Ltd | Availabl |
| Most Reliable Japanese Sedan With Luxurious Drive And Interior, Therefore The Nickname Baby Camry. New Paint Work With Wear And Tea Replaced. Fuel Efficient And Easy To Maintain! Enjoy Special Intere... | | | | | | | |
| Office No. - 64634620 Damien - 97227775 Clement - 91152539 Ken - 90219697 Derrick - 86979660 | | | | | | | |
| Toyota Allion 1.5A (COE till 12/2023) | \$31,800 | \$6,400 /yr | 30-Dec-2008 | 1,496 cc | 155,000 km | Benefit Auto Enterprise Pte Ltd | Availabl |

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (C)
(4)Not Consistent (NC)

Rear Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------|-------|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | Cut ✓ | | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | NC ✓ | | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | | | |
| 1159 | 993327 | Rear End Panel | | | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | | | |
| 1171 | 991328 | Bootlid Emblem | | | |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

Vehicle No: **5151671K**

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|----------|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | Repair ✓ | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | Cut ✓ | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | Sub ✓ | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1136 | 990247 | Sticker | | | |
| | | Rear RH Door | NC ✓ | | |
| | | Rear RH Shock absorber | | | ? |
| | | Rear RH wheel bearing | | | ? |

No of Items: _____ Assessor: _____

original photo

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 08 Jan 2019 Edit Reg | | 09 Jan 2019 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|--------------------------|

CLAIM SUBFOLDER DETAILS
[\[Created by adjuster\]](#)

| | | | |
|-----------------------------|--|------------------------|---|
| Insured: | LCRF Pte Ltd , Co. Reg. No.: NA | | |
| Main Claimant: | - | | |
| Vehicle Reg. No.: | SJJ1671K | Date of Loss: | 04/01/2019 00:00 - :59 [124 Months and 2 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 3515104578SG | Policy/Cover Note No.: | 0999994800 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLS2165C | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383 | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/01/2019] | | |
| Claimant's Solicitor: | CHIA S ARUL & LLC - Tel: 67334647 | | |

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- AIG_SG (14/01/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |




















Claim Documents

***SJJ1671K (3515104578SG)**
[SLS2165C]

TP

Jan 4 2019 12:00AM

[LCRF Pte Ltd]
A-Tec Automotive Pte Ltd

| | | | | | | | | | | | | | | | | | | |
|------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|---|-----------|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | View in Browser | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | | | Thumbnail | Print | |
| 1 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 11/01/19 14:59 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| Documentation | | | | | | | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | | | | | | | | | | Thumbnail | Print | |
| 1 | 14/01/19 09:29 | OI GIA REPORT | | | | | | | | | | | | |  | Load PDF | | |

Documents Checklist

| | | | |
|--|--------------------------------------|-------------------------------------|--------------------------------------|
| DOCUMENTS CHECKLIST | <input type="button" value="Reset"/> | <input type="button" value="Save"/> | <input type="button" value="Print"/> |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19000560/GCD3E2
Date: 16/01/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994800
Claimant Vehicle No : SJJ1671K **Insured Vehicle No :** SLS2165C
 Date of Loss: 04/01/2019 Nature of Claim: TP Claim No: 3515104578SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ1671K**
 Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD133437
 Reg. Date: 02/09/2008 (Man. Year: 2008) Chassis No: NZT2603030043
 Colour: White Odometer: 116148 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Neuton 6 mm Rear Left Side: Neuton 6 mm
 Front Right Side: Neuton 6 mm Rear Right Side: Neuton 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 09/01/2019
 Date Inspected: 10/01/2019 Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Avenue 4 # 05-27 Premier
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|-------------------------|-----------|------------|--------|
| 1 | 1 | | *REAR BUMPER | Cut | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 1 | | *REAR RH FENDER | Repair | 0.00 F | *- F |
| 4 | 1 | | *REAR RH WHEEL RIM | Cut | 0.00 F | *- F |
| 5 | 1 | | *REAR RH TYRE | Scratched | 0.00 F | *- F |
| 6 | 1 | | *REAR RH DOOR | Buckled | 0.00 F | *- F |
| 7 | 1 | | *REAR RH SHOCK ABSORBER | * Check | 0.00 F | *- F |
| 8 | 1 | | *REAR RH WHEEL BEARING | * Check | 0.00 F | *- F |
| Total Parts (S\$) | | | | | 0.00 | 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >