

ASS. REC. BY:

REF:

CS3 / ASM19000581 / Tida

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

Smart claim

From (Person):

Peter Wang

of

ASM

Date/Time:

10012019 952am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 4295A

Insured:

FBG 6621H

at Workshop m/s

Gold Auto Works

Tel:

81999149

of

48 Toh Guan Rd East #D1-119

Policy No:

Claim No:

S9M019X0

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09012019

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

10012019 10:40am

Person Contacted:

Simon

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJW 4295A - X
	FBG 6621H - X
	Demantle: 11/1/2019

Signature

Taylor

REF:

AXIA

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJW 4295A Yr Regn: Mar / 10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Honda Civic C.C. 1339
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 246658 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMFD36209S206187
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 10/1/1905pm
 Survey held at Gold Hill

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No 9/17
- Estimated repair range \$2,500 - \$3,000

14/1/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format : PRE

Lump Sum / I.B.I: (\$

100

100



Service Request Details

Claim

S9M019X0

Reference

None 

Loss Date

9 January 2019

Request Date

10 January 2019

Due Date

17 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJW4295A

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

FAHMI ZAHID

104 JALAN BUKIT MERAH, TIONG BAHRU ORCHID, #03-1994, 160104, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

NON REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: claims@goldautoworks.com.sg
Sent: Wednesday, 9 January, 2019 7:47 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Requesting for PRE-Repair survey for our vehicle number SJW4295A
Attachments: SJW4295A GIA report.pdf; LTA SEARCH FOR FBG6621H.pdf

Categories: Pragati

HI SIR/MDM,

Your Insurer client Vehicle FBG6621H had hit my client Vehicle SJW4295A on 09/1/2019 0240hrs at KJE TOWARDS TUAS EXIT CHOA CHU KANG DR .

Please kindly arrange a Pre-Repair inspection for my client Vehicle SJW4295A in 2 working days at GOLD AUTOWORKS PTE LTD at

48 TOH GUAN ROAD EAST, Enterprise hub #01-119 Singapore 608586.

Best Regard
SIMON TAN

Tel 81999149/62645948
48 Toh Guan Road
Enterprise Hub
Singapore 608586

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Road Tax Payable

Vehicle Details			
Vehicle No.:	SJW4295A		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	CIVIC IMA 1.3L CVT		
Chassis No.:	JHMF36209S206187		
Propellant:	Petrol-Electric		
Engine No.:	LDA24020640		
Motor No.:	MF51177114		
Engine Capacity:	1339 cc		
Power Rating:	15.0 kW		
Maximum Power Output:	70.0 kW (93 bhp)		
Maximum Laden Weight:	1720 kg		
Unladen Weight:	1290 kg		
Year Of Manufacture:	2008		
Original Registration Date:	25 Mar 2010		
Lifespan Expiry Date:	-		
COE Category:	A - Car (1600cc & below)		
Quota Premium:	\$20,802.00		
COE Expiry Date:	24 Mar 2020		
Road Tax Expiry Date:	24 Mar 2019		
PARF Eligibility Expiry Date:	24 Mar 2020		
Inspection Due Date:	24 Mar 2019		
Intended Transfer Date:	14 Jan 2019		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 24 Mar 2019. You may renew the road tax from 25 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 25 Mar 2019 to 24 Sep 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	295.00	-	295.00
Total Amount Payable:			320.00
Amount Payable (From 25 Mar 2019 to 24 Mar 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	590.00	-	590.00
Total Amount Payable:			615.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5392X
Vehicle Details	
Vehicle No.:	SJW4295A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC IMA 1.3L CVT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	LDA24020640
Chassis No.:	JHMF36209S206187
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$34,100.00
Original Registration Date:	25 Mar 2010
First Registration Date:	25 Mar 2010
Transfer Count:	1
Actual ARF Paid:	\$20,460.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2020
PARF Rebate Amount:	\$11,253.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$2,482.00
Total Rebate Amount:	\$13,735.00

The information contained herein is correct as at 14 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2019 14:32
Date Of Accident	09/01/2019 02:40
Exact Location Of Accident	KJE TOWARDS TUAS EXIT CHOA CHU KANG DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW4295A
Insured/Policyholder	
Name Of Registered Owner	YONG KENG HOCK, VINCENT
NRIC No	S7906607I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83180720
Alternative Phone No	OFFICE-83180720

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099102374(CLASSIC)
Cover Note Number	

Driver

Name of Driver	SIM CHIN CHU @BAY CHIN CHU
NRIC No	S0234803I
Date Of Birth	13/07/1954
Occupation	INDOOR
Date Of Driving Pass	26/11/1975
Driving Experience	43 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-83180720
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 7 #13-102 TECK WHYE AVE
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PARENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBG6621H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver ZAHID FAHMI
 NRIC/Passport Number S9674781J
 Contact Number 86991445
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/01/19 About 02:40am, I was Driving Vehicle A: SJW 4295A At
 KJE Exit Choa Chu Kang Drive Filter Lane Turning Left Checking Blind Spot -
 Suddenly Vehicle B: FBG 6621H Collided My Car Back.

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok Street 23
 Singapore 659545
 Tel: 6560 3312 Fax: 6569 0722
 Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19000581/T1cbe2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 16-01-2019		
ATTN: PETER WANG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBG 6621H	Veh. Inspected	SJW 4295A	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M019X0	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	10/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JHMF36209S206187	Colour	GREY	
Odometer	246655 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	09/01/2019	Inspect Date / Time	10/01/2019 (05:00 PM)	
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/ASM19000581/T1cbe2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.