

ASS. REC. BY:

REF

CS3/LPC1900059/Rtd300

Instruction:

Surveyor

Raisul

ASSIGNMENT (Office)

From (Person):

ong h k

of:

lpc

Date/Time:

10/1/19 @ 11:17am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS.

To Inspect Vehicle No:

FBN 3771R

Insured:

GBG 3520K

at Workshop m/s

Gp Motoring

Tel:

9061 8091

of

280 Macpherson Road

Policy No:

Claim No:

18/19/19/VCOS/02/312

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/1/19

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:28am @ 10/1/19

Person Contacted:

Mr. Ken

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBN 3771R-X

GBG 3520K-X

Submit PRS Report

Surveillance *PRR*

REF: *JPC*

ASSIGNMENT

From: _____ Date: *10/01/2019*

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *FBN 3771R*

at Workshop m/s: *GP Motoring*
of *282 Macpherson Road*

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *(up)*

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *FBN 3771R* Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *YAMAHA* G.C. _____

Colour: *MULTI*

A/C: Insured / Std / NI / NA

Sp. Reading: *29130*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MH3SG464035045481*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *110/80-14*

R: *140/70-14*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *IRC*

Front

Rear

R/Bal. *4* mm

R/Bal. *4* mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. _____

D.O.I. *10/01/19 @ 1220pm*

Survey held at *GP MOTORING*

Des. of Damages: Frt / Rear / O/S / *MS* / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 JAN 2019

Date/Time, File Pass to?

211 Typist

Date/Time, File Return to?

2)

Report Format: *TP-PRR*

Lump Sum / I.B.I. (\$) _____

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: *450*

Transportation: _____

) \$ + RS. SI

) Photos

) Others

TOTAL

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 10 January 2019 11:17 AM
To: Alfred Ng; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG; Ng Alfred
Subject: Your ref: JEQ/FBN3771R/GP/PI Our ref: 18/19/19/VC05/021312 RE: ACCIDENT INVOLVING FBN3771R AND GBG3520K ON 9 JANUARY 2019
Attachments: 10012019104843.pdf

Without Prejudice
Save as to Costs


Dear Alfred

We are not agreeable with your list of proposed surveyors. We shall appoint LKK Auto Consultants Pte Ltd to conduct the PRS. Please provide the details of the workshop.

Dear Catherine/Nivitha

Please follow up and arrange.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Thursday, 10 January, 2019 11:12 AM
To: ONG LI LI
Cc: MT_Claim_SG; Ng Alfred
Subject: ACCIDENT INVOLVING FBN3771R AND GBG3520K ON 9 JANUARY 2019

Your ref: 18/19/19/VC05/021312
Our ref: JEQ/FBN3771R/GP/PI

Dear Li Li,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;

- 4. Delta V Consultant;
- 5. Prominent Appraisal Services Pte Ltd;
- 6. Advance Automotive Consultancy Pte Ltd;
- 7. Pal's Appraiser Pte Ltd;
- 8. S K Auto Consultants;
- 9. Oh Appraisal Services;
- 10. KAAS.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

GP Motoring Pte Ltd

282 Macpherson Road

Singapore 348607

Tel: 6746-4240 Mobile: 9061-8091.

Fax: 6746-4596

Person In charge : Mr. Ken Sim

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

From: claims@juseq.com.sg

To: alfred_ng@juseq.com.sg

Sent: Thursday, January 10, 2019 11:03 AM

Subject: FW: Your Ref: JEQ/FBN3771R/GP/pl(zl) Our Ref: 18/19/19/VC05/021312

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Thursday, January 10, 2019 10:57 AM

To: claims@juseq.com.sg

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Your Ref: JEQ/FBN3771R/GP/pl(zl) Our Ref: 18/19/19/VC05/021312

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We refer to your fax of 10 January 2019

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick -
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



MGE119003065 / Glen Enterprise Pte Ltd - HQ
ENTRY DATE & TIME: 09/01/2019 15:27
SUBMITTED BY: Chai Suk Teng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2019 15:27
Date Of Accident	09/01/2019 08:30
Exact Location Of Accident	KRANJI EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN3771R
Insured/Policyholder	
Name Of Registered Owner	MOHAMAD NAZRIN BIN SA'AT
NRIC No	S9009249I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90297071
Alternative Phone No	OTHERS-90297071
Vehicle Particulars	
Manufacturer	YAMAHA
Model	GDR155A (AEROX)-155CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/18-995054-WTT
Cover Note Number	20/09/2018-18/09/2019
Driver	
Name of Driver	MOHAMAD NAZRIN BIN SA'AT
NRIC No	S9009249I
Date Of Birth	11/03/1990
Occupation	INDOOR
Date Of Driving Pass	17/12/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90297071
Fax Number	(LOCAL) +65-90297071
Contact Number	OTHERS-90297071
Email Address	NOEMAIL

Address BLK 734 WOODLANDS CIRCLE #02-359
 Postcode 730734
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
General Information of the Accident
 Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY
Other Information
 Was any foreign vehicle Involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1
Details of Police Action
 Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ALJUNIED NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 13 JOO SENG ROAD , POSTCODE: 360013 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2809999 - FAX NO: 62815960
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?
Circumstances of Accident
 REFER TO POLICE REPORT: T/20190109/2070.
Attachment(s)
 Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG3520K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category GOODS VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMAD NAZRIN BIN SA'AT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBN3771R
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19000589/R1td3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 22-01-2019		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBG 3520K	Veh. Inspected	FBN 3771R	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/VC05/021312	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	10/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3SG4640JJ045481	Colour	MULTI COLOUR	
Odometer	29130 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80-14	IRC	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-14	IRC	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5. General Information				
Accident Date	09/01/2019	Inspect Date / Time	10/01/2019 (12:20 PM)	
Survey held at	GP MOTORING PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC19000589/R1td3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.