Surveyor

REF: ALG

ASSIGNMENT

From: Date: 16.01.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 9563M

at Workshop m/s Lim Tan

of 176 Sin Ming Drive #03-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

after 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PA 9563M Yr Regn: 08, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Hiace c.c 2982

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 161828 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFST22P5000 08530

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: Pelium 185/60R15

R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	9 mm
L/Bal.	7 mm	L/Bal.	9 mm
D.O.A.	8/1/19	D.O.I.	16/1/19

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/1	File pass to Ca

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS___SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)