

REF:

Surveys Admin.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: Success United

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: 3 days Res.: Yes or NoLum Sum: ✓ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 8113A Yr Regn: 2017, MarchType: M.Car / M.Cycle / Bus / Van / Convey / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 46644 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35Y70K207606Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size F: 195R15C MicR: 155R12C BS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/01/19Survey held at Success UnitedDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPA16.

P/P = \$4542.33 with 3 repair days.

(Red = \$667.33 / 30%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ Site Insp (\$

Transportation: _____

☐ Interview (\$

) S + RS \$1

☐ Tech. Invs (\$

) Photos

☐ Weekend (\$

) Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG19000618/Abp3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 10-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBH 1816R	Veh. Inspected	GBF 8113A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/12/2018	Inspection Date	10/01/2019	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-009

Date : 10/01/2019

Vehicle Num. : GBF8113A

Make/Model : Toyota Dyna-2016

Chassis/Eng# : JTFAT35Y70K207606/1KD2686731

Accident Date : 11/12/2018

Claim No. :

Reference :

Policy No. : (22/05/2019)

Xiao Tony

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	Fuel Tank <i>Rented</i>		1,085.45
3.	1	Fuel Tank Bracket Holder <i>Berk</i>		311.00
3.	2	Side Gate Hinge <i>2ea</i>	211.55	423.10
List Total S\$:				1,819.55
25.00% Discount S\$:				454.89
				1,364.66

1396.45
1047.34

LABOUR :

To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

To putty and respray painting on affected area.

Labour Total S\$:

500

450.00 *200*

400.00 *300*

850.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

10/01/19. 03 Days.

~~45~~ P/A??

total 1547.34 (P/P) ✓

E. & O.E.

Total S\$: 2,214.66

Signature

for SUCCESS UNITED PTE LTD

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 1000J

Vehicle Details

Vehicle No.: GBF8113A
Vehicle to be Exported: No
Intended Deregistration Date: 22 Dec 2018
Vehicle Make: TOYOTA
Vehicle Model: DYNA 150 5MT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 1KD2686731
Chassis No.: JTFAT35Y70K207606
Maximum Power Output: -
Open Market Value: \$26,436.00
Original Registration Date: 23 Mar 2017
First Registration Date: 23 Mar 2017
Transfer Count: 1
Actual ARF Paid: \$1,322.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$28,945.00
COE Rebate Amount: \$23,879.00
Total Rebate Amount: \$23,879.00

The information contained herein is correct as at 21 Dec 2018

OK



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

Your Ref: CC6/AIG19000618/Agb3

15th May 2019

M/s. **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Attn: Motor Claims

Dear Sir

Re: **Acc Invlg GBF 8113A & FBH 1816R on 11.12.18**

We refer to the above accident which was caused due to the negligence of your insured driver of Veh No. FBH 1816R

We are claiming for the following costs and losses incurred:

1)	Cost of Repairs (Inc. 7% GST)	\$ 1,655.65
2)	Loss of Use (\$90 x 3 days)	\$ 270.00
3)	Search Fees	\$ 2.00
Total:		<u>\$ 1,927.65</u>

Enclosed herein the following documents for your perusal.

- 1) Tax Invoice No. S1905023
- 2) GIA Search Fee
- 3) Letter of Authorisation

We appreciate your prompt attention and response.

Yours faithfully



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19000618/Apb3

22 March 2019

PETER WILLIAM SMYTH
408 SIN MING AVENUE
#12-205
SINGAPORE 570408

Dear Sir/Madam,

ACCIDENT INVOLVING FBH 1816R / GBF 8113A / OTHERS ON 11/12/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: Ceciliachong@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

To: **Success United Pte Ltd**
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS: **GBF 8113A & FBH1816R**
ALONG **Killiney Road** ON **11.12.18**

I/We, **Chin Wah And Company** Co's Rgn/NRIC No. **00641000J**
of **63 Killiney Road** **Singapore 239523**
the owner of vehicle no. **GBF 8113A** hereby authorise you to commence repair to the said
vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request:

- a) I/We hereby irrevocably authorise you to demand claim settle receive whatever amount settled/payable by the insurance and/or third party or to commence legal proceeding, if necessary, in my name, for the costs of repair and loss of use, etc and to you appointing any Solicitor to act for me in respect of the accident claim and all and any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authorisation to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and my/our Solicitors to see the claim to a successful conclusion.
- b) If the third party claim is unsuccessful or in your discretion inappropriate for any reason, I/we hereby instruct and authorise you to claim direct from my/our insurance company on my/our behalf for all monies due to you. I undertake to pay you for the Excess applicable under my policy and to reimburse you all costs, fees and expenses incurred by you in pursuing the claim on my behalf.
- c) If the own insurers' claim is not applicable and/or the third party claim fails and/or either of the aforesaid is inadequate, I/we undertake to pay you for your expenses, costs and fees immediately.

I/We also irrevocably authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence. I/We irrevocable authorise you to appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.


I/We undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the third party's insurance company communicate with me/us directly, orally or in writing and I/we further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.

Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/we undertake to pay you and my/our solicitor the cost of repairs settled and related expenses and disbursement incurred.

My/Our insurer is/are **NTUC Income Insurance**
Policy No. **5088655300-01**

Expiry Date: **22.03.19**

Date: **22 APRIL 2019**

Excess: 

Owner s stamp
Chin Wah And Company
NRIC No: **00641000J**

Witness Signature/Name

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **SUCCESS UNITED PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,920.00** (Global Sum) for vehicle no. **GBF 8113A** that was damaged pursuant to the accident which occurred on **11/12/2018** (date) along **KILLINEY RD TOWARDS EBER RD** involving vehicle no/s **FBH 1816R**.

This is pursuant to the inspection conducted on **10/01/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHIN WAH AND COMPANY** ("the third party claimant") of vehicle no. **GBF 8113A** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBF 8113A** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23rd (day) of May (month) 2019 (year)

LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Tax Invoice : S1905023

Date : 15/05/2019
Vehicle Num. : GBF8113A
Make/Model : Toyota Dyna-2016
Chassis/Eng# : JTFAT35Y70K207606/1KD2686731
Accident Date : 11/12/2018
Claim No. :
Reference :
Policy No. : (22/05/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	Fuel Tank		1,085.45
		Fuel Tank Bracket Holder		311.00
		List TotalS\$:		1,396.45
		25.00% Discount S\$:		349.11
				1,047.34
		LABOUR :		
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		200.00
		To putty and respray painting on affected area.		300.00
		Labour Total S\$:		500.00

SUCCESS UNITED PTE LTD

Total S\$: 1,547.34
GST @ 7% S\$: 108.31
Amount Due S\$: 1,655.65
=====



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-196506

Date of Request: 21/12/2018

Your Ref No: Online Purchase

Success United Pte Ltd
2 Kaki Bukit Ave 2 #01-33
Kaki Bukit AutoHub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 21/12/2018

Enquiry By Sirina Soon

TP Vehicle No. FBH1816R

Accident Date 11/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FBH1816R	AIG Asia Pacific Insurance Pte. Ltd.	29/03/2018-28/03/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-196508

Date of Request: 21/12/2018

Your Ref No: Online Purchase

Success United Pte Ltd
2 Kaki Bukit Ave 2 #01-33
Kaki Bukit AutoHub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 21/12/2018

Enquiry By Sirina Soon

TP Vehicle No. FBH1816R

Accident Date 11/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018 Edit Reg		10 Jan 2019 00:00 Edit Adj Rpt	S\$1,547.34 Edit Estimates	S\$1,547.34 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PETER WILLIAM SMYTH, ID: S2719759								
Main Claimant:	CHIN WAH AND COMPANY, Co. Reg. No.: 00641000J								
Vehicle Reg. No.:	GBF8113A	Date of Loss:	11/12/2018 17:00 - :59 (20 Months and 18 Days From LTA Reg Date (Man Yr))						
Claim Type:	TP / 7756190490SG	Policy/Cover Note No.:	1800033179 (Comprehensive)						
Vehicle Reg. No. (Insured):	FBH1816R	Policy No. (Claimant):	5088655300-01						
		Excess:							
Repairer:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF8113A (7756190490SG)
[FBH1816R]

TP

CHIN WAH AND COMPANY

Dec 11 2018 5:00PM

[PETER WILLIAM SMYTH]

Success United Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit			
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail			Print			
1	14/01/19 10:17		Accident Statement From: SC – Reg. No: FBH1816R, Claimant: PETER WILLIAM SMYTH														Load HTM			
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
2	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
3	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
4	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
5	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
6	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
7	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
8	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
9	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
10	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
11	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
12	09/05/19 09:40		General View														Load JPG <input checked="" type="checkbox"/>			
13	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
14	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
15	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
16	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
17	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
18	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
19	09/05/19 09:40		Reinspection Photo														Load JPG <input checked="" type="checkbox"/>			
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	10/01/19 15:51		TP GIA REPORT														Load PDF			
2	09/05/19 10:12		TP ESTIMATE														Load PDF			
3	13/06/19 08:51		WORKSHOP INVOICE														Load PDF			
4	13/06/19 08:51		AUTHORISATION TO ACT FORM														Load PDF			
5	13/06/19 08:51		Release Voucher														Load PDF			
6	13/06/19 08:51		GIA SEARCH														Load PDF			
7	13/06/19 08:51		LETTER TO OI														Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBH1816R (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D
	GBF8113A (TP veh)		5MT (M)
Date of Accident:	11/12/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	2,369.69
Final Repair Cost	:	\$	1,920.00
Loss of Use	:	\$	3.00 days at \$90.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,920.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Success United Pte Ltd	:	\$ 1,920.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19000618/AGB3Q2

Date: 13/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033179
Claimant Vehicle No : GBF8113A **Insured Vehicle No :** FBH1816R
 Date of Loss: 11/12/2018 Nature of Claim: TP Claim No: 7756190490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF8113A**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2686731
 Reg. Date: 23/03/2017 (Man. Year: 2016) Chassis No: JTFAT35Y70K207606
 Colour: Silver Odometer: 46644 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Michelin 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,364.66	1,047.34	317.32	23.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	500.00	350.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,214.66	1,547.34	667.32	30.13
+ GST 7.00/7.00% (S\$)	155.03	108.31	46.72	30.14
Nett Amount (S\$)	2,369.69	1,655.65	714.04	30.13
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,927.65		
Global Sum Settlement (S\$)		1,920.00		

INSPECTION

Date of Assignment: 10/01/2019

Date Inspected: 10/01/2019 Inspected At:

 Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
 AutoHub
 Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FUEL TANK	Dented	1,085.45 FL	*1,085.45 FL
2	1		*FUEL TANK BRACKET HOLDER	Bent	311.00 FL	*311.00 FL
3	2		*SIDE GATE HINGE	Not Necessary	423.10 FL	*- FL
					Sub Total (\$\$)	1,819.55
					- List Item Discount on L Items 25.00/25.00% (\$\$)	349.11
					Total Parts (\$\$)	1,047.34

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	450.00	200.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	400.00	300.00
Gross Labour Cost (S\$)			850.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >