

ASS. REC. BY:

REF: CS/FCI19000627/Ed3

Special Instruction: ⁰²

Assignment: SRVR ASSIGNMENT (Office)

From (Person): aus Eileen Lee of FCI Date/Time: 2:38pm @ 10/1/19

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLM6368P Insured: SHD 6708L

at Workshop m/s: Hua Hong Pte. Ltd. Tel: 6661 9688

of: 250 Surajin Bendut Street 1

Policy No: _____ Claim No: D19000271MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement: _____

Date/Time: 3:19pm @ 10/1/19 Person Contacted: Jurien Vehicle: IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	<u>SLM6368P-09/ASM18017728/Nf93q2 DOA: 30/08/18</u>
	<u>SHD 6708L-003/CTI18009912/Klwb3q3 DOA: 30/5/18</u>
<u>11/9/19</u>	<u>Email preli revised to FCI</u>

ASS. BY: Sten

REF: FCI

ASSIGNMENT

From: _____ Date: 10/9/19

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 6368P

at Workshop m/s: Hua Hong

of 250 Sungai Mendut Street 1

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 10am

Veh No: SLM 6368P Yr Regn: 4/4/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai AE 1919 c.c. 1580

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 100537 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC PSI CVH4077255

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17
R: 11

(Policy Condition)

XX	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Firmza

Front		Rear	
R/Bal. <u>5</u>	mm	R/Bal. <u>5</u>	mm
L/Bal. <u>5</u>	mm	L/Bal. <u>5</u>	mm
D.O.A. <u>4/1/19</u>		D.O.I. <u>10/9/19</u>	

*Survey held at Hua Hong

Des. of Damages Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-85K
5/11/19	Finalize confirm \$158940 (PIP) - 2 repair days (Red 917.60, 370)
RECEIVED 06 NOV 2019	

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) 6/11 - typist

Report Format: CWS

Lump Sum / L.R. / C: 1589-40

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) _____

: Interview (\$) _____

: Tech. Invs (\$) _____

: Weekend (\$) _____

Survey Fee:	<u>110</u>
Transportation:	<u>50</u>
S + PS: \$1	<u>50+50</u>
Photos:	<u>53</u>
Other:	
TOTAL:	<u>313</u>



Auto
Consultants
Pte Ltd

Company Registration No. 19960719E

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: D19000271MFSH

Our ref: CS/FCI19000627/Evd3

Date : 11/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 6368P


We thank you for your instruction on 10/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/9/2019 at the premises of M/s HUA HONG PRIVATE LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$1,747.00
Revised Estimate Amount	: S\$471.00
"Check" Items Amount	: S\$836.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-01-2019	Our Ref No. D19000271MFSH
Accident Date	04-01-2019	Claim Type. Third Party
Insured Vehicle	SHD6708L	Third Party Vehicle. SLM6368P
Survey Location	25D SUNGEI KADUT STREET 1	
Contact Person.	JERLEEN TANG	
Contact No.	666196888/ 0	Fax No. 66619699
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report. *Need to Repair*

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HONG PRIVATE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 11 September 2019 10:32 AM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000271MFSH/1-SLM 6368P
Attachments: SLM 6368P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLM 6368P
Date of survey: 10/9/2019
Number of days (estimated) : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 10 January 2019 3:21 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000271MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 10 January 2019 2:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000271MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Steve Chen (LKK Auto)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Tuesday, November 05, 2019 3:37 PM
To: Steve Chen (LKK Auto)
Subject: RE: Finalisation for Vehicle No. SLM6368P

Dear Steve

Confirmed COR \$1589.40, will submit LOD to First Cap.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Friday, 18 October 2019 9:46 AM
To: Ashley Tan <ashley@huahong.com.sg>
Subject: Finalisation for Vehicle No. SLM6368P

Dear Ashley,

Kindly refer our finalize \$1589.40 (P/P, before GST). 2 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Tan [<mailto:ashley@huahong.com.sg>]
Sent: Tuesday, October 15, 2019 2:26 PM
To: Steve Chen (LKK Auto)
Subject: RE: Finalisation for Vehicle No. SLM6368P



HUA HONG PRIVATE LIMITED

25D Sungai Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

James Tan
11/9/19

14 January 2019

First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068877

Steve (LKK)
8322 8813

HHTP Claims 19-05
10/9/19, 11.00 am
2 days
L/S
By AL SM

Attn: Motor Claims Department

ACCIDENT INVOLVING SLM 6368 P & SHD 6708 L ON 04/01/2019 AT ADMIRALTY STATION DROP OFF POINT AT ABOUT 1835 HOURS

Insured : JASON TRANSPORT & TRADING
Vehicle Registration No : SLM 6368 P
Vehicle Make : HYUNDAI
Vehicle Model : AE IONIQ HEV 1.6 DCT SR
Vehicle Chassis No : KMHC851CVHU027255
Policy No : VCX/P1930117
Date of Accident : 04/01/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	10	Front Bumper Clip ✓	\$ 2.00	\$ 20.00 ✓
2	1	Front Bumper Foam ? X NAI		\$ 95.00 X
3	1	Front Bumper Moulding X NAI		\$ 110.00 X
4	1	Front Grille (Complete) ? / BR		\$ 950.00 ✓
5	1	Front Grille Inner Cover X NAI		\$ 65.00 X
				\$ 1,240.00
Less 20%				\$ (248.00)
				\$ 992.00
6	1	Front Number Plate ✓ CUT		\$ 35.00 ✓
To dismantle & refit front bumper to change front grille & repair front bumper				\$ 400.00 200
To perform wire checking				\$ 20.00 ✓
To spray front bumper				\$ 300.00 200
				\$ 1,747.00
7% GST				\$ 122.29
Total				\$ 1,869.29 455

2507



Signature

Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



HUA HONG PRIVATE LIMITED

25D SUNGAI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Supplementary List

15 October 2019

QUOT201910-000020
HHTPCLAIMS19-05

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD, #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

**ACCIDENT INVOLVING SLM6368P & SHD6708L ON 04/01/2019 AT ADMIRALTY STATION
DROP OFF POINT AT ABOUT 1835 HOURS**

Insured : JASON TRANSPORT & TRADING
Vehicle Registration No. : SLM6368P
Vehicle Make : HYUNDAI
Vehicle Model : AE IONIQ HEV 1.6 DCT SR
Vehicle Chassis No. : KMHC851CVHU027255
Policy No. : VCX/P1930117
Date of Accident : 04/01/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front bumper / OR		\$ 950.00 448 ✓
				\$ 950.00 - 20%
			Less 20%	\$ 190.00
				\$ 760.00 358.40
				\$ 760.00
			7% GST	\$ 53.20
			Total	\$ 813.20

P- 776
Supp- 358.40
L- 455
P/P - 1589.40



Authorised by Claims Dept



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000627/Evd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6708L	Veh. Inspected	SLM 6368P
Policy No.		Coverage (\$)	0.00
Claim No.	D19000271MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AE IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHC851CVHU027255	Colour	BLACK
Odometer	100537	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	FIRENZA	5 mm
L/H Front Tyre	225/45 R17	FIRENZA	5 mm
R/H Rear Tyre	225/45 R17	FIRENZA	5 mm
L/H Rear Tyre	225/45 R17	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/01/2019	Inspection Date	10/09/2019
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6368P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	FRONT BUMPER CLIP @\$2.00	NECESSARY	20.00	20.00
1	FRONT BUMPER FOAM	NOT NECESSARY	95.00	-
1	FRONT BUMPER MOULDING	NOT NECESSARY	110.00	-
1	FRONT GRILLE (COMPLETE)	BROKEN	950.00	950.00
1	FRONT GRILLE INNER COVER	NOT NECESSARY	65.00	-
1	FRONT BUMPER (ADDITIONAL)	BROKEN	950.00	448.00
	LESS 20% DISCOUNT		-438.00	-283.60
			1,752.00	1,134.40
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	CUT	35.00	35.00
			35.00	35.00
LABOUR				
	TO DISMANTLE & REFIT FRONT BUMPER TO CHANGE FRONT GRILLE & REPAIR FRONT BUMPER.		400.00	200.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO SPRAY FRONT BUMPER.		300.00	200.00
			720.00	420.00
GRAND TOTAL			2,507.00	1,589.40
RECOMMENDED COST OF REPAIRS				1,589.40

Report Ref No. CS/FCI19000627/Evd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.