

ASS. REC. BY:

REF:

08/AIG19000630/Ksd3

n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Hor Yimul

of

AIG

Date/Time:

10/1/19 @ 2:37pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLW 3083C

Insured:

GT 7135K

at Workshop n/s

Massive trading

Tel:

91082728

of

Blk 5038 - AMK Ind. park 2 #01-405

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/01/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3:10pm @ 10/1/19

Person Contacted:

Anthony

Vehicle - IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 3083C -X

GT 7135K -X

25/1/19 8:30am C. Brown

ASS. REC. BY:

REF:

A/GI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/1

File pass to NMP

25/01/19

Confirmed HS \$ 3,300/- @ 3 days with Kenneth.
(\$ 3,163.26 Red = 49%)

RECEIVED 2-5 JAN 2019

Date/Time, File Pass to?

25/01/19

1)

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Photos

: Others

TOTAL

250

10

260

Report Format :

Lump Sum / I.B.I. (\$

3,300/- 451

Veh No:

PLW 30830 Yr Regn: 101 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A/T/S

C.C. 1598

Colour

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

5025P

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH-104555249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

213/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

5/1/19

D.O.I.

11/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S 191

The UIC / Chassis frame / Body Structure affected due to collision.

- Pre repair inspection request - SLW3083C VS GT7135K (OI) DOA: 05/01/2019

From: Hor, Yinrul
To: Admin A (admin-a@lkkauto.com), 'assignments@lkkauto.com'
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur
Sent: 10/1/2019 2:37:18 PM
Attachments:  lmp284C1.tif

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**

Claim no : 8548844262SG003
Case Owner : KIAN MENG CHAN

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteopr.com]
Sent: Thursday, January 10, 2019 2:17 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur; Anthony Cheong
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GT7135K AND SLW3083C ON 05/01/2019

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-
Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA
Protocol.
Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

On Thu, Jan 10, 2019 at 1:56 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the
attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิด
ไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-01-17 13:56 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the
addressee. Please notify the sender if you have received this email in error or simply delete it.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: janice.kee@ksteoptr.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Imran.Ishak@aig.com, Aashweenjeetka
Subject: aigenrypt - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GT7135K AND SLW3083C ON 05/01/2019
Date: Thu, 10 Jan 2019 05:56:29 +0000
Without Prejudice

Your Reference : TKSF/M492-ACC-41398.19/sf(mc)
Our Reference : 8548844262SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviana)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteoptr.com]
Sent: Thursday, January 10, 2019 12:44 PM
To: Azlan, Syazairdina; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit
Cc: Anthony Cheong
Subject: Pre Repair Survey for SLW 3083 C (Your Ref: TKSF/M492-ACC-41398.19/sf)

Dear Sir

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

张景祥大律師樓
(律師兼公証及宣誓官)

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEBOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-41398.19/sf(mc)
Your Ref : GT 7135 K
Date : 10 January 2019

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16 Singapore 079120
Attn: Motor Claims Dept

WITHOUT PREJUDICE
BY PDX# 8181 & FAX 6835 7416 ONLY

Cc: Chia She Kim (Owner)
Blk 512 Ang Mo Kio Ave 8
#11-2524
Singapore 560512

BY POST ONLY
PDX Intercompany Exchange Pte Ltd



010808038138

FROM TEO KENG SIANG LLC
PDX Box No. 8902

Dear Sirs

RE: ACCIDENT INVOLVING SLW 3083 C / GT 7135 K ON 5/1/19 ALONG WHOLESALE CENTRE PASIR PANJANG CARPARK

We are instructed by Irene Wong Lee Ping to notify you of a road traffic accident on 5/1/19 at about 11:25 hours at ALONG WHOLESALE CENTRE PASIR PANJANG CARPARK involving our client's vehicle registration number SLW 3083 C and vehicle registration number GT 7135 K driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle SLW 3083 C is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,


M/s Teo Keng Siang LLC
encs

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8133H
Vehicle Details	
Vehicle No:	SLW3083C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No:	1ZRY320038
Chassis No:	MR053REH104555249
Maximum Power Output:	90.0kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	22 Nov 2016
First Registration Date:	22 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$19,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$14,992.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$41,388.00
Total Rebate Amount:	\$56,380.00

The information contained herein is correct as at 11 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2019 12:02
Date Of Accident	05/01/2019 11:25
Exact Location Of Accident	WHOLESALE CENTRE PASIR PANJANG CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW3083C
Insured/Policyholder	
Name Of Registered Owner	IRENE WONG LEE PING
NRIC No	S7288133H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81045155
Alternative Phone No	OFFICE-81045155

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098104856 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	YU LEK KEONG
NRIC No	S7439615A
Date Of Birth	21/11/1974
Occupation	OUTDOOR
Date Of Driving Pass	14/09/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81045155
Fax Number	
Contact Number	OFFICE-81045155
Email Address	NOEMAIL

Address	191 BOON LAY DRIVE #06-212
Postcode	S640191
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EX-WIFE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT7135K
Vehicle Make/Model/Colour	NISSAN CABSTAR
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok Street 23
 Singapore 659545
 Tel: 6530 3312 Fax: 6599 0722
 Email: vacbb@singnet.com.sg

- 5 JAN 2019


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Irene Wong Lee Ping
Blk 191 Boon Lay Drive
#06-212
Singapore 640191

Not Authorized
CL Ry 87
Resurvey After Pain
3 days

Vehicle No : SLW 3083 C
Make : Toyota Altis
Year : 2016

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s door assy		\$1,286.90 ✓
1 pc	Front o/s door weatherstrip		\$249.10 X
1 pc	Front o/s door frame black sticker		\$85.20 ✓
1 pc	Front o/s door inner trim board		\$655.10 X
1 pc	Front o/s door inner lock		\$539.70 X
1 pc	Front o/s door glass regulator		\$299.10 ?
1 pc	Front o/s door glass regulator motor		\$538.70 ?
2 pcs	Front o/s door hinge	\$85.10	\$170.20 X
1 pc	Front o/s door view mirror		\$1,187.60 ✓
1 pc	Front o/s door view mirror outer cover		\$86.70 ?
1 pc	Front o/s door glass		\$5,098.30
1 pc	Front o/s fender emblem		\$1,274.57
Less 25 %			\$3,823.73

Labour Charges

Remove/renew the above parts. Knock out & straighten n/s door centre pillar etc	\$800.00	3501
To putty & spray paint on accident affected portion.	\$800.00	5201
Check/reconnect wiring.	\$30.00	201
To spray anti rust on accident affected portion.	\$100.00	301
Remove/refit front & rear n/s door glass, mechanism, inner lock, trim board to new door.	\$180.00	601
Total	\$5,733.73	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

6,463,226

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Irene Wong Lee Ping
Blk 191 Boon Lay Drive
#06-212
Singapore 640191

Vehicle No : SLW 3083 C
Make : Toyota Altis
Year : 2016

Not Authorized
C/Ry 83300p
Preserving After Pain
3 days

Estimate Cost Of Repair

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	Front o/s door assy	\$1,286.90		
1 pc	Front o/s door weatherstrip	\$249.10		
1 pc	Front o/s door frame black sticker	\$85.20		
1 pc	Front o/s door inner trim board	\$655.10		
1 pc	Front o/s door inner lock	\$539.70		
1 pc	Front o/s door glass regulator	\$299.10		
1 pc	Front o/s door glass regulator motor	\$538.70		
2 pcs	Front o/s door hinge	\$170.20		
1 pc	Front o/s door view mirror	\$1,187.60		
1 pc	Front o/s door view mirror outer cover	\$86.70		
1 pc	Front o/s door glass	\$5,098.30		
1 pc	Front o/s fender emblems	\$1,274.57		
		\$3,823.73		
			\$4070.60	
			1017.65	
			3052.95	

Remove/renew the above parts. Knock out & straighten n/s door centre pillar etc

\$800.00 3501

To putty & spray paint on accident affected portion.

\$800.00 5201

Check/reconnect wiring.

\$30.00 201

To spray anti rust on accident affected portion.

\$100.00 301

Remove/refit front & rear n/s door glass, mechanism, inner lock, trim board to new door.

\$180.00 651

Total

\$5.733.73

6,46326

6903.05

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Irene Wong Lee Ping
Blk 191 Boon Lay Drive
#06-212
Singapore 640191

Vehicle No : SLW 3083 C
Make : Toyota Altis
Year : 2016

MR053R51410
4555249

Qty	Description	Unit Price	Amount
<u>Supplementary Part</u>			
1 pc	Front o/s door power window control switch ✓ 681.90	shon	\$972.70 ✓
		Less 25 %	\$243.17
			<u>\$729.53</u>

Hi Kenneth

Part - 3,052.95
Supplementary - 729.53
Labour - 980.00
4,762.48
Lump Sum ~~3,800.00~~ - 3 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19000630/KSD3N2

Date: 28/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No : SLW3083C Insured Vehicle No : GT7135K
 Date of Loss: 05/01/2019 Nature of Claim: TP Claim No: 8548844262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW3083C Engine No: 1ZRY320038
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Chassis No: MR053REH104555249
 Reg. Date: 22/11/2016 (Man. Year: 2016) Odometer: 50259 km
 Colour: Metallic Red
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,993.05	3,187.09	1,805.96	36.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	980.00	930.00	48.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,903.05	4,167.09	2,735.96	39.63
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	6,903.05	3,300.00	3,603.05	52.20

INSPECTION

Date of Assignment: 10/01/2019
 Date Inspected: 11/01/2019 Inspected At: Massive Trading & Auto
 Blk 5038 #01-405, Ang Mo Kio Industrial
 Pk 2
 Singapore 569541
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR ASSY	Bent	1,286.90 FL	*1,079.60 FL
2	1		*FRONT O/S DOOR WEATHERSTRIP	Serviceable	249.10 FL	*- FL
3	1		*FRONT O/S DOOR FRAME BLACK STICKER	Necessary	85.20 FL	*85.20 FL
4	1		*FRONT O/S DOOR INNER TRIM BOARD	Serviceable	655.10 FL	*- FL
5	1		*FRONT O/S DOOR INNER LOCK	Repair	539.70 FL	*- FL
6	1		*FRONT O/S DOOR GLASS REGULATOR	Distorted	299.10 FL	*198.40 FL
7	1		*FRONT O/S DOOR GLASS REGULATOR MOTOR	Jammed	538.70 FL	*538.70 FL
8	2		*FRONT O/S DOOR HINGE	Repair	170.20 FL	*- FL
9	1		*FRONT O/S DOOR VIEW MIRROR	Broken	1,187.60 FL	*1,128.35 FL
10	1		*FRONT O/S DOOR VIEW MIRROR OUTER COVER	Cracked	86.70 FL	*86.70 FL
11	1		*FRONT O/S DOOR GLASS	Cut	550.70 FL	*414.90 FL
12	1		*FRONT O/S FENDER EMBLEM	Necessary	35.70 FL	*35.70 FL
13	1		*FRONT O/S DOOR POWER WINDOW CONTROL SWITCH	Shorted	972.70 FL	*681.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,657.40	4,249.45
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,664.35	1,062.36
Total Parts (\$\$)	4,993.05	3,187.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS,KNOCK OUT & STRAIGHTEN N/S DOOR CENTRE PILLAR ETC	New	800.00	350.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	800.00	520.00
3	CHECK/RECONNECT WIRING	New	30.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	100.00	30.00
5	REMOVE/REFIT FRONT & REAR N/S DOOR GLASS,MECHANISM,INNER LOCK,TRIM BOARD TO NEW DOOR	New	180.00	60.00
Gross Labour Cost (S\$)			1,910.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >