

ASS. REC. BY:

REF:

CS/AGI19000638/Uqd3

n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Justin Wong

of

AGI

Date/Time:

10/11/19 @ 4:52pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGK 4064Z

Insured:

SKF 408X

at Workshop m/s:

Focus Auto

Tel:

68869097

of

1 Kaki Bukit Ave 6 # 02-50 Autobay

Policy No.:

Claim No.:

C10002988

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/01/2019

CA / REV / REP. / REV 24 HRS

lup

11/11/19

H.O.D. Endorsement:

Date/Time:

5:19pm @ 10/11/19

Person Contacted:

MS-Sin

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SGK 4064Z-X

SKF 408X-X

REF: AGI

## ASSIGNMENT

From: Date: 11/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGK 4064Z

at Workshop n/s: Focus Auto

of 1 kaki Bukit Ave 6 #02-50

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After 9am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 14500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up' 30/6/2019

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGK 4064Z Yt Regn: 8.06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or 4A1

Make: Toyota Vios C.C. 1497

Colour: 3lock A/C: Insured / Std / NI / NA

Sp. Reading: 206196 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO53H4Y4204197311

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

Rear R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 7/1/19 D.O.I. 11/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2 yrs 6 mths. LTA 11570

12/1/19 2/5 22000 confirmed with MR Wong (Lump \$1605.76, 45%)

RECEIVED 14 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) 14/1 by MR Wong

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$)

Transportation:

☐ : Interview (\$)

) \$ + RS \$

Report Format: 7P

☐ : Tech. Invs (\$)

) Photos

Lump Sum / I.B.I. (\$) 2000

☐ : Weekend (\$)

) Others

250

TOTAL

## Nivitha (LKK Auto)

---

**From:** Justin Wong <justin.wong@budgetdirect.com.sg>  
**Sent:** Thursday, 10 January 2019 4:52 PM  
**To:** assignments@lkkauto.com  
**Cc:** sur@lkkauto.com; Albert Hong  
**Subject:** Appoint LKK to conduct TP survey; Our Ref: C10002488

**Importance:** High

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Mr. Marcus Chua was chosen

Thank you.

**Justin Wong**  
**Executive, Claims**

T +65 6540 2184  
F +65 6725 0853  
E [justin.wong@budgetdirect.com.sg](mailto:justin.wong@budgetdirect.com.sg)

**Budget  
Direct**  
insurance



**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01  
Singapore Shopping Centre  
Singapore  
239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

---

**From:** Focus Auto <focus.autopteltd@yahoo.com.sg>  
**Sent:** Thursday, 10 January 2019 4:43 PM  
**To:** Claims <claims@budgetdirect.com.sg>; Justin Wong <justin.wong@budgetdirect.com.sg>

Cc: Albert Hong <albert.hong@budgetdirect.com.sg>

Subject: Re: ACCIDENT INVOLVING SGK 4064 Z, SKZ 9288 K, SGJ 7236 E & SKF 408 X ON 07/01/19 ALONG JURONG TOWN HALL RD AT ABOUT 1700 HOUR; Our Ref: C10002488

Hi Justin,

We refer to above email. Please send surveyor come down to survey the vehicle SGK 4064 Z

Thank you.

Best Regards,  
Ms Sin

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

On Wednesday, 9 January 2019 11:44:06 AM +08, Focus Auto <[focus.autopteltd@yahoo.com.sg](mailto:focus.autopteltd@yahoo.com.sg)> wrote:

Dear Justin,

Thank you for your email.

Kindly be inform that we choose 6. Marcus Chua LKK Auto Consultants Pte Ltd.

Thank you.

Best Regards,  
Ms Sin

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

On Wednesday, 9 January 2019 10:22:47 AM +08, Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)> wrote:

**Without Prejudice**

Dear Ms Sin,

We refer to your Notice of Accident dated 08/01/2019.

We propose to use one of the motor surveyors named in the list below to conduct the pre-repair survey.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Kenneth Kong LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Marcus Chua LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Kenji Tan FormTeam Adjusters Pte Ltd
13. Derrick Quok – In house Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you.

Regards,

**Justin Wong**

**Executive, Claims**

T +65 6540 2184

F +65 6725 0853

E [Justin.wong@budgetdirect.com.sg](mailto:Justin.wong@budgetdirect.com.sg)



**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore 239924

[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

---

**From:** Focus Auto <[focus.autopteltd@yahoo.com.sg](mailto:focus.autopteltd@yahoo.com.sg)>

**Sent:** Tuesday, 8 January 2019 4:40 PM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>

**Subject:** ACCIDENT INVOLVING SGK 4064 Z, SKZ 9288 K, SGJ 7236 E & SKF 408 X ON 07/01/19 ALONG JURONG TOWN HALL RD AT ABOUT 1700 HOUR

Dear Officer-In-Charge,

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 07/01/19 at about 1700 hours along ALONG JURONG TOWN HALL RD involving our client's SGK 4064 Z and SKF 408 X driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : FOCUS AUTO PTE LTD

Address: No.1 Kaki Bukit Ave 6  
AutoBay #02-50  
Singapore 417883

Telephone no. : 6886 9097

Best Regards,  
Ms Sin

**Focus Auto Pte Ltd**

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



## ANNOUNCING BENEFIT AUTO

as sgCarMart Premium Dealer for the 5<sup>th</sup> Consecutive Year

BENEFIT

VIOS

Price Range ▼

Depreciation ▼

&gt; 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » Mutual Concept Motoring Pte Ltd » Toyota Vios 1.5A E (COE till 06/2021)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



## Toyota Vios 1.5A E (COE till 06/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

**Price** \$17,999**Depreciation** \$7,320 /yr**Reg Date** 13-Jul-2006  
(2yrs 5mths 16days COE left)**Manufactured** 2006**Mileage** 142,019 km (11.3k /yr)**Transmission** Auto**Engine Cap** 1,497 cc**Road Tax** \$889 /yr**Power** 80.0 kW (107 bhp)  
View specs of the Toyota Vios (2003-2007)**Curb Weight** 1,020 kg**Features** Original Condition.**Accessories** Factory Fitted Interior.**Description** Only 2 Owners Unit. Major Wear And Tear Are Already Replaced For The Next Owner. Tip Top Condition And Low Fuel Consumption Unit. Extremely Good Deal As It Can Be Used For 30 Months At Such Attractive Pricing. Easier To Have A Resale Value In Future. Bank Loan Service Is Available Here. Viewing Till 9pm Daily.**COE** \$23,227**OMV** \$12,707**ARF** \$13,978**Dereg Value** \$11,429 as of today (change)**No. of Owners** 2**Type of Veh** Mid-Sized Sedan**Category** COE Car, Premium Ad Car**Availability** Available

PREMIUM AD

Compare

Add to Shortlist

Add to Compare

Add a Note



## Seller Information

**Company** Mutual Concept Motoring Pte Ltd  
» dealer  
» 27 years experience

**Address** 154 Hoon Street, Singapore

**Contact Person(s)** Benny

## Useful Services

Afraid of lerr



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

5916H

### Vehicle Details

Vehicle No.:

SGK4064Z

Vehicle to be Exported:

No

Intended Deregistration Date:

08 Jan 2019

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS 1.5E A

Primary Colour:

Black

Manufacturing Year:

2006

Engine No.:

1NZX457743

Chassis No.:

MR053HY4204197311

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$12,347.00

Original Registration Date:

11 Aug 2006

First Registration Date:

11 Aug 2006

Transfer Count:

2

Actual ARF Paid:

\$7,480.00

### Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

### Intended COE Rebate Details

COE Expiry Date:

30 Jun 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$23,227.00

COE Rebate Amount:

\$11,510.00

**Total Rebate Amount:**

**\$11,510.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jan 2019

OK

MSME19003536 / SME Mixor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 08/01/2019 17:35  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 08/01/2019 17:35  
 Date Of Accident 07/01/2019 17:00  
 Exact Location Of Accident ALONG JURONG TOWN HALL RD  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SGK4064Z  
**Insured/Policyholder**  
 Name Of Registered Owner TOH DE WEI DAREN  
 NRIC No S9125916H  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-93385763  
 Alternative Phone No OFFICE-93385763

## Vehicle Particulars

Manufacturer TOYOTA  
 Model VIOS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number P10078851R00  
 Cover Note Number

## Driver

Name of Driver TOH DE WEI DAREN  
 NRIC No S9125916H  
 Date Of Birth 30/07/1991  
 Occupation INDOOR  
 Date Of Driving Pass 18/10/2013  
 Driving Experience 5 YEARS AND 2 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-93385763  
 Fax Number  
 Contact Number OFFICE-93385763  
 Email Address NOEMAIL

Address BLK 317 SEMBAWANG VISTA #10-205  
 Postcode 750317  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 4  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station.  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 07/01/2019 AT ABOUT 5PM, I WAS DRIVING MY VEHICLE (SGK4064Z) ALONG JURONG TOWN HALL ROAD. IN FRONT OF MY VEHICLE SUDDENLY STOP. I ALSO STOP IN TIME. SUDDENLY, VEHICLE B FROM BEHIND OF MY VEHICLE HIT ONTO MY VEHICLE REAR PORTION. AFTER I GO DOWN TO CHECK, THEN I REALISED HAVE 2 MORE VEHICLES WHICH IS VEHICLE C AND VEHICLE D INVOLVING TOGETHER.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKF408X  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver SHAJAHAN BASHEEN  
 NRIC/Passport Number S7461526J  
 Contact Number 94891490  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SKZ9288K
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	CHEW ZI HAO
NRIC/Passport Number	S9007834H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


**DETAILS OF OTHER VEHICLE PROPERTY 3**


Vehicle Registration Number	SGJ7236E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE D
Vehicle Category	PRIVATE CAR
Name of Driver	SHAKTHI PRIYA
NRIC/Passport Number	S7276155C
Contact Number	92967074
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
Understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form], and any other personal information provided by me, in possession by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.

## Sketch Plan #2 Pg. 1



Veh. A = SGK4064Z

Veh. B = 3KF 408X

Veh. C = 3KZ 9288K

Veh. D = 3GJ 7236E

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/01/19 time about 5.00pm, I was driving my vehicle SGK4064Z along Jurong Town Hall Road in front of my vehicle suddenly stop, I also stop in time, suddenly vehicle B from behind of my vehicle hit onto my vehicle rear portion. After I go down to check then I realise have 2 more vehicle which is Veh C & vehicle D involving together.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopetd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

M/S : BUDGET DIRECT INSURANCE

ATTN: Motor Claim Department  
Your Ref No: SGK4064Z  
Claim Type: Third Party  
Accident Date: 07-01-2019  
TP Veh Reg No: SKF408X

Estimate No: EST0000789  
Date: 08 Jan 2019  
Policy No: P10078851R00  
Veh Reg No: SGK4064Z  
Make/Model: TOYOTA VIOS 1.5E A  
Chassis No: MR053HY4204197311  
Engine No: 1NZX457743  
Reg. Date: 11-08-2006

## Estimate Repair Cost to Vehicle No :SGK4064Z

PAGE: 1/1

Description	U/Price	Quantity	List Price SS	Amount SS
TOYOTA VIOS 1.5E A				
<b>List Price</b>				
1 Rear Boot	492.9000	1 PC	492.90	X
2 Rear Boot Lock	68.5000	1 PC	68.50	X
3 Rear Boot Rubber	58.2000	1 PC	58.20	X
4 Rear Boot Emblem (1.5E)	18.5000	1 PC	18.50	/
5 Rear Boot Emblem (Wfi)	30.9000	1 PC	30.90	/
6 Rear Boot Emblem (Vios)	16.3000	1 PC	16.30	/
7 Rear Boot Centre Logo	32.2000	1 PC	32.20	/
8 Rear End Panel	572.4000	1 PC	572.40	/
9 Rear End Panel Top Garnish	78.2000	1 PC	78.20	X
10 Rear Tail Lamp LH	348.9000	1 PC	348.90	/
11 Rear Bumper	398.4000	1 PC	398.40	/
12 Rear Bumper Lower Clipse	5.5000	1 PC	5.50	/
13 Rear Bumper Side Retainer LH	19.4000	1 PC	19.40	/
			2,140.30	
	Less 25%		535.08	1,605.22
				23
<b>Labour</b>				
14 Panel Beating	950.0000	1 PC	950.00	600
15 Check Wiring	60.0000	1 PC	60.00	20
16 Rust Proofing	60.0000	1 PC	60.00	30
17 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
18 Spray Painting	850.0000	1 PC	850.00	720
			2,000.00	2,000.00
			Total	SS 3,605.22
				23

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED AND FIVE AND CENTS TWENTY SIX ONLY

- To ensure a safe and secure repair
- To ensure damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No towed or modified vehicle is allowed
- Supply of parts must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For FOCUS AUTO PTE LTD  
Focus Auto Pte Ltd  
No 1 Kaki Bukit Ave 6 Auto Bay  
#02-50 Singapore 417883  
Tel: 6841 9095  
AUTHORISED SIGNATURE

P-1442-10  
1081-87  
2501-87



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19000638/Uqd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 15-01-2019



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 408X	Veh. Inspected	SGK 4064Z
Policy No.		Coverage (\$)	0.00
Claim No.	C10002488	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	10/01/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053HY4204197311	Colour	BLACK
Odometer	206196	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/50 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/50 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/50 R15	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	07/01/2019	Inspection Date	11/01/2019
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 4064Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT	TO REPAIR SEE LABOUR	492.90	-
1	REAR BOOT LOCK	NOT NECESSARY	68.50	-
1	REAR BOOT RUBBER	NOT NECESSARY	58.20	-
1	REAR BOOT EMBLEM (1.5E)	NECESSARY	18.50	18.50
1	REAR BOOT EMBLEM (W FI)	NECESSARY	30.90	30.90
1	REAR BOOT EMBLEM (VIOS)	NECESSARY	16.30	16.30
1	REAR BOOT CENTRE LOGO	NECESSARY	32.20	32.20
1	REAR END PANEL	DENTED	572.40	572.40
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	78.20	-
1	REAR TAIL LAMP LH	CRACKED	348.90	348.90
1	REAR BUMPER	DENTED / DEFORMED	398.40	398.40
1	REAR BUMPER LOWER CLIPS	NECESSARY	5.50	5.50
1	REAR BUMPER SIDE RETAINER LH	BENT	19.40	19.40
	LESS 25% DISCOUNT		-535.07	-360.62
			1,605.23	1,081.88
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOT.		950.00	600.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.		60.00	30.00
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00
	SPRAY PAINTING.		850.00	720.00
			2,000.00	1,420.00
<b>GRAND TOTAL</b>			<b>3,605.23</b>	<b>2,501.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,000.00</b>

Report Ref No. CS/AGI19000638/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.