

Surveyor

Taylor

REF:

AIG 645112A3 (2)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

846K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SKJ 37286, Yr Regn: 2013 / March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Volkswagen Golf

C.C

1395

Colour: _____

Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

87736

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

www z z z 44 z dw 080958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205 / 55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

D.O.I. _____

14/1/19 @ 1030.

Survey held at _____

VW Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Email w/ Repair Limit \$3500.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5897D
Vehicle Details	
Vehicle No.:	SKJ3728G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT BMT 5G13GZ
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	CMB120315
Chassis No.:	WVWZZZAUZDW080958
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,921.00
Original Registration Date:	26 Mar 2013
First Registration Date:	26 Mar 2013
Transfer Count:	0
Actual ARF Paid:	\$5,921.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2023
PARF Rebate Amount:	\$4,144.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$91,010.00
COE Rebate Amount:	\$38,165.00
Total Rebate Amount:	\$42,309.00

The information contained herein is correct as at 15 Jan 2019

OK