

ASS. REC. BY:

REF

CS3/MSG19000661/Jcd3

Special Instruction:

Surveyor

Menmen

From (Person):

Estimated Cost:

ASSIGNMENT (Office)

of

M81G

Date/Time:

11/11/19 @ 9.45am

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 314G

Insured:

SJA 881R

at Workshop m/s:

Hwei Peng Auto

Tel:

9688 5655

of

70 woodlands Ind. Park E9

Policy No:

B27464297SMP

Claim No:

581762

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/01/2019

CA / REV / REP. / REV 24 HRS

6up

H.O.D. Endorsement:

Date/Time:

10.27am @ 11/1/19

Person Contacted:

Francis

Vehicle IN

(OUT)

Date/Time

Action/Instruction

(4)

Estimate

SJR 314G-X

SJA 881R-CS/MSG18000164/R1/bn2

DUA: 27/12/2012

Demantle: 16/1/2019.

After repair: 18/1/2019

Hwee Jie
PRS

REF:

MSG

ASSIGNMENT

From: Date: 16/1

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR314G

at Workshop m/s: Hua Peng Auto

of 70 Woodlands Ind. PR

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJR314G

Yr Regn: 4 Jun 2009

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima

C.C. 2362

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 220589

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ACR500084159

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: -

BS: ☒ SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 6/1/2019.

D.O.I: 16/1/19

Survey held at

Hua Peng

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS.

Range: \$5,500-\$6,500
6 days

[Signature]
22/1/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$+RS \$

Photos:

Other:

TOTAL

Report Format: PRS.

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2019		11 Jan 2019 09:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	MAI JU LE, ID: S2552782H, Tel: +6597548196, Email: JULE.MAI2@GMAIL.COM		
Main Claimant:	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: 201320430G		
Vehicle Reg. No.:	SJR314G	Date of Loss:	06/01/2019 20:00 - :59 [115 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 581762	Policy/Cover Note No.:	B27464297SMP (Comprehensive) Coverage: 31/01/2018 - 30/01/2019
Vehicle Reg. No. (Insured):	SJQ881R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2019]		
Driver/Custodian (Insured):	MAI JU LE (56 / Female), NRIC: S2552782H, Tel: +6597548196		
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO to conduct the survey . Kindly contact MR FRANCIS @ 9688 5655 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2019 16:59
Date Of Accident	06/01/2019 20:15
Exact Location Of Accident	ALONG PIONEER ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR314G
Insured/Policyholder	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	201320430G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88336125

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5095694657-01
Cover Note Number	

Driver

Name of Driver	SARIMAH BINTE SHRIFF
NRIC No	S7250514Z
Date Of Birth	25/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88336125
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 19 TECK WHYE LANE #07-35
Postcode	680019
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	7
Passenger 1	NAME: : JAMIAH BINTE MOHAMAD GENDER: : FEMALE
Passenger 2	NAME: : JURAIZAH BINTE WASARIP GENDER: : FEMALE
Passenger 3	NAME: : NA GENDER: : FEMALE
Passenger 4	NAME: : NA GENDER: : MALE
Passenger 5	NAME: : NA GENDER: : MALE
Passenger 6	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJQ881R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver MAI JU-LE
NRIC/Passport Number
Contact Number 97548196
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name JAMIAH BINTE MOHAMAD
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SJR314G
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name JURAIZAH BINTE WASARIP
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SJR314G
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name SARIMAH BINTE SHARIFF
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SJR314G
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance?
Address
Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



A: SJR 3144
B: SJQ 881R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190108/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20190108/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/01/2019 12:45		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: SARIMAH BINTE SHARIFF			Address: APT BLK 19 TECK WHYE LANE #07-35 SINGAPORE 680019		
ID Type / ID No.: NRIC NO / S7250514Z			Contact No.: Home/Office: Mobile: 88336125		
Nationality: SINGAPORE CITIZEN			Email: sarimah2572@gmail.com		
Sex: Female	Age: 46	Date of Birth: 25/03/1972	Type of Informant: Driver		
Race: Boyanese			Language: English		Institution / School Name:
Occupation: Grab Driver			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/01/2019 20:15	Type of Location: Straight Road
Location: Pioneer Road North				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ881R	Car	BMW		White	Slightly Damaged	1
SJR314G	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190108/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 4
Report No. T/20190108/7009

CONTINUATION OF REPORT

Driver			
Name	SARIMAH BINTE SHARIFF	ID No.	S7250514Z
Related Vehicle	SJR314G (Car)	Contact No.	88336125
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Juraizah Binte Wasarip	ID No.	S7418379D
Related Vehicle	SJR314G (Car)	Contact No.	81272004
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/01/2019	Date Discharge	07/01/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Passenger			
Name	Jamiah Bibte Mohamad	ID No.	S14022273B
Related Vehicle	SJR314G (Car)	Contact No.	94598496
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	07/01/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

I was driving along PIE Changi, exiting at Pioneer. I turned right to the main road and saw a taxi. The taxi was exiting at Pioneer from the PIE Tuas to enter the same main road. It was out of its lane so I gave way to it in order not to hit it. Once it passed me, I followed through. A car behind me came from the same lane as the taxi and hit my car

After the accident, the driver of the car told me she was checking her right side, assuming that I already passed through. So without confirming whether I have passed through, she just drove in. That's when she hit the left rear side of my car which was carrying six passengers during the accident. When we were filing this report, two of my passenger Mdm Jamiah Binte Mohamad I/C No. S1402273B, Mdm Juraizah Binte Wasarip I/C No. S7418379D and I already went to the hospital for check up and was given 5-days MC each.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190108/7009

3 of 4

Report No. T/20190108/7009

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190108/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20190108/7009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65472076

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
08/01/2019 12:45

Classification Of Case:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0430G
Vehicle Details	
Vehicle No.:	SJR314G
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	2AZF225937
Chassis No.:	ACR500084759
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,167.00
Original Registration Date:	04 Jun 2009
First Registration Date:	04 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$35,167.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jun 2019
PARF Rebate Amount:	\$17,583.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$12,901.00
COE Rebate Amount:	\$450.00
Total Rebate Amount:	\$18,033.00

The information contained herein is correct as at 17 Jan 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2019		11 Jan 2019 09:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MAI JU LE, ID: S2552782H, Tel: +6597548196, Email: JULE.MAI2@GMAIL.COM		
Main Claimant:	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: 201320430G		
Vehicle Reg. No.:	SJR314G	Date of Loss:	06/01/2019 20:00 - :59 [115 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 581762	Policy/Cover Note No.:	B27464297SMP (Comprehensive) Coverage: 31/01/2018 - 30/01/2019
Vehicle Reg. No. (Insured):	SJQ881R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 12/01/2019]		
Driver/Custodian (Insured):	MAI JU LE (56 / Female), NRIC: S2552782H, Tel: +6597548196		
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO to conduct the survey . Kindly contact MR FRANCIS @ 9688 5655 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR314G (581762)

[SJQ881R]

TP

TW PREMIUM AUTOMOBILE PTE LTD























Jan 6 2019 8:00PM

[MAI JU LE]

Hwa Peng Auto Service (1996)

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/01/19 09:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	17/01/19 09:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	21/01/19 09:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	21/01/19 09:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	21/01/19 09:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
36	21/01/19 09:17	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
37	21/01/19 09:17	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
38	21/01/19 09:17	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	09/01/19 13:11	OI SJQ881R GIA REPORT		Load PDF
2	09/01/19 13:11	TPD SJR341G GIA REPORT		Load PDF
3	10/01/19 17:06	TPD SJR314G - PRI		Load PDF
4	10/01/19 17:06	Reject email to TP Lawyer & appoint LKK		Load PDF
5	21/01/19 15:03	OI's police report- only 2 persons from 3P car		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19000661/JCD3S2

Date: 23/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27464297SMP

Claimant Vehicle No : SJR314G

Insured Vehicle No : SJQ881R

Date of Loss: 06/01/2019

Nature of Claim: TP

Claim No: 581762

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR314G**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZF225937

Reg. Date: 04/06/2009 (Man. Year: 2008)

Chassis No: ACR500084759

Colour: Silver

Odometer: 220589 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/01/2019

Date Inspected: 16/01/2019 Inspected At:

Hwa Peng Auto Service (1996) (HQ)
70 WOODLANDS INDUSTRIAL PARK E9
Singapore 757836

Estimated Period of Repair: 6.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 - \$6,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2019)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR314G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >