

ASS. REC. BY:

REF:

CS/CT119000665/Avd37

Special Instruction:

Surveyor
Menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

10/1/2019

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDP 709 H

Insured:

YN 7041R

at Workshop m/s

Vision Autowork

Tel:

9856 4815

of

8 Jalan Bukit Ane 4 #08-09 premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

07/01/2019

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

9:21am @ 11/1/19

Person Contacted:

Michelle

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SDP 709 H - X

YN 7041R - X

4/4/19

Adrian confirmed LS \$6300 (Red 16,496.48, 729)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SDP709H.

Yr Regn: 2006 April

Type: ☒ M.Cap / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey.

c.c 2354

Colour:

Purple.

A/C

Insured / Std / NI / NA

Sp Reading:

119271

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRB18406C202118

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16 Goodrich

R: 215/60R16 Sumitomo.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodrich

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/01/19.

Survey held at

Visser.

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim.

COE Expiry: 25/04/19.

MV: 18K.

PV: 10.8K.

Nett: 7.2K.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 5/4 - typist

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ - RS. \$

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

6300/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		10 Jan 2019 17:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	AUNG PYE TUN, ID: S8277370C		
Vehicle Reg. No.:	SDP709H	Date of Loss:	07/01/2019 16:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	YN7041R	Policy No. (Claimant):	DMPC18S003165
		Excess:	S\$0.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details

Owner ID Type:	Singapore NRIC
Owner ID:	7370C

Vehicle Details

Vehicle No.:	SDP709H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSEY 2.4A
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	K24A63002118
Chassis No.:	JHMRB18406C202118
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$26,469.00
Original Registration Date:	26 Apr 2006
First Registration Date:	26 Apr 2006
Transfer Count:	3
Actual ARF Paid:	\$29,116.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$23,725.00
COE Rebate Amount:	\$10,821.00
Total Rebate Amount:	\$10,821.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.


The information contained herein is correct as at 14 Jan 2019.

OK

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

[SELL YOUR CAR](#)


FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

BMW X4 XDrive28i X Line @ \$142300.

Low Mileage, Full Pmt Service
Record, High Aft.
Hamilton Auction Pro StarAd



HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category  Save Search  Print

Sort by Date Posted  20 results/page 

12 vehicles | **Search** [Advanced Search](#) [Search](#) [View All](#)


Make  **Model**  **Price**  **Depreciation**  **Reg Date**  **Eng Cap**  **Mileage**  **Veh Type**  **Status** 

Search Selection



☐ **Honda Odyssey 2.4A (COE till 11/2020)** **\$19,500** **\$10,440 /yr** **24-Nov-2005** **2,354 cc** **-** **MPV** **Available**


Good For Short Term Drive. Owner Upgrading. Extremely Ideal Car For Family For 7. Perfect Condition And Well Maintained With Regular Servicing. Trade In Welcome. Please Call For Viewing. No Obligation...

 Posted: 16-Nov-2018 Tags: 2005 Honda Odyssey, 2005 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

[DIRECT OWNER](#)


☐ **Honda Odyssey 2.4A (COE till 02/2021)** **\$13,900** **\$6,740 /yr** **03-Feb-2006** **2,354 cc** **-** **MPV** **Available**

1 Owner, Good For Short Term Usage. Cheaper Than Rental, Scrap Now Is Already \$12k, Dealer And Exporter Welcome.

 Posted: 05-Jan-2019 Tags: 2006 Honda Odyssey, 2006 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



☐ **Honda Odyssey 2.4A Absolute (COE till 07/2021)** **\$28,000** **\$10,970 /yr** **25-Aug-2006** **2,354 cc** **-** **MPV** **Available**

Vehicle Is Well Maint. And Timely Servicing Carried Out With All Invoices. Both Engine And Transmission In Good Working Condition. Both Engine And Transmission Oil Changed Every Servicing Carried Out....

 Posted: 20-Nov-2018 Tags: 2006 Honda Odyssey, 2006 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

[DIRECT OWNER](#)


☐ **Honda Odyssey 2.4A (COE till 07/2026)** **\$44,800** **\$5,930 /yr** **28-Sep-2006** **2,354 cc** **-** **MPV** **Available**

Very Well Maintained, Auto Transmission Changed Last Year, Leather Is Nice, Good To Drive, Actual 2nd Owner Due To Renewal Of COE, First Owner Is Friend, History Of Car Can Be Traced. Price Negotiable...

 Posted: 03-Jan-2019 Tags: 2006 Honda Odyssey, 2006 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

[DIRECT OWNER](#)

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Honda Odyssey 2.4A Absolute (COE till 06/2021)** **\$20,800** **\$8,430 /yr** **10-Jan-2007** **2,354 cc** **154,516 km** **MPV** **Available**

Loan As High As 0% Down Payment With 3.98% - 4.25% Lowest Interest Guaranteed. One Of The Popular Best Selling Japanese Mpv. 1 To 1 Exchange With High Trade In Value Available.

 Posted: 03-Jan-2019 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

[PREMIUM AD](#)


☐ **Honda Odyssey 2.4A Absolute (COE till 03/2022)** **\$25,800** **\$8,010 /yr** **02-Apr-2007** **2,354 cc** **122,000 km** **MPV** **Available**

"One Year In-House Warranty", Full Loan Available. Price Stated Above Is Actual Selling Price, Bank And In-House Loan Available, Purchase With Official Warranty Certificate With A Peace Of Mind, Fully...

Carway

 Posted: 07-Jan-2019 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

SHOWRELATED HISTORY

[Compare](#) 

☐ **Honda Odyssey 2.4A (COE till 04/2022)** **\$34,500** **\$10,450 /yr** **03-May-2007** **2,354 cc** **155,000 km** **MPV** **Available**

[DIRECT OWNER](#)



Complete Overhaul Done On Car. Responsive And Smooth Engine. Gearbox Is Still Under Warranty Till Date After Overhaul. Full Sound System Installed With Additional Pioneer Subwoofers, Amplifier And Two...

★ Posted: 21-Oct-2018 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



📦 **Honda Odyssey 2.4A Absolute (COE till 10/2027)** **\$59,888** **\$6,830 /yr** **17-Oct-2007** **2,354 cc** **160,000 km** **MPV** **Available**

Major Servicing Completed 12 Months Ago-New Engine Mounts, Radiator And Hoses, Cylinder Head And Spark Plug Seats, Spark Plugs, Alternator, Imported 42k Mileage Gearbox, HKS Hybrid Filter, Mugen Sport...

Direct Owner

★ Posted: 13-Dec-2018 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



📦 **Honda Odyssey 2.4A Absolute (COE till 08/2022)** **\$33,900** **\$9,320 /yr** **24-Oct-2007** **2,354 cc** **90,000 km** **MPV** **Available**

Stunning White Odyssey! Absolute Model! Only 2 Owners! Ultra Low Documented Mileage! This MPV Boasts Amazing Overall Condition! View/Test To Affirm This Claim! Many Parts Changed With Papers To Show! ...

★ Posted: 25-Nov-2018 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



📦 **Honda Odyssey 2.4A Sunroof (COE till 11/2027)** **\$58,800** **\$6,670 /yr** **05-Nov-2007** **2,354 cc** **205,220 km** **MPV** **Available**

A Very Spacious Family Car That Can Accommodate A Large Family. Looking For A Smaller Car. Massive Boot Space. Comes With \$800 Plus Worth Of Solar Film That Reduces Up To 99% Of IR And UV Rays. More T...

Owner/Driver

Prem Ray Motoring

★ Posted: 21-Nov-2018 Tags: 2007 Honda Odyssey, 2007 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



📦 **Honda Odyssey 2.4A (COE till 11/2027)** **\$52,888** **\$5,950 /yr** **22-Jan-2008** **2,354 cc** **114,000 km** **MPV** **Available**

Black Honda Odyssey From Kah Motors. Black Leather Interior. Shelter Parking. Accident-Free. Low Mileage. Original Honda Shocks Changed In 2015. Power Steering O Rings Changed. Serviced Every 10k Km. ...

Direct Owner

★ Posted: 11-Dec-2018 Tags: 2008 Honda Odyssey, 2008 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



📦 **Honda Odyssey 2.4A Sunroof (New 10-yr COE)** **\$53,800** **\$5,380 /yr** **19-Dec-2008** **2,354 cc** **133,000 km** **MPV** **Available**

AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By One Owner Only! 100% Accident Free! Regular Servicing And Maintained By Reputable Japanese Workshop! Spacious Seats Which Prov...

Previous Owner

AA Trust Automotive

★ Posted: 07-Jan-2019 Tags: 2008 Honda Odyssey, 2008 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, motor cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & QPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used odyssey Singapore, used odyssey Singapore, used odyssey, used vehicles Singapore or even buy used odyssey Singapore. You have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussions, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/01/2019 12:18
Date Of Accident	07/01/2019 16:10
Exact Location Of Accident	PIE TOWARDS JURONG (BEF STEVENS ROAD EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDP709H
Insured/Policyholder	
Name Of Registered Owner	AUNG PYE TUN
NRIC No	S8277370C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98596202
Alternative Phone No	OTHERS-97301109
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY 2.4A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC18S003165
Cover Note Number	
Driver	
Name of Driver	ANDERSON NEVILLE ANTONY
NRIC No	G5914748Q
Date Of Birth	21/04/1962
Occupation	INDOOR
Date Of Driving Pass	19/07/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97301190
Fax Number	
Contact Number	
EMail Address	NEV@DR.COM

Address	5A HOLLAND HILL #04-00
Postcode	278730
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7041R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A = SDP 709 H

B = JN 7041 R

PIE towards Jurong
(Before Stevens Road Exit)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Al Tan

Policyholder's Signature
Date & Time:

Wah

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

On 07.01.19 at about 16:10 hours along PIE towards Jurong (Before Stevens Road Exit). I was travelling straight on the lane 2, suddenly vehicle (B) from my left cut into my lane and collided onto left hand side portion of my vehicle (A).

Vehicle (A): SDP 709H

Vehicle (B): YN 7041R

Old
AP 101

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 12.01.19

TO : CHINA TAIPING MOTOR CLAIMS DEPTS

VEHICLE NO : SDP709H

MODEL : HONDA ODYSSEY

DATE OF ACCIDENT : 07.01.19

TIME OF ACCIDENT : 16:10HRS

JHMRB18406C202118

Veron.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE MIRROR RH <i>cracked</i>	1	\$ 798.70	\$ 798.70
2	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 168.00	\$ 168.00
3	FRONT DOOR PILLAR RH <i>Repair</i>	1	\$ 875.30	\$ 875.30
4	FRONT DOOR PILLAR QUARTER GLASS WITH MOULDING RH <i>new</i>	1	\$ 320.00	\$ 320.00
5	FRONT DOOR RH <i>cracked</i>	1	\$ 971.70	\$ 971.70
6	FRONT DOOR BLACK STICKER RH <i>new</i>	1	\$ 106.20	\$ 106.20
7	FRONT DOOR HINGE (UPPER) RH <i>3rd</i>	1	\$ 38.00	\$ 38.00
8	FRONT DOOR HINGE (LOWER) RH <i>2nd</i>	1	\$ 38.00	\$ 38.00
9	FRONT DOOR INNER LOCK RH <i>2nd</i>	1	\$ 483.10	\$ 483.10
10	FRONT DOOR INNER TRIM RH <i>cracked</i>	1	\$ 892.60	\$ 892.60
11	FRONT DOOR LOCK CATCHER RH <i>new</i>	1	\$ 42.10	\$ 42.10
12	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 133.40	\$ 133.40
13	FRONT DOOR MOULDING RH <i>cut</i>	1	\$ 149.90	\$ 149.90
14	FRONT DOOR OUTER STRIP RH <i>3rd</i>	1	\$ 123.30	\$ 123.30
15	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 227.40	\$ 227.40
16	FRONT DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 596.70	\$ 596.70
17	FRONT DOOR REGULATOR RH <i>new</i>	1	\$ 298.50	\$ 298.50
18	FRONT DOOR GLASS RH <i>cut</i>	1	\$ 349.60	\$ 349.60
19	FRONT DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 104.10	\$ 104.10
20	FRONT DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 194.80	\$ 194.80
21	REAR DOOR RH <i>cracked</i>	1	\$ 943.70	\$ 943.70
22	REAR DOOR BLACK STICKER RH <i>new</i>	1	\$ 106.20	\$ 106.20
23	REAR DOOR HINGE RH (UPPER) <i>3rd</i>	1	\$ 38.00	\$ 38.00
24	REAR DOOR HINGE RH (LOWER)	1	\$ 38.00	\$ 38.00
25	REAR DOOR INNER LOCK RH <i>3rd</i>	1	\$ 452.60	\$ 452.60
26	REAR DOOR LOCK CATCHER RH	1	\$ 42.10	\$ 42.10
27	REAR DOOR INNER TRIM RH <i>new</i>	1	\$ 856.70	\$ 856.70
28	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 129.90	\$ 129.90

208.50

568.80

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SDP709H
 MODEL : HONDA ODYSSEY
 DATE OF ACCIDENT : 07.01.19
 TIME OF ACCIDENT : 16:10HRS

29	REAR DOOR POWER WINDOW MOTOR RH	1	\$ 583.60	\$ 583.60
30	REAR DOOR REGULATOR RH	1	\$ 287.30	\$ 287.30
31	REAR DOOR GLASS CHANNEL RH	1	\$ 98.60	\$ 98.60
32	REAR DOOR MOULDING RH	1	\$ 127.00	\$ 127.00
33	REAR DOOR OUTER STRIP RH	1	\$ 119.30	\$ 119.30
34	REAR DOOR GLASS RH	1	\$ 326.80	\$ 326.80
35	REAR DOOR FRAME WEATHER STRIP RH	1	\$ 158.40	\$ 158.40
36	REAR LOWER ARM RH	1	\$ 487.90	\$ 487.90
37	REAR UPPER ARM RH	1	\$ 396.10	\$ 396.10
38	REAR SWING ARM RH	1	\$ 675.70	\$ 675.70
39	REAR SHOCK ABSORBER RH	1	\$ 413.10	\$ 413.10
40	REAR LINKAGE RH	1	\$ 114.30	\$ 114.30
41	REAR WHEEL HUP WITH BEARING RH	1	\$ 386.20	\$ 386.20
42	REAR FENDER RH	1	\$ 981.60	\$ 981.60
43	REAR FENDER COWLING RH	1	\$ 87.20	\$ 87.20
44	REAR FENDER GLASS WITH MOULDING LH	1	\$ 480.00	\$ 480.00
45	TAIL LAMP LH	1	\$ 496.20	\$ 496.20
46	REAR BUMPER	1	\$ 756.30	\$ 756.30
47	REAR BUMPER SIDE BRACKET	2	\$ 38.20	\$ 76.40

5931.10
 4744.88

TOTAL PRICE \$ 16,570.60
 LESS 20% \$ 3,314.12
 SUB TOTAL PRICE \$ 13,256.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR GLASS SOLAR FILM RH	1	\$ 250.00	\$ 250.00
2	FRONT DOOR INNER TRIM CLIP RH (SET)	1	\$ 50.00	\$ 50.00
3	FRONT DOOR MOULDING CLIP RH (SET)	1	\$ 40.00	\$ 40.00
4	REAR DOOR GLASS SOLAR FLIM RH	1	\$ 250.00	\$ 250.00
5	REAR DOOR FRAME STEP GARNISH CLIP RH	1	\$ 40.00	\$ 40.00
6	REAR DOOR INNER TRIM CLIP RH (SET)	1	\$ 50.00	\$ 50.00
7	REAR FENDER SEALANT RH	1	\$ 150.00	\$ 150.00
8	REAR FENDER COWLING CLIP RH (SET)	1	\$ 50.00	\$ 50.00
9	REAR FENDER GLASS INNER SEAL RH	1	\$ 60.00	\$ 60.00
10	REAR FENDER GLASS SEALANT RH	1	\$ 80.00	\$ 80.00
11	REAR WHEEL TYRE RH	1	\$ 380.00	\$ 380.00
12	REAR WHEEL RIM RH	1	\$ 850.00	\$ 850.00
13	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SDP709H
 MODEL : HONDA ODYSSEY
 DATE OF ACCIDENT : 07.01.19
 TIME OF ACCIDENT : 16:10HRS

14	TAIL LAMP CLIP RH (SET) <i>2</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
15	REAR BUMPER CLIP (SET) <i>1 set</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
16	REAR REVERSE SENSOR	1	\$ 220.00	\$ 220.00	<i>+</i>
17	DOOR VISOR (SET) <i>1 included</i>	1	\$ 350.00	\$ 350.00	<i>60</i>
18	BRAKE OIL <i>1 set new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>

720

TOTAL \$ 3,110.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/ N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>900</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000.</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	<i>x</i>
7	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	<i>✓</i>
8	REMOVE & REFIX FRONT WINDSCREEN	\$ 120.00	<i>x.</i>
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>+</i>
10	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>
11	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>✓</i>
12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
13	REMOVE & REPLACE REAR FENDER GLASS RH	\$ 100.00	<i>50</i>
14	REMOVE AND REFIX FUEL TANK RO FACILITATE FENDER REPLACEMENT	\$ 80.00	<i>✓</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SDP709H
 MODEL : HONDA ODYSSEY
 DATE OF ACCIDENT : 07.01.19
 TIME OF ACCIDENT : 16:10HRS

15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50.
16	RESET ABS LIGHT	\$ 350.00	x
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$6,430.00

2470

TOTAL PARTS COST : \$ 16,366.48

TOTAL LABOUR COST : \$ 6,430.00

TOTAL REPAIR COST : \$ 22,796.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP : 9856 4815

Adrian Lim
 1/5 14/01/19
 OT Days.

total: 7934.85
 1/5: 6.3k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:






























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Apr 2019 11:58		10 Jan 2019 17:32 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, ID: -									
Main Claimant: AUNG PYE TUN , ID: 58277370C									
Vehicle Reg. No.: SDP709H		Date of Loss: 07/01/2019 16:00 - :59 [152 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): YN7041R		Policy No. (Claimant):	DMPC185003165						
		Excess:	S\$0.00						
Repairer: Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDP709H
[YN7041R]
TP
AUNG PYE TUN
Jan 7 2019 4:00PM
[-]
Vision Autowork Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)			Thumbnail		Print			
1	10/01/19 09:06	Accident Statement					Load HTML			
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)			Thumbnail		Print			
1	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
2	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
3	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
4	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
5	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
6	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
7	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
8	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
9	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
10	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
11	09/01/19 09:39	Accident Photo [Linked Accident Report Documents]					Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail		Print			
1	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
2	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
3	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
4	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
5	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
6	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
7	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
8	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
9	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
10	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
11	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
12	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
13	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
14	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
15	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
16	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
17	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	
18	04/04/19 16:49	General View					Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
19	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
20	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
21	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
22	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
23	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
24	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
25	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
26	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
27	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
28	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
29	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
30	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
31	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
32	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
33	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
34	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
35	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
36	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
37	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
38	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
39	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
40	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
41	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
42	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
43	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
44	04/04/19 16:49	General View		<input checked="" type="checkbox"/>
45	04/04/19 16:49	Reinspection Photo		<input checked="" type="checkbox"/>
46	04/04/19 16:49	Reinspection Photo		<input checked="" type="checkbox"/>
47	04/04/19 16:49	Reinspection Photo		<input checked="" type="checkbox"/>
48	04/04/19 16:49	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	10/01/19 09:05	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/01/19 17:32	prs contact		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	10/01/19 09:06	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
2	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
3	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
4	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
5	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
6	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
7	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
8	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
9	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
10	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
11	09/01/19 09:39	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	10/01/19 09:05	Sketch Plan		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119000665/AVD3Q2

Date: 10/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle
No : SDP709H

Insured Vehicle No : YN7041R

Date of Loss: 07/01/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDP709H

Make & Model: HONDA ODYSSEY, 2.3 (A)

Reg. Date: 26/04/2006 (Man. Year: 2006)

Colour: Purple

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: K24A63002118

Chassis No: JHMRB18406C202118

Odometer: 119271 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Good Rich 6 mm

Rear Left Side: Sumitomo 6 mm

Front Right Side: Good Rich 6 mm

Rear Right Side: Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,366.48	5,464.88	10,901.60	66.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,430.00	2,470.00	3,960.00	61.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,796.48	7,934.88	14,861.60	65.19
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	22,796.48	6,300.00	16,496.48	72.36
+ GST 7.00/7.00% (S\$)	1,595.75	441.00	1,154.75	72.36
Nett Amount (S\$)	24,392.23	6,741.00	17,651.23	72.36

INSPECTION

Date of Assignment: 10/01/2019

Date Inspected: 14/01/2019 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4, #08-09 PREMIER
@ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts:	M1-MPV	HONDA ODYSSEY 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDP709H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR RH	Cracked	798.70 FL	*798.70 FL
2	1		*FRONT WINDSCREEN MOULDING	Not Necessary	168.00 FL	*- FL
3	1		*FRONT DOOR PILLAR RH	Repair	875.30 FL	*- FL
4	1		*FRONT DOOR PILLAR QUARTER GLASS WITH MOULDING RH	Not Necessary	320.00 FL	*- FL
5	1		*FRONT DOOR RH	Dented	971.70 FL	*971.70 FL
6	1		*FRONT DOOR BLACK STICKER RH	Necessary	106.20 FL	*106.20 FL
7	1		*FRONT DOOR HINGE (UPPER) RH	Not Necessary	38.00 FL	*- FL
8	1		*FRONT DOOR HINGE (LOWER) RH	Not Necessary	38.00 FL	*- FL
9	1		*FRONT DOOR INNER LOCK RH	Damaged	483.10 FL	*268.50 FL
10	1		*FRONT DOOR INNER TRIM RH	Cracked	892.60 FL	*563.80 FL
11	1		*FRONT DOOR LOCK CATCHER RH	Not Necessary	42.10 FL	*- FL
12	1		*FRONT DOOR WEATHER STRIP RH	Not Necessary	133.40 FL	*- FL
13	1		*FRONT DOOR MOULDING RH	Cut	149.90 FL	*149.90 FL
14	1		*FRONT DOOR OUTER STRIP RH	Not Necessary	123.30 FL	*- FL
15	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	227.40 FL	*- FL
16	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	596.70 FL	*- FL
17	1		*FRONT DOOR REGULATOR RH	Not Necessary	298.50 FL	*- FL
18	1		*FRONT DOOR GLASS RH	Cut	349.60 FL	*349.60 FL
19	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	104.10 FL	*- FL
20	1		*FRONT DOOR FRAME WEATHER STRIP RH	Not Necessary	194.80 FL	*- FL
21	1		*REAR DOOR RH	Dented	943.70 FL	*943.70 FL
22	1		*REAR DOOR BLACK STICKER RH	Necessary	106.20 FL	*106.20 FL
23	1		*REAR DOOR HINGE RH (UPPER)	Not Necessary	38.00 FL	*- FL
24	1		*REAR DOOR HINGE RH (LOWER)	Not Necessary	38.00 FL	*- FL
25	1		*REAR DOOR INNER LOCK RH	Not Necessary	452.60 FL	*- FL
26	1		*REAR DOOR LOCK CATCHER RH		42.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
27	1		*REAR DOOR INNER TRIM RH	Not Necessary	856.70 FL	*- FL
28	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	129.90 FL	*- FL
29	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	583.60 FL	*- FL
30	1		*REAR DOOR REGULATOR RH	Not Necessary	287.30 FL	*- FL
31	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	98.60 FL	*- FL
32	1		*REAR DOOR MOULDING RH	Cut	127.00 FL	*127.00 FL
33	1		*REAR DOOR OUTER STRIP RH	Not Necessary	119.30 FL	*- FL
34	1		*REAR DOOR GLASS RH	Not Necessary	326.80 FL	*- FL
35	1		*REAR DOOR FRAME WEATHER STRP RH	Not Necessary	158.40 FL	*- FL
36	1		*REAR LOWER ARM RH	Not Necessary	487.90 FL	*- FL
37	1		*REAR UPPER ARM RH	Not Necessary	396.10 FL	*- FL
38	1		*REAR SWING ARM RH	Not Necessary	675.70 FL	*- FL
39	1		*REAR SHOCK ABSORBER RH	Not Necessary	413.10 FL	*- FL
40	1		*REAR LINKAGE RH	Not Necessary	114.30 FL	*- FL
41	1		*REAR WHEEL HUP WITH BEARING RH	Not Necessary	386.20 FL	*- FL
42	1		*REAR FENDER RH	Dented	981.60 FL	*981.60 FL
43	1		*REAR FENDER COWLING RH	Not Necessary	87.20 FL	*- FL
44	1		*REAR FENDER GLASS WITH MOULDING LH	Necessary	480.00 FL	*68.00 FL
45	1		*TAIL LAMP LH	Cut	496.20 FL	*496.20 FL
46	1		*REAR BUMPER	Not Necessary	756.30 FL	*- FL
47	2		*REAR BUMPER SIDE BRACKET	Not Necessary	76.40 FL	*- FL
48	1		*FRONT DOOR GLASS SOLAR FILM RH	Necessary	250.00 FS	*180.00 FS
49	1		*SET FRONT DOOR INNER TRIM CLIP RH	Necessary	50.00 FS	*30.00 FS
50	1		*SET FRONT DOOR MOULDING CLIP RH	Not Necessary	40.00 FS	*- FS
51	1		*REAR DOOR GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
52	1		*REAR DOOR FRAME STEP GARNISH CLIP RH	Not Necessary	40.00 FS	*- FS
53	1		*SET REAR DOOR INNER TRIM CLIP RH	Not Necessary	50.00 FS	*- FS
54	1		*REAR FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
55	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	50.00 FS	*- FS
56	1		*REAR FENDER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	1		*REAR FENDER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
58	1		*REAR WHEEL TYRE RH	Not Necessary	380.00 FS	*- FS
59	1		*REAR WHEEL RIM RH	Cut	850.00 FS	*450.00 FS
60	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
61	1		*SET TAIL LAMP CLIP RH	Not Necessary	40.00 FS	*- FS
62	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
63	1		*REAR REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
64	1		*SET DOOR VISOR	Cracked	350.00 FS	*60.00 FS
65	1		*BRAKE OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **19,680.60** **6,651.10**

- List Item Discount on L Items 20.00/20.00% (\$\$) 3,314.12 1,186.22

Total Parts (\$\$) **16,366.48** **5,464.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	250.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
7	TRANSFER FRONT DOOR MECHANISM	New	80.00	80.00
8	REMOVE & REFIX FRONT WINDSCREEN	New	120.00	0.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	TRANSFER REAR DOOR MECHANISM	New	80.00	80.00
12	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
13	REMOVE & REPLACE REAR FENDER GLASS RH	New	100.00	50.00
14	REMOVE AND REFIX FUEL TANK RO FACILITATE FENDER REPLACEMENT	New	80.00	80.00
15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
16	RESET ABS LIGHT	New	350.00	0.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			6,430.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >