

22/03/2002

ASS. REC. BY:

REF:

CS/GAI19000666/USD322

Special Instruction:

Surveyor

Markus

ASSIGNMENT (Office)

From (Person):

Sharon Ng

of

GAI

Date/Time:

10/11/19 @ 11:54pm

Estimated Cost:

Bill to:

☒ OD / ☐ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 3493H

Insured:

at Workshop m/s

SME Motor

Tel:

67476106

of

1 Kaki Bukit Ave 6 # 02-15

Policy No:

Claim No:

CLM/MVP000000940

Sum Insured:

Excess:

Full Waive for excess (TAA) \$0/-

Make of Veh:

D.O.A.

08/01/2019

(Client's Record)

if in order

☒ CA / ☐ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/11/19 @ 9:28am

Person Contacted:

Pei Ying

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 3493H - CS/FCI16017663/Ugh 3m2

Jua: 11/11/16

11/11/19

VNI yet

14/01/19

@ 15:09 p.m. revised PA to Sharon via email.

14/01/19

@ 15:14 p.m. revert authorize repair to Pei Ying (repairer) via email.

(08/11/13) wef

ASS. REC. BY: Marius

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 3493at Workshop m/s smc

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 65/c

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 16151

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLC 3493 Yr Regn: 51 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CarMake: Toyota Corolla c.c. 1500Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 29533 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53REH/104546473Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 205/55-R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO orFront 6 Rear 6

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/1/19 D.O.I. 14/1/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Rnd, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7.15. 493. LTA 4930721/2/19 confirmed final by \$2954.50  
( \$430/- Red - 13% )

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

21/2/191) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 290

Transportation: \_\_\_\_\_

S + RS. SI \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

290

Report Format : \_\_\_\_\_

ump Sum / I.B.I: (\$ 2,954.50 p/p)

(08/11/13) waf

ASS. REC. BY: MARILIS

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLC 3493at Workshop m/s SME

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 65%

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

16151

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

7.15. 4.15.

Veh No: SLC 3493 Yr Regn: 5-16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAIMake: Toyota Corolla c.c. 1598Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 29533 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53RE-H104546473Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: \_\_\_\_\_ R: 205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/1/19 D.O.I. 14/1/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rm, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ \_\_\_\_\_)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1615I
<b>Vehicle Details</b>	
Vehicle No.:	SLC3493H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	1ZRX555502
Chassis No.:	MR053REH104546473
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	11 May 2016
First Registration Date:	11 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2026
PARF Rebate Amount:	\$14,691.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$34,629.00
<b>Total Rebate Amount:</b>	<b>\$49,320.00</b>

The information contained herein is correct as at 14 Jan 2019

OK

**> Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1615I

**Vehicle Details**

Vehicle No.: SLC3493H

Vehicle to be Exported: No

Intended Deregistration Date: 15 Jan 2019

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT

Primary Colour: Brown

Manufacturing Year: 2015

Engine No.: 1ZR555502

Chassis No.: MR053REH104546473

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$19,589.00

Original Registration Date: 11 May 2016

First Registration Date: 11 May 2016

Transfer Count: 0

Actual ARF Paid: \$19,589.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 May 2026

PARF Rebate Amount: \$14,691.00

**Intended COE Rebate Details**

COE Expiry Date: 10 May 2026

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,300.00

COE Rebate Amount: \$34,616.00

**Total Rebate Amount: \$49,307.00**

The information contained herein is correct as at 14 Jan 2019

OK

Frost & Sullivan highlights opportunities & challenges on digital health in Asia ▶



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%p.a Lowest Interest@GV  
Cars Financing \$1800  
Downpayment Monthly From  
\$568  
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

19 vehicles

altis

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	altis		Any	Any	2016	Any	Any	Any	Available



Toyota Corolla Altis 1.6A Elegance

\$72,800

\$8,610 /yr

09-May-2016

1,598 cc

29,364 km

Sedan

Available

High Loan Available. \$1500 Servicing Credit. High Loan Available. Borneo Motors Certified Unit. High Specs Altis Elegance. Warranty Till May 2021. 160 Point Check Done. Borneo Unit With Full Service H...

Inchape Pre-Owned

Posted: 14-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$70,800

\$8,470 /yr

28-Mar-2016

1,598 cc

72,800 km

Sedan

Available

\$1500 Servicing Credit. Borneo Motors Certified Unit. High Specs Altis Elegance. Warranty Till March 2021. 160 Point Check Done. Borneo Motors Unit With Full Service History. Extremely Well Maintained...

Inchape Pre-Owned

Posted: 14-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$67,800

\$8,170 /yr

30-Mar-2016

1,598 cc

31,000 km

Sedan

Available

Goes With Nice Carplate! Pretty Red Car With Comfy Interior. Fuel Efficient, Reliable And Smooth Engine Guarantees Your Journey. Spacious And Definitely Trustworthy. Well Maintained By The Only Owner....

Car Search

Posted: 14-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$65,800

\$8,010 /yr

19-Feb-2016

1,598 cc

55,000 km

Sedan

Available

One Of The Most Wanted Sedan Car In The Market! One Of The Most Reliable Fuel Efficiency Japanese Made Sedan Model To Own In Town! Fuel Efficiency With A Smooth And Reliable Engine! A Well Known Car F...

Posted: 12-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



How the new VES affects you as a car buyer

More than half the cars in this list face a hike in taxes, no thanks to the new Vehicular Emissions Scheme. Find out how this affects you as a car buyer.

Read this article



Toyota Corolla Altis 1.6A

\$66,800

\$8,230 /yr

25-Jan-2016

1,598 cc

Sedan

Available

1 Owner Only! Well Maintained, Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available. Call For More Enquiries!

Posted: 11-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$68,500

\$8,490 /yr

21-Jan-2016

1,598 cc

27,943 km

Sedan

Available

Back To Basics With The Trusted Altis. This Fuel Efficient Car Guarantees You Smooth Travelling From Point To Point. Family Friendly, Spacious, And Definitely Trustworthy. Accident-Free And No Changes...

## Shirley Hiew (LKK Auto)

---

**From:** Ng, Sharon <Sharon.Ng@sg.gaig.com>  
**Sent:** Monday, 14 January 2019 4:29 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** REF NO: CLMOMVP000000940 - OWN DAMAGE CLAIM FOR SLC3493H

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, January 14, 2019 3:09 PM  
**To:** Ng, Sharon <Sharon.Ng@sg.gaig.com>  
**Cc:** assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** [External] RE: OWN DAMAGE CLAIM FOR SLC3493H

Dear Sharon,

According to our conversation earlier, we had confirmed with you the excess is \$ 0/-

Enclosed preliminary revised of vehicle SLC 3493H  
Date of survey: 14/01/2019  
Number of days : 4 days

**We have authorise repair.**

**Please provide us the claim no.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Friday, 11 January 2019 9:32 AM  
**To:** 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; assignments <assignments@lkkauto.com>  
**Cc:** assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: OWN DAMAGE CLAIM FOR SLC3493H

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 14 January 2019 3:09 PM  
**To:** 'Ng, Sharon'  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** RE: OWN DAMAGE CLAIM FOR SLC3493H  
**Attachments:** SLC 3493H - Preli Advise.pdf

Dear Sharon,

According to our conversation earlier, we had confirmed with you the excess is \$ 0/-

Enclosed preliminary revised of vehicle SLC 3493H  
Date of survey: 14/01/2019  
Number of days : 4 days

**We have authorise repair.**

**Please provide us the claim no.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 11 January 2019 9:32 AM  
**To:** 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; assignments <assignments@lkkauto.com>  
**Cc:** assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: OWN DAMAGE CLAIM FOR SLC3493H

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## Nivitha (LKK Auto)

---

**From:** Ng, Sharon <Sharon.Ng@sg.gaig.com>  
**Sent:** Thursday, 10 January 2019 11:54 PM  
**To:** SUR  
**Cc:** assignments  
**Subject:** FW: OWN DAMAGE CLAIM FOR SLC3493H  
**Attachments:** 4010\_001.pdf

Hi Catherine

Please arrange with SME for OD survey. Full waiver for excess.

Authorise if in order.

Regards  
Sharon  
Great American

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com> **On Behalf Of** General Claims  
**Sent:** Thursday, January 10, 2019 2:58 PM  
**To:** peiying@smemotor.com.sg  
**Cc:** Ng, Sharon <Sharon.Ng@sg.gaig.com>; Motor Claims <MotorClaims@sg.gaig.com>  
**Subject:** FW: [External] OWN DAMAGE CLAIM FOR SLC3493H

Dear PeiYing  
Acknowledge receipt of your email.

Dear Sharon  
Please assist.

**Rachel Tan**, Executive | P. +65 6804 7846 | F. +65 6235 3354 | [rachel.tan@sg.gaig.com](mailto:rachel.tan@sg.gaig.com)



**Claims** | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



**Moody's**  
A1 (Good)  
Published December 2017

**Standard & Poor's**  
A+ (Strong)  
Affirmed February 23, 2018

For more information on our financial ratings, visit [GAIG.com/FinancialStrength](http://GAIG.com/FinancialStrength).

---

**From:** [peiying@smemotor.com.sg](mailto:peiying@smemotor.com.sg) <[peiying@smemotor.com.sg](mailto:peiying@smemotor.com.sg)>  
**Sent:** 10 January 2019 12:53  
**To:** General Claims <[GeneralClaims@sg.gaig.com](mailto:GeneralClaims@sg.gaig.com)>  
**Subject:** [External] OWN DAMAGE CLAIM FOR SLC3493H

Hi,

Forward all relevant documents to you. Kindly arrange your surveyor to inspect our client's vehicle.

Thanks.

Regards,  
PeiYing

**From:** [ptr2@smemotor.com.sg](mailto:ptr2@smemotor.com.sg)

**Sent:** Thursday, January 10, 2019 11:36 AM

**To:** SME Motor-Chia Pei Ying

**Subject:** Attached Image

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 14 January 2019 3:14 PM  
**To:** peiying@smemotor.com.sg  
**Cc:** SUR  
**Subject:** SLC 3493H OD (GAI)

Dear Pei Ying,

As instructed by our client, please proceed to repair the insured vehicle **SLC 3493H (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 14 January 2019

Our Ref: CS/GAI19000666/Usd3

The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 3493H .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/01/2019 at the premises of M/s SME Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,384.50</u> .
Revised Estimate Amount	: S\$ <u>2,954.50</u> .
"Check" Items Amount	: S\$ _____ .
Total	: S\$ <u>2,954.50</u> .
Market Value	: S\$ <u>65,000.00</u> .
LTA Reimbursement Value	: S\$ <u>49,320.00</u> .
Nett Value	: S\$ <u>15,680.00</u> .

**Description of Damage:**

The vehicle sustained damages at the n/s front portion & n/s body



**Comments/ Present Status:**

Damages Consistent.  
Repair cost economical, we have authorize repair  
Repair days: 4 Days

Yours faithfully,  
Marcus Chua  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/01/2019 12:57
Date Of Accident	08/01/2019 08:10
Exact Location Of Accident	EUNOS LINK TWDS PIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLC3493H
Insured/Policyholder	
Name Of Registered Owner	PANG LOO SENG
NRIC No	S0081615I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97766683
Alternative Phone No	OFFICE-97766683
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000003679-00-000
Cover Note Number	
Driver	
Name of Driver	HAN BOON JONG
NRIC No	S0091228Z
Date Of Birth	13/09/1950
Occupation	INDOOR
Date Of Driving Pass	26/01/1979
Driving Experience	39 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91384853
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 137 BEDOK RESERVOIR ROAD #08-1451
Postcode	470137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

WE ARE IN THE MERGING LANE. I WAS IN FRONT OF VEHICLE B. SUDDENLY, VEHICLE B ACCELERATE AND OUR VEHICLES CAME INTO CONTACT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS7450P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan #2 Pg. 1

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

We are in the merging lane. I was in front of the vehicle B. Suddenly veh B accelerate and our vehicle came into contact.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Same



**SME Motor Pte Ltd**

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
 GST:201119451E RCB NO:201119451E

M/S : GREAT AMERICAN INSURANCE COMPANY  
 3 TEMASEK AVENUE #16-01  
 CENTENNIAL TOWER  
 SINGAPORE 039190

TEL: 6804 6000

FAX: 6235 2616

ATTN: Motor Claim Department

Your Ref No: 19/GA/OD-031 (01)

Claim Type: Own Damage

Estimate No: EST0004588

Date: 10 Jan 2019

Policy No: MOMVP000003679-00-

Veh Reg No: SLC3493H

Make/Model: TOYOTA ALTIS

Reg. Date: 11/05/2016

**Estimate Repair Cost to Vehicle No :SLC3493H**

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<b>Parts</b>				
1 FRT LH FENDER		1 PC	220.00	
2 FRT LH DOOR		1 PC	480.00	
3 FRT LH DOOR HANDLE		1 PC	80.00	
4 FRT LH DOOR HANDLE CHROME (OUTER MOULDING)		1 PC	70.00	
5 REAR LH DOOR		1 PC	520.00	
6 FRT LH FENDER EMBLEM 'DUAL VVT-I'		1 PC	25.00	
			1,395.00	
	Add 10%		139.50	1,534.50
<b>Labour</b>				
7 WIRE CHECKING		1 UNIT	30.00	
8 TRANSFER 2 DOOR COMPONENT FROM OLD TO NEW		1 UNIT	220.00	
9 LABOUR CHARGE		1 UNIT	700.00	
10 SPRAY PAINTING		1 UNIT	900.00	
				1,850.00

Amount Before Excess S\$ 3,384.50

Add GST @ 7% 236.92

Total Amount payable S\$ 3,621.42

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED TWENTY ONE AND CENTS FORTY TWO ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

not allowed  
 to be  
 excess?  
 14/1/19  
 To the repair shop  
 4 day.

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
GST:201119451E RCB NO:201119451E

**M/S :** GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE #16-01  
CENTENNIAL TOWER  
SINGAPORE 039190  
TEL: 6804 6000 FAX: 6235 2616  
ATTN: Motor Claim Department  
Your Ref No: 19/GA/OD-031 (01)  
Claim Type: Own Damage

**Estimate No:** EST0004588  
**Date:** 10 Jan 2019  
**Policy No:** MOMVP000003679-00-  
**Veh Reg No:** SLC3493H  
**Make/Model:** TOYOTA ALTIS

Reg. Date: 11/05/2016

## Estimate Repair Cost to Vehicle No :SLC3493H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<b>Parts</b>				
1 FRT LH FENDER		1 PC	220.00	
2 FRT LH DOOR		1 PC	480.00	
3 FRT LH DOOR HANDLE		1 PC	80.00	
4 FRT LH DOOR HANDLE CHROME (OUTER MOULDING)		1 PC	70.00	
5 REAR LH DOOR		1 PC	520.00	
6 FRT LH FENDER EMBLEM 'DUAL VVT-I'		1 PC	25.00	
			1,395.00	
	Add 10%		139.50	1,534.50
<b>Labour</b>				
7 WIRE CHECKING		1 UNIT	30.00	
8 TRANSFER 2 DOOR COMPONENT FROM OLD TO NEW		1 UNIT	220.00	
9 LABOUR CHARGE		1 UNIT	700.00	
10 SPRAY PAINTING		1 UNIT	900.00	
				1,850.00
				2954.50

Amount Before Excess	S\$ 3,384.50
Add GST @ 7%	236.92
Total Amount payable	S\$ 3,621.42

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED TWENTY ONE AND CENTS FORTY TWO ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

not Allocated  
h/bk  
Excess?  
14/1/19  
Whepke Behr party  
4 day. p/p \$ 2954.50

Accepted by Repairer  
Signature:  
Date:



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /  
DAIHATSU / KIA / SUZUKI / HONDA  
TEL: 6291 2827 FAX: 6296 4390  
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

**TAX INVOICE**

M/S : SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6  
#02-15/16/17/18 AUTOBAY @KAKI BUKIT  
SINGAPORE 417883  
SLC3493H  
GARY

NO: DLI9213317  
PAGE: 1  
DATE: 24/01/2019  
A/C CODE: LDSM446  
TERMS: CR  
P/O NO: SLC3493H

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
Our D/O No: DDO9022709						
1	T53802-02220	FENDER FR LH	DB1D33	1	220.00	220.00
2	T67002-02470	DOOR FR LH	DB1K5	1	480.00	480.00
3	T69220-02130-B3	DOOR HANDLE FR LH	DU1B87	1	80.00	80.00
4	T69250-02070-B2	DORO HANDLE	DU1P29	1	70.00	70.00
5	T67004-02430	DOOR RR LH	DB3017-7	1	520.00	520.00
6	T75444-02A20	VVTI LH	DDS	1	25.00	25.00
TOTAL QUANTITY:			6	TOTAL	SIN 1,395.00	
				ADD GST @ 7%	97.65	
				GRAND TOTAL	SIN 1,492.65	

#02-18

Print / MT / 24/01/2019 2:10:12 PM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI19000666/Usd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 22-02-2019		
		Code : GAI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		SLC 3493H	
Policy No.	MOMVP000003679-00-000	Coverage (\$)	0.00	
Claim No.	CLMOMVP000000940	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	11/01/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104546473	Colour	BROWN	
Odometer	29533	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/01/2019	Inspection Date	14/01/2019	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$65,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3493H**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT LH FENDER (WCP)	DENTED / BENT	220.00	220.00
1	FRT LH DOOR (WCP)	DENTED / BENT	480.00	480.00
1	FRT LH DOOR HANDLE (WCP)	CUT	80.00	80.00
1	FRT LH DOOR HANDLE CHROME (OUTER MOULDING) (WCP)	NECESSARY	70.00	70.00
1	REAR LH DOOR (WCP)	DENTED	520.00	520.00
1	FRT LH FENDER EMBLEM 'DUAL VVT-I' (WCP)	NECESSARY	25.00	25.00
	COST PLUS 10%		139.50	139.50
			1,534.50	1,534.50
	<b><u>LABOUR</u></b>			
	WIRE CHECKING.		30.00	20.00
	TRANSFER 2 DOOR COMPONENT FROM OLD TO NEW.		220.00	100.00
	LABOUR CHARGE.		700.00	500.00
	SPRAY PAINTING.		900.00	800.00
			1,850.00	1,420.00
	<b>GRAND TOTAL</b>		<b>3,384.50</b>	<b>2,954.50</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,954.50</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/GAI19000666/Usd3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.