

Steve

REF: AIG

7/31/17

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **GBF 79340** Yr Regn: **15/03/17**
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Hiace** CC: **2982**
 Colour: **White** A/C: Insured / Std / NI / NA
 Sp. Reading: **79888** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JTFH T02P300211.267**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **in order** / Jammed / Leaked / Burnt or
 Brake: **in order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / SRim / STD A/Rim or
 Tyre Size: F: **195R15C**
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Michlin**

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front: _____ Rear: _____
 R/Bal. **7** mm R/Bal. **7** mm
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **10/1/19** D.O.I. **26/2/19**
 Survey held at **Abwin**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
front LH
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction
 * photo cannot upload

Date/Time, File Pass to? : Prol. Report
 : Final Report

Days Of Repair:
 Resurvey No. of Trip:

Survey Fee:	
Transportation	
) 3 + RS. SI	
) Photos	
) Other	
TOTAL	

Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4873W
Vehicle Details	
Vehicle No.:	GBF7934D
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2668748
Chassis No.:	JTFHT02P300211267
Maximum Power Output:	-
Open Market Value:	\$27,952.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	1
Actual ARF Paid:	\$1,398.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,322.00
COE Rebate Amount:	\$34,042.00
Total Rebate Amount:	\$34,042.00

The information contained herein is correct as at 26 Feb 2019

OK