

22/03/2001

ASS. REC. BY:

REF: CS3/AIG19000763/Ecd30

Special Instruction:

Surveyor:

Munim

From (Person):

Steve

Chin Lee Ying

ASSIGNMENT (Office)

of

AIG

Date/Time:

14/11/19 @ 12.28pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GW 3843K

Insured:

GBE 3326R

at Workshop m/s

Autobest

Tel:

G7456932

of

Blk 3006 Ubi Rd 1 # 01-362

Policy No:

0999994646

Claim No:

1513106320SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/11/18

CA / REV / REP. / REV 24 HRS 'up)

H.O.D. Endorsement:

Date/Time:

12.31pm @ 14/11/19

Person Contacted:

Mr. Lee

Vehicle

☒ IN / OUT

Date/Time	Action/Instruction (x) Estimate
	GW 3843K - NA / CTI 18021348 / 24
	GBE 3326R - CS3 / CTI 18021665 / YCBS2
	After repair: 16/1/2019

DUA: 26/11/18

DUA: 26/11/18

REF: AIG

PRR(Menimen)

ASSIGNMENT

From: _____ Date: 14/01/19

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GW 8843K

at Workshop m/s: Autobest

of: Blk 3006 ubi rd 1 #01-362

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GW 3843K Yr Regn: 17/06/2003

Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna 150D C.C. 2986

Colour: _____ A/C: Insured / Std / NI / NA

Sp. Reading: 114810 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUF 34Y303001215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

Steel Rim
185R14
155R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 26/11/2018 D.O.I. 14/01/2019

Survey held at LKK

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 28,000

PV - 16,123

NV - 11,877

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4.

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

) TOTAL

Report Format: BAR

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Weekend (\$)

180

20

200


RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INS...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 14/1/2019 12:25:42 PM

Attachments:  [NEW PRI - GBE3326R AND GW3843K.PDF](#)

Hi LKK,

Kindly assist to survey by today, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: gslimlaw@singnet.com.sg [mailto:gslimlaw@singnet.com.sg]

Sent: Wednesday, November 28, 2018 3:55 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul; gslimlaw@singnet.com.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBE3326R AND GW3843K ON 26/11/2018

Your Ref : GBE3326R

Our Ref : HL/ABM/11953/18/ck

Dear Sirs

We refer to your email dated 28 November 2018.

Pursuant to State Courts Practice Directions Amendment No. 1 of 2016, our client is not agreeable to your list of surveyors. Our client's appointed surveyor is Mr Kent Ong (KTO Automobile Assessors).

Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them.

Workshop

Auto Best Motor Services

Address

Blk 3006 Ubi Road 1 #01-362 Singapore 408700

Contact Person

Mr Lee

Tel No.

67456932

Thank you

Regards,

G S Lim & Partners | 150 South Bridge Road #02-30 Fook Hai Building Singapore 058727
65324518 | 7 65325410 | gslimlaw@singnet.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

林
錦
秀
律
師
館

G S LIM & PARTNERS

Advocates & Solicitors
Notary Public
Commissioner for Oaths

HENRY G S LIM
LLB (Hons) (London)
Barrister-at-Law (Lincoln's Inn)

DAVID YONG KHUNG LIN
LLB (Hons) (University of Bristol)

150 South Bridge Road
#02-30 Fook Hai Building
Singapore 058727
Tel 65324518 Fax 65325410
email : gslimlaw@singnet.com.sg
UEN 53131358A
GST Reg No. M90361086A

Our Reference : HL/ABM/11953/18/ck

Your Reference :

27 November 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#08-16
SINGAPORE 079120

BY FAX 64153727 ONLY

Attn : Motor Claims Department

Dear Sirs

**PRE-REPAIR SURVEY - NOTIFICATION OF INSPECTION
ACCIDENT ALONG CTE (AYE) BEFORE BRADDELL ROAD EXIT INVOLVING GW 3843K, GBE
3326R & SKW 726M ON 26.11.18**

We are instructed by M/s Auto Best Motor Services to notify you of a road traffic accident on 26.11.18 along CTE (AYE) before Braddell Road Exit involving our client's vehicle registration number GW 3843K and GBE 3326R driven by your insured at the material time. A copy of our client(s) Singapore Accident Statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



HENRY G S LIM

Encl

cc : M/s Auto Best Motor Services

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1701D
Vehicle Details	
Vehicle No.:	GW3843K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2003
Engine No.:	5L5334732
Chassis No.:	JTFUF34Y303001215
Maximum Power Output:	-
Open Market Value:	\$23,726.00
Original Registration Date:	17 Jun 2003
First Registration Date:	17 Jun 2003
Transfer Count:	1
Actual ARF Paid:	\$1,187.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$18,773.00
COE Rebate Amount:	\$16,123.00
Total Rebate Amount:	\$16,123.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 14 Jan 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%p.a Lowest Interest@Gv
Cars Financing \$1800
Downpayment Monthly From \$568
GV Credit Pte Ltd StarAd



CERTIFIED PRE-OWNED MERCEDES-BENZ

view our car

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/p

33 vehicles

Toyota Dyna

Advanced Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Toyota Dyna

Any

Any


> 10 year(s) old

Any

Any

Any

Ava



Toyota Dyna 150 (COE till 07/2022)

Fuel Type: Diesel

Only 1 Owner, Come With Full Checker Plate, New Leather Seat Cushion, Healthy And Fit Vehicle, Call Fast For This One And Only Tip Top Condition, Good For Start Up.

SG Motor Link Pte Ltd

Posted: 14-Jan-2019

Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Toyota Dyna 150 (COE till 12/2023)


Fuel Type: Diesel

Good Condition, Most Reliable Brand In Town, Monthly At \$653 Only, Low Interest, 100% Loan Available With Our Easy Loan Approval Scheme Available Sure You Will Get Your Dream Lorry At No Time. Call Or...

SG Motor Link Pte Ltd

Posted: 14-Jan-2019

Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (New 5-yr COE)


Fuel Type: Diesel

1 Owner! New 5 Year COE! The Most Reliable 10ft Lorry With Lowest Depreciation! All Parts Done Up.Good To Go For Another 5 Years.We Provide Easy Approval In Hse Loan Up To 100%.Pls Call For Viewing An...

ABWIN Bus Pte Ltd

Posted: 14-Jan-2019

Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 01/2024)

Fuel Type: Diesel

Guarantee Cheapest In The Market. 2 Owners Only. Best Selling Lorry With Least Maintenance Costs. Well Known For Its Reliability And Power. Excellent Condition. Great Deal Not To Be Missed, 1st Come 1...

Posted: 14-Jan-2019

Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



GET YOUR COE RENEWAL LOAN

Compare

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Dyna 150 (COE till 12/2023) **\$31,800** \$6,490 /yr 09-Dec-2008 2,982 cc - Truck **Ava**

Fuel Type: Diesel

In Very Good Condition, Most Wanted 10 Feet Lorry In The Market, Powerful And Fuel Efficiency, Up To 100% Loan, Easy Loan Low Interest, Doorstep Viewing Can Be Arrange.

ABWIN (1994) Pte Ltd

Posted: 13-Jan-2019 Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 03/2022) **\$23,800** \$7,470 /yr 23-Mar-2007 2,982 cc 80,000 km Truck **Ava**

Fuel Type: Diesel

\$614 Per Month Only! In House Loan And High Trade In Available! Full Loan Also Available Subject To Approval! 10 Feet Dyna Lorry With Box Good Condition, Well Maintained Vehicle, Just Serviced, No Rep...

Bell Auto Pte Ltd

Posted: 12-Jan-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 100 (COE till 12/2023) **\$28,800** \$5,870 /yr 12-Dec-2008 2,982 cc - Truck **Ava**

Fuel Type: Diesel

Cheapest In The Market. Flexible Loan Up To 100%!New Paintwork, New Leather Seat. Engine, Gearbox All In Good Condition!.Contact Our Sales Consultant For Appointment For Viewing & Test Drive.

Car (S) Pte Ltd

Posted: 12-Jan-2019 Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (New 5-yr COE) **\$31,777** \$6,350 /yr 29-Oct-2008 2,982 cc - Truck **Ava**

Fuel Type: Diesel

Very Well Maintained, No Repairs Needed Toyota Dyna With Super Cold Cabin Height Chiller With 4 Swing Door, Easy To Load Up Your Goods! Comes With New 5 Years COE, High Loan With Low Interest Availabl...

KSL Automotive Pte Ltd

Posted: 12-Jan-2019 Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 11/2023) **\$31,800** \$6,560 /yr 20-Nov-2008 2,982 cc - Truck **Ava**

Fuel Type: Diesel

1 Owner. Good Condition. 100% Loan Ok. In House Loan. Fast Approval. Fast Delivery. Call Now For Appointment.

ABWIN (1994) Pte Ltd

Posted: 11-Jan-2019 Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 100 (COE till 01/2023) **\$27,800** \$6,980 /yr 08-Jan-2008 2,982 cc 180,000 km Truck **Ava**

Fuel Type: Diesel

(Original Paint Work From Day 1) Raw Condition, Very Well Maintained By One Single Owner, Always Service On Time, Low Mileage, Mint Interior, Fast Sales! Selling Cheap, Call Now Before It Too Late, Vi...

Posted: 11-Jan-2019 Tags: 2008 Toyota Dyna, 2008 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

ADVERTISING

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2018 16:50
Date Of Accident	26/11/2018 09:30
Exact Location Of Accident	CTE (AYE) BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GW3843K
Insured/Policyholder	
Name Of Registered Owner	M/S TJW BUILDERS PTE LTD
Co Reg No	201301701D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90253617
Alternative Phone No	OFFICE-90253617

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 D
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCVSN3025101800
Cover Note Number	

Driver

Name of Driver	AHAMMED REYAD
Passport No/FIN	G2089881Q
Date Of Birth	25/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	15/09/2016
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84863449
Fax Number	
Contact Number	OFFICE-84863449
EMail Address	NOEMAIL

Address	105 SIMS AVENUE #05-10 CHANCERLODGE COMPLEX
Postcode	387429
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME. MY VEHICLE WAS STATIONARY STOPPED ALONG STATED VENUE AS IT WAS CONGESTED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE. I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. AFTER AN IMPACT, I REALIZE THAT THERE WERE 3 VEHICLES INVOLVED IN AN ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE3326R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN YOUNG THING
NRIC/Passport Number	G7811847X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW726M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG HUI LI
NRIC/Passport Number	S1618141B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

DECLARATION

I/We declare that the foregoing particulars are true to every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1. $\text{H}(\text{Phreeq})/T = \text{H}(\text{eqn}) - \text{H}(\text{ref}) - C$
 2. $\text{H}(\text{H}(\text{Phreeq}) - \text{H}(\text{ref})) = \text{H}(\text{ref})$

Vehicle No: GW 3843K

Vehicle No: GW 5845K

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2019 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **LIAN HIN PTE LTD**, Co. Reg. No.: 201306186N
Main Claimant: **M/S TJW BUILDERS PTE LTD**
Vehicle Reg. No.: **GW3843K**
Claim Type: **TP / 1513106320SG**
Vehicle Reg. No. (Insured): **GBE3326R**
Repairster: **Auto Best Motor Services (HQ)** BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:
Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Tan, Bennie-WZ** - 6419 1718] Bennie-WZ.Tan@aig.com
Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... **[Final Rpt due 23/01/2019]**
Claimant's Solicitor: **G S LIM & PARTNERS** - Tel: 65324518

Date of Loss: 26/11/2018 09:00 - :59
[185 Months and 9 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: 0999994646 (Comprehensive)
Policy No. (Claimant):
Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (15/01/2019): Request To Upload TP GIA Report



































ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GW3843K (1513106320SG)
[GBE3326R]
TP
M/S TJW BUILDERS PTE LTD
Nov 26 2018 9:00AM
[LIAN HIN PTE LTD]
Auto Best Motor Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
2	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
3	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
4	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
5	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
6	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
7	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
8	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
9	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
10	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
11	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
12	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
13	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
14	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
15	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
16	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
17	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
18	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
19	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
20	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
21	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
22	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
23	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
24	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
25	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
26	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
27	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
28	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
29	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
30	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
31	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
32	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
33	16/01/19 14:55	General View														Load JPG	<input checked="" type="checkbox"/>			
34	16/01/19 14:56	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
35	16/01/19 14:56	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
36	16/01/19 14:56	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
37	16/01/19 14:56	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	16/01/19 14:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19000763/ECD3E2

Date: 23/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994646
Claimant Vehicle No : GW3843K **Insured Vehicle No :** GBE3326R
 Date of Loss: 26/11/2018 Nature of Claim: TP Claim No: 1513106320SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GW3843K**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 5L5334732
 Reg. Date: 17/06/2003 (Man. Year: 2003) Chassis No: JTFUF34Y303001215
 Colour: Silver Odometer: 114810 km
 Engine Capacity: 2986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185 R14 Rear Tyre Size: 155 R12
 Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
 Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/01/2019
 Date Inspected: 14/01/2019 Inspected At: Auto Best Motor Services (HQ)
 BLK 3006 UBI ROAD 1, #01-362
 Singapore 408700
 Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BRACKET	Bent	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	* Check	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	2		*TAILGATE STICKER	Necessary	0.00 F	*- F
7	1		*TAILGATE INNER METAL PLATE	Dented	0.00 F	*- F
8	4		*TAILGATE HINGE	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >