

ASS. REC. BY:

REF: CS/SMO19000784/USD3 n2

Special Instruction:

Surveyor: Marcus
From (Person): Thelma Choo

ASSIGNMENT (Office)

of SMO

Date/Time: 14/1/19 @ 4:39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 2057T

Insured: SKS9334Y

at Workshop m/s: Fastech Auto

Tel: 67465405

of 1 Kulci Bulkit Ave 6 # 01-46

Policy No: D18MTPV01007880

Claim No: EMTD1900314

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 13/01/2019

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time: 4:43pm @ 14/1/19

Person Contacted: Nancy

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
16/01/19	@ 13:37 p.m. revert pending estimate from repairer to Thelma Choo via merimer

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF20577

at Workshop m/s H.

of _____

Insured: SIK593544

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 54

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

25976

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF20577 Yr Regn: 7.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: Hyundai c.c 2982

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 110021 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1204/2318024525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green max

Front 6 mm Rear 6/6 mm

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 13/1/19 D.O.I. 14/1/19

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LRA 30139 tips 6th.

29/3/19 4/5 \$11,000 confirmed with Alan.

(\$ 20,219.81 Red - 65%)

RECEIVED 01 APR 2019

Date/Time, File Pass to?

: Preli. Report

1) 01/04/19

: Final Report

Typic

Date/Time, File Return to?

2) _____

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation: 450

Photos 10

Others _____

TOTAL 460

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ 11,000 / 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jan 2019		14 Jan 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	GOEH BOON THYE, ID: S1747487A, Tel: +6598299703, Email: derrick.goeh@dhl.com			
Main Claimant:	HAYRER PTE. LTD., Co. Reg. No.: 200902597G			
Vehicle Reg. No.:	GBF2057T	Date of Loss:	13/01/2019 09:00 - :59	
Claim Type:	TP / CMTD1900314	Policy/Cover Note No.:	D18MTPV01007880 (Comprehensive)	
Vehicle Reg. No. (Insured):	SKS9334Y	Policy No. (Claimant):		
		Excess:		
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/01/2019]			
Driver/Custodian (Insured):	GOEH BOON THYE (52 / Male), NRIC: S1747487A, Tel: +6598299703			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GBF2057T (CMTD1900314)
[SKS9334Y]**

TP
HAYRER PTE. LTD.
Jan 13 2019 9:00AM
[GOEH BOON THYE]
Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 16/01/2019 13:37 PM.
To thelma.choo@sompo.com.sg
CC sur@lkkauto.com
Subject GBF2057T (CMTD1900314) [SKS9334Y]

Dear Thelma,

Please be informed that we have inspected the vehicle GBF 2057T on 14/01/2019.

We are pending estimate from repairer.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

500+ dealers competed to buy my car!

- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Fast Deal! BMW 325i Convertible (Depre \$6.6K/Yr!).



\$6.6K/yr For BMW Convertible!
Powerful & Smooth 2.5L Engine.
Genuine Mileage!
Direct Owner StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

toyota dyna

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
toyota dyna		Any	Any	2016	Any	Any	Any	Available
	Toyota Dyna 150	\$52,800	\$6,750 /yr	08-Nov-2016	2,982 cc	57,000 km	Truck	Available
	Fuel Type: Diesel							
	Think One Automobile & Trading							
	Posted: 19-Dec-2018							
	Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150	\$53,800	\$7,530 /yr	07-Mar-2016	2,982 cc	119,000 km	Truck	Available
	Fuel Type: Diesel							
	Comes With Canopy With Metal Truck Bed, Excellent Condition, Call To View Now Before It Is Too Late, In House Loan Available.							
	Hui Hua Credit Pte Ltd							
	Posted: 04-Dec-2018							
	Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150	\$65,000	\$8,330 /yr	01-Nov-2016	2,982 cc	-	Truck	Available
	Fuel Type: Diesel							
	Toyota Dyna Clean And Well Maintained Interior And Exterior. Most Convenient And Reliable Truck For Day To Day Duties. Call Me Now.							DIRECT OWNER
	Posted: 25-Nov-2018							
	Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150	\$53,800	\$6,760 /yr	29-Dec-2016	2,982 cc	-	Truck	Available
	Fuel Type: Diesel							
	Please Call To Arrange For Viewing, Thanks.							
	Posted: 19-Nov-2018							
	Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota dyna, toyota dyna Singapore, used toyota dyna Singapore, used toyota dyna, used vehicles Singapore or even buy used toyota dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2597G
Vehicle Details	
Vehicle No.:	GBF2057T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	1KD2608604
Chassis No.:	KDY2318024525
Maximum Power Output:	-
Open Market Value:	\$32,549.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$1,628.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,999.00
COE Rebate Amount:	\$30,139.00
Total Rebate Amount:	\$30,139.00

The information contained herein is correct as at 14 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 12:21
Date Of Accident	13/01/2019 09:10
Exact Location Of Accident	ALONG JALAN EUNOS TWRDS STILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF2057T
Insured/Policyholder	
Name Of Registered Owner	HAYRER PTE. LTD.
Co Reg No	200902597G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098057567
Cover Note Number	

Driver

Name of Driver	LYU WENTAO
Passport No/FIN	G8173115U
Date Of Birth	06/09/1968
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98837459
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 514 CHAI CHEE LANE #07-08
Postcode	460029
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190113/2030;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS9334Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJP6403D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number FZ4531A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LYU WENTAO
Approximate Age 30
Injuries Sustain
Injured person in which vehicle? GBF2057T
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address BLK 514 CHAI CHEE LANE #07-08
Postcode 460029

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

14 JAN 2013
IDAC KAKI BUKIT
23, KAKI BUKIT AVE #1
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report T/20190113/2030

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

14 JAN 2010

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre **Singapore 415933**
Name: **Tel: 67416697**
NRIC/FIN No.: **Fax: 67492305**
Email: vackb@singnet.com.sg



Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20190113/2030

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/01/2019 11:07		Vide Report No.: G/20190113/0099		Station Diary No.: 22	
Informant's Particulars					
Name of Informant: LYU WENTAO			Address: APT BLK 9 LORONG 101 CHANGI #03-01 PARK COURT SINGAPORE 426641		
ID Type / ID No.: FIN NO / G8173115U			Contact No.:		Mobile: 98837459
Nationality: CHINESE			Email:		
Sex: Male	Age: 30	Date of Birth: 06/09/1988	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: 3,4,5		Date of Expiry: 27/11/2022	

General Information of the Accident					
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/01/2019 09:10	Type of Location: T-Junction	
Location: Junction of Road 1 and Road 2 JALAN EUNOS EUNOS CRESCENT Junction of Jalan Eunios and Eunios Crescent, heading towards Still Road.					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FZ4531A	Motorcycle					0
GBF2057T	Lorry					0
SJP6403D	Car					0
SKS9334Y	Car					0



Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20190113/2030

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LYU WENTAO	ID No.	G8173115U
Related Vehicle	GBF2057T (Lorry)	Contact No.	98837459
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: 27/11/2022
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	GOEH BOON THYE	ID No.	S1747487A
Related Vehicle	SKS9334Y (Car)	Contact No.	98299703
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 13/01/2019 at about 0910 hours, I was driving a lorry, bearing the registration number GBF2057T, along Jalan Eunos towards Still Road. Upon approaching the junction of Jalan Eunos and Eunos Crescent, I noticed that the car (SJP6403D) that was in front of my lorry, braked so suddenly. I also applied my brakes and managed to stop in time. However, a seconds after, I felt an impact coming from the rear of my lorry. The impact was strong enough to cause my lorry move forward and thus, hitting on the front car to which the said car hit onto a motorcycle (FZ4531A).

About a minute later, I alighted from my lorry to check on what had happened to which I realised that the car (SKS9334Y) behind my lorry, did not manage to stop in time. This resulted in it colliding into me.

Due to the accident, I am feeling some aching on my neck. Traffic Police was at scene and instructed for me to lodge a traffic accident report with regards to the accident.

I wish to state that my lorry does not have any in-car camera installed. I am unsure if there is any camera at the said junction. I only exchanged particulars with the driver of the car that was behind my lorry.



**SINGAPORE
POLICE FORCE**



T/20190113/2030

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

3 of 4

Report No. T/20190113/2030

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190113/2030

4 of 4

Report No. T/20190113/2030

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 3 MUHAMMAD SYAHIDIN BIN MATNIN

Signature Of Informant:

Signature Of Interpreter:
Not applicable


Date/Time:
13/01/2019 11:07

Officer In Charge Of Case:
TP / GIT /
SI MOHAMMAD ABDILLAH BIN PALIL
Contact No.: 65476246

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE





Date of Accident : 13/01/19 Accident Time: 09/10 (24-HR-Format)

Accident Place : Along Jalan Eunos towards Still Road

Vehicle No. (Car Plate No.) : GBF 2057T Make/Model: Toyota Dyna

Insurance Company : NTUC Policy No: 5098057567

Owner or Company Name /IC No. : Hayzer Pte Ltd / 200902597-6

Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____

DRIVER'S Name / IC No. : Lyu Wentao / 681731154

DRIVER'S Date Of Birth : 6/9/1968 DRIVER'S License Pass Date 28/11/2008

Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____

DRIVER'S Address : 514 Chai Chee Lane # 07-08 546029

DRIVER'S Contact No./ Alt No. : 1) _____ 2) _____

DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address : _____

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1 Driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SKS 9334Y (somp0)</u>	Vehicle No: <u>SJP 6403 D</u>
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender: Vehicle W/ FZ 4531A

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer. to the police report T/20190113/2030

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000784/USD3N2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01007880
Claimant Vehicle No :	GBF2057T	Insured Vehicle No :	SKS9334Y
Date of Loss:	13/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900314

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2057T	Engine No:	1KD2608604
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318024525
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	110021 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185R15	Rear Tyre Size:	185R15 (D)
Front Left Side:	GREEN-MAX 6 mm	Rear Left Side:	GREEN-MAX 6/6 mm
Front Right Side:	GREEN-MAX 6 mm	Rear Right Side:	GREEN-MAX 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,009.81	10,690.05	15,319.76	58.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	3,100.00	2,110.00	40.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,219.81	13,790.05	17,429.76	55.83
Approved Total (Overridden) (S\$)		11,000.00		
	(S\$) 31,219.81	11,000.00	20,219.81	64.77
+ GST 7.00/7.00% (S\$)	2,185.39	770.00	1,415.39	64.77
Nett Amount (S\$)	33,405.20	11,770.00	21,635.20	64.77

INSPECTION

Date of Assignment:	14/01/2019	
Date Inspected:	14/01/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 04 Apr 2019)
Parts:	N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2057T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LICENCE PLATE BRACKET	Bent	119.50 F	*119.50 FL
2	1		*REAR SPARE TYRE BRACKET & CHAIN	Damaged/Jammed	392.30 F	*392.30 FL
3	1		*REAR TAILLAMPS	N/s Cracked	732.00 F	*286.50 FL
4	1		*REAR TAILLAMP BRACKETS	N/s Bent	290.00 F	*145.00 FL
5	1		*REAR STEP BRACKET	Bent	180.00 F	*180.00 FL
6	1		*REAR EXHAUST	Repair	585.20 F	*- FL
7	1		*FRONT BUMPER	Bent/Torn	898.10 F	*698.10 FL
8	2		*FRONT BUMPER BRACKETS	Bent	700.00 F	*330.00 FL
9	1		*FRONT GRILLE	Cracked	867.91 F	*645.10 FL
10	1		*FRONT GRILLE LOGO	Necessary	68.10 F	*68.10 FL
11	2		*HEADLAMPS	Cracked	2,100.00 F	*1,532.10 FL
12	1		*FRONT PANEL	Dented	1,545.10 F	*1,455.10 FL
13	1		*FRONT PANEL DYNA STICKER	Necessary	85.00 F	*85.00 FL
14	1		*FRONT PANEL TOP BLACK GARNISH	Cut	311.10 F	*285.50 FL
15	2		*FRONT CORNER PANELS	Repair	650.00 F	*- FL
16	1		*FRONT WIPER PANEL	Dented/Bent	688.10 F	*545.10 FL
17	1		*FRONT WINDSCREEN RUBBER	Necessary	355.10 F	*299.50 FL
18	1		*AIR CON BLOWER ASSY	Cracked	2,015.10 F	*1,455.30 FL
19	1		*AIR CON HEATER HOUSING	Cracked	2,822.10 F	*1,820.50 FL
20	2		*FRONT FOG LAMPS	Cracked	1,360.00 F	*900.00 FL
21	2		*ENGINE MOUNTINGS	Torn	900.00 F	*630.50 FL
22	2		*FRONT DOORS	Repair	3,370.00 F	*- FL
23	1		*FRONT CENTRE CROSS MEMBER	Bent	895.10 F	*588.20 FL
24	1		*REAR BACK DOOR N/S	Repair	1,500.00 FS	*- FS
25	1		*REAR BACK DOOR LOWER PANEL	Bent	850.00 FS	*480.00 FS
26	1		*REAR LICENCE PLATE	Broken	20.00 FS	*14.00 FS
27	1		*REAR TOOLS BOX ASSY	Distorted	650.00 FS	*480.00 FS
28	1		*REAR TOOLS BOX BRACKET	Bent	580.00 FS	*300.00 FS
29	1		*REAR BACK DOOR STICKER N/S	Not Necessary	380.00 FS	*- FS
30	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
31	1		*FRONT DOOR ROC STICKER O/S	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,009.81	13,805.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,115.35
Total Parts (\$\$)	26,009.81	10,690.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO TRANSFER FRONT DOOR MECHANISM	New	150.00	0.00
3	TO REFILL AIR CON GAS	New	150.00	100.00
4	TO DISMANTLE & REFIX FRONT DASHBOARD	New	280.00	200.00
5	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	120.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	60.00
7	TO SPRAY RUST PROOFING	New	150.00	50.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,400.00
9	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			5,210.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >