

ASS. REC. BY:

REF:

093/AIG19000883/Bcd307

Special Instruction:

Survivor:
Melina

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

15/1/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8GT9196X

Insured:

SKQ5204B

at Workshop m/s

EM Solution

Tel:

64560226, Bernard.

of

160 SIM #03-18

Policy No:

Claim No:

9398991651SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

15/1

Person Contacted:

Vehicle **IN** / OUT

Date/Time

Action/Instruction (X) Estimate

8GT9196X - X

SKQ5204B - X

Demand: 15/1/2019

Surveyor

REF: AIG

ASSIGNMENT

From _____ Date: 15/1/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGT 9196 X

at Workshop m/s EM Solution

of 160 SIN MIN G DR # 03-18

Insured _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No SGT 9196 X Yr Regn: 26/4/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (MPV)

Make: TOYOTA PICNIC C.C 1988

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 260938 T/Radio: Insured / Std / NI / NA

Eng/No: 1AZ55A9807

C/No: JTEGH23B800023151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 215/60/16 R: 215/60/16

BS / DUN / EXNOVA / GS / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/1/2019 D.O.I. 15/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 22,000.00
PV 17,047.00
NV 4,953.00

TCU m 15/1/19

Date/Time, File Pass to? [] : Preli. Report

1) [] : Final Report

Date/Time, File Return to?

2) []

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: 180

Transportation: S + RS St

Add Fee: [] : Site Insp (\$)

[] : Interview (\$)

[] : Tech. Invs (\$)

[] : Weekend (\$)

[] : Photos

[] : Others

[]

[]

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL 200

Catherine Chong (LKK Auto)

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Tuesday, 15 January, 2019 9:07 AM
To: assignments; Admin A
Cc: Fong, Andy-SY
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKQ5204B AND SGT9196X ON 11/01/2019
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-01-22 09:06 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKQ5204B AND SGT9196X ON 11/01/2019

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Tuesday, 15 January, 2019 9:06:46 AM

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com |www.aig.sg

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Monday, January 14, 2019 2:50 PM

To: Hor, Yinrul

Cc: EM Solution Pte Ltd; judysoh@visionlawllc.com; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur

Subject: OUR REF.: E21-109291.19 (SGT 9196X @ 11.01.2019) // AIG REF.: SKQ 5204B

Importance: High

Dear Yinrul,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: YEO ENG TECK

ACCIDENT INVOLVING SGT 9196X & SKQ 5204B ON 11 JAN 2019 ALONG WOODLANDS INDUSTRIAL PARK'S STREET A SLIP ROAD TO WOODLANDS AVE 3 AT ABOUT 18:30 HRS

We refer to your email of even date below and your list of surveyors.

TAKE NOTICE that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

Name of Surveyor	Company Name
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

Please be informed that the said vehicle can be inspected at:-

Venue : E M SOLUTION PTE LTD
160, Sin Ming Drive, #03-18/19, Sin Ming
Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9985H
Vehicle Details	
Vehicle No.:	SGT9196X
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	1AZ5549807
Chassis No.:	JTEGH23B800023151
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,702.00
Original Registration Date:	26 Apr 2007
First Registration Date:	26 Apr 2007
Transfer Count:	1
Actual ARF Paid:	\$27,173.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$17,047.00
Total Rebate Amount:	\$17,047.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Jan 2019

OK

Dep 7,140/yr
595/mth

MV 22,600.00
PV 17,047.00
NV 4,953

[Signature]
15/1/19



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.88%P.A Lowest Interest@GV
Cars Financing \$1500
Downpayment Monthly From
\$468
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE.LTD. GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 100 results/page

46 vehicles

Toyota Picnic

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Picnic	Any	Any	> 10 year(s) old	Any	Any	Any	All



Toyota Picnic 2.0A (COE till 05/2022) \$23,800 \$7,140 /yr 16-May-2007 1,998 cc - MPV Available

Cny Sales New Arrival, Cheapest In Market Low Downpayment \$3k Mthly From \$638 Trade In Available Call To View Before Is Gone.

Posted: 14-Jan-2019 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota



Toyota Picnic 2.0A (COE till 04/2022) \$25,800 \$7,870 /yr 27-Apr-2007 1,998 cc - MPV Available

2.88% Per Annum Lowest Interest At \$688 Monthly For Toyota Picnic. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

Posted: 14-Jan-2019 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

PREMIUM AD



Toyota Picnic 2.0A (New 5-yr COE) \$37,888 \$7,570 /yr 23-Dec-2008 1,998 cc 113,000 km MPV Available

2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! Trade In Welcome! Priced Lowest In The Market Yet Comes With Accessories! Well Maintained, Excellent Conditio...

JDM Cars

Posted: 13-Jan-2019 Tags: 2008 Toyota Picnic, 2008 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota



Toyota Picnic 2.0A (New 5-yr COE) \$36,800 \$7,360 /yr 14-Jan-2009 1,998 cc 112,108 km MPV Available

Drive With Assurance! Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA/VICOM Inspection Welcome! Flexible Bank/ In House Loan Easy Approval, Top Up \$3k, Low Monthly Installment,...

Creative Auto

Posted: 13-Jan-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Picnic 2.0A (New 5-yr COE) \$39,800 \$7,960 /yr 14-Jan-2009 1,998 cc 120,000 km MPV Available

Beautiful Ocean Blue, Big Spacious MPV For Your Family Enjoyment & Good For Work Coupled With Toyota Reliability & Durability. Previous Owner An Expatrtie CEO Used It Only For His Family Weekend Outl...

Car House Pte Ltd

Posted: 13-Jan-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota



Toyota Picnic 2.0A (COE till 02/2022) \$52,500 \$6,490 /yr 14-Feb-2007 1,998 cc - MPV Available

1 Owner! Accident Free! Service Regularly Without Fail. Major Wear And Tears Parts Have Fully Replaced. Stylish Looks, Spacious And Comforts Yet Powerful To Move Around. Dream Of Owning It? Grab It No...

Posted: 12-Jan-2019 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

Compare

Email: sm@idac.com.sg
Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 11 / 01 / 2019 (dd/mm/yy) Time of Accident: 18 : 30 (24-HR-FORMAT)
Vehicle No.: S6T9196X Vehicle Make & Model: Toyota Picnic
Exact location of Accident: Woodland Industrial Park 3 Street 1 slip road to Woodland Avenue 3
Policyholder's Name / IC No.: Yeo Eng Teck S7269985H
Driver's Name / IC No.: _____ (As Above)
Driver's Contact No.: 82687193 Company Contact No.: _____
Driver's Address: Blk 662, Woodlands Ring Rd, #09-212, Singapore 730662
Insurance Company: AXA Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

Own Insurance Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Private use / Work purpose

Occupation (nature of job): Indoor / Outdoor

No. of Passengers (Including Driver): 1

Passenger Name : _____
Passenger Name : _____

Gender : Male / Female
Gender : Male / Female

Weather condition & Road conditions? (On the day of accident)

Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? Yes / No

Any Injuries: Yes / No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: Yes / No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: Wong Tat Hui Vehicle No.: SKQ5204B

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No.: _____


Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/1/2019 @ 1830 hrs I was at slip road waiting to turning left to Woodlands Avenue 3. A vehicle collided onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORCAR (Rear)

Vehicle No: **SGT 9196X**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEG	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RH	BR	✓ 1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEG	✓ 3	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	NEG	✓	
1185	994545	Tailgate Garnish	BR	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	BR	✓ 2	
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEG	✓	
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber	cut	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			BR
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			TN ✓
1232	993415	Rear RH Fender Inner Garnish			BR ✓
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1196	990247	Sticker			

[Handwritten Signature]
22/1/2019

No of Items: 17

Assessor: T. G. Lim

15/1/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2019 Edit Reg		15 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: WONG TAT HUI (WANG DAHUI) , Co. Reg. No.: -									
Main Claimant: YEO ENG TECK									
Vehicle Reg. No.: SGT9196X		Date of Loss: 11/01/2019 18:00 - :59 [140 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9398991651SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SKQ5204B		Policy No. (Claimant):							
		Excess:							
Repairer: Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 29/01/2019]									
Insurer's Solicitor: VISION LAW LLC (HQ) - Tel: 65342811 ... Incoming Assignment									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (21/01/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGT9196X (9398991651SG)**
[SKQ5204B]
TP
YEO ENG TECK
Jan 11 2019 6:00PM
[WONG TAT HUI (WANG DAHUI)]
Em Solution Pte Ltd (160 Sin Ming)

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <input type="button" value="View in Browser"/>
Video						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print
1	22/01/19 10:10	Video - Accident <small>From:OD - Reg. No: SKQ5204B, Claimant: WONG TAT HUI (WANG DAHUI)</small>			Load MP4	<input type="checkbox"/>
Photos/Images						3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
2	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
3	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
4	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
5	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
6	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
7	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
8	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
9	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
10	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
11	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
12	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
13	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
14	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
15	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
16	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
17	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
18	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
19	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
20	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
21	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
22	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
23	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
24	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
25	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
26	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
27	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
28	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
29	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
30	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
31	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
32	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>
33	18/01/19 13:47	General View			Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	18/01/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	18/01/19 13:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/01/19 10:10	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer Insurer's Solicitor

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19000883/BCD3E2

Date: 23/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:
Claimant Vehicle No : SGT9196X	Insured Vehicle No : SKQ5204B
Date of Loss: 11/01/2019	Nature of Claim: TP Claim No: 9398991651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT9196X	Engine No: 1AZ5549807
Make & Model: TOYOTA PICNIC, 2.0 (A)	Chassis No: JTEGH23B800023151
Reg. Date: 26/04/2007 (Man. Year: 2006)	Odometer: 260938 km
Colour: Blue	
Engine Capacity: 1998 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/01/2019	
Date Inspected:	15/01/2019 Inspected At:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR RH	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Dislodged	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
7	1		*TAILGATE	Dented	0.00 F	*- F
8	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GARNISH	Broken	0.00 F	*- F
11	2		*TAILGATE LAMP	Broken	0.00 F	*- F
12	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
15	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
16	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
17	1		*REAR RH FENDER INNER TRIM	Torn	0.00 F	*- F
18	1		*REAR RH FENDER INNER GARNISH	Broken	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >