

ASS. REC. BY:

REF:

CS/A1619000884/Bed302

Special Instruction:

家丹

Surveyor

Munir

ASSIGNMENT (Office)

From (Person):

Viviane

of

A16

Date/Time:

14/1/2019.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FT1005D

Insured:

SH 3223 Z

at Workshop m/s

O.M. Motor

Tel:

8799 0940 John Ng

of

10 Kaki Bukit Rd 2 #01-36

Policy No.:

Claim No.:

30966699768G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/1/2019

(Client's Record)

15/1/2019 After 3pm.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

15/1

Person Contacted:

John

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FT1005D - X

SH 3223Z - X

15/1

Owner drive back the vehicle without informing workshop. Repairer will rearrange.

REF: AIG

ASSIGNMENT

From: _____ Date: 15.1.19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FT 1005D

at Workshop m/s OM MOTOR

of 10 Raki Bukit Rd 2 # 01-36

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FT 1005D Yr Regn: 16A/2001

Type: M.Car / ~~M.Cyco~~ / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA C.C 399

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: Meter damaged T/Radio: Insured / Std / NI / NA

Eng/No: NC 23E2020457

C/No: NC-39-1020454

Gen. Cond: Good / Fair / ~~Poor~~ / Burnt

Steering: Inorder / ~~Jammed~~ / Leaked / Burnt or

Brake: ~~Inorder~~ / Jammed / ~~Weak~~ / Burnt or

Modi: Nil / ~~SRim~~ / STD A/Rim or

Tyre Size: F: 120/60R17

R: 160/60R17

~~BS~~ JY / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 11.1.19

D.O.I. 15.1.19

Survey held at OM MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 AUG 2019

13/03/19 Confirmed L/S \$2,700/- @ 3 days with LTA.
(\$3,149 /- Red - 54%)

[Signature]
13/3/2019

[Signature]
8/4/2019

TC time in
25/2/19

Date/Time, File Pass to? : Preli. Report

1) *Typist* : Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

240
11
261

Report Format :

Lump Sum / I.B.I: (\$ 2,700 /- L/S)

RE: Pre repair inspection request - FT1005D VS SLL3223Z (OI) DOA: 11/01/2019

From: Hor, Yinnul
 To: Admin A (admin-a@ikkauto.com), 'assignments@ikkauto.com'
 Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur
 Sent: Monday, 14 January, 2019 5:55:01 PM

Thanks & Regards,

Yin Rul, Hor (Viviane)
 AIG
 Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
 Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: Hor, Yinnul
Sent: Monday, January 14, 2019 5:44 PM
To: Claims
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur
Subject: aigencrypt Pre repair inspection request - FT1005D VS SLL3223Z (OI) DOA: 11/01/2019
Importance: High

Hi,

Please refer to the enclosed request from VISION LAW LLC

Claim no : 3096669976SG003
 Case Owner : WEI ZHONG BENNIE TAN

If you have any queries/concerns, please let us know.
 Kindly assist to assign **MOHAMAD TAUFIKH** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)
 AIG
 Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
 Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Monday, January 14, 2019 5:24 PM
To: Hor, Yinnul
Cc: ngwingann@gmail.com; 'OM Rental'; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur; judysoh@visionlawllc.com
Subject: RE: OUR REF.: O29-109297.19 (FT 1005D @ 11.01.2019) // AIG REF.: 3096669976SG003 (SLL 3223Z)
Importance: High

URGENT

Dear Yinnul,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: NUR HIDAYAT BIN JEFREE
ACCIDENT INVOLVING FT 1005D & SLL 3223Z ON 11 JAN 2019 ALONG YIO CHU KANG ROAD AT ABOUT 22:00 HRS

Further to our email of env date below, kindly arrange Mr Mohamad Taufikh to attend on 15 Jan 2019 (Tuesday) after 2.00 p.m.

Thank you.

Sally Chong

(Secretary)
 VISION LAW LLC
 133 NEW BRIDGE ROAD,
 #18-01/02, CHINATOWN POINT,
 SINGAPORE 059413
 TEL.: 6534-2811 (ext 115)
 FAX : 6535-6802

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Monday, 14 January, 2019 4:58 PM
To: 'Yinnul.Hor@aig.com'
Cc: 'ngwingann@gmail.com'; 'OM Rental'; 'Fong, Andy-SY'; 'Chin, Lee-Ying'; 'Abu Kassim, Noor Mariesa'; 'Azlan, Syazairdina'; 'Chan, Yoke Shi'; 'Lim, Sheng Yang'; 'Md Ishak, Mohd Imran'; 'Mithoosingh, Aashweenjeetkaur'; 'judysoh@visionlawllc.com'
Subject: OUR REF.: O29-109297.19 (FT 1005D @ 11.01.2019) // AIG REF.: 3096669976SG003 (SLL 3223Z)
Importance: High

URGENT

Dear Yinnul,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NUR HIDAYAT BIN JEFREE

ACCIDENT INVOLVING FT 1005D & SLL 3223Z ON 11 JAN 2019 ALONG YIO CHU KANG ROAD AT ABOUT 22:00 HRS

Thank you for your email of even date below with your list of surveyors.

Our client confirms the appointment of Mr. Mohamad Taufikh - LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue	:	O. M. MOTOR SERVICES 10, Kaki Bukit Road 2, #01-36, First East Centre, Singapore 417868
Contact	:	Mr. John Ng (Tel: 6538-1009 / H/P: 8799-0940)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL: 6534-2811 (ext 115)
FAX: 6535-6802

From: OM Rental [mailto:omrental0136@gmail.com]

Sent: Monday, 14 January, 2019 4:50 PM

To: Sally Chong

Subject: Re: OUR REF.: O29-109297.19 (FT 1005D @ 11.01.2019) // AIG REF.: 30966699765G003 (SLL 3223Z)

Dear Sally,

We advise surveyor as follow:

Mohamad Taufikh	LKK Auto Consultants Pte Ltd
-----------------	------------------------------

Thank you.

Best Regards,
Mr Ng 87990940

On Mon, Jan 14, 2019 at 4:40 PM Sally Chong <sallychong@visionlawllc.com> wrote:

Dear John/Lynn,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NUR HIDAYAT BIN JEFREE

ACCIDENT INVOLVING FT 1005D & SLL 3223Z ON 11 JAN 2019 ALONG YIO CHU KANG ROAD AT ABOUT 22:00 HRS

Pls advise on surveyor as follows:-

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: Hor, Yinrul
Sent: Mon, 14 Jan 2019 08:34:55 +0000
To: Sally Chong
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Md Ishak, Mohd Imran, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL3223Z AND FT1005D ON 11/01/2019

Without Prejudice

Your Reference : O29-MISC.19
Our Reference : 3096669976SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repairs survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repairs survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]

Sent: Monday, 14 January, 2019 3:39 PM

To: 'Yinrul.Hor@aig.com'; 'Azlan, Syazairdina'; 'Lee-Ying.Chin@aig.com'; 'AIGSGP_ClaimsSurvey@aig.com'; 'Lim, Sheng Yang'

Cc: 'ngwingann@gmail.com'; 'Leong, Kah Yin'; 'Hassim, Mohd Fitri'; 'Abu Kassim, Noor Mariesa'; 'Md Ishak, Mohd Imran'; 'judysoh@visionlawllc.com'

Subject: OUR REF.: O29-MISC.19 (FT 1005D @ 11.01.2019) // AIG REF.: SLL 3223Z

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NUR HIDAYAT BIN JEFREE

ACCIDENT INVOLVING FT 1005D & SLL 3223Z ON 11 JAN 2019 ALONG YIO CHU KANG ROAD AT ABOUT 22:00 HRS

We are instructed by NUR HIDAYAT BIN JEFREE to notify you of a road traffic accident ON 11 JAN 2019 ALONG YIO CHU KANG ROAD AT ABOUT 22:00 HRS involving our client's vehicle registration number FT 1005D and vehicle registration number SLL 3223Z driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0214E
Vehicle Details	
Vehicle No.:	FT1005D
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SFYJ
Primary Colour:	Black
Manufacturing Year:	2000
Engine No.:	NC23E2020457
Chassis No.:	NC391020454
Maximum Power Output:	-
Open Market Value:	\$8,450.00
Original Registration Date:	16 Feb 2001
First Registration Date:	16 Feb 2001
Transfer Count:	8
Actual ARF Paid:	\$1,268.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,517.00
COE Rebate Amount:	\$293.00
Total Rebate Amount:	\$293.00
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p> <p>This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.</p> <p>For more information, please visit http://www.nea.gov.sg/mtc incentive or contact NEA at 1800-2255-632.</p>	

The information contained herein is correct as at 08 Apr 2019

OK

Veron Chen (LKKAuto)

From: OM Rental <omrental0136@gmail.com>
Sent: Monday, 5 August 2019 10:47 PM
To: Taufikh (LKKAuto)
Subject: Re: FT1005D FINALISATION

Hi Taufikh,

Thank you for your email. We accept the offer.

Thank you.

Best regards,
Ms Lim 65381009

On Mon, Aug 5, 2019 at 10:15 AM Taufikh (LKKAuto) <Taufikh@lkkauto.com> wrote:

Hi John,

COR lumpsum \$2700 , 3 days.

Regards

Taufikh

Lkk Auto



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2019 12:06
Date Of Accident	11/01/2019 22:00
Exact Location Of Accident	YIO CHU KANG RD & SLIP RD OF SERANGOON GARDEN WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FT1005D
Insured/Policyholder	
Name Of Registered Owner	NUR HIDAYAT BIN JEFREE
NRIC No	S9500214E
Email Address	HIDAYAT1118@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93273559
Alternative Phone No	OTHERS-93273559

Vehicle Particulars

Manufacturer	HONDA
Model	CB400SFYJ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D18MTMC01006780
Cover Note Number	30/10/2018 TO 29/10/2019

Driver

Name of Driver	NUR HIDAYAT BIN JEFREE
NRIC No	S9500214E
Date Of Birth	07/01/1995
Occupation	OUTDOOR
Date Of Driving Pass	25/01/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93273559
Fax Number	
Contact Number	OTHERS-93273559
EMail Address	HIDAYAT1118@GMAIL.COM

Address	APT BLK 531 SERANGOON NORTH AVE 4 #02-271 (S) 550531
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED Remarks : insurer report without present the bike

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	RICHARD
Phone Number	81258770
Email Address	NIL

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL3223Z
Vehicle Make/Model/Colour	MERCEDES BENZ/ SILVER
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	SOO BENG HUAR
NRIC/Passport Number	S2571259E
Contact Number	91389920

Address	NIL
	NIL
Postcode	NIL
Insurance Company Name	
Nature Of Damage	NIL
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	NUR HIDAYAT BIN JEFREE
Approximate Age	24
Injuries Sustain	SENGKANG GENERAL HOSPITAL - 4DAYS OF MC
Injured person in which vehicle?	FT1005D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 531 SERANGOON NORTH AVE 4 #02-271
Postcode	550531

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the information so collected under (d) above may be shared / disclosed:
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.

Handwritten signature of Policyholder

Policyholder's Signature

Date & Time: 17/01/19 12:20pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Handwritten signature of Reporting Centre Personnel

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190112/2037

2 of 3

Report No. T/20190112/2037

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
505784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Details of Vehicle

Vehicle No: T/

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NUR HIDAYAT BIN JEFREE	ID No.	S9500214E
Related Vehicle	FT1005D (Motorcycle)	Contact No.	93273559
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	SOO BENG HUAR	ID No.	S2571259E
Related Vehicle	SLL3223Z (Car)	Contact No.	91389920
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/01/2019 at about 2200hrs, I was on my way back home along Yio Chu Kang Road from Serangoon avenue 3 when a Silver Mercedes registration plate number SLL3223Z came out from the slip road on the side and collided with me on my left side. The car was turning from Serangoon Garden Way heading to Yio Chu Kang Road.

After a few minutes, there was a police car assisting to control the traffic while waiting for the Traffic Police. There were dents on the right side of her vehicle and my motorcycle fell on the left side.

We are not sure whether the driver was injured or not. I had suffered injuries on my left pinky, a cut in my mouth and slight abrasion on my left hip. I then proceeded to Sengkang General Hospital for further check-up and was given 4 days of MC.

No government property were damaged.

Date Recd:
No. of P/



**SINGAPORE
POLICE FORCE**



T/20190112/2037

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

3 of 3

Report No. T/20190112/2037

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F:/ Sgt 2 ASYRAF ISKANDAR BIN RAMLI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/01/2019 11:01
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204 Authentication Stamp NP168	Classification Of Case: 

medical Pg. 1



Reg No : 201220357K

ORIGINAL

MEDICAL CERTIFICATE

EMD20193911

Name NUR HIDAYAT BIN JEFREE		NRIC No. S9500214E
This is to certify that the above-named is unfit for duty for a period of <u>4</u> days from <u>12-Jan-2019</u> to <u>15-Jan-2019</u> inclusive.		
Type of medical leave granted :		
<input type="checkbox"/> Hospitalization Leave	<input checked="" type="checkbox"/> Outpatient Sick Leave	
Admitted on : _____	<input type="checkbox"/> Maternity Leave,	Delivered on : _____
Discharged on : _____	<input type="checkbox"/> Sterilization Leave,	Operated on : _____
This certificate is not valid for absence from court attendance.		
Diagnosis	Surgical Operation (if applicable)	
Fit for light duty from <u>N.A.</u> to <u>N.A.</u>		
Comments :		
The above-named patient attended my clinic at <u>N.A.</u> and left at <u>N.A.</u> No medical leave is necessary.		
Emergency Department Sengkang General Hospital 110 Sengkang East Way Singapore 544886 Not valid without official hospital stamp	Ward No. SKH Emergency Department	Signature, Name (in BLOCK LETTERS) and Designation/MCR No.  CHUA CHENG RONG , 60478Z
	Date 12-Jan-2019	

		NATIONAL HEALTHCARE GROUP POLYCLINICS Ang Mo Kio Polyclinic 21 Ang Mo Kio Central 2 Singapore 569666	
National Healthcare Group POLYCLINICS			
MEDICAL CERTIFICATE		ORIGINAL	AMK19003142
Name : NUR HIDAYAT BIN JEFREE		NRIC : S9500214E	
Type of Medical Leave granted: OUTPATIENT SICK LEAVE The above name is unfit for duty for a period of 2 day(s) from 16/01/2019 to 17/01/2019 inclusive. The certificate is not valid for absence from court attendance. The above named attended Examination/Treatment from 08:13 AM to -- .			
Remarks : For enquiries, please call 63553000			
16/01/2019	Dr. ALVIN LEONG MING WAI (10156G)	Ang Mo Kio	
Date	Issued By	Location	Signature

REPUBLIC OF SINGAPORE DRIVING LICENCE

S9500214E

NUR HIDAYAT BIN JEFREE

Birth Date: 07 Jan 1995
Issue Date: 15 Jan 2016

002519408D



HOME TEAM NATIONAL SERVICE IDENTITY CARD

NUR HIDAYAT BIN JEFREE

S9500214E

SINGAPORE POLICE FORCE

THIS IS NOT A WARRANT CARD



insurer's nric & license Pg. 1

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

C

Class 2B Motorcycles up to 200 CC
Class 2A Motorcycles between 201 CC and 400 CC

EFFECTIVE DATE

15 Jan 2014
29 Oct 2017

S / No. 9000275039

S5500214E



License No: S5500214E

NP 428A

Unauthorized possession, use, retention, alteration, destruction or transfer of this card is strictly prohibited. This card must be returned to the nearest SPT/SCDF station if found.

Date of Birth
07/01/1995

Race
JAVANESE

Date of Enlistment
03/07/2018

Address
APT BLK 531 SERANGOON NORTH AVENUE 4
#02-271 SINGAPORE 550531



Condition (CON)

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
 (12)Missing (13)Tom (14)Unconfirmed (15)Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
 4. Not Consistent (NC)

May 2005

Motorcycle

Vehicle No: FT 1005D

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	CUT	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim	BT	✓	
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	CUT	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube	BT	✓	2
3009	991789	Front Fork Outer Tube	BT	✓	2
3010	991167	Front Fork Bracket	NEC	✓	
3011	991182	Front Fork Oil Seal	NEC	✓	
3012	991174	Front Fork Garnish	NEC	✓	
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing	BR	✓	
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH	BT	✓	
3032	992300	Handle Bar Balancer RH	BT	✓	
1252	992179	Fuel Tank	SCR	R X	
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever	BT	✓	
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard	BT	✓	
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp	BR	✓	
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1457	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem	NEC	✓	
1436	990247	Sticker			
		Rear slider RH	CUT	✓	

No of Items: 18

Assessor: TCGM

Original Copy

mi
25/2/19

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Confirmation(s) is allowed
- Item(s) must be resurveyed and approval from Insurance Company

LIQUI MOLY O.M. MOTOR SERVICES

MOTOR OILS ADDITIVES BIKE CARE

Quotation For FT1005D

Acknowledged by Repairer
Signature:
Date:

No.	Parts	Price
1	Front Fork Tube ✓	\$360.00 ✓
2	Front Fork Spring ✓	\$96.00 ✓
3	Front Fork Service include oil, oil seal, dust cover 50.00 ✓	\$80.00 ✓
4	Front Mudguard ✓	\$120.00 ✓
5	Front outer lower fork tube cover ✓	\$220.00 ✓
6	Front Mudguard Clamp ✓	\$18.00 ✓
7	Signal (Front & Rear) (1 for 1 rear) 60.00 ✓	\$136.00 ✓
8	Headlamp Complete set ✓	\$140.00 ✓
9	Meter Casing (Top glass) ✓	\$95.00 ✓
10	Meter Casing (White centre) ✓	\$85.00 ✓
11	Meter Casing (Black) ✓	\$48.00 ✓
12	Clutch lever and Brake Lever (2set) ✓	\$76.00 ✓
13	Clutch bracket Complete set ✓	\$65.00 ✓
14	Handlebars ✓	\$130.00 ✓
15	Heavy balancer ✓	\$30.00 ✓
16	Side mirror (left and right) ✓	\$48.00 ✓
17	Head Lamp stay ✓	\$85.00 ✓
18	Fuel Tank SCR	\$650.00
19	Radiator Tank Cover 160.00	\$340.00
20	Paintwork (for Fuel Tank, Full cover set, Front mudguard) L	\$480.00
21	No. Plate Mudguard 160.00 ✓	\$180.00 ✓
22	Tail Board 2	\$95.00 ✓
23	Crash Bar ✓	\$80.00 ✓
24	Front Disc ✓ 360.00 ✓	\$642.00 ✓
25	Rims Alignment L 200 ✓	\$60.00 ✓
26	Centre T bar ✓	\$220.00 ✓
27	Steering Cone ✓	\$90.00 ✓
28	Alignment body L ✓	\$380.00 ✓
29	Exhaust pipe damage Bike fall on left side	\$400.00
30	Labour L * + 300.00 ✓	\$400.00 ✓
Total		\$5,849.00

BT ✓
NEC ✓
NEC ✓ L 50 ✓
CUT ✓
NEC ✓
BT ✓
BR ✓
CUT ✓
BR ✓
BR ✓
BT ✓ \$38 ✓
CUT ✓
BT ✓
BR ✓
BT ✓
SN - \$100 L ✓
ANG DD ✓ \$160
300 ✓ L
BR ✓
ind ✓ ✓
BT ✓
ANG BT ✓
30.00 L
NEC
100 - L
NNX
L

ants 2861
10% - 2574.90
bow - 880
3454.90
165 \$ 2700 *
3 days

Lump Sum
Mr John
28/2/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HINDOO TRADING , Co. Reg. No.: 52939900L								
Main Claimant:	NUR HIDAYAT BIN JEFREE , ID: S9500214E								
Vehicle Reg. No.:	FT1005D	Date of Loss:	11/01/2019 22:00 - :59 [214 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3096669976SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 17/04/2018 - 16/04/2019						
Vehicle Reg. No. (Insured):	SLL3223Z	Policy No. (Claimant):							
		Excess:							
Repairer:	O.m. Motor Services (HQ) 10 KAKI BUKIT ROAD 2, #01-36, 417868 Kaki Bukit - Tel: 87990940								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 22/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (14/03/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FT1005D (3096669976SG)
[SLL3223Z]
TP
NUR HIDAYAT BIN JEFREE
Jan 11 2019 10:00PM
[HINDOO TRADING]
O.m. Motor Services

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View In Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
2	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
3	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
4	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
5	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
6	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
7	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
8	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
9	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
10	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
11	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
12	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
13	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
14	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
15	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
16	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
17	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
18	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
19	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
20	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
21	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
22	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
23	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
24	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
25	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
26	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
27	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
28	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
29	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
30	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
31	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
32	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
33	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
34	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
35	13/03/19 13:48	General View							Load JPG	<input checked="" type="checkbox"/>		
36	13/03/19 13:48	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
37	13/03/19 13:48	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	13/03/19 13:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/19 09:49	TP GIA REPORT.pdf	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/03/19 16:45	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19000884/BSD3E2

Date: 02/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FT1005D

Insured Vehicle No : SLL3223Z

Date of Loss: 11/01/2019

Nature of Claim: TP

Claim No: 3096669976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FT1005D	Engine No:	NC23E2020457
Make & Model:	HONDA CB400SFYJ, 399cc	Chassis No:	NC391020454
Reg. Date:	16/02/2001 (Man. Year: 2000)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60ZR17	Rear Tyre Size:	160/60ZR17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,449.00	2,629.90	1,819.10	40.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	780.00	620.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,849.00	3,409.90	2,439.10	41.70
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	5,849.00	2,700.00	3,149.00	53.84

INSPECTION

Date of Assignment: 14/01/2019

Date Inspected: 15/01/2019 Inspected At:

O.m. Motor Services (HQ)
10 KAKI BUKIT ROAD 2, #01-36
Singapore 417868

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK TUBE	Bent	360.00 F	*360.00 FL
2	1		*FRONT FORK SPRING	Necessary	96.00 F	*96.00 FL
3	1		*FRONT MUDGUARD	Cut	120.00 F	*120.00 FL
4	1		*FRONT OUTER LOWER FORK TUBE COVER	Necessary	220.00 F	*220.00 FL
5	1		*FRONT MUDGUARD CLAMP	Bent	18.00 F	*18.00 FL
6	1		*SIGNAL (FRONT & REAR)	Broken	136.00 F	*68.00 FL
7	1		*SET HEADLAMP COMPLETE	Cut	140.00 F	*140.00 FL
8	1		*METER CASING (TOP GLASS)	Broken	95.00 F	*95.00 FL
9	1		*METER CASING (WHITE CENTRE)	Broken	85.00 F	*85.00 FL
10	1		*METER CASING (BLACK)	Broken	48.00 F	*48.00 FL
11	1		*SET CLUTCH LEVER AND BRAKE LEVER (2 SET)	Bent (1 set only)	76.00 F	*38.00 FL
12	1		*SET CLUTCH BRACKET COMPLETE	Cut	65.00 F	*65.00 FL
13	1		*HANDLEBARS	Bent	130.00 F	*130.00 FL
14	1		*HEAVY BALANCER	Bent	30.00 F	*30.00 FL
15	1		*SIDE MIRROR (LEFT AND RIGHT)	Broken	48.00 F	*48.00 FL
16	1		*HEAD LAMP STAY	Bent	85.00 F	*85.00 FL
17	1		*FUEL TANK	Scratched	650.00 FS	*100.00 FS
18	1		*RADIATOR TANK COVER	Dented	340.00 F	*160.00 FL
19	1		*NO. PLATE MUDGUARD	Broken	180.00 F	*160.00 FL
20	1		*TAIL BOARD	Cut	95.00 F	*95.00 FL
21	1		*CRASH BAR	Bent	80.00 F	*80.00 FL
22	1		*FRONT DISC	Bent	642.00 F	*360.00 FL
23	1		*CENTRE T BAR	Necessary	220.00 F	*220.00 FL
24	1		*STEERING CONE	Necessary	90.00 F	*90.00 FL
25	1		*EXHAUST PIPE DAMAGE	Not Necessary	400.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,449.00	2,911.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	281.10
Total Parts (\$\$)	4,449.00	2,629.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT FORK SERVICE INCLUDE OIL, OIL SEAL, DUST COVER	New	80.00	50.00
2	PAINTWORK (FOR FUEL TANK, FULL COVER SET, FRONT MUDGUARD)	New	480.00	300.00
3	RIMS ALIGNMENT	New	60.00	30.00
4	ALIGNMENT BODY	New	380.00	100.00
5	LABOUR	New	400.00	300.00
Gross Labour Cost (S\$)			1,400.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >