

INS. CASE OWNER:

CC 6, ALG 1900

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: ☒ Email ☐ Call ☐

Repair Cost: \$5,000

(7 days) Reduction: 5% %

FINAL SETTLEMENT

Date/Time: 18-01-19

Confirm with: BOON

Email ☒ Call ☐

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 28-30000001

If NO or B 28, Ass. Lin : 100

Repair Cost: \$5,000

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS \$500

(\$50 x 7 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS \$200

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS \$5,980.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 18-01-19

Confirm with: BOON

Email ☒ Call ☐

Payee 1:

SS \$5,980.00

Name 1:

ONE CITY AUTO CENTRE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TO / TP / WS / TP RES / OD RES / EVA / INV / MV

TO Inspect Vehicle No: SGT 8074X

at Workshop n/a Car City

at _____ SKN 2150H

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Val. or Market Value: 22500

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: 1 Consistent?: Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No 35

CA / REV / REP. / 24 HRS 35697

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGT 8074X Yr Regn: 4 07

Type: ☒ M.C. / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or ☒ CA /

Make: Toyota WSL on 1794

Colour: Silver AIC: Insured / Std / NI / NA

Sp. Feeding: 38567 T-Ratio: Insured / Std / NI / NA

Engin No: _____

CIN: 2NE10 0359527

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ in order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ in order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: _____ R: 225-145R17

BS / DUN / EXNOVA / GY / FS / LCA / MIC / ORTSU / ☒ FIR / SUMI /

TOYO / YOKO or

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 13/1/19 D.O.L: 15/1/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 16/46 case unt-1 31-3-2022
	3 yrs 2nd plus dep'tk. net 6304
15/1/19	contact 4/5 @ 6000 with MR Ho
	(REQ: + 700240 54%)

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photo: _____

Others: _____

TOTAL: _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300

FAX: 6782 0300

E-mail : ccacpl@singnet.com.sg

TO: AIG ASIA PACIFIC

RANCE PTE

ATTN: MOTOR CLAIMS DEPT

DATE : 15-Jan-19

JOB TYPE : 3RD PARTY CLAIM

VEH NO : SGT8074X

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: ABDUL KARIM BIN MOHAMED SALLEH

ADDRESS:

MODEL : TOYOTA / WISH 1.8A

CHASSIS NO : ZNE100359527

ENGINE NO:

CONTACT NO H/P:

ACCIDENT DATE : 13/01/2019

TEL:

OWNERS INSURER : LIBERTY INSURANCE PTE LTD

POLICY NO: SI18V04436/VPE/RO3

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$422.16	\$422.16 X
2	FRONT BUMPER BRACKET	2	\$67.11	\$134.22 X
3	FRONT BUMPER SIDE RETAINER	2	\$76.22	\$152.44 ✓
4	FRONT BUMPER REINFORCEMENT	1	\$193.55	\$193.55 X
5	FRONT BUMPER SPONGE	1	\$93.65	\$93.65 ✓
6	FRONT BUMPER LOWER GRILLE	1	\$128.85	\$128.85 X
7	FRONT BUMPER CLIP	9	\$3.90	\$35.10 ✓
8	FRONT RADIATOR GRILLE	1	\$127.03	\$127.03 X
9	FRONT RADIATOR GRILLE CLIP	7	\$3.90	\$27.30 X
10	REAR TAILGATE COVER	1	\$1,175.91	\$1,175.91 ✓
11	REAR TAILGATE HINGES	2	\$87.15	\$174.30 X
12	REAR TAILGATE COVER LOCK	1	\$509.10	\$509.10 ✓
13	REAR TAILGATE COVER SWITCH	1	\$129.25	\$129.25 X
14	REAR TAILGATE COVER CHROME	1	\$218.68	\$218.68 ✓
15	REAR TAILGATE COVER LOGO	1	\$46.20	\$46.20 ✓
16	REAR TAILGATE COVER INNER TRIM LOWER	1	\$680.10	\$680.10 ✓
17	REAR TAILGATE COVER INNER TRIM TOP LH & RH	2	\$174.20	\$348.40 X
18	REAR TAILGATE COVER PULL DOWN HANDLE	1	\$47.40	\$47.40 X
19	REAR TAILGATE WEATHER STRIP	1	\$329.10	\$329.10 ✓
20	REAR WINDSCREEN MOULDING	4	\$70.20	\$280.80 ✓

1 OF 4

Not Adhered
when
2/5 x 6000/-
7 day.

15/1/19

Tehyph. H. H. H.
warung.

21	REAR BUMPER	D.S	1	\$422.72	\$422.72	✓
22	REAR BUMPER BRACKET	Set	2	\$57.20	\$114.40	✓
23	REAR BUMPER SIDE RETAINER	Set	2	\$75.60	\$151.20	✓
24	REAR BUMPER REFLECTOR	NF	2	\$61.50	\$123.00	X
25	REAR BUMPER CLIP	MC	9	\$3.90	\$35.10	✓
26	REAR TAILLAMP	CNA	2	\$437.30	\$874.60	✓
27	REAR TAILLAMP PANEL	2	2	\$137.90	\$275.80	X
28	REAR BUMPER EXTENSION RH & LH	2	2	\$95.30	\$190.60	X
29	REAR FENDER INNER LOWER AIR VENT	11	2	\$115.40	\$230.80	X
30	REAR END PANEL	3-1100	1	\$427.76	\$427.76	✓
31	REAR END PANEL GARNISH	1-11	1	\$450.10	\$450.10	✓
32	REAR END FLOOR PANEL	2	1	\$156.70	\$156.70	X
34	REAR FLOOR SIDE PANEL LH [58314]	2	2	\$155.40	\$310.80	X
35	REAR EXHAUST	2	1	\$780.15	\$780.15	X
36	REAR EXHAUST MOUNTING	11	1	\$37.10	\$37.10	X
37	REAR EXHAUST HEAT INSULATOR	11	1	\$115.50	\$115.50	X

PARTS PRICE : \$9,949.87

LESS 25% : \$2,487.47

SUB TOTAL PRICE : \$7,462.40

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	REAR WINDSCREEN SEALANT	2	\$35.00	\$70.00
2	REAR REVERSE SENSOR	1 Set	\$280.00	\$280.00
3	FRONT NUMBER PLATE & HOLDER	1	\$45.00	\$45.00
4	REAR NUMBER PLATE & HOLDER	1	\$45.00	\$45.00

S/N PARTS PRICE : \$440.00

TOTAL PARTS PRICE : \$7,902.40

7-5996.96
4497.72
7967



CLAIM DETAIL : LABOURS & SPRAY PAINTING

No	JOB'S DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. FRONT BUMPER, FRONT SUPPORT PANEL, FRONT HEADLAMP RH & LH, FRONT FENDER RH & LH, FRONT DOOR RH, LH & OTHER.	\$600.00	400	
2	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. REAR TAILGATE COVER, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, REAR TAILLAMP RH & LH, REAR FENDER RH & LH, REAR DOOR RH, LH, ROOF TOP PANEL & OTHER.	\$2,000.00	800	
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$200.00	80	
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT BUMPER, SUPPORT PANELETC.	\$400.00	✓	
5	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. REAR BUMPER, REAR TAILGATE COVER, REAR END PANEL, REAR FLOOR PANEL,ETC.	\$1,200.00	1100	
6	TO REMOVE & REFIT REAR WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$150.00	120	
7	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE. SIGNAL LIGHT WIRE, HEADLAMP WIRE, SENSOR WIRE & OTHER WIRING.	\$90.00	30	
8	TO REMOVE & REFIT EXHAUL. CHECK & REPAIR OR REPLACE THE DAMAGED PARTS.	\$150.00	60	
9	TO REMOVE & REFIT REAR TAILGATE COVER. REAR TAILGATE LOCK INNER & OUTTER, REAR TAILGATE COVER HANDLE, WIPER MOTOR, SWITCH, TRIM BOARD & ALL EMBLEMETC.	\$150.00	60	
10	TO INSTALL REVERSE SENSORS	\$80.00	50	
11	TO APPLY BODY SEALANT ON BODY JOINTS	\$100.00	50	
TOTAL LABOUR & SPRAY PAINTING PRICES:		\$5,120.00		

VEHICLE NO : SGT8074X

ESTIMATE REPORT

TOTAL LABOUR COST : \$5,120.00
TOTAL PARTS COST : \$7,902.40
TOTAL REPAIR COST : \$13,022.40

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

PART BY PART OR LUMP-SUM :

DATE OF SURVEY :

SURVEY BY :

CONTACT NO :

FAX NO. :

NOTE : LUMP-SUM AMOUNT OR COST OF
REPAIR WOULD BE REVISED IF
SUPPLEMENT REPAIR IS REQUIRED

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



wish

Price Range

Depreciation

> 10 year(!)

Vehicle Type



Home » Used Cars » Fei Yang Auto » Toyota Wish 1.8A (COE till 01/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

Leasing

YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Toyota Wish 1.8A (COE till 01/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$21,600	
Depreciation	\$7,230 /yr	?
Reg Date	11-Jan-2007 (2yrs 11mths 26days COE left)	
Manufactured	2006	?
Mileage	136,000 km (11.3k /yr)	
Transmission	Auto	
Engine Cap	1,794 cc	
Road Tax	\$1,166 /yr	?
Power	97.0 kW (130 bhp) View specs of the Toyota Wish (2008-2009)	
Curb Weight	1,300 kg	?
Features	-	
Accessories	-	
Description	New Road Tax, Leather Seats, Sport Rim, Reverse Sensor, Well Maintained, Call Before Coming.	
COE	\$26,330	?
OMV	\$17,783	?
ARF	\$19,562	?
Dereg Value	\$15,740 as of today (change)	?
No. of Owners	3	?
Type of Veh	MPV	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 12-Jan-2019 | Last Updated on: 12-Jan-2019

Tags: Toyota Wish, toyota wish, 2007 Toyota Wish, 2007 toyota wish, Toyota, Wish, wish, Used Toyota



Location Map

Seller Information

Company	Fei Ya » deale » 27 ve
Address	3 Ang P Search
Location	Link @
Office No	655616
Contact Person(s)	Jackso Jeffrey

Useful Services

Afraid of lerr
this car eval

Compare

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3569F
Vehicle Details	
Vehicle No.:	SGT8074X
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	VEDA01115
Chassis No.:	ZNE100359527
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,045.00
Original Registration Date:	24 Apr 2007
First Registration Date:	24 Apr 2007
Transfer Count:	1
Actual ARF Paid:	\$18,750.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,174.00
COE Rebate Amount:	\$16,146.00
Total Rebate Amount:	\$16,146.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Jan 2019

OK

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 27 June 2019 12:28 PM
To: ccacpl@singnet.com.sg
Subject: ACCIDENT INVOLVING SGT 8074X & SKN 2150H ON 13/01/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: TP/19012-SGT8074X
Our Ref: CC6/AIG19000887/Uea3

Dear Sirs,

ACCIDENT INVOLVING SGT 8074X & SKN 2150H ON 13/01/2019

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 6,420.00
2. Loss of Use (7days x \$80)	\$ 560.00
3. LTA Search Fee	\$ 2.00
Total:	\$ 6,982.00

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Date: 06 MAR 2019

Your Ref: SKA2150H

Our Ref: TP/19012 – SGT8074X

To: M/s AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way, #08-16
AIG Building
Singapore 079120
Attn: Motor Claims Department

Thru : LKK Auto Consultants Pte Ltd

Dear Sirs,

**RE: DIRECT SETTLEMENT THIRD PARTY CLAIM FOR VEHICLE SGT8074X AGAINST
YOUR INSURED SKA2150H ACCIDENT ON 13.01.2019 ALONG TAMPINES AVE. 4**

Refer to the above.

Attached copies of the following for your perusal:

- 1) Tax Invoice No. IV00017305 - (\$6,420.00)
- 2) Loss of Use 7 days x @\$100.00 - (\$ 700.00)
- 3) GIA Search Fee - (\$ 2.00)
- 4) Authorisation to Act.

Please look into the above claim and let us have your payment of **\$7,122.00** soonest.

Thank you.

Yours faithfully,

Ho Too Boon
General Manager

Showroom

210 Turf Club Road
Lot #C1, C2 & C3
Turf Club Auto Emporium
Singapore 287995
Tel: 6344 9990 Fax: 6344 7554 / 6469 5311

Service Centre

Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
☎ 24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19000887/Upa3

25 FEB 2019

PATRICK KWAN CHEE FOO
BLK 494B TAMPINES AVE 9
#11-460
SINGAPORE 520494

Dear Sir/Madam,

ACCIDENT INVOLVING SKN 2150H / SGT 8074X/ OTHERS ON 13/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SGT 8074X against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Abdul Karim Bin Mohamed Salleh ("the third party claimant")
of Apt BUC 257 Yishun Ring Road #04-1013 Singapore #0257 (address),
owner of SGT8074X (vehicle no.) hereby authorize
CAR CITY AUTO CENTRE PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGT8074X that was
damaged pursuant to the accident which occurred on 13/01/2019 (date) along
TAMPINES Ave 4 (location)
involving vehicle no/s SKN 2150H ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 14th day of JAN (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

"WITHOUT PREJUDICE
to any
PERSONAL INJURIES"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **CAR CITY AUTO CENTRE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$6,420.00** (Repair Cost), **S\$560.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **SGT 8074X** that was damaged pursuant to the accident which occurred on **13/01/2019** (date) along **TAMPINES AVE 4** (location) involving vehicle no/s **SKN 2150H**.

This is pursuant to the inspection conducted on **15/01/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ABDUL KARIM BIN MOHAMED SALLEH** ("the third party claimant") of vehicle no. **SGT 8074X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SGT 8074X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any ^{property} claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19th (day) of July (month) 2019 (year)



CKS
CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

"WITHOUT PREJUDICE
to any
PERSONAL INJURIES"



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

TAX INVOICE

GST Registration : 200719980C

Number : IV00017305

Date : 02/03/2019

Case No :

Vehicle No : SGT8074X

Mileage :

Term: CASH

Model : TOYOTA WISH 1.8 A

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	OUR REF: TP/19012-SGT8074X				
2	DATE OF ACCIDENT: 13/01/2019				
3	PLACE OF ACCIDENT: ALONG TAMPINES AVE 4				
4	BEING PARTS AND LABOUR SUPPLIED TO THE ABOVE				
5	MENTIONED VEHICLE AS PER SURVEYOR REPORT,				
	LKK AUTO CONSULTANTS PTE LTD, LUMP SUM REPAIR	1.0	6,000.00	0.00	6,000.00
SINGAPORE DOLLARS : SIX THOUSAND FOUR HUNDRED TWENTY AND CENTS ZERO ONLY			SUBTOTAL		\$ 6,000.00
			GST 7.00%		\$ 420.00
			TOTAL		\$ 6,420.00

SERVICE DUE : DATE 14/04/2019 MILEAGE 405,347

E. & O. E.

CAR CITY AUTO CENTRE PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Issued by : Ho

Service Centre

Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
☎ 24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-006701
Date of Request: 14/01/2019

Your Ref No: Online Purchase

Car City Auto Centre Pte Ltd
Blk 9006 #01-198
Tampines Street 93
Singapore 528840

Dear Sir/Madam,

Enquiry Date: 14/01/2019
Enquiry By: Ho Too Boon
TP Vehicle No.: SKN2150H
Accident Date: 13/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKN2150H	AIG Asia Pacific Insurance Pte. Ltd.	26/05/2018-25/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2019 Edit Reg		15 Jan 2019 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Patrick Kwan Chee Foo , ID: S1658473H									
Main Claimant: ABDUL KARIM BIN MOHAMED SALLEH , ID: S1393569F									
Vehicle Reg. No.:	SGT8074X	Date of Loss:	13/01/2019 14:00 - :59 [140 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3011065343SG	Policy/Cover Note No.:	2100374053 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKN2150H	Policy No. (Claimant):	S118V04436/VPE/R03						
		Excess:							
Repairer:	Car City Auto Centre Pte Ltd (HQ) Bldg 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (16/01/2019): Request To Upload TP GIA Report AIG_SG (16/01/2019): Conflicting DOA 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGT8074X (3011065343SG)
 [SKN2150H]
 TP
 ABDUL KARIM BIN MOHAMED SALLEH
 Jan 13 2019 2:00PM
 [Patrick Kwan Chee Foo]
 Car City Auto Centre Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	15/01/19 16:44		Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>			
2	15/01/19 16:44		Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>			
3	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
4	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
5	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
6	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
7	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
8	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
9	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
10	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
11	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
12	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
13	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
14	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
15	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
16	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
17	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
18	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
19	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
20	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
21	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
22	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
23	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
24	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
25	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
26	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
27	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
28	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
29	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
30	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
31	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
32	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
33	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			
34	15/01/19 16:44		General View												1	Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
67	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
68	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
69	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
70	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
71	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
72	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
73	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
74	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
75	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
76	15/01/19 16:44	General View	 Load JPG	<input checked="" type="checkbox"/>
77	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 17:13	TP ESTIMATE - MARKED	 Load PDF	
2	17/01/19 17:13	TP GIA REPORT	 Load PDF	
3	31/07/19 08:29	WORKSHOP INVOICE	 Load PDF	
4	31/07/19 08:29	AUTHORISATION TO ACT FORM	 Load PDF	
5	31/07/19 08:29	Release Voucher	 Load PDF	
6	31/07/19 08:29	GIA SEARCH	 Load PDF	
7	31/07/19 08:29	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/01/19 11:58	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKN2150H (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SGT8074X (TP veh)		
Date of Accident:	13/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	13,933.97
Final Repair Cost	:	\$	6,420.00
Loss of Use	:	\$	560.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,982.00

7.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Car City Auto Centre Pte Ltd	:	\$ 6,982.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

31 Jul

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19000887/UEA3Q2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100374053
Claimant Vehicle No : SGT8074X **Insured Vehicle No :** SKN2150H
Date of Loss: 13/01/2019 **Nature of Claim:** TP **Claim No:** 3011065343SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT8074X
Make & Model: TOYOTA WISH, 1.8 (A) **Engine No:** VEDA01115
Reg. Date: 24/04/2007 (Man. Year: 2007) **Chassis No:** ZNE100359527
Colour: Silver **Odometer:** 395607 km
Engine Capacity: 1794 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 **Rear Tyre Size:** 225/45 R17
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,902.40	4,817.72	3,084.68	39.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	3,150.00	1,970.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,022.40	7,967.72	5,054.68	38.82
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	13,022.40	6,000.00	7,022.40	53.93
+ GST 7.00/7.00% (S\$)	911.57	420.00	491.57	53.93
Nett Amount (S\$)	13,933.97	6,420.00	7,513.97	53.93
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,982.00		

INSPECTION

Date of Assignment: 15/01/2019
Date Inspected: 15/01/2019 **Inspected At:**

Car City Auto Centre Pte Ltd (HQ)
 Blk 9006 #01-198, Tampines Street 93
 Singapore 528840

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	422.16 FL	*- FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	134.22 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Bent	152.44 FL	*152.44 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	193.55 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Torn	93.65 FL	*93.65 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	128.85 FL	*- FL
7	9		*FRONT BUMPER CLIP	Necessary	35.10 FL	*35.10 FL
8	1		*FRONT RADIATOR GRILLE	Not Necessary	127.03 FL	*- FL
9	7		*FRONT RADIATOR GRILLE CLIP	Not Necessary	27.30 FL	*- FL
10	1		*REAR TAILGATE COVER	Badly Dented	1,175.91 FL	*1,175.91 FL
11	2		*REAR TAILGATE HINGES	Not Necessary	174.30 FL	*- FL
12	1		*REAR TAILGATE COVER LOCK	Dented / Jammed	509.10 FL	*509.10 FL
13	1		*REAR TAILGATE COVER SWITCH	Not Necessary	129.25 FL	*- FL
14	1		*REAR TAILGATE COVER CHROME	Bent / Cracked	218.68 FL	*218.68 FL
15	1		*REAR TAILGATE COVER LOGO	Necessary	46.20 FL	*46.20 FL
16	1		*REAR TAILGATE COVER INNER TRIM LOWER	Cracked	680.10 FL	*680.10 FL
17	2		*REAR TAILGATE COVER INNER TRIM TOP LH & RH	Not Necessary	348.40 FL	*- FL
18	1		*REAR TAILGATE COVER PULL DOWN HANDLE	Not Necessary	47.40 FL	*- FL
19	1		*REAR TAILGATE WEATHER STRIP	Twisted	329.10 FL	*329.10 FL
20	4		*REAR WINDSCREEN MOULDING	Necessary	280.80 FL	*280.80 FL
21	1		*REAR BUMPER	Distorted	422.72 FL	*422.72 FL
22	2		*REAR BUMPER BRACKET	Bent	114.40 FL	*114.40 FL
23	2		*REAR BUMPER SIDE RETAINER	Bent	151.20 FL	*151.20 FL
24	2		*REAR BUMPER REFLECTOR	Not fitted	123.00 FL	*- FL
25	9		*REAR BUMPER CLIP	Necessary	35.10 FL	*35.10 FL
26	2		*REAR TAILLAMP	Cracked	874.60 FL	*874.60 FL
27	2		*REAR TAILLAMP PANEL	Repair	275.80 FL	*- FL
28	2		*REAR BUMPER EXTENSION RH & LH	Repair	190.60 FL	*- FL
29	2		*REAR FENDER INNER LOWER AIR VENT	Not Necessary	230.80 FL	*- FL
30	1		*REAR END PANEL	Badly Dented	427.76 FL	*427.76 FL
31	1		*REAR END PANEL GARNISH	Twisted	450.10 FL	*450.10 FL
32	1		*REAR END FLOOR PANEL	Repair	156.70 FL	*- FL
33	2		*REAR FLOOR SIDE PANEL LH (58314)	Repair	310.80 FL	*- FL
34	1		*REAR EXHAUST	Repair	780.15 FL	*- FL
35	1		*REAR EXHAUST MOUNTING	Not Necessary	37.10 FL	*- FL
36	1		*REAR EXHAUST HEAT INSULATOR	Not Necessary	115.50 FL	*- FL
37	2		*REAR WINDSCREEN SEALANT	Necessary	70.00 FS	*40.00 FS
38	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
39	1		*FRONT NUMBER PLATE & HOLDER	Bent	45.00 FS	*40.00 FS
40	1		*REAR NUMBER PLATE & HOLDER	Bent	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	10,389.87	6,316.96
- List Item Discount on L Items 25.00/25.00% (S\$)	2,487.47	1,499.24
Total Parts (S\$)	7,902.40	4,817.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AFFECTED PARTS ,PANEL BEATING ON DAMAGED AREAS ,CUT ,WELD ,KNOCK STRAIGHTEN ,REALIGN & RESHAPE.FRONT BUMPER ,FRONT SUPPORT PANEL,FRONT HEADLAMP RH & LH ,FRONT FENDER RH & LH ,FRONT DOOR RH,LH & OTHER	New	600.00	400.00
2	TO REMOVE & REFIT AFFECTED PARTS ,PANEL BEATING ON DAMAGED AREAS ,CUT ,WELD ,KNOCK STRAIGHTEN ,REALIGN & RESHAPE ,REAR TAILGATE COVER ,REAR BUMPER ,REAR END PANEL,REAR FLOOR PANEL,REAR TAILLAMP RH & LH ,REAR FENDER RH & LH ,REAR DOOR RH ,LH,ROOF TOP PANEL & OTHER	New	2,000.00	800.00
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS	New	200.00	80.00
4	TO PUTTY,CLEANING ,SANDING ,POLISHING ,WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS .FRONT BUMPER,SUPPORT PANEL..ETC	New	400.00	400.00
5	TO PUTTY,CLEANING ,SANDING ,POLISHING ,WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS.REAR BUMPER,REAR TAILGATE COVER,REAR END PANEL,REAR FLOOR PANEL....ETC	New	1,200.00	1,100.00
6	TO REMOVE & REFIT REAR WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS	New	150.00	120.00
7	TO CHECK & REPAIR WIRING SYSTEM,REMOVE & REPLACE DAMAGED WIRE,SIGNAL LIGHT WIRE ,HEADLAMP WIRE,SENSOR WIRE & OTHER WIRING	New	90.00	30.00
8	TO REMOVE & REFIT EXHAUL.CHECK & REPAIR OR REPLACE THE DAMAGED PARTS	New	150.00	60.00
9	TO REMOVE & REFIT REAR TAILGATE COVER,REAR TAILGATE LOCK INNER & OTHER ,REAR TAILGATE COVER HANDLE,WIPER MOTOR ,SWITCH ,TRIM BOARD & ALL EMBLEMETC	New	150.00	60.00
10	TO INSTALL REVERSE SENSORS	New	80.00	50.00
11	TO APPLY BODY SEALANT ON BODY JOINTS	New	100.00	50.00
Gross Labour Cost (S\$)			5,120.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >