

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 JANUARY 2019

Third Party Insurer: LONPAC

Vehicle No: SLV1746S

Third Party Veh No: PC3958L

Model: HONDA VEZEL 1.5X

Date of Accident: 14 JANUARY 2019

Chassis: RU11229181 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY RH	1		<i>Not in</i> \$666.70 ✓
2	FRONT DOOR RH	1		<i>R</i> \$963.30 ✓
3	FRONT DOOR GLASS OUTER MOULDING RH	1		<i>Ru</i> \$66.80 ✓
4	FRONT DOOR POWER WINDOW REGULATOR RH	1		\$650.00 ✓
5	RUNNING BOARD EXTENTION COVER RH	1		<i>W</i> \$406.00 ✓
6	FRONT BUMPER	1		REPAIR
7	FRONT FENDER RH	1		REPAIR
8	REAR DOOR RH	1		REPAIR
SUB TOTAL				\$2,752.80
LESS 20%				-\$550.56
PARTS TOTAL				\$2,202.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK FRAME STICKER RH	1		<i>Ru</i> \$45.00 ✓
2	RUNNING BOARD EXTENTION COVER CLIPS	1 SET		<i>Ru</i> \$50.00 ✓
S/N TOTAL				\$95.00

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING / REPAIR & REPLACE ACCIDENT AREAS & ETC	\$1,000.00	<i>400</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	\$1,200.00	<i>600</i>
TO TUFF KOTE / ANTI-RUST	\$60.00	<i>30</i>
TO REMOVE & REFIX FRONT DOOR INNER TRIM RH, FRONT DOOR POWER WINDOW GLASS RH, DOOR INNER LOCK & ETC. TO EFFECT REPLACE ON FRONT DOOR RH	\$150.00	<i>60</i>
TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM BACK TO ORIGINAL CONDITIONS	\$60.00	<i>20</i>

LABOUR TOTAL \$2,470.00

ONG

Not Authorized
Penalty B4 pain
4 days

TOTAL LKK Auto Consultants hence notify the Repairer of the following: **\$4,767.24**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: