



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 14/01/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB51M
Case Reference Number	BUS/01/19/1031
Registration Date	18/12/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Zhang Yanwu
Type of Accident	Head to Rear
Accident Date and Time	11/01/2019 7:50 AM
Accident Reported Date and Time	11/01/2019 9:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB51M - FRONT RIGHT PORTION SHD7292L (TP) - REAR LEFT PORTION. INSURED WITH III. COMFORT TAXI
Prepared Date and Time	14/01/2019 11:49 AM
Chassis Number	WEB63442021000123
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$6,429.22	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$8,995.22	\$0.00
Lump Sum Total	\$9,000.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	14/01/2019 11:57 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00 1590	
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00 324	
Total Spray Painting & Panel Beating	\$446.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER IU	1.00	\$35.00	0.00	\$35.00	Replace NEC	/
			STICKER SG LOVE	1.00	\$35.00	0.00	\$35.00	Replace NEC	/
6009351	GLASS		WINDSCREEN,FRT,CEN TRE, FOR MB OC500 BUS	1.00	\$6,210.00	10.00	\$5,589.00	Replace CRA	/
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace NEC	/
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE,DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace NEC	/
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace NEC	/
6009362	BODY RH		COVER,HEADLAMP,RH, FIBREGLASS,MB OC500	1.00	\$621.00	10.00	\$558.90	Replace CRA	/
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	10.00	\$1,148.85	Replace CRA	/
6009701	VE		LAMP,BLINKER,FRONT, RIGHT, FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace MIS	/
Total					\$8,529.80		\$8,036.52		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Hwee Jie - LKK
14/1/19
c/s 3 days
Photo after paint