

ASS. REC. BY:

REF:

CS3/CT119000923/Ecd30

Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): Flaine Cheong of CTI Date/Time: 15/1/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8LB5258M Insured: GBF3598Sat Workshop m/s Neo Automotive Tel: 6385 5262 / 90914853of 53 Ubi Ave / #05-44Policy No: DMCVSN1666231802 Claim No: SNM19D20023602

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/1/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15/1 Person Contacted: Mrs Neo Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>8LB5258M - NA / INCL 19000655 / 24 DOA: 10/1/2019</u>
	<u>GBF 3598S - X</u>
	<u>Dismantle: 17/1/2019</u>
	<u>After repair: 25/1/2019</u>

Steve

REF:

CTI

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 5258M  
 at Workshop m/s Neo Automotive  
 of 53 Ubi Ave 1 #05-44

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLB 5258M Yr Regn: 12/04/2016  
 Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Toyota Axio XC.C. 1.5Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 195 956

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NRE 1610005860Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Steel rim

Tyre Size:

F:

185/60 R15

R:

185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KAPSEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

10/1/2019

D.O.I.

15/1/2019

Survey held at

Neo AutomotiveDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRE. MV - 54,000  
 PV - 36,331  
 NV - 17,669

repair 100% 11K - 12K

22/1/2019

Date/Time File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation

) S + PS. SI

) Photos

) Other:

) TOTAL

TOTAL

150

Report Format :

PRE

Lump Sum / I.B.I. / S

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

## Catherine Chong (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Tuesday, 15 January, 2019 12:47 PM  
**To:** Ganesh; 'assignments'  
**Cc:** Admin  
**Subject:** RE: FW: PRI - SLB5258M ; Our Ref: CLLC.PD.007.2019 ; Yr Ref: TO BE ADVISED ; Yr Veh: GBF3598S ; DOA: 10.01.2019  
**Attachments:** PRS - SLB5258M.pdf

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear Ganesh,

We refer to your email of 14.01.19.

We are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** Ganesh [mailto:ganesh@centrollc.com.sg]  
**Sent:** Tuesday, 15 January, 2019 11:08 AM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>

# Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road  
#02-21 Manhattan House  
Singapore 169876  
Tel: 6235 0633  
Fax: 6235 6939

Your Ref : To be advised – GBF3598S

Our Ref : CLLC.PD.007.2019

10.01.2019

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**BY EMAIL**

Attn: Officer-In-Charge

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF ORE-ACTION PROTOCOL FOR NIMA CASE**

We act for **PRESTIGE LEASING PTE LTD**, the owner of motor vehicle **SLB5258M**, who has appointed us to act on his/her/their behalf to claim against your insured's vehicle no **GBF3598S** in regards to the road traffic accident on **10.01.2019**.

Please be informed that the said motor vehicle can be inspected at:-

**NEO AUTOMOTIVE PTE LTD**

53 UBI AVE 1  
#05-44 PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934.

Kindly contact: Mrs. NEO Tel: 6385 5262 / 9091 4853 | Fax: 6385 8262

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.



M/S CENTRO-LEGAL LAW CORPORATION

Cc : Mrs. Neo

Fax : 6385 8262

Email : neoautomotive@hotmail.com

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3326H
Vehicle Details	
Vehicle No.:	SLB5258M
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	2NR8483080
Chassis No.:	NRE1610005860
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,350.00
Original Registration Date:	12 Apr 2016
First Registration Date:	12 Apr 2016
Transfer Count:	2
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$32,581.00
Total Rebate Amount:	\$36,331.00

The information contained herein is correct as at 15 Jan 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan. Trade In Are  
Welcome. 100% Refund For  
Unapproved Loan.  
Classic Credit Star4d



Browse by Category ▼








Sort by Date Posted ▼

20 results/page ▼

14 vehicles

toyota axio

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota axio	Any	Any	2016	Any	Any	Any	Available
	<b>Toyota Corolla Axio 1.5A X</b>	<b>\$60,800</b>	<b>\$7,410 /yr</b>	<b>12-Oct-2016</b>	<b>1,496 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
Fast And Easy Loan Approval! Free New Touch Screen Pioneer DVD And Free Brand New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6 Months Engine And Gearbox Full Warranty...								
88 Motor Trading								
Posted: 14-Jan-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Axio 1.5A X</b>	<b>\$59,800</b>	<b>\$7,510 /yr</b>	<b>31-Aug-2016</b>	<b>1,496 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
Fast And Easy Loan Approval! Free New Touch Screen Pioneer DVD And Free New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6/12 Months Engine And Gearbox Full Warranty! B...								
88 Motor Trading								
Posted: 14-Jan-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Axio 1.5A X</b>	<b>\$57,800</b>	<b>\$7,110 /yr</b>	<b>15-Sep-2016</b>	<b>1,496 cc</b>	<b>43,214 km</b>	<b>Sedan</b>	<b>Available</b>
Monthly Installment \$888 Only! 1 Owner Non PHV Car, Good Condition Inside Out Including Warranty And Free Servicing, High Trade In Available. Call Now For More Details.								
Apex Trading Pte Ltd								
Posted: 13-Jan-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Axio 1.5A X</b>	<b>\$53,000</b>	<b>\$7,170 /yr</b>	<b>28-Jan-2016</b>	<b>1,496 cc</b>	<b>54,000 km</b>	<b>Sedan</b>	<b>Available</b>
Irresistible Deal! Lowest Price In Town! Marvelous Condition. Great Fuel Consumption 17km/l. 101% Accident Free! Low Insurance Premium, Low Maintenance Fee. Best Buy Model! Call Us Now!								
Ka-Hup Vehicles Trading								
Posted: 12-Jan-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Hanip Automobiles Pte Ltd - Repair &amp; Servicing</b>							
Hanip Automobiles is one of the few workshops in Singapore which is owned, run and operated by a former diagnostic specialist and master technician.								
More info about this shop								
	<b>Toyota Corolla Axio 1.5A X</b>	<b>\$61,800</b>	<b>\$7,610 /yr</b>	<b>01-Nov-2016</b>	<b>1,496 cc</b>	<b>33,864 km</b>	<b>Sedan</b>	<b>Available</b>
1 Owner, Almost New Japanese Toyota Corolla Axio! Responsive Engine Performance Yet Producing Outstanding Fuel Efficiency! One Of The Best Selling Toyota In The Market! High Trade In, Attractive Loan ...								
Henly Enterprises Co								
Posted: 11-Jan-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Axio 1.5A G</b>	<b>\$58,800</b>	<b>\$7,670 /yr</b>	<b>13-Apr-2016</b>	<b>1,496 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
High Loan Approval Rate! In House Financing Available, Higher Spec G Model, 1 Owner, 100% Accident Free! Low Mileage, Very Well Maintained By								

Compare

Compare



The Previous Owner. Trade In Available, Call Now For Viewl...

Posted: 09-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A G**

**\$52,000**

**\$6,880 /yr**

**27-Jan-2016**

**1,496 cc**

**62,000 km**

**Sedan**

**Available**

Super Low Depreciation. Low Fuel Consumption. Driven By 1 Very Careful Owner, Weekly Washed And Vacuumed. No Eating In Car. Perfect For New Drivers, First Time Car Owners Or Older Folks Due To Extensi...

**DIRECT OWNER**

Posted: 02-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5M G**

**\$77,500**

**\$9,180 /yr**

**23-Nov-2016**

**1,496 cc**

**60,000 km**

**Sedan**

**Available**

One Owner Only! Reliable And Fuel Efficient Sedan. Well Maintained By Owner. Accident Free. View To Believe!

Car Search

**CONSIGNMENT**

Posted: 23-Dec-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A X**

**\$60,800**

**\$7,540 /yr**

**06-Sep-2016**

**1,496 cc**

**-**

**Sedan**

**Available**

S Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing A...

88 Motor Trading

Posted: 20-Dec-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A X**

**\$60,800**

**\$7,410 /yr**

**12-Oct-2016**

**1,496 cc**

**-**

**Sedan**

**Available**

Fast And Easy Loan Approval! Free New Touch Screen Pioneer DVD And Free New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6 Months Engine And Gearbox Full Warranty! Buy ...

88 Motor Trading

Posted: 20-Dec-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Personalise Your Ride Now!**

Differentiate from others and create a personal ride identity with customised stickers, car wraps and designed car plates. List of the best aesthetic specialists available. Each with merchant information and user reviews to help you make the best decision.

Find out more!



**Toyota Corolla Axio 1.5A X**

**\$57,800**

**\$7,110 /yr**

**19-Sep-2016**

**1,496 cc**

**-**

**Sedan**

**Available**

Fast And Easy Loan Approval! Free Brand New Touch Screen Pioneer DVD And Free Brand New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6 Months Engine And Gearbox Full Wa...

88 Motor Trading

Posted: 20-Dec-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A X**

**\$59,800**

**\$7,720 /yr**

**07-Mar-2016**

**1,496 cc**

**56,000 km**

**Sedan**

**Available**

Vehicle Well Maintained! Original Paintwork And Interior! Reliable Engine! No Major Repairs Needed! Low Depreciation! No Obligations! In-House & Bank Loans Available! Kindly Contact Our Sales Advisor ...

Posted: 17-Nov-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A X**

**\$53,700**

**\$7,000 /yr**

**29-Apr-2016**

**1,496 cc**

**36,000 km**

**Sedan**

**Available**

Elegant And Stunning White! Well Maintained By Meticulous Owner With Low Mileage Done! Zero Modification! Buy With A Peace Of Mind From A Company With 30 Years Of Excellent History! Call Now For Viewl...

Posted: 10-Nov-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Axio 1.5A X**

**\$62,800**

**\$7,820 /yr**

**31-Aug-2016**

**1,496 cc**

**21,200 km**

**Sedan**

**Available**

Flexible Loan Lowest Price In The Market Yet Negotiable! Like New Car Condition! Reliable And Economic With Low Fuel Consumption! Very Spacious And Neat Interior And Boot Space! Trade In Welcome! Call...

Tai Huat Automobile

Posted: 09-Nov-2018

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For Compare

s, view Expired ads

20 results/page

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/01/2019 16:20
Date Of Accident	10/01/2019 06:10
Exact Location Of Accident	JUNC REPUBLIC AVE & BEACH RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLB5258M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PRESTIGE LEASING PTE LTD
Co Reg No	201723326H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97984296
Alternative Phone No	OFFICE-97984296
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA AXIO 1.5X A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5094838100-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN KEE BOON DERRICK
NRIC No	S7124546B
Date Of Birth	08/06/1971
Occupation	OUTDOOR
Date Of Driving Pass	18/11/1988
Driving Experience	30 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83330222
Fax Number	
Contact Number	OFFICE-83330222
Email Address	NOEMAIL



Address	BLK 106 POTONG PASIR AVENUE 1 #03-460
Postcode	350106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190110/2081.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3598S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM WEI CHIN

NRIC/Passport Number	G2908029T
Contact Number	83479365
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF INJURED PERSON 1

Name	TAN KEE BOON DERRICK
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLB5258M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refers to police report - 7/20190110/2087

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019		17 Apr 2019 13:53 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>PRESTIGE LEASING PTE LTD,</b> Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	<b>SLB5258M</b>	Date of Loss:	10/01/2019 06:00 - :59 [32 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D200236C02</b>	Policy/Cover Note No.:	DMCVSN1666231802						
Vehicle Reg. No. (Insured):	<b>GBF3598S</b>	Policy No. (Claimant):	5094838100-01						
		Excess:	S\$3,500.00						
Repairer:	<b>Neo Automotive Pte Ltd (HQ)</b> 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 29/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents

**\*SLB5258M (SNM19D200236C02)**  
**[GBF3598S]**



















































**TP**  
**PRESTIGE LEASING PTE LTD**  
**Jan 10 2019 6:00AM**  
**[-]**  
**Neo Automotive Pte Ltd**


Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
2	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
3	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
4	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
5	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
6	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
7	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
8	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
9	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
10	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
11	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
12	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
13	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
14	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
15	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
16	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
17	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
18	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
19	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
20	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
21	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
22	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
23	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
24	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
25	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
26	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
27	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
28	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
29	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
30	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
31	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
32	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
33	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
34	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
35	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
36	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	
37	17/04/19 18:39	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/04/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/04/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>











Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	17/04/19 18:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
150	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
151	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
152	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
153	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
154	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
155	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
156	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
157	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
158	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
159	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
160	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
161	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
162	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
163	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
164	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
165	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
166	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
167	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
168	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
169	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
170	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
171	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
172	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
173	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
174	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
175	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
176	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
177	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
178	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
179	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
180	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
181	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
182	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
183	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
184	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
185	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
186	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
187	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	17/04/19 18:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>





## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/01/19 16:33	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	10/01/19 16:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/01/19 16:32	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	10/01/19 16:32	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	10/01/19 16:32	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	10/01/19 16:32	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	10/01/19 16:32	Police Report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19000923/ECD3E2

Date: 18/04/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1666231802

Claimant Vehicle  
No: SLB5258MInsured Vehicle  
No: GBF3598S

Date of Loss: 10/01/2019

Nature of Claim: TP

Claim  
No: SNM19D200236C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLB5258M

Make &amp; Model: TOYOTA COROLLA, 1.5 (A)

Reg. Date: 12/04/2016 (Man. Year: 2015)

Colour: Blue

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2NR8483080

Chassis No: NRE1610005860

Odometer: 195956 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Front Left Side: KAPSEN 5 mm

Front Right Side: KAPSEN 5 mm

Rear Tyre Size: 185/60 R15

Rear Left Side: KAPSEN 5 mm

Rear Right Side: KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 15/01/2019 Inspected At:

Neo Automotive Pte Ltd (HQ)  
53 UBI AVE 1, #05-44 PAYA UBI  
INDUSTRIAL PARK  
Singapore 408934

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00 - \$12,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2019)
<b>Parts:</b> 143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB5258M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >