

ASS. REC. BY:

RET

CS/CTI19000965/Ktd3/v

Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

15/11/19 @ 5:52pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLG 3721D

Insured:

GBG 3755A

at Workshop n/s

Comfort Delgro

Tel:

6383 8115 / 6383 7362

of

205 Braddell Road

Policy No.

Claim No:

SNM19D200227C02/5

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:11am @ 16/1/19

Person Contacted:

William

Vehicle:

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 3721D - X
	GBG 3755A - X
26/4-	Submit preli report, liability unclear.
26/4	& ✓

ASS. REC. BY:

REF:

C121

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLG 37210 Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda Shuttle c.c. 1496

Colour: M. Black AC: Insured / Std / NI / NA

Sp. Reading: 125345 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: GKR 1006733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: Devanti 185/60R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 10/1/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

0/5/15

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 29 APR 2019

Date/Time, File Pass to?

12/4 Typist

Date/Time, File Return to?

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Fees

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$

**Nivitha (LKK Auto)**

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Tuesday, 15 January 2019 5:52 PM  
**To:** braddell\_operation@sparkcarcare.com; 'assignments'  
**Subject:** FW: SLG3721D CLAIMING AGAINST GBG3755A DOA10012019 CHECK LIABILITY & ARRANGE SURVEY (CLAIM REF: SNM19D200227C02/5)  
**Attachments:** SLG3721D DOA10012019 SAS.pdf; SLG3721D DOA10012019 ESTIMATE.pdf

**WITHOUT PREJUDICE**

Dear William,

We refer to your email of 15.01.19.

Liability not clear – conflicting report.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer to the attachment and proceed to survey the third party vehicle.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell\_operation@sparkcarcare.com]  
**Sent:** Tuesday, 15 January, 2019 5:05 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Cc:** CDGE Braddell Private Cars Crash Repair Counter <braddell\_cr@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>; Denis Teo Chin Chye <denisteo@sparkcarcare.com>  
**Subject:** Fw: SLG3721D CLAIMING AGAINST GBG3755A DOA10012019 CHECK LIABILITY & ARRANGE SURVEY

Dear Elaine Cheong,

As spoken today, kindly refer to the attachment and email below.  
Kindly arrange for survey.

Thanks for your kind attention.

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

---

**From:** CDGE Braddell Private Cars Crash Repair Operation

**Sent:** Thursday, 10 January 2019 5:36 PM

**To:** China Taiping

**Cc:** CDGE Braddell Private Cars Crash Repair Counter; Patrick Chung Chan Kim; Denis Teo Chin Chye

**Subject:** SLG3721D CLAIMING AGAINST GBG3755A DOA10012019 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir / Madam

Please arrange to survey the car at CDGE, Braddell.

And to advice on the liability of the accident.

Car in workshop ready for survey.

Thanks

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAUTO)

---

**From:** CDGE Braddell Private Cars Crash Repair Operation  
<braddell\_operation@sparkcarcare.com>  
**Sent:** Friday, 26 April 2019 5:13 PM  
**To:** Denise Tay (LKKAUTO)  
**Cc:** SUR  
**Subject:** Re: SLG3721D CLAIMING AGAINST GBG3755A DOA10012019 CHECK LIABILITY & ARRANGE SURVEY (CLAIM REF: SNM19D200227C02/5)

Dear Denise Tay,

The said vehicle liability is not clear, we had repaired vehicle under cash with recovery and no finalisation is required.

William Wang

Best Regards  
External Business | ComfortDelGro Engineering Pte Ltd  
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767  
[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

---

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Friday, 26 April 2019 4:19:29 PM  
**To:** CDGE Braddell Private Cars Crash Repair Operation  
**Cc:** SUR  
**Subject:** RE: SLG3721D CLAIMING AGAINST GBG3755A DOA10012019 CHECK LIABILITY & ARRANGE SURVEY (CLAIM REF: SNM19D200227C02/5)

Dear William,

As spoken, please check for me the status of this case.

Any repair done?  
Finalization?

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/01/2019 11:13
Date Of Accident	10/01/2019 08:05
Exact Location Of Accident	PASIR PANJANG FERRY TERMINAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG3721D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	INSURANCE@LIONCITYRENTALS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE 1.5G A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SLG3721D
Cover Note Number	

### Driver

Name of Driver	ONG HAN SIONG
NRIC No	S7515839D
Date Of Birth	17/05/1975
Occupation	INDOOR
Date Of Driving Pass	03/05/2000
Driving Experience	18 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96677706
Fax Number	
Contact Number	
Email Address	GIDEON_ONGSG@YAHOO.COM.SG

Address	BLK 285 TAMPINES ST 22 #05-203
Postcode	520285
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG3755A
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG WING FOO
NRIC/Passport Number	S2584796B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

i understand, acknowledge, agree and consent that:

  - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After dropping passengers at Pasar Panjang Ferry terminal  
 I release my <sup>brake</sup> to allow my car to row forward.  
 Then suddenly van GB613755A cut into my lane at  
 fast speed with impact to the right front corner of  
 my car. ~~it~~ <sup>brake</sup> ~~did~~  
 I ~~brake~~ immediately but the van ~~did~~ not  
 stop immediately until it so close that the side ~~mirror~~ of  
 my car was also scratched.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7515839D



Name  
ONG HAN SIONG  
(WANG HANSONG)  
王 汉 松

Race  
CHINESE

Date of birth  
17-05-1975

Sex  
M

Country of birth  
SINGAPORE



430166505

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S7515839D

Name  
ONG HAN SIONG  
(WANG HANSONG)

Birth Date: 17 May 1975

Issue Date: 13 Apr 2004



001194298G



0162879

UIC No. S7515839D



Date of issue  
01-09-2006

Address  
APT BLK 285 TAMPINES STREET 22  
#05-203  
SINGAPORE 520285

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

	PASS DATE
Class 1 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	01 May 2008

NP 428A

License No. S7515839D





HOTLINE TEL: (88) 6415-2000  
FAX: (88) 6415-3723

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 188)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1989

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)

MLZ 400

COMPREHENSIVE COMMERCIAL MOTOR

CERTIFICATE NO. SLG3721D

(The below excess is subject to GST)

ALL CLAIMS EXCESS S\$2000.00

WINDSCREEN EXCESS S\$100.00

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SLG3721D

LCRF Pte Ltd

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT OF  
INSURANCE FOR THE PURPOSES OF THE ACT

25 February 2018

4) DATE OF EXPIRY OF INSURANCE

24 February 2019

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the insured's order or with their permission.

If You or Your Authorized Driver is below the age of 21 years old and/or has less than 1 year driving experience, the excess is \$50,000 (All Claims)

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### 6) LIMITATION AS TO USE\*

- 1) Use for social, domestic, pleasure purposes and business purposes of Insured
- 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired
- 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst driving a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.

LOSS OF USE Not Included

HIRE PURCHASE COMPANY Refer to Policy Terms and Conditions

\*Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Section 96 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in Singapore 13 Feb 2018

AIG Asia Pacific Insurance Pte. Ltd

000583-000  
Aon Singapore Pte Ltd  
2 Shenton Way  
#26-01 SGX Centre 1  
SINGAPORE 068804

*Marib*

ORIGINAL

AUTHORIZED REPRESENTATIVE

SEPARATE



Comfort/Deflate Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLG3721DMake & Model : HONDA SHUTTLE 1.5G AYear of Manufacture : 2016Chassis No. : GK81006733Ins Company : AIG VS CHINA TAIPINGEngine No. : L15B3537905Excess : -Policy No. : Date of Accident : 10.01.2019Time of Accident : 08:05Suggested Days of Repair : In-house Vehicle Assessor**Repair Estimate**Case Owner : Signature : Parts (a) Cost / List Price Items \$ 3,923.60Plus/Less 20% \$ 784.72Total of Cost / List \$ 3,138.88(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,138.88Labour (Appendix B) \$ 1,630.00Total Repair Cost \$ 4,768.88

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell\_cri@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell\_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
 Company : CKC  
 Survey conducted on : 16/1/19 at

Remarks By Surveyor(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 09 day(s)(c) Resurvey : Required / Not Required(d) Excess \$ (e) Signature of surveyor : Le Date: 16/1/19

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284 62815767

## Spare Parts

Vehicle No : **SLG3721D** Case Owner : **0**

Make & Model : **HONDA SHUTTLE 1.5G A**      Year Manufacture : **2016**

Chassis No : **GK81006733** Engine No : **L15B3537905**

Sales Order : Supplier :

Order By : Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper	1	CM	\$ 1,050.50			✓
2	Front bumper retainer LH	1	Sn	\$ 15.40			X
3	Front bumper retainer RH	1	D/V	\$ 15.40			✓
4	Front bumper clips	1	Rn	\$ 39.00			✓
5	Headlamp RH	1	Sn	\$ 2,250.00			X
6	Headlamp lower bracket RH	1	R	\$ 38.00			X
7	RH front fender	1	Ry	\$ 368.50			✓
8	RH front fender inner shield	1	Sn	\$ 115.60			X
9	RH front fender inner shield clips	1	nm	\$ 31.20			X
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Year of Manufacture : **2016**

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2019		05 Apr 2019 14:56 <a href="#">Edit Adj Rpt</a>	<b>\$52,173.72</b> <a href="#">Edit Estimates</a>	<b>\$52,173.72</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	ID: -								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLG3721D	Date of Loss:	10/01/2019 08:00 - :59 [27 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200227C02	Policy/Cover Note No.:	DMCVSN1750851801						
Vehicle Reg. No. (Insured):	GBG3755A	Policy No. (Claimant):	SLG3721D						
		Excess:	S\$350.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG3721D (SNM19D200227C02)  
[GBG3755A]  
TP  
LCRF PTE LTD  
Jan 10 2019 8:00AM  
[-]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print					
1	10/01/19 12:18	Accident Statement		1 Load HTM						
							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print					
1	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
2	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
3	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
4	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
5	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
6	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
7	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
8	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
9	10/01/19 12:16	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
10	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
11	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
12	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
13	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
14	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
15	10/01/19 12:17	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
2	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
3	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
4	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
5	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
6	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
7	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
8	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
9	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
10	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
11	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					
12	26/04/19 17:18	General View		1 Load JPG	<input checked="" type="checkbox"/>					



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	10/01/19 12:11	<b>Sketch Plan</b> <small>[Linked Accident Report Documents]</small>	1	Load TIF	
No.	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/04/19 15:02	<b>PRS - SLG37210</b>	1	Load PDF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	10/01/19 12:18	<b>Accident Statement</b>	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No.	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	10/01/19 12:16	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	10/01/19 12:17	<b>Accident Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	10/01/19 12:11	<b>Sketch Plan</b>	1	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119000965/KTD3Q2

Date: 06/05/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1750851801

Claimant Vehicle  
No: SLG3721DInsured Vehicle  
No: GBG3755A

Date of Loss: 10/01/2019

Nature of Claim: TP

Claim  
No: SNM19D200227C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLG3721D

Make &amp; Model: HONDA SHUTTLE, 1.5 (A)

Engine No: L15B3537905

Reg. Date: 28/09/2016 (Man. Year: 2016)

Chassis No: GK81006733

Colour: Metallic Black

Odometer: 125345 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Davanti 9 mm Rear Left Side: Giti 8 mm  
Front Right Side: Davanti 9 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,138.88	1,178.72	1,960.16	62.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	995.00	635.00	38.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,768.88</b>	<b>2,173.72</b>	<b>2,595.16</b>	<b>54.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>333.82</b>	<b>152.16</b>	<b>181.66</b>	<b>54.42</b>
<b>Nett Amount (S\$)</b>	<b>5,102.70</b>	<b>2,325.88</b>	<b>2,776.82</b>	<b>54.42</b>

## INSPECTION

Date of Assignment: 05/04/2019

Date Inspected: 16/01/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Braddell)  
205 Braddell Road  
Singapore 579701

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 May 2019)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG3721D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,050.50 FL	*1,050.50 FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	15.40 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Distorted	15.40 FL	*15.40 FL
4	1		*FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
5	1		*HEADLAMP RH	Serviceable	2,250.00 FL	*- FL
6	1		*HEADLAMP LOWER BRACKET RH	Repair	38.00 FL	*- FL
7	1		*RH FRONT FENDER	Bent	368.50 FL	*368.50 FL
8	1		*RH FRONT FENDER INNER SHIELD	Serviceable	115.60 FL	*- FL
9	1		*RH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	31.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,923.60</b>	<b>1,473.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>784.72</b>	<b>294.68</b>
<b>Total Parts (S\$)</b>	<b>3,138.88</b>	<b>1,178.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE RH FRONT FENDER INNER PANEL AND REPLACE DAMAGED PARTS	New	720.00	480.00
2	TO CHECK WIRING FUNCTIONS AND FOCUS HEADLAMPS	New	40.00	15.00
3	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE FRONT BUMPER ,RH FRONT FENDER ,RH FRONT FENDER INNER PANEL AND AFFECTED AREAS	New	750.00	500.00
4	TO CHECK /RE-SET STEERING GEOMETRY AND WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			<b>1,630.00</b>	<b>995.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >