

ASS. REC. BY:

REF

CS/FCI19000974/UTbn2

Special Instruction

Surveyor

Marus

ASSIGNMENT (Office)

From (Person):

Jacanne Yong

of

feI

Date/Time:

5:37pm

16/1/19

Estimated Cost

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3CY 5550D

Insured:

SHD 6687M

at Workshop m/s:

Fastech Auto

Tel:

67465405

of

1 kaki Bukit Ave 6 # 01-46 / 48

Policy No:

Claim No:

D19000461MF84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

8:53am @ 17/1/19

Person Contacted:

Nany

Vehicle IN/OUT

Date/Time

Action/Instruction (✓)

Estimate

17/1 @ 4:40pm - Revised via email pending estimate

(08/11/13) wef
 ASS. REC. BY: Morich REF: Ref

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SCY 5500
 at Workshop n/s: 24
 of: SH/D 6687M
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 556
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCY 5500 Yr Regn: 815
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prima Mover /
 Truck / Trailer or CA
 Make: Mercedes No: 1496
 Colour: Grey A/C: Insured / Std / Nil / NA
 Sp. Reading: 33770 T/Ratio: Insured / Std / Nil / NA
 Engine: _____
 Chassis: JM6BM42A850316163
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or ok
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / STD A/Rim or _____
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: 6 Rear: 6
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 7/1/19 D.O.I. 16/1/19
 Survey held at _____
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or 2/5 R & C
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/2/19 2/5 @ 4750	L7A 45680 6yrs full reg. cont. ins with Alu. (Red: 7955.51, 62%)

RECEIVED 22 FEB 2019

Date/Time, File Pass to? ☐ : Prel. Report
 1) 27/2 Typist ☒ : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 4
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Report Format : TP
 Lump Sum / I.B.I. (\$) 4750

Survey Fee: 170+30
 Transportation: 50
 S - RS: 50+50
 Photos: 59
 Others: 27/1/19
 TOTAL: 409

2x15 = 30

MOTOR SURVEY ASSIGNMENT**Date** 16-01-2019 **Our Ref No.** D19000461MFSH**Accident Date** 07-01-2019 **Claim Type.** Third Party**Insured Vehicle** SHD6687M **Third Party Vehicle.** SCY5550D**Survey Location** 1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY**Contact Person.** NANCY LAM**Contact No.** 67465405/ 0 **Fax No.** 67458520**Survey Type** WITHOUT PREJUDICE: LIABILITY UNCLEAR:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** FASTECH AUTO PTE LTD **Attention.** NIL**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** JOANNEY**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 17 January 2019 4:40 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000461MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SCY 5550D on 16/01/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 17 January 2019 8:54 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000461MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 16 January 2019 5:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000461MFSH/1

Dear Sir/Mdm,

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Must Buy For A 1 Owner Unit. Nice Red Interior Golf!



Extremely Low Mileage. Accident Free Unit! No Chassis Or Engine Damage At All.
AutoPrestige Gallery StarAd

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**








Browse by Category

Sort by Date Posted 20 results/page

13 vehicles

mazda 3

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mazda 3		Any	Any	2015	Any	Any	Any	Available
	Mazda 3 1.5A Deluxe		\$60,555	\$8,360 /yr	28-Jul-2015	1,496 cc	77,000 km	Sedan	Available
New Year Carnival Sale Weekend Offer! Fully Agent Maintained And Serviced! Road Tax Till July 2019! 1 Owner Only! 5 Years Agent Warranty With Free Servicing! Enjoy 2.28% Loan Interest! 100% Loan Avail... Cars Inn Credit Pte Ltd Posted: 16-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3 1.5A Sunroof		\$55,800	\$8,830 /yr	28-Jan-2015	1,496 cc	59,806 km	Sedan	Available
Non Grab/Uber/Rental Car Guarantee. 1 Owner With Low Mileage Done, Still In Original Paintwork And Condition! Peace Of Mind! 100% Accident Free! Call Us Now For Viewing Or Enquiry To Find Out More. Posted: 16-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3 1.5A		\$65,000	\$8,810 /yr	27-Oct-2015	1,496 cc	26,974 km	Sedan	Available
\$1500 Servicing Credit. Fully Agent Maintain Unit. 160 Point Check Done. Low Mileage Of 27K Km Only. One Owner. Super Well Kept Interior Condition With Smooth Running Engine. Hassle Free. No Repair Ne... Incheape Pre-Owned Posted: 14-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3 HB 1.5A Deluxe		\$61,800	\$8,060 /yr	24-Nov-2015	1,496 cc	34,000 km	Hatchback	Available
1 Owner, Low Mileage Used, Fully Maintained By Agent (Trans-Eurokars). Guarantee Non Private Hire /Grab Unit. GPS,Keyless Entry,Start /Stop. Electric Adjustment Seat,Sunroof. Head Up Display. Highest... Posted: 13-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mugen Style Door Visor								
Mugen Style Door Visor (For 2010 Mazda 3 Hatchback) More info about this product									
	Mazda 3 1.5A Deluxe		\$64,800	\$8,560 /yr	11-Nov-2015	1,496 cc	58,341 km	Sedan	Available
Not A Private Hire Unit Assured, Come With \$17,870 OMV And Is High SPECS Sunroof. 1.99% Interest Rate! High In House Loan/Bank Loan Available Call Now! Atlantic Automobile Pte Ltd Posted: 13-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3 2.0A Sport		\$65,000	\$9,540 /yr	16-Jun-2015	1,998 cc	79,000 km	Sedan	Available
1 Owner Agent Unit. Very Well Taken Care Of. Always Parked Under Shelter. Super Reliable, Comfortable And Powerful Ride. Black On Black Colour Combination, Easy To Maintain. Flexible Trade-In And High... Car Empire Automobiles Pte Ltd Posted: 12-Jan-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7532Z

Vehicle Details

Vehicle No.: SCY5550D

Vehicle to be Exported: No

Intended Deregistration Date: 16 Jan 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Grey

Manufacturing Year: 2015

Engine No.: P520307243

Chassis No.: JM6BM42A8G0316163

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$14,340.00

Original Registration Date: 19 Aug 2015

First Registration Date: 19 Aug 2015

Transfer Count: 0

Actual ARF Paid: \$9,340.00 4670

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Aug 2025

PARF Rebate Amount: \$7,005.00

Intended COE Rebate Details

COE Expiry Date: 18 Aug 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$58,700.00

COE Rebate Amount: \$38,675.00

Total Rebate Amount: \$45,680.00

The information contained herein is correct as at 16 Jan 2019

OK

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was driving my vehicle A at BLK 124 Greyland East Ave 1 open carpark. I stop my car to wait for on coming taxi to pass through, suddenly he hit on my RH side portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO SERVICE
N: SCY 5550 D
Date: 16.1.19 14:55



SCY 5550 D

Mazda : Mazda3 : 2013- (BM) : except Rough Road Suspension

Front : Left

Actual	Before	Specified Range
0°08'	0°08'	-1°12' 0°48'
6°16'	6°16'	5°29' 7°29'
-0°29'	-0°29'	-0°05' 0°16'
20°18'	20°18'	
20°26'	20°26'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°53'	-1°53'	-1°12' 0°48'
6°48'	6°48'	5°29' 7°29'
-0°26'	-0°26'	-0°05' 0°16'
21°04'	21°04'	
19°10'	19°10'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°01'	2°01'	-1°30' 1°30'
-0°32'	-0°32'	-1°30' 1°30'
-0°45'	-0°45'	
-0°55'	-0°55'	-0°09' 0°31'

Rear : Left

Actual	Before	Specified Range
-0°57'	-0°57'	-1°59' 0°01'
-0°02'	-0°02'	-0°05' 0°15'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°41'	-0°41'	-1°59' 0°01'
0°08'	0°08'	-0°05' 0°15'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°16'	-0°16'	-1°30' 1°30'
0°06'	0°06'	-0°10' 0°30'
-0°05'	-0°05'	-0°48' 0°48'

not adherent
plate
2/5 \$ 47.50
16/1/18
Hdy.

QTY	PARTICULAR	
1 PCS	FRONT BUMPER	1031.70
1 PCS	FRONT BUMPER SIDE HOLDER O/S	22.70
1 SET	FRONT BUMPER CLIPS	
1 PCS	FRONT BUMPER REINFORCEMENT	
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	
1 PCS	FRONT BUMPER FOG LAMP O/S	
1 PCS	HEADLAMP O/S	2445
1 PCS	FRONT FENDER O/S	333.90
1 PCS	FRONT FENDER INNER SHIELD O/S	129.90
1 SET	FRONT FENDER INNERSHIELD CLIPS O/S	
1 PCS	FRONT SHOCK ABSORBER O/S	428.10
1 PCS	FRONT KNUCKLE ARM O/S	388.20
1 PCS	FRONT KNUCKLE ARM BEARING O/S	168.50
1 PCS	FRONT LOWER ARM O/S	421.50
1 PCS	FRONT DRIVESHAFT O/S	
1 PCS	WIPER WASHER TANK	225.40
1 PCS	FRONT SUPPORT PANEL	
1 PCS	FRONT SPORT RIM O/S	

Deepcut	\$1,215.30	/
Sup	<u>\$68.50</u>	/
rec	<u>\$50.00</u>	/
17	\$574.11	X
17	\$188.50	X
17	\$388.20	X
C24	\$1,866.10	/
MD/Bent	\$615.30	/
Tom	<u>\$288.20</u>	/
rec	<u>\$50.00</u>	/
Sup	<u>\$633.10</u>	/
Carl	<u>\$688.20</u>	/
rec	<u>\$325.00</u>	/
Sup	<u>\$611.20</u>	/
17	\$1,455.10	X
2c	<u>\$285.30</u>	/
17	<u>\$525.20</u>	X
MD/Sup	\$1,018.20	/
	\$10,845.51	

TO CHECK WIRING
TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE
TO REFILL AIR CON GAS
TO CONDUCT WHEEL ALIGNMENT
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$180.00	120
47	\$120.00	X
	\$100.00	80
	\$60.00	30
	\$600.00	400
	\$750.00	400
TO	\$12,705.51	

$p = 6133.3$
 $4906.6 \downarrow$
 2956.64

Acknowledged by Repairer:
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000974/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-02-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6687M	Veh. Inspected	SCY 5550D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000461MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	16/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6BM42A8G0316163	Colour	GREY	
Odometer	33770	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/01/2019	Inspection Date	16/01/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCY 5550D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEEP CUT	1,215.30	1,031.70
1	FRONT BUMPER SIDE HOLDER O/S	BENT	68.50	22.70
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	574.11	-
1	FRONT BUMPER FOG LAMP COVER O/S	NOT NECESSARY	188.50	-
1	FRONT BUMPER FOG LAMP O/S	NOT NECESSARY	388.20	-
1	HEADLAMP O/S	CRACKED	1,866.10	1,866.10
1	FRONT FENDER O/S	DENTED / BENT	615.30	333.90
1	FRONT FENDER INNER SHIELD O/S	TORN	288.20	129.00
1	SET FRONT FENDER INNERSHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT SHOCK ABSORBER O/S	BENT	633.10	428.10
1	FRONT KNUCKLE ARM O/S	BENT	688.20	388.20
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	325.00	168.50
1	FRONT LOWER ARM O/S	BENT	611.20	421.50
1	FRONT DRIVESHAFT O/S	NOT NECESSARY	1,455.10	-
1	WIPER WASHER TANK	DEFORMED	285.30	225.40
1	FRONT SUPPORT PANEL	NOT NECESSARY	525.20	-
1	FRONT SPORT RIM O/S	DENTED / BENT	1,018.20	1,018.20
	LESS 20% DISCOUNT		-	-1,226.66
			10,845.51	4,906.64
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		180.00	120.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		100.00	80.00
	TO SPRAY RUST PROOFING.		60.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		750.00	400.00
			1,860.00	1,050.00
GRAND TOTAL			12,705.51	5,956.64