

INS. CASE OWNER:

DANIEL

CC 4/111 1900

5990, Rinasay

LKK:

IDAC:

Surveyor:

KAGUL

D.O.I.

ASSIGNMENT

23/01/19

Date / Time

Registers: J / a Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 7794 X

Name of Insured:

C/M

Insured Tel No.:

HP:

Excess Sec II :S5

D.O.A.:

10/1/19

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

HCT 19010247

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Insurance:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

23/1/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
29/01/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
29/01/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
07/02/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
26/02/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
28/02/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c
12/04/19	pk 76 c	pk 76 c	pk 76 c	pk 76 c	pk 76 c

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$ 998.03	(1 days) Reduction:	33 %
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	26
Repair Cost:	S\$ 1,067.89		
Loss of Rental (LOR):	S\$ -	( days)	
Loss of Use (LOU):	S\$ 30.00	(530 x 1 days)	
Loss of Income (LOI):	S\$ -	(S x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	(Tick only one)	
GIA/LTA Search	S\$ -		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost	S\$ -		
Total:	S\$ 1,097.89	Global Sum S\$:	-
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ 1,097.89	Name 1:	PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	S\$ -		
Payee 3: (Strike if N.A.)	S\$ -		

<div style="display: flex; justify-content: space-between;"> <div> <p>Form</p> <p>REF:</p> </div> <div> <p>990 (Kha3)</p> <p>12558</p> </div> </div>							
<p><b>ASSIGNMENT</b></p>							
<p>From: _____ Date: _____</p> <p>Estimated Cost: _____</p> <p>OD: <u>C</u> / TP / WS / TP RES / OD RES / EVA / INV / MV</p> <p>To Insured Vehicle No: <u>FK 76C</u></p> <p>at Workshop n/s: <u>PERFORMANCE</u></p> <p>at: <u>315, ALEXANDRA RD</u></p> <p>Insured: <u>111</u></p> <p>Policy No: _____</p> <p>Claims No: _____</p> <p>Sum Insured: _____ Excess: _____</p> <p>(Client's Record)</p> <p>Make of Veh: _____</p> <p><u>William 96328105</u></p> <p>(Policy Condition)</p> <p>Remark: The veh had commenced its repair at the time of inspection.</p> <div style="display: flex; align-items: center;"> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr> <td colspan="2"></td> </tr> <tr> <td>N/S</td> <td>O/S</td> </tr> <tr> <td></td> <td></td> </tr> </table> <div style="margin-left: 10px;"> </div> </div> <p>Bal. or Market Value: _____</p> <p>IDAC Accident Rpt: _____ Consistent? : Yes or No</p> <p>GIA / PR Seen: _____ Consistent? : Yes or No</p> <p>Est. Repairs: <u>1</u> days Res: Yes or No</p> <p>Lum Sum: <u>-</u> % 3 Val: Yes or No</p> <p>CA / REV / REP. / 24 HRS</p> <p>Date: _____ Person Contacted: _____</p> <p style="text-align: right;">Vehicle: IN / OUT</p>			N/S	O/S			<p>Veh No: <u>FK 76C</u> Vt Regn: <u>2017 MATR</u></p> <p>Type: M/Car / <u>Cycle</u> / Bus / Van / Lorry / Taxi / Prime Mover /</p> <p>Truck / Trailer or _____</p> <p>Make: <u>B.M.W R 1200 GSA</u> CC: <u>1170</u></p> <p>Colour: <u>BLACK</u> A/C: Insured / Std / NI / NA</p> <p>Sp. Reading: <u>16256</u> T/Radio: Insured / Std / NI / NA</p> <p>Eng/No: _____</p> <p>C/No: <u>WB10 A0208H2911367</u></p> <p>Gen. Cond: Good / <u>Poor</u> / Poor / Burnt</p> <p>Steering: <u>Order</u> / Jammed / Leaked / Burnt or</p> <p>Brake: <u>Order</u> / Jammed / Leaked / Burnt or</p> <p>Mod: <u>C</u> / S/Rim / STD A/Rim or</p> <p>Tyre Size: F: <u>120/70R19</u></p> <p style="margin-left: 150px;">R: <u>170/60R17</u></p> <p>BS / DUN / EXNOVA / GY / FS / LIZA / <u>MC</u> / OHTSU / PIR / SUMI /</p> <p>TOYO / YOKO or _____</p> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p><u>Front</u></p> <p>R/Bal: <u>5</u> mm</p> <p>L/Bal: _____ mm</p> <p>D.O.A: <u>10/01/19</u></p> </div> <div style="width: 45%;"> <p><u>Rear</u></p> <p>R/Bal: <u>6</u> mm</p> <p>L/Bal: _____ mm</p> <p>D.O.A: <u>23/01/19</u></p> </div> </div> <p>Survey held at: <u>PERFORMANCE</u></p> <p>Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or</p> <p style="text-align: center;"><u>N/S REAR</u></p> <p>The U/C / Chassis frame / Body Structure affected due to collision:</p>
N/S	O/S						
<p>Date / Time      Action / Instruction</p>							

P/P \$ 998.03  
(RSP: \$ 511.76 / 51%)

Date/Time: File Pass to?

1)

Date/Time: File Return to?

2)

Report Format:

Lump Sum / L.B.E (\$

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp \$

☐

Inten/ow \$

☐

Tech Insp \$

☐

Workshop \$

Survey Fee

Transportation

1 24 RS \$

1 \$

1 \$

1 \$

TOTAL


## Performance Motors Limited

A member of the Fine Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Fine Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190886 (AfterSales)  
Fax: 63449771

315, Alexandra Road  
Fine Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/535 (Motorrad)  
64786631 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : w5 49769  
Date Estimated : 15/01/2019  
Prepared By : William Teh Hooi Teik

Page No. : 1 of 4

## - ESTIMATE REPAIR FOR -

Mohamed Nasruddin Bin Mohamed ISA  
273 Tampines Street 22  
#03-46

Singapore 520273

## - ACCOUNT - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FK76C	Z911367	03/03/2017	R 1200 GSA	15949

## DESCRIPTION

Replacing damaged parts cause by accident.

Accident on 10/01/2019 0830hrs at service road of carpark Blk  
273 Tampines St 22.

3rd party claim against SHA7794X  
-India International Insurance Pte Ltd.

This estimate is based on visual inspection only.  
Additional fees and parts may be require during the course  
of repair.

All parts price is subject to change without prior notice.

## VALUE

300 650.00

0.00

0.00

0.00

0.00

Total Labour 1: 650.00

## PART NUMBER DESCRIPTION

77418562409 ALUMINIUM CASE 1/2  
77498544517 REPAIR KIT LOCK CYLINDER

Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QTY	PRIC	DISC	VALUE
1	698.03	0.00	698.03
3	53.92	0.00	161.76

Total Parts : 859.79

Labour 1	:	650.00
Parts	:	859.79
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	105.69
Grand Total	:	1,615.48

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

1,309.79

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190128 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : w5 49769 Page No. : 1 of 4  
Date Estimated : 15/01/2019  
Prepared By : William Teh Hooi Teik

## - ESTIMATE REPAIR FOR -

Mohamed Nasruddin Bin Mohamed ISA  
273 Tampines Street 22  
#03-46

Singapore 520273

## - ACCOUNT - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FK76C	Z911367	03/03/2017	R 1200 GSA	15949

## DESCRIPTION

Replacing damaged parts cause by accident.

## VALUE

300.00

Accident on 10/01/2019 0830hrs at service road of carpark Blk  
273 Tampines St 22.

0.00

3rd party claim against SHA7794X  
-India International Insurance Pte Ltd.  
-Claim ref-CC4/III19000990/ha3

0.00

Total Labour 1: 300.00

## PART NUMBER DESCRIPTION

77418562409 ALUMINIUM CASE LH

QTY	PRIC	DISC	VALUE
1	698.03	0.00	698.03

Total Parts : 698.03

Labour 1	:	300.00
Parts	:	698.03
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	69.86
Grand Total	:	1,067.89

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## Nivitha (LKK Auto)

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 16 January 2019 1:50 PM  
**To:** Teh Hooi Teik; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Pooi Chin Han Daniel  
**Subject:** RE: FK76C - Accident on 10/01/2019 0830hrs at service road of carpark Blk 273 Tampines St 22 - 3rd party claim against SHA7794X(India International Insurance Pte Ltd)  
**Attachments:** FK76C GIA report.pdf; FK76C Repair estimate.pdf

2.27pm @ 16/1/2019

Person @ William

VNI  
Reputation on 23/01/19

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FK76C and let us have your report urgently.

This claim will be handled by Daniel.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
Gabriel Wee



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Teh Hooi Teik [mailto:teh.hooi.teik@simeдарby.com.sg]  
**Sent:** 16 January, 2019 12:02 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Kris Chew L C <kris.chew.leechye@simeдарby.com.sg>; Elaine Wong <elaine.wong.kengloon@simeдарby.com.sg>; Muhammad Hasroy Osman <hasroy.osman@simeдарby.com.sg>  
**Subject:** RE: FK76C - Accident on 10/01/2019 0830hrs at service road of carpark Blk 273 Tampines St 22 - 3rd party claim against SHA7794X(India International Insurance Pte Ltd)

Hi Gabriel,

Please assign to LKK Auto Consultants Pte Ltd.

Thanks

William Teh  
Customer Service Advisor  
Performance Motors Limited  
DID: +65 6319 0530 | Fax: +65 6479 6601 | Email: [teh.hooi.teik@simeдарby.com.sg](mailto:teh.hooi.teik@simeдарby.com.sg)

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Wednesday, 16 January, 2019 9:11 AM

**To:** Teh Hooi Teik <[teh.hooi.teik@simedarby.com.sg](mailto:teh.hooi.teik@simedarby.com.sg)>

**Subject:** RE: FK76C - Accident on 10/01/2019 0830hrs at service road of carpark Blk 273 Tampines St 22 - 3rd party claim against SHA7794X(India International Insurance Pte Ltd)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street, #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

---

**From:** Teh Hooi Teik [<mailto:teh.hooi.teik@simedarby.com.sg>]

**Sent:** 15 January, 2019 8:35 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Cc:** Kris Chew L C <[kris.chew.leechye@simedarby.com.sg](mailto:kris.chew.leechye@simedarby.com.sg)>; Elaine Wong

<[elaine.wong.kengloon@simedarby.com.sg](mailto:elaine.wong.kengloon@simedarby.com.sg)>; Muhammad Hasroy Osman <[hasroy.osman@simedarby.com.sg](mailto:hasroy.osman@simedarby.com.sg)>

**Subject:** FK76C - Accident on 10/01/2019 0830hrs at service road of carpark Blk 273 Tampines St 22 - 3rd party claim against SHA7794X(India International Insurance Pte Ltd)

Dear Sir/Madam,

Please arrange a survey for accident bike FK76C on 23/01/2019(Wednesday) at address below:-

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

**NOTE – The bike is currently with owner, he will send in only on 23<sup>rd</sup> January 2019 morning.**

Please avoid lunch timing from 1230-1330

Contact person – William +65 96328105

Thanks




William Teh  
Customer Service Advisor  
Performance Motors Limited  
DID: +65 6319 0530 | Fax: +65 6479 6601 | Email: [teh.hooi.teik@sime-darby.com.sg](mailto:teh.hooi.teik@sime-darby.com.sg)

**CELEBRATE PERFORMANCE FROM 1 to BMW i.**  
ENJOY HIGH PERFORMANCE DEALS ON THE ENTIRE BMW RANGE.

[FIND OUT MORE](#)

BMW  
PERFORMANCE  
FEST



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



## Print Received Message

This mail is associated with :

**\*FK76C (MCT19010247)**  
**[SHA7794X]**

TP

MOHAMED NASRUDDIN BIN MOHAMED ISA

Jan 10 2019 8:00AM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 28/03/2019 10:48 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$1097.89) - FK76C - Claim Handler: Pooi Chin Han Daniel

Approved:1097.89.

**Performance Motors Limited**

A member of the Sime Darby Group  
Co Reg No: 197401559W

**DISCHARGE / SATISFACTION CERTIFICATE**

Vehicle No. : FK76C

Make / Model : BMW (K51) R1200GSA

Accident Location : Along service road of carpark Blk 273  
Tampines St 22

Date of Accident : 10/01/2019

Name of Owner / Insured : Mohamed Nasruddin Bin Mohd ISA

Repairer : Performance Motors Limited

Own Insurer : Direct Asia Insurance


Motor Insurance Policy No. : MC/00457261

Claim Reference No. : CC4/III9000990/  
HA3

Policy Excess (W/GST) : \_\_\_\_\_

Official Receipt No. : \_\_\_\_\_

I/We hereby declare and confirm that I have received from the Repairers my/our Vehicle and that the repairs have been carried out to my/our entire satisfaction. I/We agree that the settlement of the cost of repairs by the Insurance Company to the account of the Repairers for the repairs shall be in full discharge of all claims under the Motor Insurance Policy in respect of damage to my/our vehicle resulting from the Accident/Loss on the Date of Accident/Loss.

Signature of Owner / Insured : 

Date : 27/2/19

Without Prejudice for any  
Personal Injury Claim

# Performance Motors Limited

A member of Sime Darby Group

## Acknowledgement Form

Accident Involving FK76C & SHA7794X on 10/01/2019

I, MOHAMED NASRUDDIN BIN MOHD ISA the owner of Vehicle Registration Number FK76C, have been advised by Customer Service Adviser and understand the content of my motor claim as specify herein:

1. Type of claim: ☐ Own-Policy + Uninsured Losses  
☒ Direct Settlement with 3<sup>rd</sup>-Party Insurer
2. Costs of repair: \$ ~~1,064.68~~ 1,067.79
3. Excess (if applicable): \$ N/A
4. Loss of Rental / Loss of Use: \$ 30.00
5. Injuries: ☐ Yes ☒ No
6. Others (subject to proof of receipt): N/A
7. I am fully aware that Performance Motors Limited is assisting me in my claim against the third-party insurer. I shall release Performance Motors Limited against any liability, loss claim or proceedings which may arise out of or in the course of or by reasons of execution of the services.
8. In the event that my insurer/third party insurer is not prepared to settle the claim due to breach of policy or other reasons, I shall pay Performance Motors Limited the full repair bill.
9. A towing charge of \$120.00, administration fee of \$300.00 and storage fee \$50.00/ day is chargeable to me if my vehicle is not repaired by Performance Motors Limited.
10. The average time span to settle a claim is **6 months** or longer for complex cases. Any correspondence or status enquiry of the mentioned claim shall be directed to the under-mentioned personnel:

Name: Mr Kris Chew  
Tel.: 63190531  
email: [kris.chew.leechee@sime-darby.com.sg](mailto:kris.chew.leechee@sime-darby.com.sg)

Signed by:



Name: MOHAMED NASRUDDIN BIN MOHD ISA  
NRIC No.: S8011295E  
Date: 27/02/2019

## LETTER OF AUTHORISATION

ACCIDENT INVOLVING FK76C & SHA7794X ON 10/01/2019 .

I MOHAMED NASRUDDIN BIN MOHD ISA owner of Vehicle Registration No. FK76C hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:



Name : MOHAMED NASRUDDIN BIN MOHD ISA (Date) 11/01/2019

NRIC No.: S8011295E

In the presence of:



Name : TEH HOOI TEIK

(Date) 11/01/2019

NRIC No.: G6666108W



INDIA  
INTERNATIONAL  
INSURANCE  
PTE LTD  
100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

INDIA INTERNATIONAL INSURANCE PTE LTD

100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER

#### III- Direct Settlement (PODS)

India Ref: NOT19010247  
Claimant Ref: PK76C

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 1,067.89 (repair cost), S\$ 30.00 (loss of use/~~use~~), S\$ — (search fee), vehicle no. PK76C that was damaged pursuant to the accident which occurred on 10/01/2019 (date) at BLOCK 213 TAMPINES ST 22 (location) involving vehicle no. SWATRAK insured vehicle. This is pursuant to the inspection conducted on 23/01/2019 (date) at "the workshop".

We/I confirm that we/I am/am authorized by the owner MOHAMMED NIKRUDDIN BIN MOHAMMED ISA ("the third party claimant") of vehicle no. PK76C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to PK76C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,097.89 to PERFORMANCE MOTORS LIMITED

Dated this 12 day of APRIL 20 19

#### CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

GARY POH CHAI HOON

Performance Motors Limited

Signed by "the Workshop" (with chop)  
Sima Darby Performance Centre  
Singapore 159941

#### WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



HBR

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

219, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190527 (AfterSales)  
63190533/530 (Motorrad)  
64794601 (AfterSales)  
64794624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : w5 1340391	Page No. : 1 of 1
Date IN : 26/02/2019	Invoice Number : 2070586 / WSB
Cust. Svc. Advisor : William Teh Hooi Teik	Invoice Date : 27/02/2019
	Payment Term : 30 Days From Invoice
	Invoice By : William Teh Hooi Teik

## - CUSTOMER INFORMATION -

Mohamed Nasruddin Bin Mohamed ISA  
273 Tampines Street 22  
#03-46  
  
Singapore 520273

## - INVOICE TO - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO. FK76C	CHASSIS NO. Z911367	REGN. DATE 03/03/2017	MODEL R 1200 GSA	MILEAGE 16764
--------------------	------------------------	--------------------------	---------------------	------------------

CODE	DESCRIPTION	UNITS	NETT
0099000	Replacing damaged parts caused by accident.	1.00	300.00
	Accident on 10/01/2019 0830hrs at service road of carpark Blk 273 Tampines St 22.	0.00	0.00
	3rd party claim against SHA7794X.	0.00	0.00
	-India International Insurance Pte Ltd		
	-Claim ref-CC4/IIII9000990/ha3		
	-Accident vehicle survey by Mr Rasul from LKK on 23/01/2019.	0.00	0.00
	-Repair authorised by Poh Kin from LKK on 24/01/2019.		
	Sub-Total :		300.00

CODE	DESCRIPTION	UNITS	NETT
77418562409	ALUMINIUM CASE LH	1.00	698.03
	Sub-Total :		698.03

Labour Charges :	300.00	Total Labour & Parts Charges :	S\$ 998.03
Parts Charges :	698.03	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	0.00	Invoice Total Amount Exclude GST :	S\$ 998.03
		GST @ 7% :	S\$ 69.86
		Invoice Total Amount Include GST :	S\$ 1,067.89
		Less Deposit/Voucher :	S\$ 0.00

Computer generated invoice. No signature is required.	Amount Payable Include GST:	S\$ 1,067.89
---	-----------------------------	--------------

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2019 <a href="#">Edit Reg</a>		16 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$998.03</b> <a href="#">Edit Estimates</a>	<b>S\$998.03</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	MOHAMED NASRUDDIN BIN MOHAMED ISA, ID: S8011295E		
Vehicle Reg. No.:	FK76C	Date of Loss:	10/01/2019 08:00 - :59 [22 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19010247	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHA7794X	Policy No. (Claimant):	MC/00457261
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/01/2019]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III\_SG (28/03/2019): Alert - Adj Mandate Approved (S\$1097.89) - FK76C - Claim Handler: Pool Chin Han ...
- III\_SG (24/01/2019): Alert - Adj Mandate Approved (S\$0.00) - FK76C - Claim Handler: Pool Chin Han Dan...

## ALL ASSOCIATED TASKS


































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*FK76C (MCT19010247)  
[SHA7794X]  
TP  
MOHAMED NASRUDDIN BIN MOHAMED ISA  
Jan 10 2019 8:00AM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	07/03/19 11:40	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
2	07/03/19 11:40	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
3	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	07/03/19 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
20	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
21	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
22	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
23	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
24	07/03/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	16/01/19 16:15	TP ESTIMATE	 Load PDF		
2	16/01/19 16:15	TP GIA REPORT	 Load PDF		
3	16/01/19 16:15	ACKNOWLEDGEMENT EMAIL TO III DD 16.01.2019	 Load PDF		
4	29/01/19 13:18	TP ESTIMATE - MARKED	 Load PDF		
5	11/03/19 16:13	WORKSHOP INVOICE	 Load PDF		
6	11/03/19 16:13	LOD	 Load PDF		
7	17/04/19 08:53	DISCHARGE VOUCHER	 Load PDF		
8	17/04/19 08:53	AUTHORISATION TO ACT FORM	 Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print	
1	17/01/19 08:51	Singapore Accident Statement	 Load PDF		

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19000990/R1HA3Q2

Date: 17/04/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle  
No : FK76C

Insured Vehicle No : SHA7794X

Date of Loss: 10/01/2019

Nature of Claim:

TP

Claim No: MCT19010247

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FK76C

Make &amp; Model: BMW R1200 GSA, 1.2

Engine No: 122EN41161105

Reg. Date: 03/03/2017 (Man. Year: 2016)

Chassis No: WB10A0208HZ911367

Colour: Black

Odometer: 16256 km

Engine Capacity: 1170 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70 R19

Rear Tyre Size:

170/60 R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	859.79	698.03	161.76	18.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	300.00	350.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,509.79</b>	<b>998.03</b>	<b>511.76</b>	<b>33.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>105.69</b>	<b>69.86</b>	<b>35.83</b>	<b>33.90</b>
<b>Nett Amount (S\$)</b>	<b>1,615.48</b>	<b>1,067.89</b>	<b>547.59</b>	<b>33.90</b>
<b>+ Loss of Use (1.0 x S\$30.00/day) (S\$)</b>		<b>30.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,097.89</b>		

## INSPECTION

Date of Assignment: 16/01/2019

Date Inspected: 23/01/2019 Inspected At:

315 ALEXANDRA ROAD  
Repairer: Performance Motors Limited  
(Alexandra)

Estimated Period of Repair: 1.0 days

**Adjuster:** MOHD RASUL

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 11 Mar 2019)	
<b>Parts:</b>	N/A	BMW R1200 GSA 1.2 (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FK76C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALUMINIUM CASE LH	Scratched	698.03 FS	*698.03 FS
2	3		*REPAIR KIT LOCK CYLINDER	Not Necessary	161.76 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>859.79      698.03</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING DAMAGED PARTS CAUSE BY ACCIDENT	New	650.00	300.00
Gross Labour Cost (S\$)			650.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >