

ASS. REC. BY:

REF CS3/LPC19000997/RH d3 n2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Ong Ki Ki

of JPC

Date/Time: 16/1/19 @ 12:40pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 5480D

Insured: GY 3826A

at Workshop m/s: Willy Motor

Tel: 927 67180

of 27A Jurong Port Road #01-32

Policy No: Claim No: SKT 5480D / WM / ms / w /

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 15/01/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 2:36pm 16/1/19 Person Contacted: Ms. Khoo

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	GY 3826A - NA / TMI / 6014861/s
	SKT 5480D - X
22/1/2019	Submit P&S Report.



## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Wednesday, 16 January 2019 12:40 PM  
**To:** Accident@kscgp.com; MT\_Claim\_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'  
**Subject:** Our Ref: TBA RE: 2nd Notice to conduct Pre- Repair Survey (Your Ref: GY 3826A Our Ref: SKT 5480D/WM/ms/wl)  
**Attachments:** 2nd PRS - GY 3826A (Lonpac).pdf; 1st PRS - GY 3826A (Lonpac).pdf; GIA.PDF

Without Prejudice  
Save as to Costs


Dear Wei Lin

We are not agreeable to your proposed list of surveyor and we shall appoint LKK Auto Consultants Pte Ltd to conduct the pre-repair survey.

Dear Catherine/Nivitha

Fya

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



**From:** Accident@kscgp.com [mailto:Accident@kscgp.com]  
**Sent:** Wednesday, 16 January, 2019 12:34 PM  
**To:** ONG LI LI; MT\_Claim\_SG  
**Subject:** 2nd Notice to conduct Pre- Repair Survey (Your Ref: GY 3826A Our Ref: SKT 5480D/WM/ms/wl)

Dear Sirs,

Please find enclosed herein the 2nd Notice to conduct Pre-Repair Survey for your immediate attention and necessary action. Our client is not agreeable to your proposed list of motor surveyors.

Thank you.

Regards,  
Wei Lin  
for and on behalf of Mr Gurdeep Singh Sekhon  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0983 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** ONG LI LI [mailto:[llong@lonpac.com](mailto:llong@lonpac.com)]  
**To:** [Accident@kscgp.com](mailto:Accident@kscgp.com), [mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)  
**Sent:** Wed, 16 Jan 2019 04:17:32 +0000  
**Subject:**

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>
4	Bryan Ang	<input type="checkbox"/>
5	Adrian Ling	<input type="checkbox"/>
6	Mohammed Rasul	<input type="checkbox"/>
7	Marcus Chua	<input type="checkbox"/>
8	Kenneth Kong	<input type="checkbox"/>
9	Muhammad Nazril Bin Abdullah	<input type="checkbox"/>
10	Sathya Sai Kathirrasen	<input type="checkbox"/>

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



**From:** [Accident@kscgp.com](mailto:Accident@kscgp.com) [mailto:Accident@kscgp.com]

**Sent:** Tuesday, 15 January, 2019 6:15 PM

**To:** MT\_Claim\_SG

**Subject:** Notice to conduct Pre-Repair Survey (Your ref: GY 3826A Our Ref: SKT 5480D/WM/ms/wl)

Dear Sirs,

Please find enclosed herein the Notice to conduct Pre-Repair Survey, for your immediate attention and necessary action.

Thank you.

Regards,

Wei Lin

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0983 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Your Ref : GY 3826A  
Our Ref : **SKT 5480D/WM/ms/wl**  
Date : 16 January 2019

Fax : **6538 3708**  
Tel : **3152 0983**  
Email : **accident@kscgp.com**

Lonpac Insurance Bhd

BY EMAIL ONLY

**DATE OF ACCIDENT: 15 JANUARY 2019**  
**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email dated 16 January 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services
4.	Leslie Lim	Premier Appraisal Services
5.	Ng Kong Beng, Patrick	Carlink Consultancy
6.	Andrew How	Prominent Appraiser Services Pte Ltd
7.	Gan Song Sing, Roger	ROG Associates
8.	Dennis Yap	Pal's Appraiser Pte Ltd
9.	Michael Yap	Mc-Coy Appraiser Pte Ltd
10.	Nicky Seah	Absolute Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Willy Motor Company  
27A Jurong Port Road  
#01-32  
Singapore 619101

Contact Person/Tel : Ms Khoo (h/p: 9276 7180)

Yours faithfully,

*WL*

Your Ref : GY 3826A

Our Ref : SKT 5480D/WM/ms/wl

Date : 16 January 2019

**Acknowledgement**

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of  
\_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC19000997/R1td3n2 Date: 23-01-2019 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GY 3826A	Veh. Inspected	SKT 5480D
Policy No.		Coverage (\$)	0.00
Claim No.	KT5480D/WM/ms/wl	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	16/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11022268	Colour	WHITE
Odometer	99010 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information			
Accident Date	15/01/2019	Inspect Date / Time	16/01/2019 ( 04:47 PM )
Survey held at	WILLY MOTOR COMPANY 27A JURONG PORT ROAD #01-32 SINGAPORE 619101		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19000997/R1td3n2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.