

ASS. REC. BY:

REF: CS/MSG19001004/Gnd30p

Special Instruction:

Survivor:

merimen

From (Person):

Gao Qiang  
Jowyn Tay

ASSIGNMENT (Office)

of

MSG

Date/Time:

16/11/19 @ 3:57pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 4168K

Insured:

YN 3941U

at Workshop m/s

Chew Goon Motor

Tel:

6 484 1626

of

Blk 10, Amk Ind. Park 2A #01-15/16

Policy No:

29090174MKF

Claim No:

582385

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6  
27/01/2019

CA / REV / REP. / REV 24 HRS

'up'

17/11/19

H.O.D. Endorsement:

Date/Time:

4:32pm @ 16/11/19

Person Contacted:

Grace / Kelly

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 4168K - X

YN 3941U - X

18/11/19

Send preli revised via merimen

30/7/19

Gao Qiang sent E-Mail to, the price \$3675.68

22/8/19

Final fig \$4237.13 confirmed by email (Ref 1265.87, 23/9)

Xme

REF: MSIG

B296

## ASSIGNMENT

From Date: 17/01/19

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLW 4168K

at Workshop m/s

Chew Goon

of

Blk 10, Amk Ind. park 2A # 01-15

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW4168K

Veh Regn:

09 Feb 2018

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota C-HR

C.C.

1797

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading:

29701

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

8YX102060295

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD MRim or

Tyre Size:

F:

255/60R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

Survey held at

w/s

17-01-19

4:30pm

Des. of Damages: Frt / Rear / ☒ D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

22/8 - typist

Report Format:

menmen

Lump Sum / I.B.I: (\$)

4237.13

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

190

Transportation:

) 3 + PS \$

) Photos

) Others

) Total

TOTAL

11

161

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		16 Jan 2019 15:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

<b>CLAIM SUBFOLDER DETAILS</b>		<a href="#">[Created by insurer]</a>
Insured:	SKYLINK VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201710755G	
Main Claimant:	LIM LAM HUI, ID: S1296329G	
Vehicle Reg. No.:	SLW4168K	Date of Loss: 07/01/2019 18:00 - :59 [10 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582385	Policy/Cover Note No.: 29090174MKF (TP, Fire & Theft) Coverage: 23/07/2018 - 22/07/2019
Vehicle Reg. No. (Insured):	YN3941U	Policy No. (Claimant):
		Excess:
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 17/01/2019]</b>	
Adj Asg. Remarks:	SJE AGREED / LIABILITY NOT CLEAR ( NON REPORTING ) VEHICLE IN THE WORKSHOP Please appoint LKK AUTO to conduct the survey . Kindly contact MS GRACE @ 6484 1626 to arrange for survey .	

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jowyn Tay Mei Ling	Date: 18 Jan 2019
<b><u>Preliminary Advice</u></b>	

Insured Vehicle No	: YN3941U	Accident Date	: 07/01/2019
TP Vehicle No	: SLW4168K	Assignment Date	: 16/01/2019
Make	: TOYOTA C-HR HYBRID	Est. Duration of Repair	: 4.00
Date of Inspection	: 17/01/2019		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,503.00
Revised Amount	:S\$	4,566.50
Check Items (Estimated)	:S\$	240.00
Total	:S\$	4,806.50
Lump Sum Repair	:S\$	
<b>Total Loss Consideration</b>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 6329G

### Vehicle Details

Vehicle No.: SLW4168K  
Vehicle to be Exported: No  
Intended Deregistration Date: 18 Jan 2019  
Vehicle Make: TOYOTA  
Vehicle Model: C-HR HYBRID 1.8S CVT  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: 2ZR8158308  
Chassis No.: ZYX102060295  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$27,587.00  
Original Registration Date: 09 Feb 2018  
First Registration Date: 09 Feb 2018  
Transfer Count: 0  
Actual ARF Paid: \$10,622.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 08 Feb 2028  
PARF Rebate Amount: \$7,966.00

### Intended COE Rebate Details

COE Expiry Date: 08 Feb 2028  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$45,289.00  
COE Rebate Amount: \$41,022.00  
**Total Rebate Amount: \$48,988.00**

The information contained herein is correct as at 18 Jan 2019

OK

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6329G

**Vehicle Details**

Vehicle No.:	SLW4168K
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZR8158308
Chassis No.:	ZYX102060295
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,587.00
Original Registration Date:	09 Feb 2018
First Registration Date:	09 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$10,622.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2028
PARF Rebate Amount:	\$7,966.00

**Intended COE Rebate Details**

COE Expiry Date:	08 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$41,150.00
<b>Total Rebate Amount:</b>	<b>\$49,116.00</b>

The information contained herein is correct as at 07 Jan 2019

OK

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

License Number: **S1296329G**

Name: **LIM LAM HUI**

Basic Date: **15 Mar 1958**

Issue Date: **05 Jun 2004**

001232513K



**REPUBLIC OF SINGAPORE**

IDENTITY CARD NO. **S1296329G**

Name: **LIM LAM HUI**



林南輝

Race: **CHINESE**

Date of Birth: **15-03-1958**

Sex: **M**

Country of Birth: **SINGAPORE**





**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

Class	Description	PASS DATE
Class 3	Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver, and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg	05 Aug 1978
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kg	25 May 1999

Licence No: **S1296329G**

NP 428A



0580494

**S1296329G**

Blood Group: **AB** Date of Issue: **23-10-1992**

APT BLK 11 ST. GEORGE'S ROAD #02-286  
SINGAPORE 320011

NRIC No: **S1296329G** Date: **17-12-2003(R)** No: **4840510**




## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/01/2019 14:54
Date Of Accident	06/01/2019 18:50
Exact Location Of Accident	QUEEN STREET / ROCHOR RD OSCP LOT 36
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW4168K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM LAM HUI
NRIC No	S1296329G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92360249
Alternative Phone No	OTHERS-92360249

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 E G CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098026366
Cover Note Number	09/02/2018 - 08/02/2019

### Driver

Name of Driver	LIM LAM HUI
NRIC No	S1296329G
Date Of Birth	15/03/1958
Occupation	INDOOR
Date Of Driving Pass	05/08/1978
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92360249
Fax Number	
Contact Number	OTHERS-92360249
Email Address	NOEMAIL



Address	BLK 11 ST GEORGE'S ROAD #02-286
Postcode	320011
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED POLICE REPORT (T/20190106/2121)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO SIZE TOO BIG
Was there any audio recorded?	NO

#### Details of Witness 1

Name	
Phone Number	81864246
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN3941U
Vehicle Make/Model/Colour	LORRY
Details Of Properties	REAR PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

NTUC Income Motor Service Centre 6 119  
Report No: MT/ D.O.A: /

Vehicle No: SLW4168K  
Make : Model: 71CHR

Report Date: 1/7/2019 Start Time: 3:03 PM  
Reporting Type: 7P End Time: /

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, law or court orders.

1/7/2019 15:02

Policyholder's Signature  
Date & Time:

1/7/2019 15:02

Driver's Signature (If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Chen Jun Liang  
NRIC / Fin No: S890765

Sketch Plan Pg. 2

SKETCH PLAN

QUEEN STREET / ROCHOR RD OSCP LOT 36.


Vehicle A: SLW4168K      Vehicle B: YN3941U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


REFER TO ATTACHED POLICE REPORT (T/20190106/2121)

DECLARATION

We declare the foregoing particulars are true in every respect.

  
1/7/2019 15:02  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

1/7/2019 15:02  
\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: Chen JunLiang  
NRIC/ Fin No: S990765

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190106/2121

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

1 of 3

Report No. T/20190106/2121

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 06/01/2019 22:43		Vide Report No.:	Station Diary No.: 143
<b>Informant's Particulars</b>			
Name of Informant: LIM LAM HUI		Address: APT BLK 11 ST. GEORGE'S ROAD #02-286 SINGAPORE 320011	
ID Type / ID No.: NRIC NO / S1296329G		Contact No.:	Mobile: 92360249
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 60	Date of Birth: 15/03/1958	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SELF-EMPLOYED		Driving Licence Information: Class: 3,4 Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 06/01/2019 18:50	Type of Location: Car Park
Location: Along Road 1 QUEEN STREET				
Open Space Carpark (Lot 36), Queen Street/Rochor Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLW4168K	Car	TOYOTA	C-HR HYBRID 1.8S CVT	Blue	Seriously Damaged	0
YN3941U	Lorry	MITSUBISHI		White		0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE  
POLICE FORCE**



T/20190106/2121

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

2 of 3

Report No. T/20190106/2121

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLW4168K	NTUC Income Insurance Co-Operative Limited	5098026366	09/02/2018	08/02/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Driver:		Use of Pedestrian Crossing: NA	
Name	LIM LAM HUI	ID No.	S1296329G
Related Vehicle	SLW4168K (Car)	Contact No.	92360249
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 06/01/2019 at about 1835hrs, I parked in the open space carpark (Q0007, located along Queen Street/Rochor Road) in Lot 36. I secured my vehicle and left the lot. All was in order at the time.

On the same day at about 2100hrs, I returned to the vehicle and spotted a note on the windshield stating "Review your dash cam at 1850hrs onwards. Call us for eye-witness - 81864246", thus I made a check around my vehicle and saw that there was some damages to the right body of my car. Thus I immediately called the number. The eye-witness, Raja Muhammad Israafil, informed that he had seen a white lorry appearing to do what seemed like a 3-point turn to move out of the carpark and it had scraped badly against my vehicle. The driver had come out to check but walked around the rear of the car and I am unsure if the rear cam managed to capture him.

I reviewed the dash cam footage and saw a white lorry (YN3941U) seemingly parking on the right side of my car, then subsequently moved off from the lot. I have no particulars of this driver and do not recall seeing this lorry before. This is the 1st time such an incident has occurred.

Damages to my car included scratches on the right body of the car, slight dents on the driver side door and rear right passenger door and scratches to the right side view mirror.



**SINGAPORE  
POLICE FORCE**



T/20190106/2121

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

3 of 3

Report No. T/20190106/2121

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: A / Sgt 2 STEPHANIE JESSICA ANG HUIZHEN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 06/01/2019 22:43
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authentication Stamp NP188 	Srt 2

WITNESS NOTE Pg. 1

Review  
Push Cam 4  
185072379041 works  
Call us for more  
Private Limited, a copy of which may be inspected at any Singapore  
Public place for a fee of \$1.00 per hour and \$1.00 per page.  
We have S.S.  
81866246  
Take a look at our website  
www.singapore.com



# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Accident Date : 06.01.2019

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third Party

Policy No:

Acknowledged by Repairer

Signature:

Date:

Date:

15.01.2019

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota CHR" Reg. No. SLW4168K Claiming Against Your Insured Veh. No. YN3941U			
1pc	Front Fender Protector / <i>scr.</i>		134.00 /
1pc	Front Door RH / <i>Buc</i>		1,256.00 /
1pc	Front Door Sticker / <i>mc</i>		136.00 /
1pc	Front Door Wing Mirror / <i>cut *</i>		1,260.00 /
1pc	Front Door Wing Mirror Cover / <i>x repair.</i>		102.00 X
1pc	Front Door Outer Handle / <i>cut *</i> (auto open)		403.00 /
1pc	Front Door Outer Handle End Cover / <i>CA</i>		36.00 /
10pcs	Front Door Trim Board Clips / <i>mc.</i>	4.20	42.00 20(SN)
1pc	Rear Door RH / <i>Buc</i>		1,153.00 /
1pc	Rear Door Sticker / <i>mc</i>		125.00 38.9
10pcs	Rear Door Trim Board Clips / <i>mc.</i>	4.20	42.00 20(SN)
1pc	Rear Fender Protector / <i>scr.</i>		155.00 /
	Less 25%		4,844.00 4249.5
			1,211.00
			3,633.00 2,187.13
2pcs	Front/ Rear Door Inner Sound Insulation Matte <i>X MN</i>	120.00	X 240.00 SN
	To Dismantle / Transfer 2x Door Fittings / Ancillary Accessories		100 280.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60 100.00
	Labour Charge - Panel Beating, Repairing Of Door "B" Pillar and Parts Replacement		400 600.00
	To Respray Affected Areas <i>18/1/19</i>		450 650.00
			400 650.00
		Total :	5,503.00
	4 Days. part by part. before paint photos. Gmo Qiang - 8288 0282 17/1/19.	SN: 40	Total: 4237.13

# 趙 源 摩 哆 Chew Goon Motor

新加坡坡底第2A工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)  
Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint  
Singapore 66047

Business Reg. No: 221880/00C DST Reg. No: MX-0488007-A0  
TEL: 6484 1626 (24Hrs) FAX: 6484 0455

◀ 修理各种汽车 敲焊 打吗 喷漆 等 ▶

JAE

DATE : 2/8/2019

MAY

TEL : 64179796

FAX : 67454442

Kelly

OUR REF : SLW4168K

CHASSIS : ZYX102060295

Engine no : 2ZR8158308

YEAR : 2017

L PAGE : 1/1

& MODEL : Toyota CHR

## LIST PRICE : (GENUINE PARTS)

Front Door Sticker	795.60
Front Door Wing Mirror	1190.60
Front Door Wing Mirror Cover	96.95
Rear Door Sticker	95.60

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 22 August 2019 2:12 PM  
**To:** Chew Goon Motor(ad3); Guo Qiang (LKKAUTO); SUR  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Kelly,

Noted with thanks.

**Kindly send Final invoice and all supporting documents directly to MSIG INSURANCE**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>  
**Sent:** Thursday, 22 August 2019 1:59 PM  
**To:** Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>  
**Cc:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Guo Qiang,

Confirm P/P amount \$4237.13 before GST @ 4 working days.

Thanks & Regards,  
Kelly

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15 , 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>  
**Sent:** Friday, August 16, 2019 9:50:21 AM  
**To:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>  
**Cc:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Kelly,

WITHOUT PREJUDICE

Finalize amount \$4237.13 before GST @ 4 working days.

Front Door Sticker	= \$ 48.00
Wing Mirror ( <b>complete</b> )	= \$ 1050.00
Outer Handle	= \$ 378.60
Rear Door Sticker	= \$ 38.9

---

**From:** Chew Goon Motor(ad3) [<mailto:ad3@chewgoonmotor.com.sg>]

**Sent:** Friday, 2 August, 2019 4:53 PM

**To:** Guo Qiang (LKKAuto)

**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Guo Qiang,

Kindly refer to the attached document.

Thanks & Regards,  
Kelly

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15 , 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Chew Goon Motor(ad3)

**Sent:** Friday, August 2, 2019 1:47:06 PM

**To:** Guo Qiang (LKKAuto) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg) <[chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; Eric <[eric@chewgoonmotor.com.sg](mailto:eric@chewgoonmotor.com.sg)>

**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Guo Qiang,

The list price offered is too low.  
We have check with our supplier & would like to propose

Front Door Sticker	= \$ 67.00
Wing Mirror ( <b>complete</b> )	= \$ 1260.00
Outer Handle	= \$ 378.60
Rear Door Sticker	= \$ 62.31

Thanks & Regards,

Kelly

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15, 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Guo Qiang (LKKAUTO) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>  
**Sent:** Tuesday, July 30, 2019 11:11:11 AM  
**To:** Chew Goon Motor(ad3) <[ad3@chewgoonmotor.com.sg](mailto:ad3@chewgoonmotor.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg) <[chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)>; Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Grace,

WITHOUT PREJUDICE

Finalize amount \$3675.68 before GST @ 4 working days.

Please check and confirm.

---

**From:** Chew Goon Motor(ad3) [<mailto:ad3@chewgoonmotor.com.sg>]  
**Sent:** Tuesday, 19 February, 2019 1:19 PM  
**To:** Guo Qiang (LKKAUTO); SUR; Admin A  
**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Mr Guo Qiang,

Gentle reminder.

Please finalise with us for this case.

Thanks & Regards,  
Grace

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15, 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Chew Goon Motor(ad3)  
**Sent:** Tuesday, 29 January 2019 1:12 PM  
**To:** Guo Qiang (LKKAUTO); [sur@lkkauto.com](mailto:sur@lkkauto.com); Admin A

**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)

**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Mr Guo Qiang,

Please finalise with us for this case.

Thanks & Regards,  
Grace

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15 , 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** [Chew Goon Motor\(ad3\)](#)

**Sent:** Monday, 21 January 2019 3:27 PM

**To:** [Guo Qiang \(LKKAuto\)](#)

**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)

**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Mr Guo Qiang,

As spoken, kindly refer to the attached before paint photos.

Thanks & Regards,  
Grace

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15 , 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** [Chew Goon Motor\(ad3\)](#)

**Sent:** Monday, 21 January 2019 2:48 PM

**To:** [Guo Qiang \(LKKAuto\)](#)

**Cc:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)

**Subject:** SLW4168K Accident Date: 06.01.2019

Dear Mr Guo Qiang,

As spoken, kindly refer to the attached before paint photos.

Thanks & Regards,  
Grace

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,

Ave 5 #01-15 , 16 & 17,  
\* Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

**Veron Chen (LKKAUTO)**

---

**From:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>  
**Sent:** Friday, 2 August 2019 1:47 PM  
**To:** Guo Qiang (LKKAUTO); SUR; Admin A  
**Cc:** chewgoon@singnet.com.sg; Veron Chen (LKKAUTO); Eric  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Guo Qiang,

The list price offered is too low.  
We have check with our supplier & would like to propose

Front Door Sticker	= \$ 67.00	48-00
Wing Mirror ( <b>complete</b> )	= \$ 1260.00	1050-00
Outer Handle	= \$ 378.60	✓
Rear Door Sticker	= \$ 62.31	38-90

Thanks & Regards,  
Kelly

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15 , 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>  
**Sent:** Tuesday, July 30, 2019 11:11:11 AM  
**To:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Cc:** chewgoon@singnet.com.sg <chewgoon@singnet.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019

Dear Grace,

WITHOUT PREJUDICE

Finalize amount \$3675.68 before GST @ 4 working days.

Please check and confirm.

---

**From:** Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]  
**Sent:** Tuesday, 19 February, 2019 1:19 PM  
**To:** Guo Qiang (LKKAUTO); SUR; Admin A  
**Cc:** chewgoon@singnet.com.sg  
**Subject:** RE: SLW4168K Accident Date: 06.01.2019



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		16 Jan 2019 15:57 <a href="#">Edit Adj Rpt</a>	<b>S\$4,237.12</b> <a href="#">Edit Estimates</a>	<b>S\$4,237.12</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>SKYLINK VEHICLE RENTAL PTE LTD</b> , Co. Reg. No.: 201710755G									
Main Claimant: <b>LIM LAM HUI</b> , ID: S1296329G									
Vehicle Reg. No.:	<b>SLW4168K</b>	Date of Loss:	06/01/2019 18:00 - :59 [10 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 582385</b>	Policy/Cover Note No.:	29090174MKF (TP, Fire & Theft) Coverage: 23/07/2018 - 22/07/2019						
Vehicle Reg. No. (Insured):	<b>YN3941U</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Chew Goon Motor (AMK)</b> Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 15/02/2019]								
Adj Asg. Remarks:	SJE AGREED / LIABILITY NOT CLEAR ( NON REPORTING ) VEHICLE IN THE WORKSHOP Please appoint LKK AUTO to conduct the survey . Kindly contact MS GRACE @ 6484 1626 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





















## Claim Documents

\*SLW4168K (582385)  
[YN3941U]  
TP  
LIM LAM HUI  
Jan 6 2019 6:00PM  
[SKYLINK VEHICLE RENTAL PTE LTD]  
Chew Goon Motor

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Letters/Correspondences					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	16/01/19 15:14	Non Reporting Letter to OI		Load HTM		
Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	18/01/19 15:49	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
2	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
3	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
4	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
5	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
6	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
7	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
8	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
9	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
10	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
11	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
12	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
13	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
14	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
15	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
16	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
17	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
18	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
19	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
20	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
21	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
22	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
23	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
24	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
25	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
26	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
27	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
28	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
29	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
30	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
31	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
32	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
33	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
34	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
35	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	
36	18/01/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
37	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/01/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	22/08/19 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 15:13	TPD SLW4168K GIA REPORT	 Load PDF	
2	16/01/19 15:13	TPD SLW4168K - PRI	 Load PDF	
3	16/01/19 15:13	Reply email from TP Workshop & appoint LKK AUTO	 Load PDF	
4	19/06/19 10:50	Police Report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001004/GVD3E2

Date: 11/09/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29090174MKF  
**Claimant**  
**Vehicle No :** SLW4168K **Insured Vehicle No :** YN3941U  
**Date of Loss:** 06/01/2019 **Nature of Claim:** TP **Claim No:** 582385

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

**Reg No:** SLW4168K  
**Make & Model:** TOYOTA C-HR HYBRID, 1.8 S CVT (A) **Engine No:** 2ZR8158308  
**Reg. Date:** 09/02/2018 (Man. Year: 2017) **Chassis No:** ZYX102060295  
**Colour:** Blue **Odometer:** 29701 km  
**Engine Capacity:** 1797 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

## CONDITION OF TYRES

**Front Tyre Size:** 215/60 R17 **Rear Tyre Size:** 215/60 R17  
**Front Left Side:** Dunlop 6 mm **Rear Left Side:** Dunlop 6 mm  
**Front Right Side:** Dunlop 6 mm **Rear Right Side:** Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,873.00	3,227.12	645.88	16.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,010.00	620.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,503.00</b>	<b>4,237.12</b>	<b>1,265.88</b>	<b>23.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>385.21</b>	<b>296.60</b>	<b>88.61</b>	<b>23.00</b>
<b>Nett Amount (S\$)</b>	<b>5,888.21</b>	<b>4,533.72</b>	<b>1,354.49</b>	<b>23.00</b>

## INSPECTION

**Date of Assignment:** 16/01/2019  
**Date Inspected:** 17/01/2019 Inspected At:

Chew Goon Motor (AMK)  
 Blk 10 Ang Mo Kio Industrial Park 2A,  
 #01-15/16 & 17, AMK Autopoint  
 Singapore 568047

**Estimated Period of Repair:** 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$4,237.13

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2019)
<b>Parts:</b>	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW4168K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER PROTECTOR	Scratched	134.00 FL	*134.00 FL
2	1		*FRONT DOOR RH	Buckled	1,256.00 FL	*1,256.00 FL
3	1		*FRONT DOOR STICKER	Necessary	136.00 FL	*48.00 FL
4	1		*FRONT DOOR WING MIRROR	Cut	1,260.00 FL	*1,050.00 FL
5	1		*FRONT DOOR WING MIRROR COVER	Repair	102.00 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE	Cut	403.00 FL	*378.60 FL
7	1		*FRONT DOOR OUTER HANDLE END COVER	Cut	36.00 FL	*36.00 FL
8	10		*FRONT DOOR TRIM BOARD CLIPS	Necessary	31.50 FS	*20.00 FS
9	1		*REAR DOOR RH	Buckled	1,153.00 FL	*1,153.00 FL
10	1		*REAR DOOR STICKER	Necessary	125.00 FL	*38.90 FL
11	10		*REAR DOOR TRIM BOARD CLIPS	Necessary	31.50 FS	*20.00 FS
12	1		*REAR FENDER PROTECTOR	Scratched	155.00 FL	*155.00 FL
13	2		*FRONT / REAR DOOR INNER SOUND INSULATION MATTE	Not Necessary	240.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>5,063.00      4,289.50</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,190.00      1,062.38</b>
					<b>Total Parts (\$\$)</b>	<b>3,873.00      3,227.12</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE / TRANSFER 2x DOOR FITTINGS / ANCILLARY ACCESSORIES	New	280.00	100.00
2	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	100.00	60.00
3	LABOUR CHARGE - PANEL BEATING, REPAIRING OF DOOR B PILLAR AND PARTS REPLACEMENT	New	600.00	400.00
4	TO RESPRAY AFFECTED AREAS	New	650.00	450.00
<b>Gross Labour Cost (S\$)</b>			<b>1,630.00</b>	<b>1,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >