

 SERVICE REQUESTSMESSAGESCLAIMS

Claim	S9M01AH4
Reference	CC4/ASM19001038/Apa3s2
Loss Date	January 12, 2019
Report Date	Jan 14, 2019 12:00:00 AM
Request Date	January 16, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #SLQ506B

MakeTPVD OPEL

ModelMOKKA X-1.6 CDTI 6AT (LED) (A)

Service Address

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

5

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type		Document SubType				
+ Upload Documents						
NAME		TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED	
 Accident Statement		Reports & Statement		Merimen		
 LKKInvoice1[2].pdf		Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	
 LKKAdjustment1a[1].pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	
 LKKInspection[2].pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	
 LTA SEARCH.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	
 WORKSHOP INVOICE.pdf		Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	
 PAYMENT BREAKDOWN - EXPRESS SETTLEMENT FORM.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 20, 2019	

